

22/03/2003

ASS. REC. BY:

REF: CS3/MSG18019 707/UCB⁵⁷

Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time: 30/10/18 @ 9:10am

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 8377U

Insured:

812 6988E

at Workshop m/s

A-S Auto Service

Tel:

9738 8183

of

1 Kaki Blk Ave 6 # 01-106 Autobay

Policy No:

804200930MY

Claim No:

574360

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/10/2018

(Client's Record)

31/10/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

11:23am @ 30/10/18

Person Contacted:

Ah Soon

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKB 8377U - X
	812 6988E - X
	Dismantle: 31/10/2018
	After repair: 2/11/2018

Surrounding merous

REF:

MS161

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / 18 / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKR 83774
 at Workshop m/s AS Aut. -106
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 277
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3829C

Vehicle: IN / OUT

Date: _____ Person Contacted: 17A 22802

Veh No: SKR 83774 Yr Regn: 6111
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Renault FIVE 1598
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 155794 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VFIL2B50TUC248612
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55ZR16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 31/10/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No settl. @ 11.45 am.</u>
	<u>4-5h.</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format : PRG.

Lump Sum / I.B.I. (\$) _____

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		30 Oct 2018 09:10 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	MDM TOH HONG CHOO, ID: S1724828F		
Main Claimant:	ACS-RUSHOE PTE LTD, Co. Reg. No.: 200403829C		
Vehicle Reg. No.:	SKB8377U	Date of Loss:	26/10/2018 18:00 - :59 [87 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 574360	Policy/Cover Note No.:	80420093QMY (Comprehensive) Coverage: 11/12/2017 - 10/12/2018
Vehicle Reg. No. (Insured):	SJZ6988E	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	A S Auto Service (HQ) Blk 1, Kaki Bukit Avenue 6,, #01-106 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67448183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/10/2018]		
Adj Asg. Remarks:	SJE : DISAGREE / LIABILITY NOT CLEAR(NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact AH SOON @ 9738 8183 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/10/2018 12:33
Date Of Accident	26/10/2018 18:45
Exact Location Of Accident	PIE - CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB8377U
Insured/Policyholder	
Name Of Registered Owner	ACS-RUSHOE PTE LTD
Co Reg No	200403829C
Email Address	ZHAOYI@INNOVENTE.COM
Mobile Phone No	(LOCAL) +65-91197229
Alternative Phone No	OFFICE-91197229

Vehicle Particulars

Manufacturer	RENAULT
Model	FLUENCE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100264364-07
Cover Note Number	

Driver

Name of Driver	ZHAO YI
NRIC No	S8464132D
Date Of Birth	27/11/1984
Occupation	OUTDOOR
Date Of Driving Pass	12/08/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91197229
Fax Number	
Contact Number	
Email Address	ZHAOYI@INNOVENTE.COM

Address BLK 149 SIMEI ST 1 #07-103 S520149

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer to attached report

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ6988E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TOH KAI GUAN

NRIC/Passport Number S8011237H

Contact Number 97349380

Address NA

Postcode NA

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1 NAME: : PASSANGER

GENDER: : FEMALE

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Please Chop Sign & inc...

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12:50

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A. SKB 83774
B. SJZ 1988E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary due to traffic jam, suddenly I felt an impact from behind + realised vehicle B had hit onto my rear portion

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please Chop Sign & Return

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 12:50 PM

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : zhao yi
VEHICLE NUMBER : SKB8377U
DATE/TIME OF ACCIDENT : 26/10/2018 @1845
PLACE OF ACCIDENT : PIE - CHANGI
THIRD PARTY VEHICLE (IF ANY) : SJZ6988E

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

KIAN TECK RD - SIMEI ST 1

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

NO

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

FRONT TO REAR

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO

Name: 

I Affirmed The Above Information Is Given To My Best Knowledge.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3829C
Vehicle Details	
Vehicle No.:	SKB8377U
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	FLUENCE 1.6L CVT ABS D/AB 2WD 4DR SR
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	H4MC721F096839
Chassis No.:	VF1LZB50TUC248612
Maximum Power Output:	82.0 kW (109 bhp)
Open Market Value:	\$15,864.00
Original Registration Date:	30 Jun 2011
First Registration Date:	30 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$15,864.00 7832
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2021
PARF Rebate Amount:	\$9,518.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,244.00
COE Rebate Amount:	\$13,384.00
Total Rebate Amount:	\$22,902.00

The information contained herein is correct as at 31 Oct 2018

OK

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Fast Selling! Come And Get It!
Fast! Low Depre Yrly! Lots Of
New COE Cars Avail!
Classic Credit StarAd

HIN LUNG AUTO

HoBee Group

One Stop Car Hub

Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category


Sort by Date Posted

20 results/page

4 vehicles

Renault Fluence

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Renault Fluence		Any	Any	2011	Any	Any	Any	Available
	Renault Fluence	1.6A	\$30,800	\$7,320 /yr	16-Dec-2011	1,598 cc	-	Sedan	Available
\$0 Down Payment Available! S Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Vie... 88 Motor Trading Posted: 30-Oct-2018 Tags: 2011 Renault Fluence, 2011 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault Fluence	1.6A	\$28,800	\$7,170 /yr	29-Sep-2011	1,598 cc	118,300 km	Sedan	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only. Boeki Auto & Marine Posted: 25-Oct-2018 Tags: 2011 Renault Fluence, 2011 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault Fluence	1.6A	\$25,800	\$7,180 /yr	27-Apr-2011	1,598 cc	-	Sedan	Available
No Need Repair Any Thing. Engine And Gear Box Both In Good Condition. Low Mileage. Maintained And Serviced Regularly. Posted: 10-Oct-2018 Tags: 2011 Renault Fluence, 2011 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									
	Renault Fluence	1.6A	\$32,800	\$8,080 /yr	29-Nov-2011	1,598 cc	91,908 km	Sedan	Available
Low Down Payment Available! Well Kept And Maintained By Previous Owner, Original Paintwork With Clean And Neat Interior, GPS Navigation, Serious Offer Will Be Considered. 100% Loan Approval With Our F... Posted: 13-Sep-2018 Tags: 2011 Renault Fluence, 2011 renault fluence, Renault Fluence, renault fluence, Renault, Fluence, fluence, Used Renault									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & GPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Renault Fluence, Renault Fluence Singapore, used Renault Fluence Singapore, used Renault Fluence, used vehicles Singapore or even buy used Renault Fluence Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		30 Oct 2018 09:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MDM TOH HONG CHOO, ID: S1724828F		
Main Claimant:	ACS-RUSHOE PTE LTD, Co. Reg. No.: 200403829C		
Vehicle Reg. No.:	SKB8377U	Date of Loss:	26/10/2018 18:00 - :59 [87 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 574360	Policy/Cover Note No.:	80420093QMY (Comprehensive) Coverage: 11/12/2017 - 10/12/2018
Vehicle Reg. No. (Insured):	SJZ6988E	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	A S Auto Service (HQ) Blk 1, Kaki Bukit Avenue 6,, #01-106 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67448183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 31/10/2018]		
Adj Asg. Remarks:	SJE : DISAGREE / LIABILITY NOT CLEAR(NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact AH SOON @ 9738 8183 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB8377U (574360)

[SJZ6988E]































TP









ACS-RUSHOE PTE LTD

Oct 26 2018 6:00PM

[MDM TOH HONG CHOO]

A S Auto Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 13:18	Non Reporting Letter to OI	 Load HTM	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/11/18 09:29	Accident Statement From:OD - Reg. No: SJZ6988E, Claimant: TOH HONG CHOO	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/11/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page ▼	✓
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	07/11/18 12:40	General View	 Load JPG	✓
30	07/11/18 12:40	General View	 Load JPG	✓
31	07/11/18 12:40	General View	 Load JPG	✓
32	07/11/18 12:40	General View	 Load JPG	✓
33	07/11/18 12:40	General View	 Load JPG	✓
34	07/11/18 12:40	General View	 Load JPG	✓
35	07/11/18 12:40	General View	 Load JPG	✓
36	07/11/18 12:40	General View	 Load JPG	✓
37	07/11/18 12:40	General View	 Load JPG	✓
38	07/11/18 12:40	General View	 Load JPG	✓
39	07/11/18 12:40	General View	 Load JPG	✓
40	07/11/18 12:40	General View	 Load JPG	✓
41	07/11/18 12:40	General View	 Load JPG	✓
42	07/11/18 12:40	General View	 Load JPG	✓
43	07/11/18 12:40	General View	 Load JPG	✓
44	07/11/18 12:40	General View	 Load JPG	✓
45	07/11/18 12:40	General View	 Load JPG	✓
46	07/11/18 12:40	General View	 Load JPG	✓
47	07/11/18 12:40	General View	 Load JPG	✓
48	07/11/18 12:40	General View	 Load JPG	✓
49	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
50	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
51	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
52	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
53	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
54	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
55	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
56	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
57	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
58	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
59	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
60	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
61	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
62	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
63	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
64	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
65	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
66	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
67	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
68	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
69	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
70	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
71	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
72	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
73	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
74	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
75	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	✓
76	07/11/18 12:41	Photographs of Damaged Parts	Load JPG	✓

Letters/Correspondences			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
77	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	07/11/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	07/11/18 12:42	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
125	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	07/11/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 13:22	TPD SKB8377U - PRI	 Load PDF	
2	29/10/18 16:04	TPD SKB8377U - PRI	 Load PDF	
3	29/10/18 16:05	Reject email to TP workshop & appoint LKK AUTO	 Load PDF	
4	13/11/18 09:32	SKB8377U	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18019707/UCD3S2

Date: 21/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80420093QMY

Claimant Vehicle No : SKB8377U

Insured Vehicle No : SJZ6988E

Date of Loss: 26/10/2018

Nature of Claim: TP

Claim No: 574360

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB8377U

Make & Model: RENAULT FLUENCE, 1.6 CVT ABS D/AB 2WD (A)

Engine No: H4MC721F096839

Reg. Date: 30/06/2011 (Man. Year: 2011)

Chassis No: VF1LZB50TUC248612

Colour: Grey

Odometer: 155194 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/55ZR16

Rear Tyre Size:

205/55ZR16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/10/2018

Date Inspected: 31/10/2018 Inspected At:

A S Auto Service (HQ)

Blk 1, Kaki Bukit Avenue 6., #01-106 Autobay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2018)

Parts: 143 RENAULT FLUENCE 1.6 CVT ABS D/AB 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB8377U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >