

10/1/18
Surveyor

YKL.

REF: III

19730 / Alfa - 92098

ASSIGNMENT

From: Date: 07-11-2018

Estimated Cost:

OD / ☒ PI / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 5280X

at Workshop m/s Kah motor

of 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Any
Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 5280X Yr Regn: 04 Oct 2016

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HR-V c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 58892 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU1830 GX200560

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: "

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / ☒ MZ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 07-11-18

Survey held at w/s 10Am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear w/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$1717.67

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9209Z
Vehicle Details	
Vehicle No.:	SLG5280X
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4530562
Chassis No.:	JHMRU1830GX200560
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$23,650.00
Original Registration Date:	04 Oct 2016
First Registration Date:	04 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$20,110.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Oct 2026
PARF Rebate Amount:	\$15,082.00
Intended COE Rebate Details	
COE Expiry Date:	03 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$41,490.00
Total Rebate Amount:	\$56,572.00

The information contained herein is correct as at 08 Nov 2018

OK