Fro	MMM) m (Person):	catterine thia	The second secon	VT (Office)	Date/Time: 30 0 180 2,58pm
	imated Cost			Bill to:	
	The second second		EVA/INV/MV7CS		
To	Inspect Veh	icle No:	SKG 769	59L	Insured:
	Workshop m		ir city Auto		Tel: 6781 0300
of.		BIK 9006,	Tampines st-9	3 #01-10	18
		MPCSN 3008 7			8NM18D05095001
	m Insured:_				\$ 500-00
	ake of Veh:				D.O.A. 25/10/2018
(CI	ient's Record)				0011
	A // REV Y	REP. / REV 24 HR	Sec.		H.O.D. Endorsement:
	1			10× 110	
	1	40 pm 30/10/18	Person Contacted:	L.II. A.	Vehicle IN OUT
Da	ite/Time: 3			Lui-40	Vehicle IN (OUT)
Da	1	Action/Instruction (/ Estimate		Vehicle IN (OUT)
Da	ite/Time: 3		/ Estimate	Lilita	Vehicle IN (OUT)
_Da	ite/Time: 3	Action/Instruction (SKG 7659].	/ Estimate	Luita	Vehicle IN (OUT)
_Da	ite/Time: 3	Action/Instruction (/ Estimate	Lui-Ac	Vehicle IN OUT
Da	ite/Time: 3	Action/Instruction (SKG 7659) Revert via	/ Estimate		

	in mercus.	REF:		C7./			
	,		45.0)	UNMEST		11	108
	From	Date:		Veh No. S.KG.7 Type (M.Czr.) M.Cycle / But	659 C	Yr Regn: Y	
	Estimated Cost					1.1001111111111111111111111111111111111	
	OD TP WS TTP RES TOD REST	EVA/INV/MV		Truck / Trailer of			- 3 ()
	To inspect Vehicle No	S KG 7689	1	Make Terjot	£ 851	A/C. Insured / Std	ZSG C
	at Workshop pt/5	carcity		1/-	CG .	T/Pladic: Insured / Sto	EZ-NEZ-NZ
				Sp.Reading /679	els-		
				Eng/No:	1000	00.452	64
	Policy No					0014	
	Claims No	m		Gen. Cond. Good / Pair / P			
	Sum Insured:	Excess: SO)	Steering: Inorder / Jamme			
	(Glient's Record)			Braket Incoder / Jamme	d / Leaked / B	urnt er	
	Make of V6h:			Modi: Nil / SURIE / ST	D A/Rim or	/	
				Tyre Size: F:	2151	160 NH	<u>ģ</u>
	(Policy Condition)			R;	/		
	Remark: The veh had commence	d its N/S	O/S	BS I DUN I EXNOVA I GY	/FS/LIZA/M	IC / OHTSU / PIR / SU	JML/
	repair at the time of ins	pection.		TOYO / YOKO or			
	Bal, or Market Value: 4	61K.		Front /		Rear 6	
		Consistent? : Yes or No		R/Bal.	mm	R/Bal.	111173
	House Legislating and an arrangement of the second	Consistent? : Yes or No		L/Bal. 6, ,	mm	L/Bal. 6	mm
	Est. Repairs: 6 day	D V No.		D.O.A. 25/10/18	>	D.O.I. 3///0	2/16
	Lum Sum: 20 %	3 Val.: Yes or No		Survey held at		./	1 0
		, le	110	Des. of Damages : Frt / I	Rear / O/S /	N/S / U/C / Rooftop	or or
	CA / REV / REP. / 24 HR	S LTA YS-	¥O↑ ∷IN/OUT	6	01		
	Date: Person Go	ntacted: 30/11/20	27	The U/C / Chassis fr	rame / Body S	Structure affected du	e to collision.
	Date / Time Action / Instruct	ion 2.7					
	9 yrs Inle	a. Dep / (c.			-		
	Date / Time Action / Instruct 9 yrs who	1 11/2	- 111	100 01 11	11 40	1001 1270	C3 21150
2	(1) Confirm	1 7/5 4	5 40.	so will M	12 MO	(KEC) -390.	39, 0412
	_ = = = = =	DECEME	D 0 1	FER 2019			
		RECEIVE	U Z-1	LED TOIS			
	*						
	П.			Days Of Repair:	6		
		Prell, Report			^	Survey Fee:	
	Located Located	Final Report		Resurvey No. of Trip:	1	Transportation	
	DeleyTime. Pile Return to?		Add Fe	e: Site Insp (\$) _8+F5_ \$I	
	>1/2- typist		Aug Fe	Interview (\$) Fhotos	
	Danast Format i	rimen		Tesh, Invs 18) (there	
		Sola		Weakend (\$,	
	CHURCHARD PROPERTY CO.	271112		0.000		The state of the s	CONTRACTOR OF STREET

...CLAIM SUBFOLDER...(New Assignment)

-	FOLDER TRACKI	Est Submitted	Adl Assigned	Adi Rot	Ad	Submitted	Ins Auth'ed	Sta	etus:	
Main	30 Oct 2018 Sendback Est	30 Oct 2018 11:49 \$\$7,002.53	30 Oct 2018 14:58 Assign					garrie	New Assignment Cancel Case	
	Main	Refere	nce	Clai	im Details		Documen	ts	5	how All
CLAIM SU	IBFOLDER DETA	ILS								
Insured:	GOH PEI PEI	JANICE, ID: S8	726931J, Tel: +	+65985657	32, Email:	DOLLIEPOLLIE				
Vehicle Re	SKG7659L			C	Date of Loss:	25/10/2018 [126 Month	17:00 - :59 s From LTA Res	Date (Ma	n Yr)]	
Claim Type	Type: OD / SNM18D05095C01 Policy/Cover Note No.: DMPCSN3008701800 (Comprehensive)					ehensive)				
			Excess: S\$500.00							
Repairer:	Car City Aut	o Centre Pte Ltd ((HQ) Blk 9006 #	01-198, Tar	mpines Stree	et 93, 528840	Tampines - Tel	: 6781 03	00	
Handling Insurer:		g Insurance (Sin						Thia]		
Adjuster:	LKK Auto Co	nsultants Pte Ltd	(HQ) - Tel: 625	6-3561	[Final Rpt	due 09/11,	/2018]			
Driver/Cus dian:	GOH PEI PEI	JANICE (31 / Fema	le), NRIC: S87	26931), 1	Tel: +659856	55732				
ASSOCIA	TED MAIL RECE	IVED						View All	Compose	Case Ma
There are	no mail for this ca	se.								
	OCIATED TASKS					View All	Search Tasks	Create !	New Task	Complet

No results.

View Sent Message

This mail is associated with:

SKG7659L (SNM18D05095C01)

OD Oct 25 2018 5:00PM [GOH PEI PEI JANICE] Car City Auto Centre Pte Ltd

Print Message Delete Message Forward View Recipients Resend

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/01/2019 09:46 AM. CHINA_TAIPING; catherine.thia@sg.cntaiping.com SKG 7659L-SUPPLEMENTARY From

To Subject

Dear Catherine,

Please be informed that we have received supplementary from repairer.

Refer supplementary list uploaded.

Best Regards, Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 2 November 2018 2:52 PM

To:

ccacpl@singnet.com.sg

Cc:

SUR

Subject:

SKG 7659L-DOA: 25/10/18 (CHINA TAI PING)

Dear Mr Ho.

As instructed by our client, please proceed to repair the insured vehicle SKG 7659L on Lump Sum Repair (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with:

SKG7659L (SNM18D05095C01)

OD Oct 25 2018 5:00PM [GOH PEI PEI JANICE] Car City Auto Centre Pte Ltd

From	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 02/11/2018 12:58 PM.
To	LKK_HQ
Subject	Alert - Adj Mandate Approved (\$\$6115.59) - SKG7659L - Claim Handler: Catherine Thia
Libbiosen.	:6115.59: Please proceed to authorize repairs UP TO \$6,115.59 BEFORE Excess of \$500.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd China Taiping Insurance (Singapore) Pte. Ltd. To: 51 Ubi Ave 1 #01-25 3 Anson Road Paya Ubi Industrial Park #16-00 Springleaf Tower Singapore 408933 Singapore 079909 Date: 01 Nov 2018 Catherine Thia Attn: **Preliminary Advice** Accident Date : 25/10/2018 Vehicle No : SKG7659L Policy No. : TOYOTA ESTIMA Make DMPCSN3008701800 : S\$500.00 Excess Assignment Date : 30/10/2018 : 6.00 Est. Duration of Repair Date of Inspection: 31/10/2018 : CAR CITY AUTO CENTRE PTE LTD (HQ) Inspection At BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840 Point of Impact / General Description of Damages The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. 7,002.53 Repairer's Estimate (Gross) :S\$ 3,643.20 :S\$ Revised Amount :S\$ 2,472.39 Check Items (Estimated) 6,115.59 :S\$ Total :SS Lump Sum Repair **Total Loss Consideration** :S\$ New for Old Value :S\$ 61,000.00 Pre-Accident Value 45,555.00 COE / PARF Rebate :S\$ Salvage Value :S\$:\$\$ 15,445.00 Margin for Repair Remarks (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

SINGAPORE ACCIDENT STATEMENT

Enril - 26/10/18

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2, This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

ACCIDENT STATEMENT
26/10/2018 13:02
25/10/2018 17:15
ALONG YISHUN AVE 6 NEAR BLK 405
SINGAPORE
DETAILS OF OWN VEHICLE
SKG7659L
GOH PEI PEI JANICE
S8726931J
DOLLIEPOLLIE@LIVE,COM
(LOCAL) +65-98565732
OFFICE-98565732
ТОУОТА
ESTIMA-2.4 (A)
PRIVATE USE
YES
PRIVATE CAR
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
COMPREHENSIVE
NO
DMPCSN3008701800
GOH PEI PEI JANICE
S8726931J
29/08/1987
INDOOR
15/05/2013
5 YEARS AND 5 MONTHS
FEMALE
(LOCAL) +65-98565732

OFFICE-98565732

DOLLIEPOLLIE@LIVE.COM

Address

BLK 365 YISHUN RING RD #01-1592

Postcode

760364

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

OWNER

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

3

Number of Passengers (Including Driver)

Passenger 1

NAME:

: DARIUS CHIN

GENDER:

: MALE

Passenger 2

NAME:

: DEMI CHIN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJM5309R

Vehicle Make/Model/Colour

MAZDA 5

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MICHAEL

NRIC/Passport Number

Contact Number

97814441

Address Postcode

Insurance Company Name

Nature Of Damage

FRONT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLQ8975C

Vehicle Make/Model/Colour

HONDA HRV WHITE COLOUR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

PHUA RUI TING GENEVIEVE

NRIC/Passport Number

S9025914H

Contact Number

96395491

Address Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

4

Passenger 1

NAME:

GENDER:

Passenger 2

NAME:

GENDER:

Passenger 3

NAME:

GENDER:

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external-cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 56 10 18.


Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

front	with my two kids Danine and Demi home 1 school.	
WWi	le driving towards the traffic light along	_
	un are 6 the car so infront of me stop	_
	denly when it was already green light.	
SHAV	ted driving and Stop suddenly. I had step t	1
@ b	rake and did not stop in time, and causes the	
	g to SJM 5309 R.	
The	driver infront called the ambulance and police t	0
the	scence and had checkeel all 8 of us. 1	10
200	e injury involved and no one was sent +	~
the	e hospital via the ambulance.	
	He driving I notice	
100	ome out of the for there's another car-	-
. 7	and the state of t	0
(e/fx	out of sea 89752 . SJM 5309 R.	_
=0=		_

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder' Signature

Date & Time: 0 6 10 18 GIARMCSketchPlanForm_43 12.05pm

Driver's Signature (If driver is not the policyholder) Date & Time:

Name:

NRIC/FIN No .:

Reporting Centre Personnel's Signature Name:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Cia NIDIC	
Owner ID Type:	Singapore NRIC	
Owner ID:	6931J	
Vehicle Details	SKG7659L	
Vehicle No.:	No	
Vehicle to be Exported:	01 Nov 2018	
Intended Deregistration Date:	TOYOTA	
Vehicle Make:	ESTIMA 2.4X A	
Vehicle Model:	Black	
Primary Colour:	2007	
Manufacturing Year:	2AZF062710	
Engine No.:	ACR500045264	
Chassis No.:		
Maximum Power Output:	125.0 kW (167 bhp)	
Open Market Value:	\$37,400.00	
Original Registration Date:	25 Apr 2008	
First Registration Date:	25 Apr 2008	
Transfer Count:	3	
Actual ARF Paid:	\$31,022.00	
Intended PARF Rebate Details PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	(The second sec	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	30 Nov 2027	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
PQP Paid:	\$50,168.00	
COE Rebate Amount:	\$45,555.00	
Total Rebate Amount:	\$45,555.00	

The information contained herein is correct as at 01 Nov 2018

ОК

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model: Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value: Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 26 Oct 2018

Singapore NRIC

6931J

SKG7659L

Yes

31 Oct 2018

TOYOTA

ESTIMA 2.4X A

Black

2007

2AZF062710

ACR500045264

125.0 kW (167 bhp)

\$37,400.00

25 Apr 2008

25 Apr 2008

\$31,022.00

Forfeited

\$0.00

30 Nov 2027

B - Car (1601cc & above)

10

\$50,168.00

\$45,569.00

\$45,569.00

SGEARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum .

Login Sign up

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Price Range Toyota Estima

▼ Depreciation ▼ > 10 year(; ▼ Vehicle Type

Home » Used Cars » Direct Owners » Toyota Estima 2.4A Aeras (COE till 07/2027)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

ORT

Putting time

things that

matter most

into the

On The Move

Lifestyle

Car Tyres

MICHELIN

Toyota Estima 2.4A Aeras (COE till 07/2027) Similar **Financial** Accessories

Add to Compare

Add a Note

Report Error

Photos

0

0

0

0

0

Map

Share

Car Details

Price

\$65,888

Depreciation Reg Date

Add to Shortlist

\$7,530 /vr 26-Sep-2007

(8yrs 8mths 29days COE left)

Manufactured

2007

Mileage

168,000 km (15.1k /yr)

Transmission

Auto

Engine Cap

2,362 cc \$1,802 /vr

Road Tax Power

125.0 kW (167 bhp)

View specs of the Toyota Estima (2006-2010)

Curb Weight

Features

Most Major Wear And Tear Replaced. Gearbox Done Overhaul, New Paintwork Done On Full Body.

Accessories

Double Din Display, Bluetooth. Roof Display Link To Double Din Player. Estima Blue Wording Light At The Door Side. Twin Auto Door, Both Working.

Description

Regular Servicing Done On Every 8000KM, Mostly Use For Travelling To Work. Under Usage Of MPV. No Longer Drive With Grab For 9 Months, Spent Over \$15k

For All Wear And Tear To Be Replaced, Quiet And

Smooth Engine.

COE

\$52,473

OMV

\$26,220

\$28,842

Dereg Value

\$45,917 as of today (change)

No. of Owners

3

Type of Veh

Category

CDE Car, Direct Owner Sale

Availability

Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 11-Oct-2018 | Last Updated on: 26-Oct-2018

Tags: Toyota Estima, toyota estima, 2007 Toyota Estima, 2007 toyota estima,

Toyota, Estima, estima, Used Toyota

Upfront Payment

« Imore Financial Info

Transfer Fee **Down Payment** \$25

\$19,766 (change)

Maximum 70% Loan

1st Instalment

Total Upfront Payment

\$693

\$20,484 (excluding insurance)

0 0

0

















Seller Information

Contact Person(s) David

Contact No.

85699551

Enquiry

Contact Seller

USEFUL FORMS

» Indemnity form

» Sales agreement » Hand-over form

» Receipt » M01

Instructions on how to complete a seller to end-

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE. CONNECT

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation. Free Valuation

CAR CITY AUTO CENTRE PTE LTD **BLK 9006 TAMPINES** STREE 93

> #01-198 SINGAPORE 528840

Claim Reference:

Full Report - V1

SGD

TBA

25/10/2018

Assessment Number: CCA00393

Registration: SKG7659L

Version: CAR CITY/1

Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

HO TOO BOON

Interim

China Taiping Insurance

(S) Pt

DMPCSN3008701800

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Repairs Authorised:

Estimated Repair Time:

Quote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration: Registration Month:

Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

ACR500045264 167425

Black

TOYOTA

BASE MODEL

Estima

YM2 01

SKG7659L

2AZF062710

%

Model Specs

FROM 05/2007 TYRES 215/55 VR 17

FOUR WHEEL DRIVE

2.4 LTR 117/125 KW

VERSION X

PAINTING OFF VEHICLE

NOT Afformal NAC Exuss RSUD

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage: Tyres Condition:

Tyres - Tread Depth (MM):

Left Tyre

Right Tyre Depth

Axles LHF 0 LHR 1

Depth 7.0

0.0 7.0 0.0 Severity of Impact: Vehicle Status on

Inspection: Date of Inspection:

29/10/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- RHEmentary item(s) must be resurveyed and RHRect to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

Claim Reference:

Full Report - V1

Assessment Number: CCA00393


Registration: SKG7659L

Version: CAR CITY/1


Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

Damage Areas:



Direction of Impact:



Addresses

Insured

Name: GOH PEI PEI JANICE

Address:

BLK 365 YISHUN RING RD

#01-1592

Post Code: 760364

Cost Summary

Total Labour		\$655.20
Total Paint/Material		\$127.79
Total Parts		\$5,769.54
Total of Additional Costs		\$450.00
Repair Cost Exc GST:		\$7,002.53
Overall Discount (0.0%):		- \$0.00
Excess:		-\$500.00
After Deduction -	Grand Total Exc GST:	\$6,502.53
	7 % GST:	\$455.18
	Grand Total Inc GST:	\$6.957.71

Repair Information

LABOUR	Time Basis 10 WU	경기 (10 10 10 10 10 10 10 10 10 10 10 10 10 1	1 = \$42.00/HR nt = \$42.00/HR
Repair /			
Guide Numbe	er Repair Details	wu	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
B100 ZAX	R + R LEFT FRONT WING	4.0	16.80
	(FRT BUMPER AND L/HEADLAMP ASSY REMOVED)		
B100 ZAX	R + R RIGHT FRONT WING	4.0	16.80
	(FRT BUMPER AND R/HEADLAMP ASSY REMOVED)		
B110) ZAX	RENEW RIGHT FRONT WING (REMOVED)	2.0	8.40
B131) ZAX	RENEW L/HEADLAMP PANEL	3.0	12.60
B131) ZAX	RENEW R/HEADLAMP PANEL	3.0	12.60
B010) ZAX	R + R FRONT BUMPER	5.0	21.00
	NOT INCLUDED: RADIATOR GRILLE R + R		
B020) ZAX	RENEW FRONT BUMPER (REMOVED)	6.0	25.20
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
NO NUMBER	R + R FRONT BUMPER ATTACHED PARTS	2.0	8.40
B010) ZAX	R + R FRONT BUMPER REINFORCEMENT	2.0	8.40

Claim Reference:

Full Report - V1

Assessment Number: CCA00393

Registration: SKG7659L

Version: CAR CITY/1

Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

B030 ZAX	R + R RADIATOR GRILLE	2.0	8.40
B040) ZAX	R + R LEFT HEADLAMP	1.0	4.20
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B020) ZAX	RENEW FRONT BUMPER REINFORCEMENT	1.0	4.20
B040) ZAX	R + R HEADLAMPS	1.0	4.20
3040) ZAX	R + R RIGHT HEADLAMP	1.0	4.20
N. S. C. L. C. F. M. L. C.	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B070 ZAX	RENEW BONNET	4.0	16.80
B080 ZAX	R + R L/BONNET HINGE	1.0	4.20
B080 ZAX	R + R R/BONNET HINGE	1.0	4.20
3085) ZAX	R + R SCUTTLE PANEL GRILLE	4.0	16.80
	INCLUDES: R + R BOTH WIPER ARMS		
B085) ZAX	R + R COWL PANEL TRIM	2.0	8.40
NO NUMBER	R + R UPPER RADIATOR COVER	1.0	4.20
NO NUMBER	RENEW CONDENSER / COMPRESSOR PIPE	4.0	16.80
M010 ZAX	DRAIN + REFILL AIR CONDITIONING	4.0	16.80
NO NUMBER	R + R CONDENSER/EVAPORATOR PIPE	4.0	16.80
160101) ZAX	R + R UPPER RADIATOR HOSE	1.0	4.20
160111) ZAX	R + R LOWER RADIATOR HOSE	1.0	4.20
M010 ZAX	RENEW RADIATOR AND CONDENSER	25.0	105.00
170031 ZAX	R + R HEAT SHIELD PANEL	3.0	12.60
895131) ZAX	R + R UPPER LAMBDA PROBE	4.0	16.80
LA	BOUR COST		
	Total Work Units	98.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	9.8HRS	\$411.60
	Paint Labour	5.8HRS	\$243.60
	Total Labour	15.6HRS	\$655.20

PAINT WO	RK T	ime Basis 10 WU = 1 HR. Price	= \$42.00/HR
Guide Nun	nber Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
420	FRONT BUMPER SUPPORTSURFACE PA	INT 4.0	
471	BONNET NEW PART PAINTING	14.0	
742	R/F WING NEW PART PAINTING	10.0	
1187	L/F PANEL SURFACE PAINT	4.0	
1188	R/F PANEL SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	11.0	
ı	LABOUR COST - PAINT		
	TIME(PAINT)	47.0	
	Preparation Main Work Metal	8.0	
	Preparation Comp. Work Plastic	3.0	
	Preparation Work Multi Layer Pain	t 0.0	
	Total Work Units (10WU/HR)	58.0	
	Total Paintwork Labour	5.8HRS	\$243.60
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$50.38
	New Part Painting - Plastic K1R		\$44.67
	Surface-/Blend Paint		\$5.64

Claim Reference:

DADTE

Full Report - V1

Assessment Number: CCA00393

Registration: SKG7659L

Version: CAR CITY/1

Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

Material-Const Main Work Metal \$18.10
Material-Const Comp. Work Plastic \$9.00
Total Excluding Pearlescent Uplift \$127.79
Pearlescent Uplift @ 0.0% \$0.00
Total Paint Material Cost \$127.79

PARTS					9725		v Merck Sylves v	
Cuida N	la Ohii	Danielie-		- "	Pr			06/2015
Guide N 283		Description FRONT BUMPER	Part Number	Supplier		Bet		rice (\$)
285	1	L/F BUMPER COVER	52119 28957		- /		DIS	200.00*-
286	1	R/F BUMPER COVER	52127 28180A1 52127 28180A1		- /	0%	7910	10.00*
295	1	L/F LWR BUMPER TRIM	81482 28100			V 2727	2017	10.00*
296	1	R/F LWR BUMPER TRIM	81481 28160		- /	0%	7000	50.00*
297	1	LWR RADIATOR GRILLE	53112 28010			0%	7010	50.00*
319	1	L/F OUT BUMPER BRKT	52116 28060				SNU	
320	1	R/F OUT BUMPER BRKT	52115 28120		/	0%	34	
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PART		/	0%		30.00*
365	3			5		0%	11	
		CLIP FASTENING	52161 02030			0%	77	
366	2	MOUNTING CLAMP	90179 06349			0%	11	2.56U
410	1	GRILLE MOULDING	53101 28472A1		-	0%	500	160.00*
420	1	FRT BUMPER SUPPORT	52021 28220		- /	0%	8-1	115.00*
423	1	FRT BUMPER REINF	52029 28040		-	0%	シ・フ・フ	
431	1	GRILLE BADGE	75311 28140		-	0%	1.5	33.00
471	1	BONNET	53301 28110		/	0%	Buc	
475	1	L/BONNET HINGE	53420 28130		/	0%	3/	25.00*
476	1	R/BONNET HINGE	53410 28130		1	0%	4	25.00*
477	1	BONNET STRIPE	53381 28090		-	0%	n	20.00*
493	1	BONNET LOCK	53510 28090		/	0%	7~1	25.00*
561	1	LEFT HEADLAMP ASSY	81150 28D50		- /	0%	Cne	300.00*
562	1	RIGHT HEADLAMP ASSY	81110 28D50		1	0%	cre	300.00*
647	1	L/F FOG LAMP	81220 0D042			0%	17	100.00*1/
648	1	R/F FOG LAMP	81210 0D042		1	0%	cne	100.00*
742	1	R/F WING	53811 28080			0%	1	190.00*x
789	1	L/F WING CLAMP KIT	USE SINGLE PART	S		0%	11	0.00 0
790	1	R/F WING CLAMP KIT	USE SINGLE PART	S		0%	nn	0.00 ×
841	1	L/F WHEELHOUSE COVER	53806 28030		1	0%	trea	100.00*
842	1	R/F WHEELHOUSE COVER	53805 28030			0%	12	100.00*
867	1	MOUNTING CLAMP	53813 52020			0%	11	1.600
868	1	MOUNTING CLAMP	53813 52020			0%	11	
873	6	SCREW	91631 B0614			0%	17	CONTRACTOR OF CONTRACTOR OF CONTRACTOR
874	6	SCREW	91631 B0614			0%	12	3.90UX
1011	1	UPP RADIATOR COVER	53292 28071		1	0%	Con	90.00*
1187	1	L/F PANEL	53203 28110			0%	n	135.00*€
1188	1	R/F PANEL	53202 28110			0%	n	135.00*0
1333	1	UPP BATTERY BRACKET	74404 28190		1	0%	31	20.00*
1336	1	BATTERY BRACKET	74451 52010			0%	12	10.00*
1430	1	AIR GUIDE TRIM	55708 28160			0%	11	220.00
1436	1	WASHER CONTAINER	85315 28230			0%	De	60.00*
1438	1	FILLER PIPE	85319 28230			0%	11	15.00*
4465	1	CONDENSER	88460 42100		-	0%	-	500.00*
4481	1	FRONT TUBE PIPE	88711 2J340		1	0%	sul	135.00
4482	1	EVAPORATOR TUBE	88710 2X240		- /	0%	sent	325.00
7757	1	L/UPP RADIATOR BRKT	16533 28041		- 5	0%	Buy	20.00*
			10000 10011			0 70		20.00

Claim Reference:

Full Report - V1

Assessment Number: CCA00393

Registration: SKG7659L

Version: CAR CITY/1

Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

7758	1	R/UPP RADIATOR BRKT	16533 28041	/ 0%	6 14	20.00*
7759	1	L/LWR RADIATOR BRKT	16535 20030	/ 0%		20.00*
7760	1	R/LWR RADIATOR BRKT	16535 20030	0%		20.00*
7761	1	RADIATOR	16400 28560		1.00	550.00*
7767	1	RADIATOR SHROUD	16711 28340	/ 0%		115.00*7
7769	1	UPP RAD AIR DEFLECT	16712 28060	0%		48.83UX
7770	1	TANK WATER HOSE	16261 28080	0%		25.00 ×
7771	1	WATER HOSE	16267 28070	/ 0%	- OF A	25.00
7773	1	LWR RADIATOR HOSE	16571 28060	0%	-	30.00
7774	1	EXPANSION TANK HOSE	16264 28100	- 0%		25.00
7776	1	UPPER RADIATOR HOSE	16572 28220	- 0%		30.00
7787	1	EXPANSION TANK	16470 28140	0%	200	140.00*X
7789	1	L/FAN MOTOR	16363 28300	/ 0%		135.00*
7790	1	R/FAN MOTOR	16363 28370	/ 0%		135.00
7793	1	L/BLOWER FAN	16361 28250	/ 0%	The second second	78.00 ₺
7794	1	R/BLOWER FAN	16361 28230	/ 0%	100	78.00*5
8783	1	FRONT LWR ENGINE CVR	51441 12230	0%		78.00*
8804	1	HEAT SHIELD	17167 28060	0%	11	100.00
9646	1	R/HORN	86510 28280	0%	0 47	55.00*X
f: OEM Parts			Sub Total		\$5	,669.54
g: Original			Sundry Parts	(Fixed)		\$100.00
h: Secon		d	Total Parts	,		,769.54

THIS ASSESSMENT CONTAINS UNPRICED PARTS NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	_			٠	-	
	_	,	٠.	L	а	3

x: Exchange

1000000	Description		Betterment		Price -
	FRONT NOS	SPECIALIST	0%	520	\$50.00
	PLATE, HOLD				,
	CHECK WIRING	SPECIALIST			\$50.00 30
	TOP UP AIR-CON G	GASSPECIALIST	0%		\$50.00
	COOLANT	SPECIALIST			\$50.00 —
	BATTERY	SPECIALIST	0%	SVI	\$250.00 7
			Total Extras	7/7/2	\$450.00

Final Calculation

Total Parts	\$5,769.54				
Labour					
Total Panel/Mechanical	\$411.60 407-40 369-60				
Total Paintwork	\$243.60 201.60 201.60				
Total Labour	\$655.20				
Additional Costs	36				
Corr Prot Materials External	\$0.00				
Corr Prot Materials Internal	\$0.00				
Cost of Specialist	\$450.00				
Total of Additional Costs	\$450.00				
Total Paint/Material Costs	\$127.79	00			
Repair Costs Excludes GST	\$7,002.53				
Deductions					
Deduction for Excess (Fixed)	-\$500.00				
Total Deductions	-\$500.00				

· Claim Reference:

Full Report - V1

Assessment Number: CCA00393

Registration: SKG7659L

Version: CAR CITY/1

Printed: 30/10/2018 11:40

Date Calculated: 30/10/2018 03:39

7020.53

Grand Total Excludes GST (After Deduction)

\$6,502.53

GST @ 7 % **Grand Total Includes GST (After Deduction)**

\$455.18 \$6,957.71

Assessment Notes

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel; 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

(SUPPLEMENTARY)

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLA	AIM		
Claim Type:	OD (Own Damage)	Ref. No:	OD/19004
Policy No:	DMPCSN3008701800	Date of Loss:	25/10/2018
Vehicle Reg. No.:	SKG7659L	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH PEI PEI JANICE	Contact No:	+6598565732
Driver:	GOH PEI PEI JANICE		
Make/Model:	TOYOTA ESTIMA, 2.4 (A)	Vehicle Reg. Date:	25/04/2008
Vehicle Colour:	Black		
Engine No:	2AZF062710	Chassis No:	ACE500045264
Odometer:	167425 KM		
Paint Type:			

Total Loss?

NO

Est. Duration of Repair (day) 10

Description of Accident/Loss AS PER SKETCH PLAN ATTACHED.

Present Location:

CAR CITY AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	518.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	518.00
+ GST 7.00% (S\$)	36.26
Nett Amount (S\$)	554.26
+ Previous Estimates (S\$)	6,957.71
Claim Total (S\$)	7,511.97

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Jan 2019)

Parts:

M1-MPV

TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Car City Auto Centre Pte Ltd/SKG7659L/17/01/2019 17:28

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

-	Qty Part No.	Particulars		%Disc	%Depr		Amount	211
1	1	*OIL COOLER (TRANSMISSION)		0.00	0.00		*180.00 F	
2	1	*OIL COOLER HOSE	400	0.00			7 *18.00 F	
3	1	*FRONT CROSSMEMBER	> '	0.00	0.00	sur	*320.00 F	_
F=Fra	anchise part.		Total Parts (S\$)				518.00	

Car City Auto Centre Pte Ltd/SKG7659L/17/01/2019 17:28. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items There are no new miscellaneous items selected.

Estimates on Labour There are no labour items selected.

Car City Auto Centre Pte Ltd/SKG7659L/17/01/2019 17:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >