ASS.REC.BY: REF CO FOLIA	09756/Nad3e7 Special Instruction:
	MENT (Office)
From (Person): Karen tan	Pet Dete/Time 3.48pm @30/10/18
Estimated Cost:	Bill to:
OD TO WS/TP RES/OD RES/EVA/INV/M	7 CS
	186 y Insured: SHA 2786C
at Workshop m/s Carz Au	Tel: 9023 6692
of No.61 Woodlands	nd. Park E9 # 04-04
Policy No:	Claim No: D18007761MFSH
Sum Insured:	Excess:
Make of Veh: (Client's Record)	D.O.A. 25/10/2018
CA / REV / REP. / REV 24 HRS CDS)	311016@ Morning H.O.D. Endorsement:
Date/Time: 4:35pm@ 30110118 Person Contact	
Date/Time Action/Instruction () Estim	te
3/C 486 Y - NA/INCO80	
- 1 8HA 2786c - CSIFCI	
05/11/18@14-28pm Revised to Care	n Tan by email.
04/1/190 12,29m N92 Fraksed	
· CRed 8 9731.50, 66	
	21

4	1
REF: FCI	
AMSTAL: NAT	CNMENT
<u>ASSI</u>	GNMENT
From: Date:	Veh No: STC 486 Y Yr Regn: 30 JAN 2 00
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: HONDA FIT 1.3 GA C.C.
To Inspect Vehicle No:	
at Workshop m/s	Colour S(LNEL A/C: Insur.d/Std/NI/NA
of	Sp.Reading 16587 TRadio: (insured / std / N1710)
Insured:	Eng/No:
Policy No.	C/No: GE61003544.
OL No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 175/65 R 14
(Refer Condition)	R:
(Policy Condition) Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO /YOKO or
	Rear
Bal, or Market Value: 2 4 K	R/Bal. 5 mm R/Bal. 5 mm
IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No	L/Bal, mm L/Bal. mm
Oli 11 1 Oddin	D.O.A. 25/10/18 D.O.I. 37/10/18
Est. Repairs; days Res.: Yes or No	
Lurn Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OUT	The U/C / Chassis frame / Body Structure affected due to collision.
	sed Syeas FC L/C
OF RESIDE \$18,296	. 0
	PERFUEB.
Mergin for (1pair \$6K-\$7K	RECEIVED 1 1 JAN 2019
NGZ)	sar markin 1 to
TIS CHERTIC	granks- Much
1111/ 524 K(est) 7 (18:8 (829)	5-NV= \$5704 DINIA
MV P/4 22 / 1 / 1 / 1 . P (01)) INTEGER
Daler me, me race in	Days Of Repair: 4 4 120140
1) /// turist : Final Report	Resurvey No. of Trip: Survey Fee: 130+60
Date/Time, File Return 107	
Add Fee:	: Site Insp (\$)S+RSSi
70	: Interview (\$), others
Report Format:	:Weekend (\$)
Lump Sum / I.B.t.: (\$ 5000)	TOTAL 328



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

26-10-2018

Our Ref No. D18007761MFSH

Accident Date

25-10-2018

Claim Type. Third Party

Insured Vehicle

SHA2786C

Third Party Vehicle. SJC486Y

Survey Location

NO 61, woodlands industrial park E9, #04-04, E9 Premium, s(757047)

Contact Person.

ALLAN

Contact No.

0/90236692

Fax No. 0

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

LKK AUTO CONSULTANTS PTE LTD

Surveyor

NA

Fax No. 68416315

Contact Person
Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

CARZ AUTO SERVICES

Attention. NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

KARENT

PTE LTD

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Re: HONDA FIT SJC 486Y FINALIZATION

Alex <alex@carzauto.com.sg> Fri 4/1/2019 12:29 PM To: Naz (LKKAuto) < Naz@lkkauto.com>; Hi Naz Thanks regards With Regards Mr Alex Teo Workshop Manager Carz Auto Services Pte Ltd Mobile: +65 9380 9969 Fax: +65 6493 1928 Email: alex@carzauto. com. sg On 4 Jan 2019 12:23, "Naz (LKKAuto)" <Naz@lkkauto.com> wrote: Dear Alex. As per our phone conversation, kindly acknowledge the Lump Sum COR of \$5000.00 / 9 Repair Days. Thank you. Best Regards, Naz | Technical Investigator LKK Auto Consultants

From: Naz (LKKAuto)

Sent: Wednesday, 2 January 2019 10:39:38 AM

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

To: allan_goh@carzauto.com.sg Cc: Shiau Chan (LKKAuto); SUR

Subject: Re: HONDA FIT SJC 486Y FINALIZATION

To whom it may concern,

I have submitted the estimate marking to my technical adviser for review. I will finalize the COR once he has done so.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: allan_goh@carzauto.com.sg <allan_goh@carzauto.com.sg>

Sent: Friday, 16 November 2018 1:40 PM

To: Naz (LKKAuto)

Subject: FW: AFTER REPAIR PHOTOS - HONDA FIT SJC486Y VS FIRST CAPITAL

Hi maz,

Kindly help to finalize for the total repair cost.

Thank you.

Regards,

Allan

----Original Message----

From: allan_goh@carzauto.com.sg <allan_goh@carzauto.com.sg>

Sent: Tuesday, 13 November 2018 10:53 AM To: 'naz@lkkauto.com' <naz@lkkauto.com>

Subject: AFTER REPAIR PHOTOS - HONDA FIT SJC486Y VS FIRST CAPITAL

Hi Naz,

Please refer to the after repair photos and help to finalized for the total repair cost.

There is one supplementary part (rear exhaust protector)that I have send u earlier in another mail.

The total repair number of days to be fixed at 10 days.

. Thank you

Regards, Allan

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 5 November 2018 4:28 PM 'CWS Motor Claims'; assignments

To: Cc:

'Karen Tan'; SUR

Subject:

RE: SURVEY ASSESSMENT - D18007761MFSH/1

Attachments:

CSFCI18019756Nqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJC 486Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 30 October 2018 4:41 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007761MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 31/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 30 October 2018 3:48 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan < karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007761MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: <u>D18007761MFSH</u> Our Ref: <u>CS/FCI18019756/Nqd3</u> Date: 05 November 2018

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJC 486Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/10/2018 at the premises of M/s CARZ AUTO. and have the following to report:-

Workshop Estimate Amount	: S\$	14,684.96	1.0
Revised Estimate Amount	: S\$	9,333.20	
"Check" Items Amount	: S\$	2,570.32	
Market Value	: S\$	_	
LTA Reimbursement Value	: S\$		
Nett Value	: S\$	21	

Description of Damage:
The vehicle sustained damages
at the rear portion.

rear front offside

Yours faithfully

Naz

Automotive Assessor

> Back to OneMotoring

Enquire Transfer Fee

Vehicle No. :	SJC486Y
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme :	Normal
Vehicle Make:	HONDA
Vehicle Model :	FIT 1.3GA
Chassis No.:	GE61003544
Propellant:	Petrol
Engine No. :	L13A4004176
ingine Capacity:	1339 cc
Maximum Power Output:	73.0 kW (97 bhp)
Maximum Laden Weight:	1285 kg
Jnladen Weight :	1010 kg
ear Of Manufacture :	2007
Original Registration Date:	30 Jan 2008
ifespan Expiry Date:	(*)
COE Category :	A - Car (1600cc & below)
PQP Paid :	\$21,485.00
COE Expiry Date :	29 Jan 2023
Road Tax Expiry Date :	29 Jan 2019
nspection Due Date :	29 Jan 2019
ntended Transfer Date :	31 Oct 2018
CO2 Emission :	
CO Emission :	
HC Emission :	
NOx Emission :	
PM Emission :	
the current road tay expire is 20 Is	on 2019. You may renew the road tay from 30 Oct 2018 with all pre-requisite(s) fulfilled. If the road tay is renewed after 29 Jan 2019.

The current road tax expiry is 29 Jan 2019. You may renew the road tax from 30 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00		25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	354.00		354.00
Total Amount Payable:			379.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

ck to OneMotoring

quire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Company Owner ID Type: 4323H Owner ID:

Vehicle Details

Vehicle No.: SJC486Y No Vehicle to be Exported:

26 Oct 2018 Intended Deregistration Date: HONDA Vehicle Make: FIT 1.3G A Vehicle Model:

Primary Colour: Silver 2007 Manufacturing Year:

L13A4004176 Engine No.: GE61003544 Chassis No.: 73.0 kW (97 bhp) Maximum Power Output: \$11,388.00 Open Market Value:

30 Jan 2008 Original Registration Date: 30 Jan 2008 First Registration Date: 2

Transfer Count:

\$12,527.00 Actual ARF Paid:

Intended PARF Rebate Details Forfeited

PARF Eligibility: PARF Eligibility Expiry Date:

\$0.00 PARF Rebate Amount:

Intended COE Rebate Details 29 Jan 2023

COE Expiry Date:

A - Car (1600cc & below) COE Category:

COE Period(Years):

\$21,485,00 PQP Paid: \$18,296.00 COE Rebate Amount:

\$18,296.00 Total Rebate Amount:

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Oct 2018

X153.R

7. Posted: 31-Oct-2018



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby con aforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	26/10/2018 17:15
Date Of Accident	25/10/2018 13:30
Exact Location Of Accident	BEF JUNCTION OF POTONG PASIR AVE 1 & WAN THO AVE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJC486Y
Insured/Policyholder	
Name Of Registered Owner	GOLDEN WHEEL AUTO PTE LTD
Co Reg No	201624323H
Email Address	NOEMAIL

Mobile Phone No

OFFICE-98188163 Alternative Phone No

Vehicle Particulars

Manufacturer HONDA **FIT 1.3G A** Model

Exact Purpose for which vehicle was being used at COMMERCIAL time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

AXA INSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

Policy Number GA130824/1

Cover Note Number

Driver

FOONG CHEE KEONG Name of Driver

S0151864Z NRIC No Date Of Birth 06/03/1951 **OUTDOOR** Occupation Date Of Driving Pass 06/05/1970

48 YEARS AND 5 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-98188163 Mobile Number

Fax Number

Contact Number

NOEMAIL **EMail Address**

Address

132 PUNGGOL WALK #13-18

Postcode

828777

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA2786C

Vehicle Make/Model/Colour

Details Of Properties

TAXI

Vehicle Category

THIRUMURUGAN S/O MARIMUTHU

Name of Driver

NRIC/Passport Number

S7923669A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence; statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

25-10-2018 Date & Time:

1600

Driver's Signature

(if driver'is not the policyholder) 25-16-2018

1600


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Terles

GIARMC ShatchPlanForm_V3



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 25.10	-2018, at about 1330, my vehicle was stationary on the
third lane	from the extreme right lane, before the Junction of Pollony
Pasir Ave	I and wan The Avenue due to red truthic Light Ahead.
Suddenly,	I heard a land being and impact from the rear of my
vehicle A	(STC4964) . When I alighted, I realized it was vehicle B
SHA 2786 C) who tail to brake on time and collided to my vehicle A,
	dimages to the rear portion of my vehicle 14.
	8

DECLARATION

foregoing particulars are true nevery respect.

Policyholder biarature 25 · /U · 2018 Date & Time: /600 Driver's Signature 25-10-2018
(If driver is not the policyholder) /660
Date & Time:

Reporting Centre Personnel's Signature Name:

Name: NRIC/FIN No.:

GIARMC SketchPlanForm_V3

CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel:90236692 Allan

Email:allan_goh@carzauto.com.sg

Office 69093080 GST: 201409457D FC1 PC1 RV \$26 K

COE CLEME \$ 18,300

Estimate

MS FIRST CAPITAL INSURANCE LIMITED

36, ROBINSON ROAD,#16-01 CITY HOUSE ,S(068877)

cwsmotorclaims@msfirstcapital.com.sg

TEL: 65073848 FAX: 65073849 Date: 26.10.2018 Vehicle No.: SJC486Y Make/Model: HONDA FIT Chassis GE61003544

Date of Accident: 26.10.2018 Date of Register: 30.01.2008

No.	Parts (List Price)	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	REAR TAILGATE	1	\$ 803.00	20%	\$ 642.40
2	REAR TAILGATE HINGES	2	\$ (210.00	20%	\$ 250 168.00
4	REAR TAILGATE STRIKER	1	\$ 110.00	20%	\$ xsv 88.00
5	REAR TAILGATE OUTER GARNISH	1	\$ 186.00	20%	\$ /LRK 148.80
6	REAR TAILGATE TOP LOCK ASSY	1	\$ 185.00	20%	\$ 148.00
7	REAR TAILGATE LOWER LOCK	1	\$ 203.00	20%	\$ X \N\ 162.40
8	REAR TAILGATE OPENER CABLE	1	\$ 108.00	20%	\$ XSVL ? 86.40
9	REAR TAILGATE DAMPER	2	\$ 360.00	20%	\$ 87 288.00
10	REAR TAILGATE LOGO	1	\$ 68.00	20%	\$ 54.40
11	REAR TAILGATE "FIT " EMBLEM	1	\$ 55.00	20%	\$ 44.00
12	REAR TAILGATE INNER TRIM	1	\$ 396.20	20%	\$ 316.96
13	REAR TAILGATE WEATHERSTRIP	1	\$ 182.70	20%	\$ / DEF 146.16
14	REAR TAILGATE WIPER	1	\$ 106.00	20%	\$ X 54 84.80
15	REAR TAILGATE WIPER MOTOR	1	\$ 482.00	20%	\$ \$ XSVL 385.60
16	NUMBER PLATE LAMPS	2	\$ 89.60	20%	\$? XSVL 71.68
17	REAR BUMPER	1	\$ 509.20	20%	\$ / LRY 407.36
18	REAR BUMPER TOWING COVER	1	\$ 85.60	20%	\$ MIC 68.48
19	REAR BUMPER RETAINERS	2	\$ 76.60	20% >	\$ LH @ 2 RH 61.28
20	REAR FENDER	2	\$ 1,560.20	20%	\$ LHXSW R1X R248.16
21	REAR FENDER INNER COWLING 5 121,20	12	\$ (242.40)	20%	\$LHKSVE RH TN193.92
22	REAR FENDER INNER TRIMS 4221.40	2	\$ 442.80	20%	\$? THISK, MHCLB54.24
23	REAR END PANEL	1	\$ 450.10	20%	\$ DEE 360.08
24	REAR SIDE PANEL	2	\$ 268.40	20%	\$ 7 XR 214.72
25	REAR SIDE PANEL STIFFENER	2	\$ 220.80	20%	\$ 7 XSVC 176.64
26	REAR END PANEL TOP GARNISH	1	\$ 85.60	20%	\$ DEF 68.48
27	REAR FLOOR PANEL	1	\$ 753.70	20%	\$ / DE1 602.96
28	REAR FLOOR PANEL TOP BOARD	1	\$ 485.00	20%	\$ / DEF 388.00
29	REAR FLOOR PANEL TOP BOARD TRIM	1	\$ 319.60	20%	\$ 7 NN 255.68
30	REAR TOOLS SPONGE TRAY	1	\$ 286.20	20%	\$ / DEF 228.96
31	REAR CHASSIS MEMBER RH	1	\$ 485.70	20%	\$? XSVC 388.56
32	TAILAMP	2	\$ 402.20	20%	\$/CRK 321.76
33	TAILAMP GASKETS	2	\$ 68.80	20%	\$ /NL 55.04
34	REAR SILENCER BOX	1	\$ 720.10	20%	\$ BT 576.08
35	REAR SILENCER BOX MOUNTING	2	\$ 186.20	20%	\$? CRIC 148.96
	Total List	Price:	\$11,193.70		\$ 8,954.96

5,418.76

No.	Special Nett Items	QTY	NE	TT Price		Final price	(\$)
1	NUMBER PLATE WITH CASING	1 SET	\$	50.00		\$ 40 neu	50.00
2	REAR BUMPER CLIPS	1 SET	\$	30.00	-	\$ Nec	30.00
3	REVERSE SENSOR	1 SET	\$	250.00	-	\$ 200 DEF	250.00
4	REAR TAILGATE STOPPER	2	\$	40.00	-	\$ NRC	40.00
5	WINDSCREEN SEALANT	2	\$	80.00	-	\$ ALL	80.00
6	REAR TAILGATE GARNISH CLIPS	1 SET	\$	30.00		\$ Ne L	30.00
7	REAR FENDER INNER COWLINGS CLIPS	2 SET	\$	60.00	91	\$ RH MU30	60.00
	Special Nett Ite	ms Total:	\$	540.00		\$	540.00

450

No.	Labour Charges		Price (\$)
1	To renew damaged parts, replace ,beat ,weld realign and align all parts	\$	1,400 2,000.00
2	To respray affected areas	\$	1400 1,800.00
3	To conduct Water leakage test	\$	120.00
4	To apply sealant on end panel and floor panel XNN	\$	250.00
5	To remove & refit rear windscreen for tailgate replacement	\$	80 120.00
6	To tuffcoat affect areas	\$	50 150.00
7	To remove & renew tailgate mechanism	\$	60.00
8	To remove & replace silencer box	\$	50 100.00
9	To remove & replace reverse sensor and distance settling	\$	30 -120.00
10	To tuffcoat affect areas X duplicate X	\$	go 200 .00
11	To remove/refit wiring check	\$	80.00
12	Rear Chassis alignment	\$	XNN 150.00
	Total:	\$	5,190.00

Estimate Report

Total Parts Cost

\$9494.96

Total Labour Cost

\$ 5190

Total Repair Cost

\$14684.96

Lumpsum Repair 20%:

\$11747.968

Surveyor name

Contact Number

Email

No of Days Awarded:

Date



9-10 lays

NAZ LKK

31/10/18

Carz Auto Services Pte Ltd

GrandTotal SSA: Consultants her

the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

check items photos after read protes.

need to check M and calculate

14731.52

- Naz @ Ikkauto rom

REQUEST FOR SUPPLEMENTS PARTS

Accident Case Number		Date of Collection	/ /
Vehicle No	SJC486Y	Date of Request	01.11.2018
Vehicle Model	HONDA FIT	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	LIST PRICE
1		REAR EXHAUST PROTECTOR	1	\$58.20
		7		

<>< Please submit photographs for damaged parts >>>

Signature of person making this declaration (to be signed in front of an authorised witness)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Cart.		Affiliated to Federation Inte	rnationale Des Experts En Autom	obile
MS I	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI1801975	66/Nqd3e2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 15-01-2019 Code: FCI2		
		Policy Particu	lars :- THIRD PARTY CLAI	M
	Insured Veh.	SHA 2786C	Veh. Inspected	SJC 486Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18007761MFSH	Excess (\$)	0.00
	Assign From	KAREN TAN	Assign Date	30/10/2018
		Vehicle I	Particulars & Condition	
	Make & Model	HONDA FIT 1.3G A	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GE61003544	Colour	SILVER
	Odometer	165871	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	175/65 R14	YOKOHAMA	5 mm
	L/H Front Tyre	175/65 R14	YOKOHAMA	5 mm
	R/H Rear Tyre	175/65 R14	YOKOHAMA	5 mm
	L/H Rear Tyre	175/65 R14	YOKOHAMA	5 mm
		Desc	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT TH	E REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Ge	neral Information	
	Accident Date	25/10/2018	Inspection Date	31/10/2018
	Survey held at	61 WOODLANDS IND.PAF	RK E9#04-04	
	Repairer	CARZ AUTO SERVICES P	TE LTD	
5a.			Remarks	
	B)THE INSPECTION		EPORT. A"WITHOUT PREJUDICE" BAS NS, WE HAVE NOT AUTHORIS	
5b.		Estir	mate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR	9 Working Day	s



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 486Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	DEFORMED	803.00	803.00
2	REAR TAILGATE HINGES	SERVICEABLE	210.00	
1	REAR TAILGATE STRIKER	SERVICEABLE	110.00	
1	REAR TAILGATE OUTER GARNISH	CRACKED	186.00	186.00
1	REAR TAILGATE TOP LOCK ASSY	BENT	185.00	185.00
1	REAR TAILGATE LOWER LOCK	NOT NECESSARY	203.00	8
1	REAR TAILGATE OPENER CABLE	SERVICEABLE	108.00	3
2	REAR TAILGATE DAMPER	BENT	360.00	360.00
1	REAR TAILGATE LOGO	NECESSARY	68.00	68.00
1	REAR TAILGATE "FIT" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE INNER TRIM	CRACKED	396.20	396.20
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	182.70	182.7
1	REAR TAILGATE WIPER	SERVICEABLE	106.00	
1	REAR TAILGATE WIPER MOTOR	SERVICEABLE	482.00	
2	NUMBER PLATE LAMPS	SERVICEABLE	89.60	
1	REAR BUMPER	CRACKED	509.20	509.2
1	REAR BUMPER TOWING COVER	MISSING	85.60	85.6
2	REAR BUMPER RETAINERS	N/S CRACKED	76.60	38.3
2	REAR FENDER	N/S SERVICEABLE / O/S TO REPAIR SEE LABOUR	1,560.20	į
2	REAR FENDER INNER COWLING	N/S SERVICEABLE / O/S TORN	242.40	121.2
2	REAR FENDER INNER TRIMS	N/S SERVICEABLE / O/S CRACKED	442.80	221.4
1	REAR END PANEL	DEFORMED	450.10	450.1
2	REAR SIDE PANEL	TO REPAIR SEE LABOUR	268.40	
2	REAR SIDE PANEL STIFFENER	SERVICEABLE	220.80	
1	REAR END PANEL TOP GARNISH	DEFORMED	85.60	85.6
1	REAR FLOOR PANEL	DEFORMED	753.70	753.7
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	485.00	485.0

Report Ref No. CS/FCI18019756/Nqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FLOOR PANEL TOP BOARD TRIM	NOT NECESSARY	319.60	-
1	REAR TOOLS SPONGE TRAY	DEFORMED	286.20	286.20
1	REAR CHASSIS MEMBER RH	SERVICEABLE	485.70	-
2	TAILAMP	CRACKED	402.20	402.20
2	TAILAMP GASKETS	NECESSARY	68.80	68.80
1	REAR SILENCER BOX	BENT	720.10	720.10
2	REAR SILENCER BOX MOUNTING	CRACKED	186.20	186.20
1	REAR EXHAUST PROTECTOR (ADDITIONAL)	DEFORMED	58.20	58.20
	LESS 20% DISCOUNT		-2,250.38	-1,341.54
			9,001.52	5,366.16
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE WITH CASING (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	DEFORMED	250.00	200.00
2	REAR TAILGATE STOPPER (SN)	NECESSARY	40.00	40.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	SET REAR TAILGATE GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
2	SET REAR FENDER INNER COWLINGS CLIPS (SN)	O/S NECESSARY	60.00	30.00
			540.00	450.00
	LABOUR			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD REALIGN AND ALIGN ALL PARTS. INCLUSIVE OF THE REPAIR OF O/S REAR FENDER AND REAR SIDE PANEL.		2,000.00	1,400.00
	TO RESPRAY AFFECTED AREAS.		1,800.00	1,400.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO APPLY SEALANT ON END PANEL AND FLOOR PANEL.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT REAR WINDSCREEN TO TAILGATE REPLACEMENT.		120.00	80.00
	TO TUFFCOAT AFFECT AREAS.		150.00	50.00
	TO REMOVE & RENEW TAILGATE MECHANISM.		100.00	60.00
	TO REMOVE & REPLACE SILENCER BOX.		100.00	50.00
	TO REMOVE & REPLACE REVERSE SENSOR AND DISTANCE SETTLING.		120.00	30.00
	TO TUFFCOAT AFFECT AREAS.	NOT NECESSARY	200.00	1-

Report Ref No. CS/FCI18019756/Nqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE / REFIT WIRING CHECK.		80.00	50.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	150.00	-
			5,190.00	3,120.00
	GRAND TOTAL		80.00 150.00 5,190.00 14,731.52	8,936.16

RECOMMENDED COST OF LUMP SUM REPAIRS	5,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18019756/Nqd3e2

MARKET VALUE: \$24,000.00(EST)-LTA REIMBURSEMENT VALUE: \$18,296.00=NETT VALUE: \$5,704.00

1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

XX.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.