



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD	Ref : CC4/ASM18019781/K1pa3q2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG	Date : 17-04-2020  Code : ASM



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b> SJF 2819S	<b>Veh. Inspected</b> SHC 6346C
<b>Policy No.</b> GA358317/1	<b>Coverage (\$)</b> 0.00
<b>Claim No.</b> S8M0114V	<b>Excess (\$)</b> 0.00
<b>Assign From</b>	<b>Assign Date</b> 30/10/2018

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b> KIA OPTIMA	<b>c.c</b> 1685
<b>Engine No.</b> HIDDEN	<b>Year of Reg.</b> 2015
<b>Chassis No.</b> KNAGM414MF5561555	<b>Colour</b> SILVER
<b>Odometer</b> 339457	<b>Steering</b> IN ORDER
<b>Brakes</b> IN ORDER	<b>Modification</b> STANDARD ALLOY RIM
<b>General</b> FAIR	

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/65 R16	ACHILLES	7 mm
<b>L/H Front Tyre</b>	205/65 R16	ACHILLES	7 mm
<b>R/H Rear Tyre</b>	205/65 R16	ACHILLES	7 mm
<b>L/H Rear Tyre</b>	205/65 R16	ACHILLES	7 mm

**4. Description of Damages**

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
--	---

**5. General Information**

<b>Accident Date</b> 29/10/2018	<b>Inspection Date</b> 30/10/2018
<b>Survey held at</b> PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------