

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

30-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6346 C

1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
2 pcs	Front bumper o/s & o/s side retainer @ \$16.00 <i>npx o/s?</i>	\$	32.00
2 pcs	Front bumper o/s & o/s upper bracket @ \$16.00 ✗	\$	32.00
2 pcs	Front bumper o/s & o/s support bracket @ \$16.00 ✗	\$	32.00
1 pc	Front o/s fender ✓	\$	384.00
1 pc	Front o/s fender inner shield ✓	\$	120.00
1 pc	Washer tank ✗	\$	47.00
1 pc	Washer tank motor ✗	\$	48.00
1 pc	Wheel cover ✓	\$	116.00
		\$	1,386.00
		Less 10%	\$ 138.60
		\$	1,247.40

S/NETT

1 pc	Front bumper clips ✓	\$	48.00
1 set	Front o/s fender inner shield clips ✓	\$	24.00
1 pc	Front o/s fender stickers ✗	\$	30.00
	Towing Fee	\$	50.00 ✓
	Sundry	\$	50.00 20
	To check wheel alignment	\$	80.00 ✗
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	400 650.00
	To putty and spray painting on front bumper, front o/s fender	\$	400.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 30
		\$	2,659.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka lun 16/10/18
30/10/18 1330 hrs.
3 Days
45
After Repair photo



Victory Recovery (Business Reg No.: 53096358B)
 65 Teban Gardens Rd #23-617, Singapore 600065.
 Mobile: 9618 0311 Fax: 6267 8996

CASH /
 W.O. No. 96834

TOW JOB WORKS ORDER

M premier Taxi Svc Date 29/10/18
 Car Make/Model Kia Vehicle No. SHC 6346C
 License/VRIC No./Card No. _____ Contact No. 97 65 8988
 Name - Rec'd _____ Arrived 22.00 Completed 23.00
 Amount Charge S\$ _____ M/Car park _____ Tow Truck No. GR 3375
 Destination (from) Punggol Field (to) 23 Changi (LI)
 Remark (if any) _____
 Driver's Signature [Signature] Member's Signature _____
 Tires & Towing Using King Dolley Use Car Carrier
 _____ Release Brake /