

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

30-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6418 D

1 pc	Rear n/s fender <i>X repair</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>X</i>	\$	120.00
1 pc	Rear windscreen moulding <i>X</i>	\$	87.00
1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper side bracket n/s <i>X</i>	\$	29.00
1 pc	Wheel cover <i>X repair</i>	\$	116.00
		\$	<u>2,253.00</u>
	Less 10%	\$	225.30
		\$	<u>2,027.70</u>

### S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Rear fender n/s inner shield clips <i>X</i>	\$	38.00
1 pc	Rear n/s fender sticker <i>-</i>	\$	60.00
1 pc	Sealant <i>X</i>	\$	50.00
1 set	N/s door sticker <i>X</i>	\$	100.00
	Sundry	\$	<del>50.00</del> 20
	To dismantle and refit rear windscreen	\$	<del>120.00</del> X
	To dismantle / refit reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc	\$	<del>950.00</del> 400
	To putty and spray painting on rear bumper, rear n/s fender, rear n/s door	\$	<del>600.00</del> 500
	To apply rustproofing on the repaired and replaced panels.	\$	<del>180.00</del> X
		\$	<u>4,523.70</u>

( ALL THE REPAIR COSTS ARE SUBJECT TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Centre informs and notify the Repairer of the following:  
 • To resurvey before after spray painting  
 • To display damaged part(s) during re-survey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "No Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Any temporary item(s) must be resurveyed and is subject to approval from insurance Company  
 Acknowledged by Repairer  
 Signature \_\_\_\_\_  
 Date: \_\_\_\_\_

*Kalvi LKK*  
*30/10/18 1615hr*  
*3 Days*  
*45*  
*After Repair*