

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

30-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6223 Z

1 pc	Bootlid emblem X	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover X <i>my</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge X	\$	114.00
1 pc	Rear bumper reinforcement X	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 X	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00 X	\$	46.00
		\$	1,961.00
	Less 10%	\$	196.10
		\$	1,764.90

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	Rear bumper top protector ✓	\$	80.00 50
	Sundry	\$	50.00 20
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$	650.00 300
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, X	\$	800.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
		\$	4,192.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

we hereby acknowledge and hence notify the Repairer of the following:

- * Repair only before/after spray painting
- * To delay damaged part(s) during resurvey
- * Partinances are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * Any illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin Chik
30/10/18 1000hrs
2 Pm
After Repair