

Service Order Confirmation

SERVICE ORDER NO: 18IC0047

CUSTOMER NO.: CV037597

CUSTOMER NAME: S.JORDAN ADVERTISING PTE. LTD

TELEPHONE NO.:

ADDRESS: 216D COMPASSVALE DRIVE #15-572 COMPASSVALE MAST

Singapore

VEH No.: GBG9889H

Order Date: 10/26/18

Reg Date: 08/18/17

KM: 9,663

VIN NO.: WV1ZZZ2KZHX160922

ENGINE NO:

SA: Tang Shu Shi

MODEL: CADDY 4 VAN TDI 75(A)WGDRF MODEL NO.: SAAA26

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH ELECTRICAL CHECK OR MECHANICAL REPAIR	1	TU	280		280 X
2	B&P DIAG PROGRAMMING & CALIBRATION-NETT	1	TU	480		480 /
3	B&P MACP LABOUR LABOUR	4	UNIT	840		3,360 / 1680
4	B&P MACP PAINT SPRAY PAINT	3	UNIT	800		2,400 / 1600
5	B&P NUMBER PLATE NAME PLATE 70KM	1	ST	20		20 ne /
6	B&P NUMBER PLATE NAME PLATE 6PAX	1	ST	20		20 ne /
7	B&P SENSOR SUPPLY & INSTALL REVERSE SENSOR	1	PCS	400		400 ?
Item						
8	2K5807417B 9B9 REAR BUMPER	1	PCS	683.80		683.80
9	2K5807305 REINFORCEMENT	1	PCS	630.63		630.63
10	2K5807393 BUMPER SIDE BRACKET LH	1	PCS	33.03		33.03 X
11	2K5807394 BUMPER SIDE BRACKET RH	1	PCS	33.03		33.03 X
12	357853586B GROMMET	10	PCS	1.88		18.80 ne /
13	N 0385501 RIVET	10	PCS	0.54		5.40 ne /
14	7E0853630D DPJ VW SIGN	1	PCS	75.30		75.30 ne /
15	5G0853675D 2ZZ NAME PLATE TDI	1	PCS	59.70		59.70 ne /
16	2K5853687 739 NAME PLATE CADDY	1	PCS	51.05		51.05 ne /

Remarks: FWD DIRECT SETTLEMENT

DOA: 19/10/2018

TP VEH: SJQ7326G

SURVEY BY:



Service Order Confirmation

SERVICE ORDER NO: 18IC0047
CUSTOMER NO.: CV037597
CUSTOMER NAME: S. JORDAN ADVERTISING PTE. LTD.
TELEPHONE NO.:
ADDRESS: 216D COMPASSVALE DRIVE #15-572 COMPASSVALE MAST
Singapore

VEH No.: GBG9889H

Order Date: 10/26/18
Reg Date: 08/18/17 KM: 9,663
VIN NO.: WV1ZZZ2KZHX160922 ENGINE NO:
MODEL: CADDY 4 VAN TDI 75(A)WGDRF MODEL NO.: SAAA26

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

Resue

Hp 90010068

4 days

31/10/18 @1535

Resue after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

TOTAL	8,550.74
GST AMOUNT	598.55
TOTAL AMOUNT	9,149.29

On Behalf Of "COMPANY"



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT