

ASS. REC. BY:

REF:

CS3 / LPC18019848 / G4031

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

31/10/18 @ 2:55pm.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 9246T

Insured:

SJC 1152D

at Workshop m/s

Service @ Riverview

Tel:

64819810

of

Blk 10, AMK Ind. Park 2A # 04-11

Policy No:

Claim No:

18/18/18 / VPOS / 021084

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/10/2018

CA / REV / REP. / REV 24 HRS

(up)

1/11/2018

H.O.D. Endorsement:

Date/Time:

3:48pm @ 31/10/18

Person Contacted:

Kenia

Vehicle IN (OUT)

Date/Time

Action/Instruction

(X) Estimate

SKS 9246T - X

SJC 1152D - X

15/11/18

Submit PRS.

Surveyor

PRS

REF: JPC

ASSIGNMENT

From: Date: 01/11/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8KS9246T
at Workshop m/s Service @ Riverview
of Blk 10 Amk Ind-park 2A # 04-11

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Kevin @ 64819810

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 8KS9246T Yr Regn: 14/5/2015

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima C.C. 2262

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 71895 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ACR 500 187 206

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIZ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$500 - \$1000
	RECEIVED 15 NOV 2018

Date/Time, File Pass to?

1) 15/11/2018

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

450

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 31 October 2018 2:55 PM
To: Cheonghoh Law; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Our ref: LCH.jp/AMK02-80995.18 Your ref: 18/18/18/VP05/021084 - Accident involving SKS 9246 T / SJC 1152 D (Lonpac) on 26/10/18 along Gilstead Road - Pre-repair survey ("PRS" of SKS 9246 T)

Without Prejudice
Save as to Costs

Dear Jennifer

We are not agreeable to your proposed list of surveyors. We shall appoint LKK Auto Consultants Pte Ltd to conduct PRS.

Dear Catherine/Nivitha

Please arrange.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Wednesday, 31 October, 2018 2:53 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: Our ref: LCH.jp/AMK02-80995.18 Your ref: 18/18/18/VP05/021084 - Accident involving SKS 9246 T / SJC 1152 D (Lonpac) on 26/10/18 along Gilstead Road - Pre-repair survey ("PRS" of SKS 9246 T)

URGENT

Dear Gerald

We refer to the above matter and to your letter dated 31 October 2018.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) S Kumanan
- (2) Patrick Ng Kong Beng
- (3) Dennis Yap
- (4) Philip Foo
- (5) How Andrew
- (6) Loi Boon Juan
- (7) Lek Boon Hwee
- (8) Jayson Liaw Leong San

- (9) Dave Chang Fuh Keong
(10) Lee Kok Weng

If you are not agreeable to our above list of surveyors, kindly liaise with our client's repairers for your appointed surveyor to conduct the pre-repair survey ("PRS") of our client's vehicle no. SKS 9246 T at our client's repairer workshop, the details are as follows :-

Service @ Riverview Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A #04-11
AMK Autopoint
Singapore 568047

Person to contact : Kevin (contact no. 64819810)

Kindly acknowledge.

Thank you.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 31 Oct 2018, at 12:42, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/021084

Dear Sirs,

Please see attached and revert to us.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Wednesday, 31 October, 2018 12:05 PM
To: MT_Claim_SG
Subject: Re: Our ref: LCH.jp/AMK02-80995.18 Your ref: SJC 1152 D - Accident involving SKS 9246 T / SJC 1152 D (Lonpac) on 26/10/18 along Gilstead Road - Notice of Accident

URGENT

Dear Sirs

Kindly see attached our letter dated 31 October 2018 - Notice of Accident for your attention.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

<31102018124009.pdf>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5681B
Vehicle Details	
Vehicle No.:	SKS9246T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS PREMIUM 2.4 CVT ABS AIRBAGS
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	2AZJ131673
Chassis No.:	ACR500187206
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$30,319.00
Original Registration Date:	14 May 2015
First Registration Date:	14 May 2015
Transfer Count:	0
Actual ARF Paid:	\$34,447.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2025
PARF Rebate Amount:	\$25,835.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$50,648.00
Total Rebate Amount:	\$76,483.00

The information contained herein is correct as at 15 Nov 2018

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC18019848/Gqd3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 16-11-2018		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJC 1152D	Veh. Inspected	SKS 9246T	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/021084	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	31/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ACR500187206	Colour	SILVER	
Odometer	71895 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	MICHELIN	6 mm	
L/H Front Tyre	235/50 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
5. General Information				
Accident Date	26/10/2018	Inspect Date / Time	01/11/2018 (11:30 AM)	
Survey held at	SERVICE @ RIVERVIEW PTE LTD BLK 10 AMK AUTOPOINT ANG MO KIO INDUSTRIAL PARK 2A #04-11 SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18019848/Gqd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.