

ASS. REC. BY:

REF:

031 FC18019850 / T1 CD327

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCF

Date/Time:

31/10/18 @ 3:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 60263

Insured:

8HA 3656M

at Workshop m/s

UCB Engineering

Tel:

97 317714

of

2C Julien Pesawat

Policy No:

Claim No:

D18007835MP84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/10/2018

CA / REV / REP. / REV 24 HRS

(up)

2/11/18 @ 3pm

H.O.D. Endorsement:

Date/Time:

4:12pm @ 31/10/18

Person Contacted:

Mr. Lim

Vehicle IN (OUT)

Date/Time

Action/Instruction

(X) Estimate

PA 60263 - X

8HA 3656M - CS / FCF 16002949 / Fgh 3c2

DoA: 13/02/2016

MV

Signature: *Tayhm*

REF:

FCI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Mr Lim

Date / Time

Action / Instruction

97317799

9/1/19

No GIA. Talk to Ah Sing, w/s will email to GIA, use lawyer for claims PRS case.

M.V. \$25,000

15/1/2019

Veh No

PA60263

Yr Regn:

Apr / 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Scania

C.C. *11705*

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

405 983

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

9BSK4X 2000 3572 703

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 295 / 80d 22.5

R: 6 4 (7)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ofan:

Front

Rear

R/Bal.

8 mm

S/S mm

L/Bal.

8 mm

S/S mm

D.O.A.

D.O.I. 02/11/18 @ 315pc

Survey held at

UCB Eng 2C Jln Persant

Des. of Damages: Frt / Rear / UIC / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Report Format: *PRS*

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) S + RS (\$

) Photos

) Others

TOTAL

150

150

MOTOR SURVEY ASSIGNMENT

Date	31-10-2018	Our Ref No. D18007835MFSH
Accident Date	29-10-2018	Claim Type. Third Party
Insured Vehicle	SHA3656M	Third Party Vehicle. PA6026S
Survey Location	160 SIN MING DRIVE, #04-05 AUTOCITY,	
Contact Person.	LIM	
Contact No.	97317794/ 97317794 /	Fax No. 65383708
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SOON SENG COMPANY	Attention. NIL
Cc : TP Solicitor	KSCGP JURIS LLP	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 31 October 2018 4:58 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: Karen Tan; CWS Motor Claims
Subject: 2nd Notice to conduct Pre -Repair Survey (Your Ref : D18007835MFSH ; Our Ref: PA6026S)

Dear Sirs,

Third party has amended the WS details as mentioned in the below mail.

Please do the needful.

Thank you.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Wednesday, October 31, 2018 2:13 PM
To: cwsmotorclaims@msfirstcapital.com.sg
Cc: cwsmotorclaims@msfirstcapital.com.sg; karentan@msfirstcapital.com.sg
Subject: 2nd Notice to conduct Pre -Repair Survey (Your Ref : D18007835MFSH ; Our Ref: PA6026S)

Dear Sirs,

We enclose herein an amended copy of the 2nd Notice to conduct Pre-Repair Survey, for your attention and information.

The workshop's details are as follows:

UCB Engineering Pte Ltd

2C Jalan Pesawat Jurong

Singapore 619359

Contact: Mr Lim / 9731 7794 (Please look for Ah Koon at the workshop)

Thank you.

Regards,
Wei Lin
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0984 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
To: ACCIDENT@KSCGP.COM
Cc: cwsmotorclaims@msfirstcapital.com.sg, karentan@msfirstcapital.com.sg
Sent: Wed, 31 Oct 2018 07:29:46 +0000
Subject:

Dear Sir/Madam

PRI Request For **PA6026S** Accident Involving **SHA3656M** On 29-10-2018 AT 22:15:00HRS.

Please find below details for your reference

- **Claim number :** D18007835MFSH
- **Insured vehicle number :** SHA3656M
- **Accident date :** 29-10-2018
- **Third-party vehicle number :** PA6026S
- **Assignment type :** WITHOUT PREJUDICE
- **Surveyor :** LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge :** KARENT

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System

· Motor Claims Department
· MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

This email has been scanned by the MxScan Email Security System.

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PA6026S		
Vehicle Type :	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	SCANIA		
Vehicle Model :	K124IB4X2		
Chassis No. :	9BSK4X20003572703		
Propellant :	Diesel		
Engine No. :	8053323		
Engine Capacity :	11705 cc		
Power Rating :	0.0 kW		
Maximum Power Output :	-		
Maximum Laden Weight :	16000 kg		
Unladen Weight :	11940 kg		
Year Of Manufacture :	2005		
Original Registration Date :	12 Apr 2006		
Lifespan Expiry Date :	11 Apr 2026		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$22,831.00		
COE Expiry Date :	11 Apr 2021		
Road Tax Expiry Date :	11 Apr 2019		
Inspection Due Date :	11 Apr 2019		
Intended Transfer Date :	16 Jan 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 11 Apr 2019. You may renew the road tax from 12 Jan 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 11 Apr 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 12 Apr 2019 to 11 Oct 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	364.00	-	364.00
Total Amount Payable :			389.00
Message			
This vehicle has a road tax Over Payment of \$9.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1936W
Vehicle Details	
Vehicle No.:	PA6026S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	SCANIA
Vehicle Model:	K124IB4X2
Primary Colour:	Multi-Colour
Manufacturing Year:	2005
Engine No.:	8053323
Chassis No.:	9BSK4X20003572703
Maximum Power Output:	-
Open Market Value:	\$138,090.00
Original Registration Date:	12 Apr 2006
First Registration Date:	12 Apr 2006
Transfer Count:	0
Actual ARF Paid:	\$6,905.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,831.00
COE Rebate Amount:	\$10,286.00
Total Rebate Amount:	\$10,286.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 10 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2018 13:55
Date Of Accident	29/10/2018 22:15
Exact Location Of Accident	HOLIDAY INN EXPRESS CLARKE QUAY DRIVEWAY ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA6026S
Insured/Policyholder	
Name Of Registered Owner	RMG TOURS PTE LTD
Co Reg No	197401936W
Email Address	PHLIM@RMGTOURS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62261811
Vehicle Particulars	
Manufacturer	SCANIA
Model	K124IB4X2
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	SD18V03922/VBS/R05
Cover Note Number	
Driver	
Name of Driver	YEO KOK KEE
NRIC No	S1131059A
Date Of Birth	30/05/1955
Occupation	INDOOR
Date Of Driving Pass	24/04/1987
Driving Experience	31 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96966260
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 435 HOUGANG AVE 8 #10-1677
Postcode 530435
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED .

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA3656M
Vehicle Make/Model/Colour HYUNDAI
Details Of Properties
Vehicle Category TAXI
Name of Driver LIM KOK LEONG
NRIC/Passport Number S1153075C
Contact Number 96687541
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Lim P. H.
 Hp 9731 7794
 Fleet Maintenance Manager
 RING TOURS PTE. LTD.
 109B Anson Street
 Singapore 069929
 Date & Time: 30-10-2018
 @1350 hrs.


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 30-10-2018
 @1350 hrs.


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 29-10-2018 @ 2215 hrs, I was driving my company bus PA6026S along Magazines Road fetching passengers to hotel Holiday Inn Express Clarke Quay. While I was entering the hotel drive way I noticed one taxi SHA3656M on my rear right side about to right turn into the drive way also. I already enter the driveway but the taxi continue to move forward & resulted graze onto my bus Right hand side rear portion. I then alighted & check and found scratches marks over the RHS rear wheel portion. Today the taxi's keep deny he is in the wrong & we unable to come to private settlement. Thus we wish to lodge this report & claims accordingly. We do have dash camera vedio capture, captured for this incident. There was no one injured. That's all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Lim P. H.
 Policyholder's Signature
 Fleet Maintenance Manager
 RMG TOURS PTE LTD
 109B Amoy Street 30-10-2018
 Singapore 069929 @1350 hrs


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 30-10-2018
 @1350 hrs


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
MS FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI18019850/T1cd3e2		
36 ROBINSON ROAD		Date: 22-01-2019		
#16-01 CITY HOUSESINGAPORE 068877				
Code: FCI2				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHA 3656M	Veh. Inspected	PA 6026S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007835MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	31/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA	c.c	11705	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	9BSK4X20003572703	Colour	WHITE	
Odometer	405983 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	OTANI	8 mm	
L/H Front Tyre	295/80 R22.5	OTANI	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	OTANI	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	OTANI	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information				
Accident Date	29/10/2018	Inspect Date / Time	02/11/2018 (03:15 PM)	
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$25,000.00				

Report Ref No. CS3/FCI18019850/T1cd3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.