

REF:

CS/TP18019865/Uqpn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKR13273

at Workshop m/s

Bury

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

5

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKR13273

Yr Regn:

15

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A1

Make:

Mer 3012 3100

CC

15-98

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

57220

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD2462422J289331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

30/10/18

D.O.I.

1/11/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S R.P.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 53633 R.P. x

Note new pols replaced.

Repair sum £1100 (lid £6939.77, 46%).

RECEIVED 07 NOV 2018.

Date/Time, File Pass to?



: Preli. Report

07/11/18 R.P. x



: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

Y 3 + RS 91

Y Phone

Y Other

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / L.B.I. (\$

800

5x15:75

170+75

50

50

59

80

80


80

80

80

80

80

Ref. No : <u>CS/TP18019865/Uqbn2</u>	Res. Date: <u>5/11/18</u>	Date Received:
Veh. No : <u>SKR 13273</u>	SP:	WKSP: <u>BW1</u>
C/No :		
Action/Instruction:		
1.File	2.Submit Photo? YES / NO	
3.Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to a) No authorisation b) Days of repair		
others:		
Final Re-inspection or Progress Photos		Inspected By: 

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5a



2.88% p.a. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$488
GV Credit Pte Ltd - StarAd


[Browse by Category](#)
[Sort by Date Posted](#)

13 vehicles

Mercedes-Benz b180

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Mercedes-Benz b180	Any	Any	2015	Any	Any	
	Mercedes-Benz B-Class B180 Urban	\$89,800	\$11,390 /yr	26-Aug-2015	1,595 cc	30,000 km	
Up To 90% Loan With Low Interest Rates Available! Special Interest Rate 2.18% With Major Bank! 100% Accident Free! 1 Owner, Fully Fuel Consumption Up To 18.2 Km/L. Very Well Maintained ...							
Autotruster Traders Pte Ltd							
Posted: 04-Nov-2018		Tags: 2015 Mercedes-Benz B180, 2015 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180	\$75,288	\$10,720 /yr	27-Jan-2015	1,595 cc	47,365 km	
Original Immaculate Condition. Clean And Neat Interior With New Car Feel! All Our Cars Have Gone Through Complete Checks And All N Repairs Done With Glossy New Paint. Backed By Our Own In Hous...							
Posted: 02-Nov-2018		Tags: 2015 Mercedes-Benz B180, 2015 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180	\$73,800	\$10,550 /yr	12-Jan-2015	1,595 cc	102,000 km	
1 Year Comprehensive Warranty. 100% Loan Avail. Fully Serviced And Maintained By Cycle And Carriage. Low Mileage, Excellent Conditi Fuel Efficient! Spacious, Quiet And Comfortable Cabin F...							
Hua Yang Credit Pte Ltd							
Posted: 02-Nov-2018		Tags: 2015 Mercedes-Benz B180, 2015 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Mercedes-Benz B-Class B180 Style	\$81,800	\$10,600 /yr	02-Jul-2015	1,595 cc	-	
Excellent Condition! Extremely Fuel Efficient! Spacious, Quiet And Comfortable Cabin For 4 Passengers To Travel In Top Notch Comfort, Meticulously Groomed! Flexible Bank/In House Loan Avail...							
Benefit Auto Enterprise Pte Ltd							
Posted: 02-Nov-2018		Tags: 2015 Mercedes-Benz B180, 2015 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz					
	Reverse Camera & Interface Kit (With GPS & Monitor Upgrade)						
Specially designed for Mercedes-Benz A, B, & C Class. Call us now for more info or drop by today!							
More info about this product							

Mercedes-Benz B-Class B180 \$76,800 \$11,050 /yr 08-Jan-2015 1,595 cc 40,000 km

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8018E

Vehicle Details

Vehicle No.: SKR1327B
Vehicle to be Exported: No
Intended Deregistration Date: 05 Nov 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: B180 (R16 BI)
Primary Colour: Grey
Manufacturing Year: 2014
Engine No.: 27091030508574
Chassis No.: WDD2462422J289331
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$25,004.00
Original Registration Date: 20 Jan 2015
First Registration Date: 20 Jan 2015
Transfer Count: 1
Actual ARF Paid: \$17,006.00

Intended PARF Rebate Details


PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Jan 2025
PARF Rebate Amount: \$12,754.00

Intended COE Rebate Details

COE Expiry Date: 19 Jan 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$65,889.00
COE Rebate Amount: \$40,879.00
Total Rebate Amount: \$53,633.00

The information contained herein is correct as at 05 Nov 2018

OK



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwei2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

SKR 1327B

Front bumper	1	1366.25	X
Front bumper moulding	11	102.00	X
headlamp n/s	one	2685.00	—
Front fender n/s	body	743.32	—
Front fender inner shield n/s	de	245.60	—
1 set front fender inner shield clips n/s	new	50.00	—
Bonnet	1	2445.00	X
Front door n/s	body	2166.00	—
2 pcs front door hinges @150.00	one	300.00	X
front door inner rubber n/s	new	245.00	—
front door glass outer moulding n/s	new	166.00	—
front door mirror casing n/s	one	765.30	—
front door mirror cover n/s	cur	266.00	—
front door mirror signal lamp n/s	SCN	125.00	—
front door mirror lower cover n/s	D.S	168.00	—
front door pillar n/s	1	981.30	X
1 set front door inner trim board rivets	new	80.00	—
	10%	12899.77	7105.22

To check w.r.g	80.00	30
To spray rust proofing	80.00	80
To disassemble & refit front door mechanism	120.00	100
To conduct wheel alignment	11	100.00 - X
labour for paint heating & replacing parts	680.00	500
To putty & spray painting	1080.00	900
	TOTAL	15039.77

We, the undersigned hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8544.69



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP18019865/Uqbn2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 09-11-2018		
ON BEHALF OF CHUA HONG CHOR		Code : TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SKR 1327B	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		01/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ B180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2462422J289331	Colour	GREY	
Odometer	57220	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	7 mm	
L/H Front Tyre	205/55 R16	PIRELLI	7 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	7 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2018	Inspection Date	01/11/2018	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1327B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,366.25	-
1	FRONT BUMPER MOULDING	NOT NECESSARY	102.00	-
1	HEADLAMP N/S	CRACKED	2,685.00	2,685.00
1	FRONT FENDER N/S	BADLY DENTED	743.32	743.32
1	FRONT FENDER INNER SHIELD N/S	DEFORMED	245.60	245.60
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	BONNET	TO REPAIR SEE LABOUR	2,445.00	-
1	FRONT DOOR N/S	BADLY DENTED	2,166.00	2,166.00
2	FRONT DOOR HINGES @\$150.00	SERVICEABLE	300.00	-
1	FRONT DOOR INNER RUBBER N/S	NECESSARY	245.00	245.00
1	FRONT DOOR GLASS OUTER MOULDING N/S	NECESSARY	166.00	166.00
1	FRONT DOOR MIRROR CASING N/S	CRACKED	765.30	765.30
1	FRONT DOOR MIRROR COVER N/S	CUT	266.00	266.00
1	FRONT DOOR MIRROR SIGNAL LAMP N/S	SCRATCHED	125.00	125.00
1	FRONT DOOR MIRROR LOWER COVER N/S	DISTORTED	168.00	168.00
1	FRONT DOOR PILLAR N/S	TO REPAIR SEE LABOUR	981.30	-
1	SET FRONT DOOR INNER TRIM BOARD RIVETS	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-770.52
			12,899.77	6,934.70
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		80.00	80.00
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM.		120.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,BONNET AND FRONT DOOR PILLAR N/S.		680.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	900.00
			2,140.00	1,610.00
	GRAND TOTAL		15,039.77	8,544.70
	RECOMMENDED COST OF REPAIR SUM			8,100.00

Report Ref No. CS/TP18019865/Uqbn2



Report Ref No. CS/TP18019865/Uqbn2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NR/5115141771 / National Assessment Centre, Serangoon - Ubi
 ENTRY DATE & TIME: 01/11/2018 13:11
 SUBMITTED BY: Jackson Ho Zheo Tian

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 01/11/2018 13:25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/11/2018 13:11
 Date Of Accident 30/10/2018 15:30
 Exact Location Of Accident BLK 122 GEYLANG EAST CENTRAL CARPARK
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKR1327B
 Insured/Policyholder
 Name Of Registered Owner CHUA, HONG CHOR
 NRIC No S8518018E
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-91998287
 Alternative Phone No OFFICE-91998287
 Vehicle Particulars
 Manufacturer MERCEDES-BENZ
 Model B180 (R16 BI)
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MT/00398481
 Cover Note Number
 Driver
 Name of Driver CHUA HONG CHOR (CAI HONGZUO)
 NRIC No S8518018E
 Date Of Birth 23/06/1985
 Occupation INDOOR
 Date Of Driving Pass 29/04/2005
 Driving Experience 13 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91998287
 Fax Number
 Contact Number OFFICE-91998287
 EMail Address NOEMAIL

Address 134 PUNGGOL WALK
#06-23
Postcode 828778
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

MY CAR WAS PARKED IN A LOT AT BLK 122 GEYLANG EAST CENTRAL CARPARK. AT ABOUT 4:30PM, MY SISTER WENT TO COLLECT MY CAR AND SAW A NOTE LEFT ON THE FRONT WINDSCREEN. I CALLED A GUY NAME SIRA AND HE TOLD ME THAT HIS DRIVER DOING REVERSING ACCIDENTALLY HIT THE FRONT LEFT HAND SIDE OF MY CAR.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP4072K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAN CHEE KEONG
NRIC/Passport Number S7504833I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKR1327B

SKETCH PLAN

IMPORTANT NOTICES

1. Please report promptly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may show insured's negligence to void the policy liability.
 4. The issue and acceptance of this Form by Insurance Company is not an admission of policy liability on the part of the Insurance Company.
 5. Any claim or dispute may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the Insurers, you hereby consent to the storage of this report at the Centre and to copies of this report being made available elsewhere.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurer's lawyer/solicitor firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover or development packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurer's lawyer/solicitor firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s) and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to third party service providers or agents (including my lawyer/solicitor firm), which may be based outside of Singapore, for one or more of the above Purpose(s).

Policyholder's Signature: Date

Driver's Signature (If driver is not the Policyholder): Date

Witnessed by: Signature

Sketch Plan

