From (Person): Kitty TeO	ASSIGNMENT (Office) ASSIGNMENT (AXA)	90302 Special Instruction: Date/Time: 01/11 20 8
Estimated Cost: OP/TP/WS/TP RES/OD RES/	Po211	•
at Workshop m/s	SDQ 8896S	Insured:
of Ikaki Bukit Policy No:	the 6 # 01-35 Autoba	38M0/049
Sum Insured:	Excess:	NIL
Client's Record) CA / (REV) / REP. / REV 24 HRS		D.O.A. 25 10 2018 H.O.D. Endorsement: Vehicle INVOUT
Pate/Time Action/Instruction (Estimate
Helis Subnit Prel	repaire that the o	wher withdraw on dain
	,	



. .

Service Request Details

Claim

S8M010U9

Reference

None 🥒

Loss Date

October 25, 2018

Request Date

November 1, 2018

Due Date

November 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDQ8896S

Make

LEXUS

Model RX270 2.7 Service Address 1 KAKI BUKIT AVE 6, , , 417883 Primary Contact/Insured **CHUE SWEE PING** BLK 109 TECK WHYE LANE, #02-568, 680109, Singapore 96798896 Claim Handler TEO Kitty 6568804602 kitty.teo@axa.com.sg Additional Instructions **EXCESS NIL** Notes Metrics Messages Invoices History Documents Assessment New Message TYPE 0 SENT 11/1/18 9:48 AM

TEO Kitty

WP SURVEY

Hi Please get estimate.

FROM

SUBJECT

BODY

RATAN BHOSALE Pragati

From: Sent: Tan Boon Seng <hup.ley.huat@gmail.com> Wednesday, October 31, 2018 12:15 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

SDQ 8896S

Attachments:

SDQ 8896S.pdf

Categories:

Pragati

Dear Sir/Mdam,

Please assist to escalate request. Had fax in previously but was to no prevail. Thank you.

Regards,

Hup Ley Huat Motor

51 UBIAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK. SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 02/11/18

Survey Details:

Date of loss	25-Oct-18
Date of appointment	1-Nov-18
Date of survey	1-Nov-18
Location of survey	HUP LEY HUAT

Vehicle Details:

Claim Type:	Own Dama	age
Vehicle number	SDQ 8896S	
Make and Model	TOYOTA LEXUS RX270 A STD	
Date of registration	18/8/2011	
Excess	-	
Market Value	\$	61,000.00
Parf Rebate	\$	47,406.00
Nett Loss	\$	13,594.00

Repair details:

		1
Initial Estimate	\$ 13,369.54	List Prices

Proposed/Revised repair cost:

Parts	\$ 5,667.24
Check items (estimate)	\$ 627.75
Labour	\$ 2,200.00
Total	\$ 8,494.99
Lump Sum(if applicable)	\$ =

Number of days for repair	7

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
ACCORDING TO THE REPAIRER, THE OWNER WITHDRAW
OD CLAIM. WE WILL SUBMIT OUR REPORT ACCORDINGLY.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

'> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	8448D	
Vehicle No.:	SDQ8896S	
Vehicle to be Exported:	No	
Intended Deregistration Date:	01 Nov 2018	
Vehicle Make:	TOYOTA	
Vehicle Model:	LEXUS RX270 AUTO STD	
Primary Colour:	White	
Manufacturing Year:	2011	
Engine No.:	1AR0534267	
Chassis No.:	JTJZA11A302409712	
Maximum Power Output:	138.0 kW (185 bhp)	
Open Market Value:	\$46,012.00	
Original Registration Date:	18 Aug 2011	
First Registration Date:	18 Aug 2011	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$46,012.00 23,806	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	17 Aug 2021	
PARF Rebate Amount: Intended COE Rebate Details	\$27,607.00	
COE Expiry Date:	17 Aug 2021	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$70,890.00	
COE Rebate Amount:	\$19,799.00	
Total Rebate Amount:	\$47,406.00	

The information contained herein is correct as at 01 Nov 2018

OK

SGCARMART.COM

Login Sigr

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! 2009 BMW 3 Series 323i Convertible \$72888.



Tip Top Condition, Newly Wrapped Matt Blue Sticker, All Wear And Tear Replaced. Direct Owner StarAd



Browse by Category

Post an Ad

2 vehicles

RX270

Model

Ways of Selling

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh

Search Selection

RX270

Advertiser Login

۲

Make

Anv

Any

2011

Any

Апу

Sort by Date Posted

Advanced Search

Lexus RX270

\$68,000

\$14,550 /yr

06-Dec-2011

2,672 cc

Well Maintained.

Posted: 29-Oct-2018 Tags: 2011 Lexus RX270, 2011 lexus rx270, Lexus RX270, lexus rx270, Lexus rx270, Lexus, RX270, rx270, Used Lexus



Lexus RX270 Panoramic Roof

\$58,800

\$15,590 /yr

13-Jan-2011

2.672 cc

85,000 km

Only Model With Sunroof, Higher OMV & Lowest Mileage, Reliable Lexus SUV With Full Records History, Evaluation Welcome, High Loan Ava To 90%, Trade In Welcome Too, Viewing By Appointment

Posted: 30-Sep-2018 Tags: 2011 Lexus RX270, 2011 lexus rx270, Lexus RX270, lexus rx270, Lexus rx270, Lexus, RX270, rx270, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh '

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpar buy used RX270, RX270 Singapore, used RX270 Singapore, used RX270, used vehicles Singapore or even buy used RX270 Singapore. We have new car dealers or authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

Compare

Addendum Sheet Pg. 1

GENERAL INSURANCE e Rather Coat +18 CT bir proces CARDED Territoria Colonia Fax 551 6724 8030 Operating House Monday to Micky 09 CD Little School Coat Reg. No. MISSIGITES

IMPORIANT NOTE. Please submit the completed Addendam form to the Jame Authorised Reporting Centre with whom you submitted the Original Report ADDENDUM (A) PARTICULARS OF PERSON MAKING THEAMENDMENTS: Vehicle Registration No. DQ 88965 Original Report No : MSME 18139371 Name is shown in NEC. COLC STATE PARTY NRIC/FIN/Passport No : 9/7894 481) [*Vehicle Driver / Vehicle Owner] (*) Please delete as appropriate 319 Pavilian Grote Address Mobile No :_ Contact (Tel) Email Address 9 30Pm Date of Accident 420 insurance Company: (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: - OD to third party.

Policyholder / Driver's Signature Date

Reporting Centre Personnel's Signature

Name: NRIC/FINNO.

Date:

1/11/2018

4. 51 pm

MSME18139371-01 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 26/10/2018 17:10 SUBMITTED BY: Ang Guo Bao

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report stong made attained.		
	ACCIDENT STATEMENT	
Date Of Report	26/10/2018 17:10	
Date Of Accident	25/10/2018 14:30	
Exact Location Of Accident	EUNOS RD 4 CARPARK LOT 429.	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDQ8896S	
Insured/Policyholder		
Name Of Registered Owner	CHUE SWEE PING	
NRIC No	S1788448D	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96798896	

OFFICE-96798896

Alternative Phone No Vehicle Particulars

Manufacturer LEXUS
Model 270

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA000855/1

Cover Note Number

Driver

Name of Driver CHUE SWEE PING

 NRIC No
 S1788448D

 Date Of Birth
 02/11/1967

 Occupation
 INDOOR

 Date Of Driving Pass
 24/12/1986

Driving Experience 31 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96798896

Fax Number

Contact Number OFFICE-96798896

EMail Address NOEMAIL

MSME18139371 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 26/10/2018 17:10 SUBMITTED BY: Wen Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Professional Control (Control Control		
	ACCIDENT STATEMENT	
Date Of Report	26/10/2018 17:10	
Date Of Accident	25/10/2018 14:30	
Exact Location Of Accident	EUNOS RD 4 CARPARK LOT 429.	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDQ8896S	
Insured/Policyholder		
Name Of Registered Owner	CHUE SWEE PING	
THE STATE OF THE S		

NRIC No S1788448D Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-96798896

Alternative Phone No OFFICE-96798896

Vehicle Particulars

Manufacturer LEXUS Model 270

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA000855/1

Cover Note Number

Driver

Name of Driver CHUE SWEE PING

 NRIC No
 S1788448D

 Date Of Birth
 02/11/1967

 Occupation
 INDOOR

 Date Of Driving Pass
 24/12/1986

Driving Experience 31 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96798896

Fax Number

Contact Number OFFICE-96798896

EMail Address NOEMAIL

Address

319 PAVILION CIRCLE

Postcode

658580

Was driver an employee of the Insured's Company NO

was driver an employee of the modred's company in

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JSR3027 (COMMERCIAL VEHICLE)

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

KAMPONG UBI NEIGHBOURHOOD POLICE POST

ROAD: BLK 9 EUNOS CRESCENT #01-2687, POSTCODE: 400009,

Police Station Address

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-7479999 - FAX NO: 67453410

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT NO.T/20181025/2107.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

JSR3027

Vehicle Make/Model/Colour Details Of Properties

VEH B

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

ider's Signature Pallin

Date & Time

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

the way the single

Accident Sketch Plan Pg. 1

SKETCH PLAN			10.0	
110	40/17	1	T	
1 3 9		TIT		
	**		V	
		15	The_	
		iddi	HILLIAN	
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT			
Re	fer to p	police	report.	
F				
			10	
				, V
74				
DECLARATION //We declars the foregoing part	culars are true in every respect.			
We declare the foregoing part	cours are une m every respecti			
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the police Date & Time:	yholder)	Reporting Centre Personna Name: NRIC/FIN No.:	el's Signature





1 of 3

Report No. T/20181025/2107

Police Station Of Origin: Kampong Ubi NPP 9 Eunos Crescent #01-2687 SINGAPORE 400009

Tel No: 1800-7479999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
25/10/2018 16:05	G/20181025/0108	.14

20/10/20	10 10.00		0/20101020/0100		
Informa	nt's Particul	ars.			
Name of Informant: CHUE SWEE PING			Address: 319 PAVILION CIRCLE SINGAPORE 658580		
ID Type / ID No.: NRIC NO / S1788448D		BD	Contact No.: Home/Office: 96798896	Mobile:	
Nationality: SINGAPORE CITIZEN		N	Email:		
Sex: Male	Age: 50	Date of Birth: 02/11/1967	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3	Date of Expiry:	

General Inform	nation of the Accide	nt			
Type of Accident: Non-Injury Hit and Run		Drink Drive: No	Date/Time of Accident: 25/10/2018 14:30	Type of Location:	
Location:	17				
EUNOS ROA	D 4				
B/1045 EUNC	S RD 4 CARPARK LO	OT 429			
Weather:		Road Surface:	Ro	ad Speed Limit:	
Traffic Flow:		Traffic Control:	Tra	Traffic Volume:	
Type of Collision:				yone conveyed by abulance:	

Details of Vehicle Involved						
Vehicle No.	Type .	Make	Model	Color	Condition	No of Passenger
JSR3027	TRAILER			3 2 3		0
SDQ8896S	Car	ТОУОТА	LEXUS RX270 AUTO STD	White	Seriously Damaged	

Details of V	ehicle Insurance			All the second
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDQ8896S	AXA INSURANCE SINGAPORE PTE	GA000855	18/08/2018	17/08/2019





Police Station Of Origin: Kampong Ubi NPP 9 Eunos Crescent #01-2687 SINGAPORE 400009

Tel No: 1800-7479999

2 of 3 Report No. T/20181025/2107

CONTINUATION OF REPORT

Brief Details.

On the 25/10/2018 at 0630 hrs I parked my car SDQ8896S at Blk 1045 Eunos Rd 4 lot 429 which is a parallel lot. At 1440 hrs my friend came to my shop and told me a trailer had hit my car and left. I went back to my car and discovered the rear left and right of my car was ripped off, seriously damaged. When came back to the lot, a male Chinese witness (Hp: 93741313) approached me and told me earlier at 1430 hrs a blue trailer JSR3027 wanted to turn out from the carpark and while turning the rear right of the trailer hit the rear left side of my car. The witness managed to talk to the trailer driver who was a Malay man, told him hit already, however despite that, he just drove off. My car does not have in car camera. That is all.





/20181025/2107

3 of 3

Report No. T/20181025/2107

Police Station Of Origin: Kampong Ubi NPP 9 Eunos Crescent #01-2687 SINGAPORE 400009

Tel No: 1800-7479999

* W

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: G / Staff Sgt MOHAMMAD HAFEEZ ASHRAF BIN HARON	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/10/2018 16:05
	in the second se
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp	

Authentication Stamp NP168 合利發摩哆噴漆服務 HUP LEY HUAT MOTOR SPRAY PAINTING SERVICES Blk 1 Kaki Bukit Ave 6 #01-35 Singapore 417883 Tel: 6746 0674 Fax 6841 7639 Not Authorised
LULA.
Morius
Tel: 6256356/
Squess N.C
Tokephoto Represent

Vehicle Number:

SDQ 8896 S

SPARE PARTS

cost plus 10%

11/2 #	,
7	Workshop
- 1	Estimation
	(54)

QTY	PARTS DESCRIPTION		stimation (S\$)
1 pc 1 pc 2 pcs 1 pc 2 pcs 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	List Items Rear fender Rear door assy Rear door hinges Rear door checker Rear door lock Rear door lock Rear door lock striker Rear door window glass Rear door window glass channel bracket Rear door window glass channel rubber Rear door window glass outer moulding Rear door window frame black sticker Rear door window regulator Rear door window regulator Rear door window regulator Rear door weatherstrip Tail lamp Als Tail lamp Als Rear bumper Rear bumper Rear bumper side attachment Rear bumper clips Rear end side panel Rear fender glass moulding Rear fender glass inner seal Rear fender glass clips Rear fender glass clips Rear fender inner trim board clips	************************	972.40 / 1,218.10 / 264.22 / 174.45 / 87.40 / 182.10 / 174.25 / 122.10 / 374.25 / 58.40 / 375.00 / 80.00 / 28.50 / 1,218.25 / 120.00 / 140.00 / 129.00 / 363.80 / 172.80 / 38.00 / 781.80 / 100.00 / 100.
1 pc	Rear door protector chorme	\$	121.10 ?

Parts Sub-Total Discount 25.00%

Consultants hence notify The Proof the following: Defore/after spray painting Lemaged part(s) during resurvey Are subject to confirmation Very survey is on a "Without Prejudice" basis modification(s) is allowed Are entary item(s) must be resurveyed and survect to final approval from Insurance Company Acknowledged by Repairer Acknowledged by Repairer Acknowledged by Repairer

合利發摩哆噴漆服務 HUP LEY HUAT MOTOR SPRAY PAINTING SERVICES Blk 1 Kaki Bukit Ave 6 #01-35 Singapore 417883 Tel: 6746 0674 Fax: 6841 7639

Vehicle Number: SDQ 8896 S

SPARE PARTS

QTY	PARTS DESCRIPTION		forkshop stimation (S\$)
	Special Nett Items		
1 pc	Rear door window glass solar flim 1 1	\$	120.00 X
1 set	Sound clad n 1,	\$	450.00 X
2 pcs	Tyre assembly cun / 2 Lp 2 fox 2 - 500	\$	650.00 70%
2 pcs	Rim assembly (sport) TO /Ser	\$	900.00
Special N	lett Sub-Total	\$	2,120.00
Spare Parts Total			8,999.54

LABOUR COST

S/No	JOB DESCRIPTIONS		- 20	Norkshop Estimation (S\$)
Spare Pa	artsTotal c/f		\$	8,999.54
1	To tuff coat affected areas	NZ	\$	250.00 🗶
2	To remove replace interior upholstery		\$	220.00 fc
3	To respray affected areas		\$	1,600.00 /00
4	Labour charge		\$	1,600.00 / 06 2,000.00 / 0
5	To remove & replace door assy		\$	180.00 6
6	To check and adjust computer wheel alignment		\$	120.00 6
Tota	ıl		\$	13,369.54



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internat	ionale Des Experts En Auton	nobile			
AXA INSURANCE PT	ELTD	Ref : CS/ASM18019	867/Uqd3e2			
3 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 07-11-2018				
		Code: ASM				
1.	Policy Particu	lars :- OWN DAMAGE	SDQ 8896S			
Insured Veh.	0.4.00005514	Veh. Inspected	0.00			
Policy No.	GA000855/1	Coverage (\$)	Total State			
Claim No.	S8M010U9	Excess (\$)	0.00			
Assign From		Assign Date	01/11/2018			
2.	Vehicle Par	ticulars & Condition				
Make & Model	TOYOTA LEXUS RX270 (A)	c.c	2672			
Engine No.	HIDDEN	Year of Reg.	2011			
Chassis No.	JTJZA11A302409712	Colour	WHITE			
Odometer	133745	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	GOOD					
3.	Cond	itions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	235/60 R18	CONTINENTAL	7 mm			
L/H Front Tyre	235/60 R18	CONTINENTAL	7 mm			
R/H Rear Tyre	235/60 R18	CONTINENTAL	7 mm			
L/H Rear Tyre	235/60 R18	CONTINENTAL	7 mm			
4.	Descrip	tion of Damages				
THE VEHICLE SU	USTAINED DAMAGES AT THE C SE AFFECTED DUE TO COLLISI	O/S BODY AND N/S REAR ON.	PORTION, THE			
DAMAGES SEE I	DETAILS.					
5.	Gene	ral Information				
Accident Date	25/10/2018	Inspection Date	01/11/2018			
Survey held at	HUP LEY HUAT MOTOR SPR	AY PAINTING SVS				
	BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883					
5a.		Remarks				
A)THE MARKET	VALUE IS \$\$61,000.00(EST. AV	ERAGE)	DEDAIDS			
B)IN ACCORDAN	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 8896S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER	BADLY DENTED	972.40	972.40
1	REAR DOOR ASSY	BADLY DENTED	1,218.10	1,218.10
2	REAR DOOR HINGES	NOT NECESSARY	264.22	-
1	REAR DOOR CHECKER	NOT NECESSARY	174.45	-
2	REAR DOOR STOPPER	NOT NECESSARY	87.40	
1	REAR DOOR LOCK	* CHECK	581.45	
1	REAR DOOR LOCK STRIKER	NOT NECESSARY	42.10	19
1	REAR DOOR WINDOW GLASS	NOT NECESSARY	581.40	-
1	REAR DOOR WINDOW GLASS CHANNEL BRACKET	NOT NECESSARY	174.40	:-
1	REAR DOOR WINDOW GLASS CHANNEL RUBBER	NOT NECESSARY	182.10	-
1	REAR DOOR WINDOW GLASS OUTER MOULDING	NOT NECESSARY	174.25	-
1	REAR DOOR WINDOW FRAME BLACK STICKER	NECESSARY	122.10	122.10
1	REAR DOOR WINDOW REGULATOR	NOT NECESSARY	374.25	:-
1	REAR DOOR WINDOW REGULATOR MOTOR	NOT NECESSARY	58.40)-
1	REAR DOOR OUTER HANDLE	* CHECK	134.45	,-
1	RERA DOOR WEATHERSTRIP	NECESSARY	182.40	182.40
1	TAIL LAMP N/S	BROKEN	375.00	375.00
1	TAIL LAMP SEALANT	NOT NECESSARY	80.00	
2	TAIL LAMP CLIPS	NOT NECESSARY	28.50	
1	REAR BUMPER	DISTORTED	1,218.25	1,218.25
1	REAR BUMPER SIDE RETAINER	BENT	120.00	120.00
1	REAR BUMPER SIDE ATTACHMENT	BENT	140.00	140.00
10	REAR BUMPER CLIPS	NECESSARY	129.00	129.00
1	REAR END SIDE PANEL	BADLY DENTED	363.80	363.80
1	REAR FENDER GLASS MOULDING	NECESSARY	172.80	172.80
1	REAR FENDER GLASS INNER SEAL	NECESSARY	38.00	38.00
14	REAR FENDER GLASS CLIPS	NOT NECESSARY	180.60	-
1	REAR FENDER UNDER TRIM N/S	DISTORTED	781.80	781.80
8	REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	100.00	2
1	REAR DOOR PROTECTOR CHROME	* CHECK	121.10	-

Report Ref No. CS/ASM18019867/Uqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

% DISCOUNT AL NETT ITEMS OOR WINDOW GLASS SOLAR FLIM (SN)		-2,293.18 6,879.54	-1,458.41 4,375.24
		6,879.54	4,375.24
			-13/4-076-0
OOR WINDOW GLASS SOLAR FLIM (SN)	I	1	
	NOT NECESSARY	120.00	15
UND CLAD (SN)	NOT NECESSARY	450.00	7.
SSEMBLY (SN) (LOCAL REPAIR) (\$560) (70%)	CUT / PUNCTURE	650.00	392.00
2 RIM ASSEMBLY (SPORT) (SN)	DENTED / BENT	900.00	900.00
		2,120.00	1,292.00
<u>IR</u>			
F COAT AFFECTED AREAS.	NOT INSURED	250.00	
IOVE REPLACE INTERIOR UPHOLSTERY.		220.00	80.00
PRAY AFFECTED AREAS.		1,600.00	1,000.00
R CHARGE.		2,000.00	1,000.00
IOVE & REPLACE DOOR ASSY.		180.00	60.00
TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT.		120.00	60.00
		4,370.00	2,200.00
TOTAL		13,369.54	7,867.24
IENT	AL		4,370.00 AL 13,369.54

Report Ref No. CS/ASM18019867/Uqd3e2

(EXCLUDE CHECK ITEMS \$\$627.75 NETT)

CHUA KANG SENG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.