

ASS. REC. BY:

REF: es/MSG18019871 / T1sd3⁵⁴ Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Winnie chua

of

MSG

Date/Time:

01/11/2018 @ 11:33am

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDG 6833P

Insured:

at Workshop m/s

performance Motor

Tel:

81214600

of

303 Alexandra Road

Policy No:

27530845 SMP

Claim No:

574755

Sum Insured:

Excess:

\$750.00

Make of Veh:

(Client's Record)

D.O.A.

29/10/2018

CA REV / REP. / REV 24 HRS

02/11/2018 @ 10am

H.O.D. Endorsement:

Date/Time:

11:58am @ 1/11/18

Person Contacted:

Ithiran

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SDG 6833P - NA/INC18019723/24 DOA: 29/10/18
05/11/18	@ 15:17 p.m. revised IA to Winnie chua Ping Ping via merimen.
05/11/18	@ 15:18 p.m. mandate requested authorize repair to Winnie chua Ping Ping via merimen.
05/11/18	@ 16:57 p.m. mandate approved by Kenny Ong Thiam Beng via merimen.

Taufikh

REF:

MSIG

MSIG

From: _____ Date: _____
 Estimated Cost
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$750
 (Client's Record)
 Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$83K
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 3DG 6833P Yr Regn: 2013 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 520I 1997
 Colour: Grey Brown A/C Insured / Std / NI / NA
 Sp. Reading: 107791 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WBA XG12030DX53928

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / R / STD A/Rim or

Tyre Size: F: 225 / 55 R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI / TOYO / YOKO or

Front R/Bal: 6 mm Rear R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. D.O.I: 02/11/180/09m

Survey held at PML
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

07/11/18 @ 11:23 am. revert authorize repair to Intiran (Crydun) via email.
 21/12/18 Confirmed P/P \$3,744.95 @ 3 days with Taufikh.
 (\$1,420.50 Red - 28%)

[Signature]
 2/1/2019

RECEIVED 03 JAN 2019

Date/Time File Pass to? : Preli. Report
 02/01/19 : Final Report
 To: Taufikh
 Date/Time File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: Site Insp. \$
 Interview \$
 Tech. Adv. \$
 Wash and \$

Survey Fee:	150
Transport:	
Site - P1:	
Site - P2:	
Site - P3:	
Site - P4:	
Site - P5:	
Site - P6:	
Site - P7:	
Site - P8:	
Site - P9:	
Site - P10:	
Site - P11:	
Site - P12:	
Site - P13:	
Site - P14:	
Site - P15:	
Site - P16:	
Site - P17:	
Site - P18:	
Site - P19:	
Site - P20:	
Site - P21:	
Site - P22:	
Site - P23:	
Site - P24:	
Site - P25:	
Site - P26:	
Site - P27:	
Site - P28:	
Site - P29:	
Site - P30:	
Site - P31:	
Site - P32:	
Site - P33:	
Site - P34:	
Site - P35:	
Site - P36:	
Site - P37:	
Site - P38:	
Site - P39:	
Site - P40:	
Site - P41:	
Site - P42:	
Site - P43:	
Site - P44:	
Site - P45:	
Site - P46:	
Site - P47:	
Site - P48:	
Site - P49:	
Site - P50:	
Site - P51:	
Site - P52:	
Site - P53:	
Site - P54:	
Site - P55:	
Site - P56:	
Site - P57:	
Site - P58:	
Site - P59:	
Site - P60:	
Site - P61:	
Site - P62:	
Site - P63:	
Site - P64:	
Site - P65:	
Site - P66:	
Site - P67:	
Site - P68:	
Site - P69:	
Site - P70:	
Site - P71:	
Site - P72:	
Site - P73:	
Site - P74:	
Site - P75:	
Site - P76:	
Site - P77:	
Site - P78:	
Site - P79:	
Site - P80:	
Site - P81:	
Site - P82:	
Site - P83:	
Site - P84:	
Site - P85:	
Site - P86:	
Site - P87:	
Site - P88:	
Site - P89:	
Site - P90:	
Site - P91:	
Site - P92:	
Site - P93:	
Site - P94:	
Site - P95:	
Site - P96:	
Site - P97:	
Site - P98:	
Site - P99:	
Site - P100:	

Report Format: _____
 Lump Sum / L.B. \$3,744.95 P/P

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Oct 2018		01 Nov 2018 11:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	KOH CHIN KOON, ID: S6833478J, Tel: +6597818711, Email: VKOHCK@YAHOO.COM.SG	
Vehicle Reg. No.:	SDG6833P	Date of Loss: 29/10/2018 23:00 - :59 [69 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 574755	Policy/Cover Note No.: 27530845SMP (Comprehensive) Coverage: 12/06/2018 - 11/06/2019
		Excess: S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2018]	
Driver/Custodian:	KOH CHIN KOON (50 / Male), NRIC: S6833478J, Tel: +6597818711	
Adj Asg. Remarks:	Car in on 02/11/2018 9AM, owner leaving car. Pls revert.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Winnie Chua

From: Woon Choo Kwok
Sent: Wednesday, 31 October 2018 4:11 PM
To: Winnie Chua
Cc: Foo Ai Ngoh
Subject: FW: Message from KM_558e
Attachments: SKM_558e18103115492.pdf

Dear WC

Fya - VEH NO : SDG 6833P

Best Regards

Kwok Woon Choo
Senior Admin Officer, Claims Services
Tel : 6643 1330 Fax: 6225 7402 | woonchoo_kwok@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Wednesday, 31 October 2018 3:51 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: Message from KM_558e

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey on 2.11.18@ 9a.m.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended

Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 2 January 2019 5:45 PM
To: 'PBSP'
Cc: Taufikh (LKKAuto); SUR
Subject: RE: RESEND: FINAL REPORT / SDG6833P

Dear Caroline,

Confirmed final fig \$3,744.95 (part by part) @ 3 days of repairs before excess \$750/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 21 December 2018 3:15 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; taufikh@lkkauto.com
Subject: RESEND: FINAL REPORT / SDG6833P

Resend to include Shirley in the email.

From: PBSP
Sent: Friday, 21 December 2018 3:12 PM
To: taufikh@lkkauto.com
Subject: FINAL REPORT / SDG6833P

Dear Taufik

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,097.00

Total Parts : 1,647.95

Total Labour & Parts : 3,744.95

Repair days: 3

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 7 November 2018 11:23 AM
To: inthiran.thurasamy@simedarby.com.sg
Cc: SUR; chua.kee.sin@simedarby.com.sg; teng.wai.khan@simedarby.com.sg; 'Han Kwan Yong'
Subject: SDG 6833P-DOA: 29/10/2018 (MSIG OD)

Dear Inthiran,

As instructed by our client, please proceed to repair the insured vehicle **SDG 6833P (Excess \$ 750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SDG6833P (574755)**

OD

Oct 29 2018 11:00PM

[KOH CHIN KOON]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **02/01/2019 13:41 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3744.95) - SDG6833P - Claim Handler: Winnie Chua Ping Ping

Approved:3744.95:a if c

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SDG6833P (574755)**

OD

Oct 29 2018 11:00PM

[KOH CHIN KOON]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **05/11/2018 16:57 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3464.55) - SDG6833P - Claim Handler: Winnie Chua Ping Ping

Approved:3464.55:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 21 Dec 2018

Preliminary Advice

Vehicle No	: SDG6833P	Accident Date	: 29/10/2018
Make	: BMW 520I	Policy No.	: 27530845SMP
Assignment Date	: 01/11/2018	Excess	: S\$750.00
Date of Inspection	: 02/11/2018	Est. Duration of Repair	: 3 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,165.45 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	3,744.95 (INCLUSIVE SUPPLEMENATRY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,744.95
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	66,272.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,728.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 247.00.

() The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 05 Nov 2018

Preliminary Advice

Vehicle No	: SDG6833P	Accident Date	: 29/10/2018
Make	: BMW 520I	Policy No.	: 27530845SMP
Assignment Date	: 01/11/2018	Excess	: S\$750.00
Date of Inspection	: 02/11/2018	Est. Duration of Repair	: 3 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,884.75
Revised Amount	:S\$	3,464.55
Check Items (Estimated)	:S\$	864.20
Total	:S\$	4,328.75

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	66,272.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,728.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2018 09:54
Date Of Accident	29/10/2018 23:20
Exact Location Of Accident	CHANGI AIRPORT T3 B1 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDG6833P
Insured/Policyholder	
Name Of Registered Owner	KOH CHIN KOON
NRIC No	S6833478J
Email Address	VKOHCK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97818711
Alternative Phone No	OTHERS-97818711

Vehicle Particulars

Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	KOH CHIN KOON
NRIC No	S6833478J
Date Of Birth	04/09/1968
Occupation	INDOOR
Date Of Driving Pass	29/11/1986
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97818711
Fax Number	
Contact Number	OTHERS-97818711
Email Address	VKOHCK@YAHOO.COM.SG

Address	26 EE TEOW LENG ROAD
Postcode	549636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : KOH JIA KIT GENDER: : MALE
Passenger 2	NAME: : KOH JIN KAI GENDER: : MALE
Passenger 3	NAME: : FOO HUI SIAH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP9008E
Vehicle Make/Model/Colour	TOYOTA SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	INDARTO DONNY BUDIARTO
NRIC/Passport Number	S2676186G
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Inthiran A/L. Thurassamy
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Coming out of a parking lot, a car suddenly turned into my lane I managed to stop but his car brushed against my bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Inthi An Ail. Thurasamy
NRIC/FIN No. Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3478J
Vehicle Details	
Vehicle No.:	SDG6833P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	A3200467N20B20B
Chassis No.:	WBAXG12030DX53928
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,706.00
Original Registration Date:	12 Jun 2013
First Registration Date:	12 Jun 2013
Transfer Count:	0
Actual ARF Paid:	\$45,389.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2023
PARF Rebate Amount:	\$31,772.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$34,500.00
Total Rebate Amount:	\$66,272.00

The information contained herein is correct as at 05 Nov 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6833478J



Name:
KOH CHIN KOON

許振群

Race:
CHINESE

Date of birth:
04-09-1968

Sex:
M

Country/Place of birth:
SINGAPORE



S6833478J

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6833478J

Name:
KOH CHIN KOON

Birth Date: 04 Sep 1968
Issue Date: 25 Sep 2003

1000861798F




5751597



NRIC No. S6833478J



Date of issue:
03-06-2017

Address

26 EE TEOW LENG ROAD
SINGAPORE 549636

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Nov 1988

NP 428A



Appt on 2.11 @ 9.00am

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528
63190533/530 (AfterSales)
Fax. 64796601
64796624 (Motorrad)

Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Page No. : 1 of 4

GST REG. NO : M2 - 0020081

ESTIMATE

Estimate No. : b1 48956
Date Estimated : 31/10/2018
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Koh Chin Koon
26 Ee Teow Leng Road

Singapore
Singapore 549636

- ACCOUNT -

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Acknowledged by Repairer
Signature:

Date: 66

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDG6833P	DX53928	12/06/2013	520iA	0

DESCRIPTION	VALUE
To replace front bumper and attachments.	850 1,275.00
Painting front bumper.	931 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To supply front emboss number plate.	Ad- 83.00
Sundries.	un-? 80.00
Total Labour 1:	2,653.00

DESCRIPTION	QTY	PRIC	VALUE
Set of mount	1	33.85	un- 33.85
FRT BUMPER TOP IMPACT ABSORBER	1	46.60	un- 46.60
FRT BUMPER TOW HOOK COVER PRIMED	1	46.45	un- 46.45
FRT BUMPER TRIM PRIMED (PDC)	1	1,277.55	1309.50 de- 1,277.55
BMW EMBLEM	1	69.50	7.25 un- 69.50
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	un- 20.20
BUMPER PDC SENSOR (A17 HAVANNA)	2	368.80	un- 737.60
Total Parts :			2,231.75

Claims On / 3rd Party / Indirect losses / Direct Settlement

Date & Time: 2/11/18 @ 10:15
Surveyor's Name: Taufik
Surveyor's Tel: 97495714
Authorised Date: Revout
RESURV: TO BY SURVEYOR Yes/No P.M. Yes/No
Surveyor's E-mail: Taufik @ khanda.com

Labour 1 : 2,653.00
Parts : 2,231.75
Labour 2 : 4284.25 0.00
Excess : 4918.45 0.00
Total GST @ 7% : 341.93
Grand Total : 5165.45 5,226.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48956
Date Estimated : 31/10/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Koh Chin Koon
26 Ee Teow Leng Road

Singapore
Singapore 549636

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SMF7941C	DX53928	12/06/2013	5201A	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LH GRILLE CHROME *	123.50	1.00		123.50
# RH GRILLE CHROME *	123.50	1.00		123.50

Total Labour :	
Total Parts :	247.00
Total Labour & Parts :	247.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740159W, GST Reg. No. M2-0020001-X



FINAL REPORT

Estimate No. : b1 48956 Page No. :
Date Estimated : 31/10/2018
Prepared By : Inthiran A/L Thurasamy

REPAIR FOR -
Koh Chin Koon
26 Ee Teow Leng Road

Singapore
Singapore 549636


- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SMP7941C	DX53928	12/06/2013	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
To supply front emboss number plate.	83.00		83.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER TRIM PRIMED (PDC)	1,309.50	1.00		1,309.50
# LH GRILLE CHROME *	123.50	1.00		123.50
# RH GRILLE CHROME *	123.50	1.00		123.50
BMW EMBLEM	71.25	1.00		71.25
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20

SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,647.95
Total Labour & Parts :	3,744.95
Deduction for Excess :	750.00
Total Repair Costs less Excess:	2,994.95
GST @7%:	209.65
Grand Total :	3,204.60



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Oct 2018		01 Nov 2018 11:33 Edit Adj Rpt	S\$3,744.95 Edit Estimates	S\$3,744.95 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOH CHIN KOON, ID: S6833478J, Tel: +6597818711, Email: VKOHCK@YAHOO.COM.SG		
Vehicle Reg. No.:	SDG6833P	Date of Loss:	29/10/2018 23:00 - :59 [64 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 574755	Policy/Cover Note No.:	27530845SMP (Comprehensive) Coverage: 12/06/2018 - 11/06/2019
		Excess:	S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/12/2018]		
Driver/Custodian:	KOH CHIN KOON (50 / Male), NRIC: S6833478J, Tel: +6597818711		
Adj Asg. Remarks:	Car in on 02/11/2018 9AM, owner leaving car. Pls revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (02/01/2019): Alert - Adj Mandate Approved (S\$3744.95) - SDG6833P - Claim Handler: Winnie Chua...
- MSIG_SG (05/11/2018): Alert - Adj Mandate Approved (S\$3464.55) - SDG6833P - Claim Handler: Winnie Chua...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDG6833P (574755)

OD

Oct 29 2018 11:00PM

[KOH CHIN KOON]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/10/18 10:05	Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 15:17	Adjuster Immediate Advice	Load HTM	
2	21/12/18 16:46	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 14:06	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	05/11/18 14:06	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
32	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
33	05/11/18 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
34	21/12/18 16:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	21/12/18 16:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	21/12/18 16:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/10/18 16:59	od estimates, IC DL	Load PDF	
2	31/10/18 17:00	email from workshop	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 14:05	ESTIMATE .pdf	Load PDF	
2	21/12/18 16:34	ESTIMATE MARKED & SUPPLEMENTARY.pdf	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/10/18 10:05	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	30/10/18 10:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	30/10/18 10:01	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18019871/T1SD3S2
Date: 03/01/2019

REFERENCE

Insured/Claimant: KOH CHIN KOON Policy No: 27530845SMP
Date of Loss: 29/10/2018 Nature of Claim: OD Claim No: 574755

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDG6833P**
Make & Model: BMW 520i, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) Engine No: A3200467N20B20B
Reg. Date: 12/06/2013 (Man. Year: 2013) Chassis No: WBAXG12030DX53928
Colour: Brown Odometer: 107791 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/55R17 Rear Tyre Size: 275/55R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,675.45	1,810.95	864.50	32.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,165.45	3,744.95	1,420.50	27.50
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	4,415.45	2,994.95	1,420.50	32.17
+ GST 7.00/7.00% (S\$)	309.08	209.65	99.43	32.17
Nett Amount (S\$)	4,724.53	3,204.60	1,519.93	32.17

INSPECTION

Date of Assignment: 01/11/2018
Date Inspected: 02/11/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2019)**Parts:** 143 BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SDG6833P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET OF MOUNT	Not Necessary	33.85 FS	*- FS
2	1		*FRT BUMPER TOP IMPACT ABSORBER	Not Necessary	46.60 FS	*- FS
3	1		*FRT BUMPER TOW HOOK COVER PRIMED	Not Necessary	46.45 FS	*- FS
4	1		*FRT BUMPER TRIM PRIMED (PDC)	Deformed	1,309.50 FS	*1,309.50 FS
5	1		*BMW EMBLEM	Necessary	71.25 FS	*71.25 FS
6	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
7	2		*BUMPER PDC SENSOR (A17 HAVANNA)	Not Necessary	737.60 FS	*- FS
8	1		*FRONT EMBOSS NUMBER PLATE	Dented	83.00 FS	*83.00 FS
9	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
10	1		*LH GRILLE CHROME	Cut	123.50 FS	*123.50 FS
11	1		*RH GRILLE CHROME	Cut	123.50 FS	*123.50 FS
Total Parts (S\$)					2,675.45	1,810.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND ATTACHMENTS.	New	1,275.00	850.00
2	PAINTING FRONT BUMPER.	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER INCLUDING ADJUSTMENTS OF HEADLIGHTS.	New	177.00	150.00
Gross Labour Cost (S\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >