

ASS. REC. BY:

REF:

CS/MSG/18019873/Gtd3ST

Special Instruction:

Surveyor:

Guo Ding

ASSIGNMENT (Office)

From (Person):

Meimien Pauline Tham

of

MSG

Date/Time:

31/10/18 @ 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 2270P

Insured:

FBD 646S

at Workshop m/s

Chew Goon Motor

Tel:

G4841626

of

Blk 10, AMK Ind. park 2A #01-15/16

Policy No:

MSD/VM1/18-990481-WT1

Claim No:

MSC/V/18-001462

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/10/2018

CA / REV / REP. / REV 24 HRS

Imp)

H.O.D. Endorsement:

Date/Time:

1/11/18 @ 9:18am

Person Contacted:

Grace

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SMA 2270P - NA/MSG/18019751/h4	DOA: 29/10/18
	FBD 646S - NA/MSG/18019751/h4	DOA: 29/10/18
2/11 @	Revised via preli advise	
13/5 -	Part by Part \$4,437.58 (Red 2145.52, 32%)	

Summary

Xkl

REF: MSIG

ASSIGNMENT

From: Date: 01/11/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMA 2270P
at Workshop m/s chew Goon Motor
of BLK 10, AMK Ind. park 2A # 01-15/16

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Avoid 1pm-2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="radio"/>	N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMA 2270P Yr Regn: 25. May 2015
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Value 560 D2 c.c 1560

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 78083 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YVIFS 84A BF. 2359 730

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inoper / Jammed / Leaked / Burnt or

Brake: ☒ Inoper / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45 R17
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 01-11-18

Survey held at w/s 12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

refundize \$3821.98

RECEIVED 14 MAY 2019

14/5/2019

Date/Time, File Pass to?

1) 14/5 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

3821.98

Lump Sum / I.B.I: \$4437.58

150
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018		31 Oct 2018 15:56 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	78 ST PTE LTD, Co. Reg. No.: 20133272D		
Main Claimant:	GRAPE & CO, Co. Reg. No.: 53346890J		
Vehicle Reg. No.:	SMA2270P	Date of Loss:	29/10/2018 10:00 - :59 [41 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/18-990481-WTT Coverage: 30/03/2018 - 29/03/2019
Vehicle Reg. No. (Insured):	FBD646S	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/11/2018]		
Adj Asg. Remarks:	liability 100%, tp agree with sje - assign LKK Auto Consultants Pte Ltd.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 02 Nov 2018

Preliminary Advice

Insured Vehicle No	: FBD646S	Accident Date	: 29/10/2018
TP Vehicle No	: SMA2270P	Assignment Date	: 31/10/2018
Make	: VOLVO S60	Est. Duration of Repair	: 3.00
Date of Inspection	: 01/11/2018		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,280.00 Labour only
Revised Amount	:S\$	700.00 Labour only
Check Items (Estimated)	:S\$	0.00
Total	:S\$	700.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis. Pending parts price

Pang Xiu Shi

From: Pang Xiu Shi
Sent: Wednesday, 31 October 2018 11:28 AM
To: 'ad3@chewgoonmotor.com.sg'
Cc: Pauline Tham
Subject: RE: SMA2270P Claiming Against Your Insured FBD646S Accident Date: 29.10.2018

Dear Sirs

Thank you for your email.

We have both agreed on a common surveyor **LKK Auto Consultants Pte Ltd** to be the SJE (Single Joint Expert).

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Thank you.

From: Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]
Sent: Tuesday, October 30, 2018 5:32 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Margaret Loh <margaret_loh@sg.msig-asia.com>; chewgoon@singnet.com.sg; Eric <eric@chewgoonmotor.com.sg>
Subject: SMA2270P Claiming Against Your Insured FBD646S Accident Date: 29.10.2018

Dear Sirs/ Mdm,

Vehicle **SMA2270P** is lying at our workshop.

According to your list, we will prefer **LKK Auto Consultants Pte Ltd** to survey the vehicle.
Kindly arrange for survey.

Thanks & Regards,
Grace

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Denise Tay (LKKAuto)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Wednesday, 15 May 2019 3:12 PM
To: Denise Tay (LKKAuto)
Cc: chewgoon@singnet.com.sg
Subject: RE: SMA2270P Date of acc: 29.10.2018

Dear Denise,

Confirm P/P \$3,821.98 .

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, May 15, 2019 10:40:01 AM
To: Chew Goon Motor(ad3)
Cc: chewgoon@singnet.com.sg; Eric
Subject: RE: SMA2270P Date of acc: 29.10.2018

Dear Kelly,

As spoken,

The correct finalize amount should be \$3,821.98

Please confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Monday, 13 May 2019 5:44 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Denise Tay (LKKAuto)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Monday, 13 May 2019 5:44 PM
To: Denise Tay (LKKAuto)
Cc: chewgoon@singnet.com.sg; Eric
Subject: RE: SMA2270P Date of acc: 29.10.2018

Dear Denise,

Confirm P/P \$4437.58 and 3 working days.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from [Mail](#) for Windows 10

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, May 13, 2019 9:58:39 AM
To: Chew Goon Motor(ad3)
Cc: chewgoon@singnet.com.sg; Eric
Subject: RE: SMA2270P Date of acc: 29.10.2018

Dear Sir/Madam,

Enclosed estimate for finalization.

Offer on part by part \$4437.58, 3 Days

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Friday, 29 March 2019 1:51 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2018 10:19
Date Of Accident	29/10/2018 10:20
Exact Location Of Accident	UBI AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA2270P
Insured/Policyholder	
Name Of Registered Owner	GRAPE & CO
Co Reg No	53346890J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94598884

Vehicle Particulars

Manufacturer	VOLVO
Model	S60 D2
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102150055
Cover Note Number	

Driver

Name of Driver	ANG MENG THEW
NRIC No	S1456558B
Date Of Birth	07/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	27/11/1980
Driving Experience	37 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94598884
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 472A FERNVALE STREET #10-41
Postcode	791472
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 29/10/2018, 1020HRS, MY CAR WAS STOPPED AT UBI AVE 1, OUTSIDE PAYA UBI. IT'S TRAFFIC JAM, THE MOTORBIKE (B) CAME OUT FROM PAYA UBI CUT TO MY LEFT HAND SIDE FROM MY CAR BACK SIDE. DUE TO ROAD SURFACE UNEVEN, MOTORBIKE FALL DOWN AND HIT MY CAR LEFT SIDE BOTH DOORS AND GET DAMAGED SCAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBD646S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TOO AH LIANG
NRIC/Passport Number	S1691685D
Contact Number	96756211
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/10/18, 10.20am, my car was stopped at Ubi Ave 1, outside Paya Ubi. It's traffic jam, the motor bike (B) came out from Paya Ubi cut to my left hand side from my car back side, due to road surface uneven motor bike fall down and hit my car left side both doors and get damaged scral

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	6890J

Vehicle Details

Vehicle No.:	SMA2270P
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	VOLVO
Vehicle Model:	S60 D2
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	D4162T3188115
Chassis No.:	YV1FS84ABF2359730
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$29,416.00
Original Registration Date:	25 May 2015
First Registration Date:	25 May 2015
Transfer Count:	1
Actual ARF Paid:	\$18,183.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2025
PARF Rebate Amount:	\$13,637.00

Intended COE Rebate Details

COE Expiry Date:	24 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,590.00
COE Rebate Amount:	\$43,713.00
Total Rebate Amount:	\$57,350.00

The information contained herein is correct as at 30 Oct 2018

OK

► Volvo S60 Used Vehicle List (15 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
Volvo S60 T5	\$88,999	\$12,650 /yr	16-Jan-2015	1,969 cc	62,000 km	Premium Automobiles	Available

Special 2.48% Banks Interest Rate! Peace Of Mind With Certified Premium Preowned 110 Points Check, Perfect Condition, Classy White On Brown Interior, Smooth Engine With Economical Fuel Consumption.

Office No. - 68366223

Kelvin Neo - 91818000

Volvo S60 Diesel D2 (Diesel - Euro 5 Engine and Above)	\$72,800	\$10,240 /yr	21-Jan-2015	1,560 cc	44,000 km	Car House Enterprise (S) Pte Ltd	Available
---	-----------------	---------------------	--------------------	-----------------	------------------	---	------------------

1.99%-2.28% Interest Rates Promo! Very Well Maintained By Only 1 Previous Owner. Fully Agent Maintained With Wearnes! Original Paintwork/Interior. Fantastic Fuel Efficiency! Trade Ins Welcome. Call Th...

Office No. - 64433902

Damien - 97227775 | Clement - 91152539 | Ken - 90219697 | Derrick - 86979660

Volvo S60 Diesel D2 (Diesel - Euro 5 Engine and Above)	\$76,800	\$10,780 /yr	11-Feb-2015	1,560 cc	48,700 km	Car House Enterprise (S) Pte Ltd	Available
---	-----------------	---------------------	--------------------	-----------------	------------------	---	------------------

1.99%-2.28% Interest Rates Promo! 90% Loan Approval With Flexible Loan Packages With Low Interest And Monthly Installments! 100% Approval! Well Maintained And Agent Serviced! Pristine Condition! STA/V...

Office No. - 64433902

Glen Wong - 81009969 | Keven Sum - 98556677

Volvo S60 Diesel D2 (Diesel - Euro 5 Engine and Above)	\$74,800	\$10,460 /yr	12-Feb-2015	1,560 cc	70,000 km	Hua Yang Credit Pte Ltd	Available
---	-----------------	---------------------	--------------------	-----------------	------------------	--------------------------------	------------------

Maintained By Only 1 Previous Owner. Agent Maintained With Wearnes! Original Paintwork/Interior. Fantastic Fuel Efficiency! High Trade In Available, 100% Fast Approved Loan, Hurry Call Now.

Office No. - 64625111

Iskandar - 92471297 | Miss Tan - 86864198

Volvo S60 T5	\$84,800	\$11,330 /yr	20-May-2015	1,969 cc	84,000 km	Tan Wei Auto Pte Ltd	Available
---------------------	-----------------	---------------------	--------------------	-----------------	------------------	-----------------------------	------------------

10% Down Payment! Cheapest In The Market And Full Agent Serviced! No Wear And Tear To Replaced, All Good As New! Great Paintwork Condition And Very Clean Interior. No Mishap, As Good As It Could Be. P...

Office No. - 64595535

Ben Ong - 82981601 | Vernon Wong - 92770277

Volvo S60 T5	\$85,800	\$11,570 /yr	25-Jun-2015	1,969 cc	35,110 km	Republic Auto	Available
---------------------	-----------------	---------------------	--------------------	-----------------	------------------	----------------------	------------------

\$2,000 Republic Auto Warranty Workshop Credits. Agent Unit. Beautiful Sports. Well Maintained By 1 Owner. Call Handphone Below For View Appointment.

Office No. - 65672000

Ray Lee - 94506234

Volvo S60 T5 Drive-E	\$88,800	\$11,990 /yr	26-Jun-2015	1,969 cc	46,500 km		Available
-----------------------------	-----------------	---------------------	--------------------	-----------------	------------------	--	------------------

Low Mileage And Usually Parked Under Shade. Accident Free And Fully Agent-serviced With Records. Ceramic Coating And Clean Interior, Car Looks As Good As New. Front And Rear Car Cam. Comes With Additi...

Office No. - -

Ang Cher Hao - 98309244

Volvo S60 Diesel D2 (Diesel - Euro 5 Engine and Above)	\$81,800	\$10,640 /yr	27-Aug-2015	1,560 cc	42,000 km	Autorol Pte Ltd	Available
---	-----------------	---------------------	--------------------	-----------------	------------------	------------------------	------------------

Low Mileage And Full Maintained By Agent With Warranty Check Done In July! Beautiful Seashell Metallic With Black Leather Interior. Drive V Passion! Trade In And High Loan Available. Please Call Fo...

Office No. - -

Hari - 94594812 | Roland - 97666881

Volvo S60 T5 Drive-E	\$93,000	\$11,570 /yr	31-Aug-2015	1,969 cc	65,000 km	Wearnes Automotive	Available
-----------------------------	-----------------	---------------------	--------------------	-----------------	------------------	---------------------------	------------------


REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S1456558B

ANG MENG THEW

Date of Birth: 07 Feb 1960
 Validity Date: 19 Dec 2002

000040971F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1456558B




Name: **ANG MENG THEW**

洪明涛

Race: **CHINESE**

Date of Birth: 07-02-1960 Sex: **M**

Country of Birth: **SINGAPORE**


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 01 Motor Cars and Motor Tractors the weight of which laden does not exceed 2500 kilograms

PASS DATE: 27 Nov 1990

NR 429A

Licence No: S1456558B



012749300

Barcode

Identity Card No. S1456558B

Fingerprint

Blood Group: A+ Date of Issue: 05-03-1992

APT BLK 472A FERNVALE STREET #10-41
 SINGAPORE 791472

NR No: S1456558B Date: 04/02/2016

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5102150055

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SMA2270P**
Chassis Number : YV1FS84ABF2359730
2. Name of Policyholder : GRAPE & CO
3. Effective Date of Insurance : 10 Jul 2018
4. Expiry Date of Insurance : 09 Jul 2019
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.
Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: ANG MENG THEW
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: HONG LEONG FINANCE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : MOTOR UNIVERSE CREDIT PTE. LTD. (00000615288)
Date of Issue : 09 Jul 2018 16:52 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Accident Date : 29.10.2018

Policy No: Third Party

Date: 30.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volvo S60" Reg. No. SMA2270P Claiming Against Your Insured Veh. No. FBD646S			
1pc	Front Door LH BUC		2,293.30 ✓
1pc	Front Door Sticker NEC		116.00 ✓
1pc	Front Door Glass Outer Moulding (Chrome) SCR		256.50 ✓
6pcs	Front Door Panel Rivets	9.00	54.00 ✓
19pcs	Front Door Trim Boards Clips } NEC	5.50	104.50 ✓
1pc	Front Door Glass SCR	3418.5	440.10 ✓
1pc	Front Door Wing Mirror LH X NN	2934.3	1,650.00 X
1pc	Rear Door Weatherstrip / NN		132.20 ✓
1pc	Rear Door Glass Outer Moulding (Chrome) SCR		256.50 ✓
			5,303.10
	To Dismantle / Transfer Door Fittings / Ancillary Accessories	-5%:	150.00 60
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	3737.58	80.00 40
	Labour Charge - Panel Beating, Repairing Of Rear N/S Door and Parts Replacement	3247.58	400.00 200
	To Respray Affected Areas		650.00 400
	Total :		6,583.10

~~4437.58~~
3947.58

Ins. Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **MSIG Insurance (S) Pte Ltd**

Accident Date : 29.10.2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date:

Third Party

30.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Volvo S60" Reg. No. SMA2270P Claiming Against Your Insured Veh. No. FBD646S		
1pc	Front Door LH <i>one</i>		
1pc	Front Door Sticker <i>one</i>		
1pc	Front Door Glass Outer Moulding (Chrome) <i>scr</i>		
1pc	Front Door Panel Rivets		
19pcs	Front Door Trim Boards Clips <i>one</i>		
1pc	Front Door Glass <i>scr</i>		
1pc	Front Door Wing Mirror LH <i>one</i>		
1pc	Rear Door Weatherstrip <i>one</i>		
1pc	Rear Door Glass Outer Moulding (Chrome) <i>scr</i>		
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		60 150.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		40 80.00
	Labour Charge - Panel Beating, Repairing Of Rear N/S Door and Parts Replacement		200 400.00
	To Respray Affected Areas		400 650.00
		700 Total :	1,280.00

3 Days.
part by part.
before paint photos.
Gino Qoy (82880282)
01/11/18

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 30.10.2018

Accident Date : 29.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volvo S60" Reg. No. SMA2270P Claiming Against Your Insured Veh. No. FBD646S			
1pc	Front Door LH ✓		2293.30
1pc	Front Door Sticker ✓		116.00
1pc	Front Door Glass Outer Moulding (Chrome) ✓		256.50
1pc	Front Door Panel Rivets ✓	9.00	54.00
19pcs	Front Door Trim Boards Clips ✓	5.50	104.50
1pc	Front Door Glass ✓		440.10
1pc	Front Door Wing Mirror LH ✗		1650.00
1pc	Rear Door Weatherstrip ✓		132.20
1pc	Rear Door Glass Outer Moulding (Chrome) ✓		256.50
			5303.10
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		60 150.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		40 80.00
	Labour Charge - Panel Beating, Repairing Of Rear N/S Door and Parts Replacement		200 400.00
	To Respray Affected Areas		400 650.00
		Total :	6583.10

3 Days.

part by part.

before paint photos.

Gno Qup (8288082)

01/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018		31 Oct 2018 15:56 Edit Adj Rpt	S\$3,821.98 Edit Estimates	S\$3,821.98 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: 78 ST PTE LTD , Co. Reg. No.: 20133272D	
Main Claimant: GRAPE & CO , Co. Reg. No.: 53346890J	
Vehicle Reg. No.: SMA2270P	Date of Loss: 29/10/2018 10:00 - :59 [41 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / MSC/V/18-001462	Policy/Cover Note No.: MSD/VMT/18-990481-WTT (Third Party Only) Coverage: 30/03/2018 - 29/03/2019
Vehicle Reg. No. (Insured): FBD646S	Policy No. (Claimant):
	Excess:
Repairer: Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/11/2018]	
Adj Asg. Remarks: liability 100%. tp agree with sje - assign LKK Auto Consultants Pte Ltd.	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA2270P (MSC/V/18-001462)**
[FBD646S]
TP
GRAPE & CO
Oct 29 2018 10:00AM
[78 ST PTE LTD]
Chew Goon Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/11/18 14:55	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
2	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
13	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
14	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
15	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
16	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
17	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
18	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
19	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
20	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
21	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
22	14/05/19 15:52	General View		Load JPG	<input checked="" type="checkbox"/>
23	14/05/19 15:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	14/05/19 15:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	14/05/19 15:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	14/05/19 15:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/10/18 11:28	TP agree SJE - assign LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019873/GTD3S2
Date: 15/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/18-990481-WTT
Claimant Vehicle No : SMA2270P **Insured Vehicle No :** FBD646S
Date of Loss: 29/10/2018 **Nature of Claim:** TP **Claim No:** MSC/V/18-001462

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA2270P**
 Make & Model: VOLVO S60, 1.6 D2 (A) Engine No: D4162T3188115
 Reg. Date: 25/05/2015 (Man. Year: 2015) Chassis No: YV1FS84ABF2359730
 Colour: Silver Odometer: 78083 km
 Engine Capacity: 1560 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45ZR17 Rear Tyre Size: 235/45ZR17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,303.10	3,121.98	2,181.12	41.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	700.00	580.00	45.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,583.10	3,821.98	2,761.12	41.94
+ GST 7.00/7.00% (S\$)	460.82	267.54	193.28	41.94
Nett Amount (S\$)	7,043.92	4,089.52	2,954.40	41.94

INSPECTION

Date of Assignment: 31/10/2018
 Date Inspected: 01/11/2018 Inspected At: Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17,
 AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA2270P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	2,293.30 F	*2,293.30 FL
2	1		*FRONT DOOR STICKER	Necessary	116.00 F	*116.00 FL
3	1		*FRONT DOOR GLASS OUTER MOULDING (CHROME)	Scratched	256.50 F	*256.50 FL
4	6		*FRONT DOOR PANEL RIVETS	Necessary	54.00 F	*54.00 FL
5	1		*FRONT DOOR TRIM BOARD CLIPS (19 Pcs)	Necessary	104.50 F	*80.00 FL
6	1		*FRONT DOOR GLASS	Scratched	440.10 F	*230.00 FL
7	1		*FRONT DOOR WING MIRROR LH	Not Necessary	1,650.00 F	*- FL
8	1		*REAR DOOR WEATHERSTRIP	Not Necessary	132.20 F	*- FL
9	1		*REAR DOOR GLASS OUTER MOULDING (CHROME)	Scratched	256.50 F	*256.50 FL
					Sub Total (S\$)	5,303.10 3,286.30
					- List Item Discount on L Items 0.00/5.00% (S\$)	0.00 164.32
					Total Parts (S\$)	5,303.10 3,121.98

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE/TRANSFER DOOR FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	80.00	40.00
3	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR N/S DOOR AND PARTS REPLACEMENT	New	400.00	200.00
4	TO RESPRAY AFFECTED AREAS	New	650.00	400.00
Gross Labour Cost (\$\$)			1,280.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >