

ASS. REQ. BY:

REF:

CS/CT18019880/R1#bn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

M/mon

From (Person):

- Elaine Cheung

of

CT

Date/Time:

01.11.2018 2.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 1231M

Insured:

YN 5050C

at Workshop m/s

Shy Ah Tee

Tel:

6268 6183

of

Bik 3 Pioneer Rd North #01-18

Policy No:

DMCV SN 16087 21802

Claim No:

SNM18D05178C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

18.11.2018 @ 11am

13

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Joyce

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Part by Part \$540 (Red: 200; 27%)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐To Inspect Vehicle No: PC 1231Mat Workshop m/s: SNG AH TEEof PIONEER RO NORTHInsured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: 11am
over early
The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PC 1231M Yr Regn: 2012 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HIACE M C.C. 2982Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 179646 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TF3762P9 00001449Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 195R15R: ~BS / DUN / EXNOVA / GY / FS / LIZA / MIC / CHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

1) 20/3 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / KB: (\$ 5401)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018 Sendback Est	29 Oct 2018 12:08 S\$740.00	01 Nov 2018 14:01 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ALRICH SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	MEP SYSTEMS PTE. LTD., Co. Reg. No.: 200502632R		
Vehicle Reg. No.:	PC1231M	Date of Loss:	23/10/2018 17:00 - :59 [78 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05178C02	Policy/Cover Note No.:	DMCVSN1608721802
Vehicle Reg. No. (Insured):	YN5050C	Policy No. (Claimant):	P1621906
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2018]		
Adj Asg. Remarks:	EST \$791.80, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results,									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2632R
Vehicle Details	
Vehicle No.:	PC1231M
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER MANUAL
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	1KD2118848
Chassis No.:	JTFJT02P900001449
Maximum Power Output:	-
Open Market Value:	\$34,844.00
Original Registration Date:	29 Mar 2012
First Registration Date:	29 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$1,743.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$14,998.00
Total Rebate Amount:	\$14,998.00

The information contained herein is correct as at 24 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 14:27
Date Of Accident	23/10/2018 17:00
Exact Location Of Accident	ALONG THIRD LOK YANG RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1231M
Insured/Policyholder	
Name Of Registered Owner	MEP SYSTEMS PTE. LTD.
Co Reg No	200502632R
Email Address	CHRISTINETAN@MEPSYSTEMS.COM.SG
Mobile Phone No	(LOCAL) +65-91803335
Alternative Phone No	OFFICE-66810774

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1621906
Cover Note Number	

Driver

Name of Driver	GOH CHONG WONG
Passport No/FIN	F7841054W
Date Of Birth	14/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	15/01/2013
Driving Experience	5 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83866965
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	9D, JURONG PIER ROAD, #03-01, MEP BUILDING, SINGAPORE 619177
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/10/2018 AT ABOUT 1700 HRS.MY VEHICLE STATIONARY AT PARKING LOT OF THIRD LOK YANG RD. SUDDENLY A VEHICLE COME WITH FAST SPEED HIT ONTO MY VEHICLE CAUSING MY SIDE MIRROR DROP. DRIVER OF VEHICLE B REFUSE TO EXCHANGE ANY PARTICULAR .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN5050C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/10/2018
Vehicle Reg. No.:	PC1231M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	GOH CHONG WONG		
Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	29/03/2012
Vehicle Colour:	WHITE		
Engine No:	1KD2118848	Chassis No:	JTFJT02P900001449
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		

Description of Accident/Loss: ON 23/10/2018 AT ABOUT 1700 HRS.MY VEHICLE STATIONARY AT PARKING LOT OF THIRD LOK YANG RD. SUDDENLY A VEHICLE COME WITH FAST SPEED HIT ONTO MY VEHICLE CAUSING MY SIDE MIRROR DROP. DRIVER OF VEHICLE B REFUSE TO EXCHANGE ANY PARTICULAR .

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	120.00
Miscellaneous Items	0.00
Labour	620.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	740.00
+ GST 7.00% (S\$)	51.80
Nett Amount (S\$)	791.80

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Oct 2018)
Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT SIDE MIRROR (RH) <i>BR</i> ✓ WITH ARM	0.00	0.00	*80.00 F
2	1		*FRT DOOR GLASS OUTER MOULDING (RH) <i>CRA</i> ✓	0.00	0.00	*40.00 F
Total Parts (S\$)						120.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	20.00
2	TO KNOCK FRT DOOR (RH), WELD, REMOVE & REFIX ABOVE PARTS	New	200 308.00
3	TO PUTTY & REPSRAY PAINTING ON FRT DOOR (RH), WELD, REMOVE & REFIX ABOVE PARTS	New	200 308.00
Gross Labour Cost (S\$)			420 620.00

Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rome
H/90010068
15/11/18

2 days

9/P

13/11/18 @ 1100

Resurvey new mickel

120
420
540

2 days

Finished with
sharon

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey (To resurvey spray painting)
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (deposit) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/10/2018
Vehicle Reg. No.:	PC1231M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	GOH CHONG WONG		
Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	29/03/2012
Vehicle Colour:	WHITE		
Engine No:	1KD2118848	Chassis No:	JTFJT02P900001449
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	ON 23/10/2018 AT ABOUT 1700 HRS.MY VEHICLE STATIONARY AT PARKING LOT OF THIRD LOK YANG RD. SUDDENLY A VEHICLE COME WITH FAST SPEED HIT ONTO MY VEHICLE CAUSING MY SIDE MIRROR DROP. DRIVER OF VEHICLE B REFUSE TO EXCHANGE ANY PARTICULAR .		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	120.00
Miscellaneous Items	0.00
Labour	620.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	740.00
+ GST 7.00% (S\$)	51.80
Nett Amount (S\$)	791.80

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Oct 2018)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT SIDE MIRROR (RH) <i>BR</i> ✓ WITH ARM	0.00	0.00	*80.00 F
2	1		*FRT DOOR GLASS OUTER MOULDING (RH) <i>CRA</i> ✓	0.00	0.00	*40.00 F
Total Parts (S\$)						<i>(10)</i> ✓ 120.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	20.00
2	TO KNOCK FRT DOOR (RH), WELD, REMOVE & REFIX ABOVE PARTS	New	200 300.00
3	TO PUTTY & REPSRAY PAINTING ON FRT DOOR (RH), WELD, REMOVE & REFIX ABOVE PARTS	New	200 300.00
Gross Labour Cost (S\$)			620.00

Sng Ah Tee Motor & Panel Service Pte Ltd/PC1231M/29/10/2018 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Same

Hp 90010068

2 days

9/P

13/11/18 @ 1100

Resurvey new milestone

*total \$540/-
C/M w/ Panel
on 13/11/2018
11:00 AM*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *DC* after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019880/R1TBN2

Date: 25/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Claimant Vehicle No: PC1231M

Date of Loss: 23/10/2018

Policy No: DMCVSN1608721802

Insured Vehicle No: YN5050C

Nature of Claim: TP

Claim No: SNM18D05178C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC1231M

Make & Model: TOYOTA HIACE, 3.0 (A)

Reg. Date: 29/03/2012 (Man. Year: 2011)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1KD2118848

Chassis No: JTFJT02P900001449

Odometer: 173046 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Front Left Side: OHTSU 6 mm

Front Right Side: OHTSU 6 mm

Rear Tyre Size: 195R15

Rear Left Side: OHTSU 6 mm

Rear Right Side: OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	120.00	120.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	420.00	200.00	32.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	740.00	540.00	200.00	27.03
+ GST 7.00/7.00% (S\$)	51.80	37.80	14.00	27.03
Nett Amount (S\$)	791.80	577.80	214.00	27.03

INSPECTION

Date of Assignment: 01/11/2018

Date Inspected: 13/11/2018 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC1231M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT SIDE MIRROR (RH) WITH ARM	Broken	80.00 F	*80.00 FS
2	1		*FRT DOOR GLASS OUTER MOULDING (RH)	Cracked	40.00 F	*40.00 FS
					Total Parts (\$\$)	120.00 120.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	20.00	20.00
2	TO KNOCK FRT DOOR (RH),WELD, REMOVE & REFIX ABOVE PARTS	New	300.00	200.00
3	TO PUTTY & REPSRAY PAINTING ON FRT DOOR (RH),WELD, REMOVE & REFIX ABOVE PARTS	New	300.00	200.00
Gross Labour Cost (S\$)			620.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >