

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 01 November 2018

Third Party Insurer: AIG

Vehicle No: SLG3853G

Third Party Veh No: SJK975K

Model: VOLKSWAGEN POLO 1.2 TSI (A)

Date of Accident: 20 October 2018

Chassis: WVVZZZ6RZGU037079

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1SET	SIDE MIRROR ASSY COMPLETE RH		<i>Pin</i> \$910.00 ✓
1			
	SUB TOTAL		\$910.00
	Less 10%		-\$91.00
	PARTS TOTAL		\$819.00

ESTIMATE

LABOUR CHARGES:

TO REMOVE & RE INSTALL NEW SIDE MIRROR ASSY

\$80.00 ✓

TO RESPRAY SIDE MIRROR COVER

\$80.00 *601*

TO CHECK ALL WIRING RELATED TO SIDEMIRROR

\$60.00 *201*

TOTAL \$220.00

AZMAN

LABOUR TOTAL

\$1,039.00

Not Acknowledged
Repairing B & paint
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: