

ASS. REC. BY:

REF: CS/EGI18019936/R1+d3<sup>57</sup>

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Yee pei Li

of EGI

Date/Time: 2/11/18 @ 11

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 9420L

Insured:

GBB9143C

at Workshop m/s

Tan chong Motor  
913 Bukit timah

Tel:

6703 8916

Policy No:

Claim No:

CDMCG18000703

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Comp

H.O.D. Endorsement:

Date/Time: 11:31am @ 2/11/18

Person Contacted:

zuhri

Vehicle  IN /  OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBE 9420L - X</u>
	<u>GBB 9143C - X</u>
<u>7/11/18 @ 11:33 AM</u>	<u>Revised via. preli advise</u>
	<u>Part by part \$9644.08 (Red: 2360.76, 19%)</u>

Signature

REF: E67

0311M

ASSIGNMENT

From: \_\_\_\_\_ Date: 02-11-2018

Estimated Cost: \_\_\_\_\_

OD:  TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: GBE 9420L

at Workshop m/s: Tan Hong

of: 913 Bukit Timah Rd

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Zuhri

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBE 9420L Yr Regn: 2016 APR

Type: M.Gar / M.Cycle / Bus /  Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: NISSAN NV 350 PANEL VAN 2.5 CC 2484

Colour: GRAY A/C: Insured / Std / NI / NA

Sp Reading: 66448 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1MC2E262000 6435

Gen. Cond: Good /  Fair / Poor / Burnt

Steering: In order /  Jammed / Leaked / Burnt or

Brake: In order /  Jammed / Leaked / Burnt or

Mod:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C R: "

BS:  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal. 6 mm		R/Bal. 6 mm	
L/Bal. 6 mm		L/Bal. 6 mm	

D.O.A. 21/10/18 D.O.I. 02/11/18

Survey held at: TAN HONG

Des. of Damages: Frt / Rear /  O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 FEB 2019

Signature and date 01/11/2019

Date/Time: File Pass to?  Preli. Report  Final Report

1) 31/1 Typist

Date/Time: File Return to? \_\_\_\_\_

Days Of Repair: 14

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 350

Transportation: \_\_\_\_\_

Site Insp: \_\_\_\_\_

Interview: \_\_\_\_\_

Tech Invs: \_\_\_\_\_

Weekend: \_\_\_\_\_

FOCAL: \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I. / \$ 9644.08

Add Fee:  Site Insp. (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Friday, 2 November 2018 11:16 AM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM'  
**Subject:** OI : GBB9143C / TP : GBE9420L/LKK / DOA : 21/10/2018 (CDMCG18000703)  
**Attachments:** OI - GBB9143C - SAS.pdf; GBE9420L - SAS.pdf; SJA3393Y - SAS.pdf; GBE9420L - ESTIMATE.pdf; GBE9420L - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD**,

ADDRESS : 913 BUKIT TIMAH ROAD  
SINGAPORE 589622

PERSON TO CONTACT : ZUHRI @ 6703 8916 / 6469 4091

ERGO OFFICER-IN-CHARGE : STEVE LIM

**Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimates, insured and TP's SAS (**note: reports not to be released to any Third Party**). Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

**ERGO**

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 7 November 2018 11:33 AM  
**To:** Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.); assignments  
**Cc:** SUR  
**Subject:** RE: GBB9143C / TP : GBE9420L/LKK / DOA : 21/10/2018 (CDMCG18000703)  
**Attachments:** PRELI ADVISED GBE 9420L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBE 9420L**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 2 November 2018 11:29 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments  
<[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: GBB9143C / TP : GBE9420L/LKK / DOA : 21/10/2018 (CDMCG18000703)

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Friday, 2 November 2018 11:16 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM' <[ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)>  
**Subject:** OI : GBB9143C / TP : GBE9420L/LKK / DOA : 21/10/2018 (CDMCG18000703)

Dear Catherine/Nivitha,

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 31 January 2019 5:49 PM  
**To:** 'Muhammad Zuhri'; Rasul (LKKAuto)  
**Cc:** Norsipah  
**Subject:** RE: GBE 9420L / TP / ERGO / DOA: 21/10/2018

Dear Zuhri,

Confirm final figure \$9644.08, 14days.

Please submit all relevant documents to ERGO.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Muhammad Zuhri <[zuhri@tanchong.com](mailto:zuhri@tanchong.com)>  
**Sent:** Monday, 28 January 2019 5:19 PM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** Norsipah <[norsipah@tanchong.com](mailto:norsipah@tanchong.com)>; Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Subject:** RE: GBE 9420L / TP / ERGO / DOA: 21/10/2018

Dear Rasul ,

Kindly refer the attached photo .

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: [zuhri@tanchong.com](mailto:zuhri@tanchong.com)

Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

---

**From:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Sent:** 17 January 2019 09:33  
**To:** Muhammad Zuhri <[zuhri@tanchong.com](mailto:zuhri@tanchong.com)>; Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Cc:** Norsipah <[norsipah@tanchong.com](mailto:norsipah@tanchong.com)>  
**Subject:** RE: GBE 9420L / TP / ERGO / DOA: 21/10/2018

Hi Zuhri,

Kindly forward to me the damage supplementary damage photo of ACTUATOR ASSY



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CDMCG18000703  
Our Ref: CS/EGI18019936/R1td3

Date: 7/11/2018

The Motor Claims Department  
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. GBE 9420L .**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 02/11/2018 at the premises of M/s Tan Chong and have the following to report: -

Workshop Estimate Amount	: S\$	<u>11,734.44</u>
Revised Estimate Amount	: S\$	<u>9,238.68</u>
"Check" Items Amount	: S\$	<u>1,357.20</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

**Description of Damage:**

The vehicle sustained damages at rear n/s portion.



Repair days: 14 Days

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Rasul  
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

S/C  
DS

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/10/2018 10:29  
Date Of Accident 21/10/2018 06:05  
Exact Location Of Accident AT 263 PAVILION CIRCLE  
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE9420L  
**Insured/Policyholder**  
Name Of Registered Owner KOK WEE ENTERPRISE PTE. LTD.  
Co Reg No 201600311M  
Email Address KOKWEE88ENTERPRISE@GMAIL.COM  
Mobile Phone No  
Alternative Phone No OFFICE-97546090 / 9663 5794 - Mdm Lee .

Vehicle Particulars

Manufacturer NISSAN  
Model NV350 PANEL VAN 2.5 5AT 5DR EURO V  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number VCA/P1773873  
Cover Note Number

Driver

Name of Driver TAN KOK BOON  
NRIC No S1582678I  
Date Of Birth 29/03/1963  
Occupation INDOOR  
Date Of Driving Pass 21/03/1983  
Driving Experience 35 YEARS AND 7 MONTHS  
Gender FEMALE  
Mobile Number +65-97546090  
Fax Number  
Contact Number  
EMail Address NOEMAIL

Address	APT BLK 769 BEDOK RESERVOIR VIEW #12-195
Postcode	470769
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9143C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN ZHI XIONG
NRIC/Passport Number	S8824137A
Contact Number	82226021
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJA3393Y
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

國威企業私人有限公司  
KOK WEE ENTERPRISE PTE LTD


.....  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN A - GBE 9420 L, B - GBB 9143 C, C - SJA 33934



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 21/10/18 0605

Accident Location: 263 pavilion circle

My vehicle was parked at the mentioned location. Suddenly I heard a loud sound. I went outside & noted that vehicle B had collided onto my stationary vehicle as well as vehicle C which was also parked there.

Nobody was seen injured at scene.

Reporting Only  Own Damage  Third Party  Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\* IMPORTANT NOTE:  
You have been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a FOURTEEN (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

國威企業有限公司  
KOK WEE ENTERPRISE PTE LTD  
Policyholder's Signature  
Date & Time: .....

*Judy*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I, TAN ZHI XIONG (S8824137A) collided my  
Hoc Vehicle (G5B 9A3C) into vehicle GBE 9420L  
And SJA 3393 Y at ~~the~~ outside 265/263 pavilion  
circle at 6.10am 21/10/18. It was my  
fault.



TAN ZHI XIONG  
(S8824137A)  
8222 6021

BRILLIANT  
RISHALL

(witness) Tan Shikun  
S9629026 H  
GBE 9420L

(witness) TAN KOK BOON  
S1E74984B.

96787475



8222 6021

96787475



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MHH 118137369 Vehicle Registration No: GBE 94206
Name (as shown in NRIC) : Tan Kok Boon NRIC/FIN/Passport No : S15826781
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate
Address : Singapore ( )
Contact (Tel) : Mobile No. : 97546090
Email Address :
Date of Accident : 21/10/2018 Time of Accident : 06:05
Place of Accident : 263 Pavilion Circle
Insurance Company : AXA Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I was the driver who parked the vehicle at time of accident.
Casslyn reported on my behalf as I was overseas from
21/10/2018 - 23/10/2018

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 - 17:00  
UEN: S66550020G / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

**ADDENDUM**

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MHH 118137369-01 Vehicle Registration No: GBF 9420L  
Name (as shown in NRIC) : Tan Kok Boon NRIC/FIN/Passport No : S15826787  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 97546090  
Email Address : \_\_\_\_\_  
Date of Accident : 21/10/2018 Time of Accident : 06:03  
Place of Accident : 263 Pavilion Circle  
Insurance Company: AXA Insurance Pte Ltd

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To attach Third party's admittance note  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



License Number: **S9300493J**  
Name:  
**TAN YEE TENG CASSALYN**

Birth Date: 02 Jan 1993  
Issue Date: 23 Mar 2012



002053940C

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. **S9300493J**



Name  
**TAN YEE TENG CASSALYN**

**陳 愉 婷**

Race  
**CHINESE**

Date of birth Sex  
**02-01-1993 F** **S9300493J**

Country of birth  
**SINGAPORE**

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



License Number: **S9300493J**  
Name:  
**TAN YEE TENG CASSALYN**

Birth Date: 02 Jan 1993  
Issue Date: 23 Mar 2012



002053940C

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. **S9300493J**



Name  
**TAN YEE TENG CASSALYN**

**陳 愉 婷**

Race  
**CHINESE**

Date of birth Sex  
**02-01-1993 F** **S9300493J**

Country of birth  
**SINGAPORE**

AXA INSURANCE PTE LTD  
8 Shenton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel:(65)63387288 Fax:(65)63382522  
Website:www.axa.com.sg  
GST Registration Number: 199903512M  
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VCA/P1773873 Account No. : 04437  
Coverage : Comprehensive  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : KOK WEE ENTERPRISE PTE LTD  
Vehicle Registration No. : GBE9420L  
Period of Insurance : From 28/04/2018 To 27/04/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE\*

- (a) Use in connection with the Policyholder's business
  - (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
  - (c) Use for social, domestic and pleasure purposes
- This Policy does not cover
- (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
  - (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

EXCESS :

Sect I - Any Authorised Driver : SGD 700.00  
Windscreen Excess : SGD 140.00

(Please refer to your policy for Additional Excess)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

  
Authorized Signature

Issued by - SGOSTPR on 26/04/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

**ALLINK INSURANCE AGENCY**  
Blk 153 Bukit Batok Street 11  
#02-290 Singapore 650153  
Tel : 6567 4722  
Fax: 6567 4460

6425 647 ERINE,  
VEHICLE INSURANCE CLAIMS dept

**AXA INSURANCE PTE LTD**

8 Shenton Way, #24-01  
 AXA Tower, Singapore 068811  
 Customer Service Centre #B1-01  
 Tel: 6336 7288 Fax: 6338 2522  
 Website: www.axa.com.sg  
 GST Registration Number: 199903512M



Original

Agent Code: **04437**Policy No.(if any): **P1773873****Renewal**

SmartDrive Quote Ref:

**MOTOR COVER NOTE**No. **CN887599**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

**SCHEDULE**

THE COMPANY	<b>AXA INSURANCE PTE LTD</b>
INSURED	<b>KOK WEE ENTERPRISE PTE LTD</b>
INSURED BUSINESS REGISTRATION NO.	
MAKE AND DESCRIPTION OF VEHICLE	NISSAN NV350 VAN
VEHICLE REGISTRATION NO.	GBE9420L
YEAR OF MANUFACTURE	2016
ENGINE NO.	YD25393761A
CHASSIS NO.	JN1MC2E26Z0006435
ENGINE CAPACITY/TONNAGE	1.5 TONS
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	N/A
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: <b>28/04/2018</b> TO: <b>27/04/2019</b>
EXCESS (S\$)	\$700 (I) ; \$140 (WINDSCREEN)
<b>AXA PREMIUM WORKSHOP?</b>	<b>NO</b>

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

**AXA INSURANCE PTE LTD**

Issued by **ALLINK INSURANCE AGENCY** on **16/04/2018 6:23pm**

  
 Authorised Signature

**Note** : This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged:
  - Cover note issued and cancelled before inception.
  - Retaining the old registration number for a new vehicle insuring with AXA.

**PREMIUM WARRANTY**For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0482/2018  
DATE : 30-OCT-2018

ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
S(038985)  
TEL : 68299199  
FAX : 68299247/9248  
ATTN : CLAIM MANAGER

OWNER'S NAME : M/S KOK WEE ENTERPRISE PTE LTD  
ADDRESS : 9005 TAMPINES STREET 93  
#03-224 TAMPINES INDUSTRIAL PARK A  
S(528839)  
TELEPHONE NO : 93363739

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-GBB9143C  
VEHICLE NO : GBE9420L  
MODEL CODE : MVL2RDKE26KW3GBR-D  
MODEL/YEAR : NISSAN NV350 PANEL VAN AT EURO5  
ENGINE NO : YD25393761A  
CHASSIS NO : JN1MC2E2620006435  
MILEAGE : 1 KM  
DATE IN : 30/10/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 21/10/2018

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / CAR NOT AT WORKSHOP**

**KINDLY REVERT TO ME ASAP**

**EMAIL : [zuhri@tanchong.com](mailto:zuhri@tanchong.com)**

**OFFICE : 67038916 FAX : 64697472**

01/11/2018

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBE9420L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL	<del>360.00</del>	240 ✓
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	/ ✓
3	TRANS2000	TRANSFER DOOR/BACKDOOR MECHANISM 2000CC	120.00	/ ✓
4	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	/ 103 ✓
5	ZZ/001	REPAIR REAR INNER FENDER RH,RR TAILGATE,ROCKER RH RENEW RR FENDER RH,RR DOOR RH & RR BUMPER	<del>3900.00</del>	3120 ✓
6	ZZ/002	S/PAINT RR FENDER RH,RR DOOR RH,RR BUMPER,RR TAILGT RR INNER FENDER RH,FRT DOOR RH &ROCKER RH	<del>1750.00</del>	1500 1625 ✓
7	ZZ/003	R/INSTALL SIDE BOARD RR DOOR RH & QUATER BOARD RH	<del>320.00</del>	160 ✓
TOTAL LABOUR CHARGES			6743.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9420L

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		net 70.00 50 ✓
2	SEALANT - FRONT W/SCREEN GLASS(2X\$80)	SEALANT - 2		net 160.00 80 ✓
3	LAMP ASSY-RH <i>PRO ✓</i>	26010-3XA1D	366.40 ✓	
4	CAP-ROAD WHEEL <i>MU ✓</i>	40315-1GK0A	151.20 ✓	
5	LID-FUEL FILLER <i>PA ✓</i>	G8830-3XAMA	95.00 ✓	
6	SIDE PANEL <i>RE ✓</i>	G7422-3XBMA	1793.40 ✓	
7	DUCT-DRAPTER ?	76804-VW000	50.30 X	} <i>see</i>
8	FINISHER-SLIDE ?	76826-3XB2B	107.00 X	
9	RAIL ASSY-GUIDE DOOR RR RH ?	77760-3XA2B	641.00 X	
10	STOPPER-RH ?	82440-3XA0A	60.00 X	
11	ROLLER A-S/DOOR ?	82420-3XA0C	112.70 X	
12	RAIL GIUDE UPPER RH ?	77790-3XA0A	241.20 X	
13	CHECKER ASSY-SL ?	82430-3XA0A	39.50 X	
14	SUB ROLLER-SLID RH ?	82404-WL60A	50.90 X	
15	SIM-S/DOOR UPR ?	82404-01N00	3.70 X	
16	ROLLER ?	82400-3XA0A	50.90 X	
17	WEATHERSTRIP <i>RE ✓</i>	82830-3XA0C	159.40 ✓	
18	DOOR ASSY <i>PA ✓</i>	H210M-3XBMA	1255.70 ✓	
19	EMBLEM-BACK DOO <i>RE ✓</i>	90890-3XY0A	101.30 ✓	
20	EMBLEM-REAR <i>RE ✓</i>	90890-JX00A	59.70 ✓	
21	CLIP(10X1.2) <i>RE ✓</i>	01553-05933	12.00 ✓	
22	FACE-RR BUMPER <i>SEE ✓</i>	85022-3XA0A	600.50 ✓	
SUB TOTAL			5951.80	0.00 230.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1190.36	0.00 0.00
GRAND TOTAL			4761.44	0.00 230.00



SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBE9420L

TOTAL LABOUR CHARGES 6743.00  
TOTAL SPARE PARTS CHARGES 4991.44  
-----  
GRAND TOTAL 11734.44 \*

\* All charges do not include GST.

2014.04

*[Handwritten Signature]*  
7/11/18

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE : 0.00  
LIABILITY : 0.00  
REMARKS :

RASUL - Hp 90010068  
02/11/18 @ 1745  
14 days

Resy 54 percent

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0482/2018  
DATE : 30-OCT-2018

DS ⇒ RASU

ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
S(038985)  
TEL : 68299199  
FAX : 68299247/9248  
ATTN : CLAIM MANAGER

ZHR

OWNER'S NAME : M/S KOK WEE ENTERPRISE PTE LTD  
ADDRESS : 9005 TAMPINES STREET 93  
#03-224 TAMPINES INDUSTRIAL PARK A  
S(528839)  
TELEPHONE NO : 93363739

(14 Days)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-GBB9143C  
VEHICLE NO : GBE9420L  
MODEL CODE : MVL2RDKE26KW3GBR-D  
MODEL/YEAR : NISSAN NV350 PANEL VAN AT EUROS  
ENGINE NO : YD25393761A  
CHASSIS NO : JN1MC2E26Z0006435  
MILEAGE : 66448 KM  
DATE IN : 30/10/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 21/10/2018

LOW = \$90 x 14  
= \$1260

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBE9420L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RIFT	REMOVE/INSTALL FUEL TANK(SUPPLEMENTARY LABOUR)	150.00	150.00 (A) N/S
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL	360.00	240.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	200.00
4	TRANS2000	TRANSFER DOOR/BACKDOOR MECHANISM 2000CC>	120.00	120.00
5	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	103.00
6	Z2/001	REPAIR REAR INNER FENDER RH,RR TAILGATE,ROCKER RH RENEW RR FENDER RH,RR DOOR RH & RR BUMPER	3900.00	3120.00
7	Z2/002	S/PAINT RR FENDER RH,RR DOOR RH,RR BMPER,RR TAILGT RR INNER FENDER RH,FRT DOOR RH &ROCKER RH	1750.00	1625.00
8	Z2/003	R/INSTALL SIDE BOARD RR DOOR RH & QUATER BOARD RH	320.00	160.00
TOTAL LABOUR CHARGES			6903.00	5718.00

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO G8E9420L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	ACTUATOR ASSY(SUPPLEMENTARY ITEM) <i>3(A) OK ✓</i>	78850-VW00A	138.00		OK
2	LABEL 70KM/H(SUPPLEMENTARY ITEM) <i>✓</i>	SWD-70KM			10.00 OK
3	CAP-ROAD WHEEL	40315-1GK0A	151.20 ✓		OK
4	LID-FUEL FILLER	G8830-3XAMA	95.00 ✓		OK
5	SIDE PANEL	G7422-3XBMA	1793.40 ✓		OK
6	DUCT-DRAFTER	76804-VW000	50.30		X
7	FINISHER-SLIDE	76826-3XB2B	107.00		X
8	RAIL ASSY-GUIDE DOOR RR RH	77760-3XA2B	641.00		X
9	STOPPER-RH	82440-3XA0A	60.00		X
10	ROLLER A-S/DOOR	82420-3XA0C	112.70		X
11	RAIL GIUDE UPPER RH	77790-3XA0A	241.20		X
12	CHECKER ASSY-SL	82430-3XA0A	39.50		X
13	SUB ROLLER-SLID RH	82404-WL60A	50.90		X
14	SUNDRIES	NPN			50.00 OK
15	SEALANT - FRONT W/SCREEN GLASS(2X\$80)	SEALANT - 2			80.00 OK
16	LAMP ASSY-RH	26010-3XA1D	366.40 ✓		OK
17	SIM-S/DOOR UPR	82404-01N00	3.70		X
18	ROLLER	82400-3XA0A	50.90		X
19	WEATHERSTRIP	82830-3XA0C	159.40		OK
20	DOOR ASSY	H210M-3XBMA	1255.70		OK
21	EMBLEM-BACK DOO	90890-3XY0A	101.30		OK
22	EMBLEM-REAR	90890-JX00A	59.70		OK
23	CLIP(10X1.2)	01553-05933	12.00		OK
24	FACE-RR BUMPER	85022-3XA0A	600.50		OK

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9420L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		4732.60	0.00	140.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		946.52	0.00	0.00
GRAND TOTAL		3786.08	0.00	140.00
OVERALL TOTAL		3926.08		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBE9420L

NETT ITEM	4732.60
LESS 20.00%)	-946.52
NETT AMOUNT	3786.08
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	140.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	140.00
TOTAL LABOUR CHARGES	5718.00
TOTAL SPARE PARTS CHARGES	3926.08
TOTAL CHARGES	9644.08
ADD 7 % GST	675.09
GRAND TOTAL	10319.17



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18019936/R1td3s2

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 07-02-2019



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 9143C	Veh. Inspected	GBE 9420L
Policy No.		Coverage (\$)	0.00
Claim No.	CDMCG18000703	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/11/2018

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350 PANEL VAN 2.5	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1MC2E26Z0006435	Colour	GREY
Odometer	66448	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	6 mm
L/H Front Tyre	195 R15C	DUNLOP	6 mm
R/H Rear Tyre	195 R15C	DUNLOP	6 mm
L/H Rear Tyre	195 R15C	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/10/2018	Inspection Date	02/11/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913 BUKIT TIMAH ROAD SINGAPORE 589623		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>14 Working Days</b>
-------------------------------------	------------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9420L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LAMP ASSY - RH (N)	BROKEN	366.40	366.40
1	CAP - ROAD WHEEL (N)	MISSING	151.20	151.20
1	LID - FUEL FILLER (N)	BENT	95.00	95.00
1	SIDE PANEL (N)	BUCKLED	1,793.40	1,793.40
1	DUCT - DRAFTER (N)	SERVICEABLE	50.30	-
1	FINISHER - SLIDE (N)	SERVICEABLE	107.00	-
1	RAIL ASSY - GUIDE DOOR RR RH (N)	SERVICEABLE	641.00	-
1	STOPER - RH (N)	SERVICEABLE	60.00	-
1	ROLLER A-S/DOOR (N)	SERVICEABLE	112.70	-
1	RAIL GUIDE UPPER RH (N)	SERVICEABLE	241.20	-
1	CHECKER ASSY-SL (N)	SERVICEABLE	39.50	-
1	SUB ROLLER - SLID RH (N)	SERVICEABLE	50.90	-
1	SIM - S/DOOR UPR (N)	SERVICEABLE	3.70	-
1	ROLLER (N)	SERVICEABLE	50.90	-
1	WEATHERSTRIP (N)	NECESSARY	159.40	159.40
1	DOOR ASSY (N)	BENT	1,255.70	1,255.70
1	EMBLEM - BACK DOO (N)	NECESSARY	101.30	101.30
1	EMBLEM - REAR (N)	NECESSARY	59.70	59.70
10	CLIP @ \$1.20 (N)	NECESSARY	12.00	12.00
1	FACE - RR BUMPER (N)	SCRATCHED	600.50	600.50
1	ACTUATOR ASSY (N) (ADDITIONAL)		138.00	138.00
	LESS 20% DISCOUNT		-1,217.96	-946.52
			<b>4,871.84</b>	<b>3,786.08</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NECESSARY	70.00	50.00
2	SEALANT - FRONT W/SCREEN GLASS @ \$80.00 (SN)	NECESSARY	160.00	80.00
1	LABEL 70KM/H (SN) (ADDITIONAL)	NECESSARY	10.00	10.00
			<b>240.00</b>	<b>140.00</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL.		360.00	240.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL.		200.00	200.00
	TRANSFER DOOR / BACK DOOR MECHANISM 2000CC. (N)		120.00	120.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - PASSENGER.		103.00	103.00
	REPAIR REAR INNER FENDER RH, RR TAILGATE, ROCKER RH RENEW RR FENDER RH, RR DOOR RH & RR BUMPER.		3,900.00	3,120.00
	S/PAINT RR FENDER RH, RR DOOR RH, RR BUMPER, RR TAILGT RR INNER FENDER RH, FRT DOOR RH & ROCKER RH.		1,750.00	1,625.00
	R/INSTALL SIDE BOARD RR DOOR RH & QUARTER BOARD RH.		320.00	160.00
	REMOVE / INSTALL FUEL TANK. (ADDITIONAL)		150.00	150.00
			6,903.00	5,718.00
	<b>GRAND TOTAL</b>		<b>12,014.84</b>	<b>9,644.08</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>9,644.08</b>

Report Ref No. CS/EG18019936/R1td3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.