

22/03/2002

ASS. REC. BY:

REF:

CS3/CT118019955/Gcb02

Special Instruction:

Surveyor:

merlin

GQ

ASSIGNMENT (Office)

From (Person):

Elaine Cheung

of

CN

Date/Time:

02.11.2018 3:47pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 2875 R

Insured:

SGZ 5538 M

at Workshop m/s

Hiap Lek Automobile

Tel:

5660 1347

of

160 Sin Ming Drive #05-17

Policy No:

DMPCSN13090531700

Claim No:

SNM18D0518702

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

02.11.2018 3:47pm

Person Contacted:

Han Wei

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJR 2875 R - X

SGZ 5538 M - X

PRS

REF: CTL

30 2013

Meatmen

Xhl

ASSIGNMENT

From Date: 02-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR 2875R

at Workshop m/s

of 160 sin mny Drw #05-17

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJR 2875R Yr Regn: 17 Jun 2009

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios C.C. 1497

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 296991 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO53H4 930 5117069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 02-11-18

Survey held at w/s 5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$10000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

Report Format : PRS.

Lump Sum / I.B.I: (\$

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Nov 2018		02 Nov 2018 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KOH HUP HENG , ID: S8222069J								
Main Claimant:	HENG CHIN CHYE , ID: S2193020B								
Vehicle Reg. No.:	SJR2875R	Date of Loss:	01/11/2018 06:00 - :59						
Claim Type:	TP / SNM18D05187C02	Policy/Cover Note No.:	DMPCSN3090531700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGZ5538M	Policy No. (Claimant):	5046196851-07 (DRIVO CLASSIC)						
		Excess:	S\$0.00						
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]								
Driver/Custodian (Insured):	KOH HUP HENG (36 / Male), NRIC: S8222069J								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3020B

Vehicle Details

Vehicle No.:	SJR2875R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1NZX922813
Chassis No.:	MR053HY9305117069
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,876.00
Original Registration Date:	17 Jun 2009
First Registration Date:	17 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$13,876.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jun 2019
PARF Rebate Amount:	\$6,938.00

Intended COE Rebate Details

COE Expiry Date:	16 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$8,489.00
COE Rebate Amount:	\$521.00
Total Rebate Amount:	\$7,459.00

The information contained herein is correct as at 05 Nov 2018

OK

► Vios Used Vehicle List (18 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Toyota Vios 1.5A E	\$9,988	-	16-Jan-2009	1,497 cc	146,859 km	Wheels Singapore Pte Ltd	Availabl
2nd Owner Refinanced 4years Ago. Car Runs Perfectly With No Undercarriage Sounds, Suspensions All Working Fine, Bodywork Close To Perfect! Accident Free Vehicle. Buy Now And Wait For Cheaper COE Or Re...							
Office No. - 66815662 Jacson - 87881825 Mok - 97285889 Mr Ng - 86857799 Benjamin - 83237600							
Toyota Vios 1.5A E Sports	\$14,000	\$13,630 /yr	02-Jun-2009	1,497 cc	-		Availabl
Lady Owner, Very Well Taken Care Sporty Nice White Car, Look Like New, Brand New Tyres, New Paint, Servcing Just Done, Well Taken Car Interior, Very Low Maintenance, Must Sell! Road Tax Till 01 Decem...							
Office No. - - Serene - 98989996							
Toyota Vios 1.5A J	\$15,800	\$9,550 /yr	10-Nov-2009	1,497 cc	120,000 km	Ka-Hup Vehicles Trading	Availabl
Well Maintained Condition And Superb Fuel Economy Model. Suitable For Future COE Renewable Too. Hurry Up And Give Me A Call For View Now.							
Office No. - 67415939 DJ Lim - 82333664 Johnson Lim - 90722292							
Toyota Vios 1.5A J	\$15,800	\$14,100 /yr	17-Jul-2009	1,497 cc	-	Mandai Motor Trading	Availabl
One Of The Well Known Vehicle For Fuel Efficient! Well Maintained! Trade In Welcome! Flexible/High Loan Available, Hurry Don't Miss! Call Now!							
Office No. - 67775585 Darren - 82233251 Heng Heng - 90058812 David - 93860705 Ms Li Jin - 97548093							
Toyota Vios 1.5A E (New 5-yr \$27,800 COE)	\$5,560 /yr		23-Feb-2009	1,497 cc	-	Trust Motor Trading	Availabl
1 Owner Only Elegant Silver Color. Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, GST Included, Flexible In-House Loan Packages Available. Call...							
Office No. - 63384472 Alvin Chea - 90295022 Benson Tan - 84187320 Mr Lim - 96263081							
Toyota Vios 1.5A E (New 5-yr \$27,800 COE)	\$5,560 /yr		14-Jan-2009	1,497 cc	116,376 km	Mayfair Motoring	Availabl
Cheap And Reliable Sedan! Excellent Fuel Efficiency! Good To Drive Till Scrap! Selling Cheap! Low Costing Car To Own! Call For A Viewing Appointment Today!							
Office No. - 64792220 Richard Ho - 98625691 Kenny Toh - 91871230 Terry Cheah - 84840005 Kohji - 97327889							
Toyota Vios 1.5A E (New 5-yr \$27,800 COE)	\$5,560 /yr		21-Jan-2009	1,497 cc	101,000 km	Crown Motoring Pte Ltd	Availabl
Option To Renew 10 Years COE, Tip Top Condition, Low Depreciation And Best Price In Town, View To Believe, Bank Or In House Loan Available.							
Office No. - 68733133 Eric - 93869133 Danny - 86833133							
Toyota Vios 1.5A E (New 5-yr \$27,800 COE)	\$5,560 /yr		03-Mar-2009	1,497 cc	-	Lei Fu Trading Co.	Availabl
Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Availabl Best For Grab And Transportation Usages! Trade In Welcome. Call...							
Office No. - 67469005 Ben - 94528805 Wee Beng - 91040878 Tan - 96942466							
Toyota Vios 1.5A G (New 5-yr \$28,899 COE)	\$5,780 /yr		11-Feb-2009	1,497 cc	91,953 km	A4 Car Motor	Availabl

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2018 16:14
Date Of Accident	01/11/2018 06:35
Exact Location Of Accident	SLIP RD OF PUNGGOL RD TWDS TPE/SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR2875R
Insured/Policyholder	
Name Of Registered Owner	HENG CHIN CHYE
NRIC No	S2193020B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98580242
Alternative Phone No	OTHERS-98580242

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5046196851-07 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	HENG CHIN CHYE
NRIC No	S2193020B
Date Of Birth	24/03/1967
Occupation	INDOOR
Date Of Driving Pass	11/02/1997
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98580242
Fax Number	
Contact Number	OTHERS-98580242
EMail Address	NOEMAIL

Address	BLK 102A #06-438 PUNGGOL FIELD
Postcode	821102
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGZ5538M
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH HUE WENG
NRIC/Passport Number	S8222069J
Contact Number	83397313
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

01 NOV 2018



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Punggol Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 01/11/18 @ about 06:30am, I am travelling along Punggol Road. At the Jip Road of Punggol Road, I stopped my vehicle to give way to the oncoming traffic of TPE direction. Before the traffic could even be clear, I felt an impact on my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

01 NOV 2018



Stacy
Policyholder's Signature
Date & Time:

Stacy
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:































...CLAIM SUBFOLDER...(Pending for Survey Report)















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Nov 2018		02 Nov 2018 15:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case


Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KOH HUP HENG , ID: S8222069J									
Main Claimant: HENG CHIN CHYE , ID: S2193020B									
Vehicle Reg. No.: SJR2875R		Date of Loss: 01/11/2018 06:00 - :59 [112 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05187C02		Policy/Cover Note No.: DMPCSN3090531700 (Comprehensive)							
Vehicle Reg. No. (Insured): SGZ5538M		Policy No. (Claimant): 5046196851-07 (DRIVO CLASSIC)							
		Excess: S\$0.00							
Repairer: Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/11/2018]									
Driver/Custodian (Insured): KOH HUP HENG (36 / Male), NRIC: S8222069J									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents














***SJR2875R (SNM18D05187C02)**
[SGZ5538M]
TP
HENG CHIN CHYE
Nov 1 2018 6:00AM
[KOH HUP HENG]
Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print	
1	01/11/18 16:20	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print	
1	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
7	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
8	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
9	01/11/18 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	05/11/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
22	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/11/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/11/18 09:19	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
28	05/11/18 09:19	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
29	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/11/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/11/18 15:46	PRS	 Load PDF	
2	02/11/18 15:47	OI GIA	 Load PDF	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	01/11/18 16:19	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	01/11/18 16:19	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
3	01/11/18 16:19	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print		
1	01/11/18 16:20	Accident Statement	 Load HTM			
Photos/Images			3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print		
1	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
2	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
3	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
4	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
5	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
6	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
7	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
8	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
9	01/11/18 16:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
Documentation			1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print		
1	01/11/18 16:19	Sketch Plan	 Load TIF			
2	01/11/18 16:19	Sketch Plan #2	 Load TIF			
3	01/11/18 16:19	Sketch Plan #3	 Load TIF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118019955/GCBE2

Date: 09/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3090531700

Claimant Vehicle
No: SJR2875RInsured Vehicle
No: SGZ5538M

Date of Loss: 01/11/2018

Nature of Claim: TP

Claim
No: SNM18D05187C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR2875R

Make & Model: TOYOTA VIOS, 1.5 (A)

Reg. Date: 17/06/2009 (Man. Year: 2009)

Colour: Black

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZX922813

Chassis No: MR053HY9305117069

Odometer: 296991 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2018

Date Inspected: 02/11/2018 Inspected At:

Hiap Lek Automobile Trading (HQ)
160 Sin Ming Drive, #05-17 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2018)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR2875R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >