

NATIONAL Assessment Centre Services (ver 1 Jan 2003)

Date In: 02/11/2018 15:16	Job description	Date & Time Completed	Done by
Ref No: NA/INC18019956/K4	SAS e-filing		
Veh No: SLW6506E	E-mail (within 8hrs, AIC 2hrs)		
D.O.A: 02/11/2018 10:00	I-Motor Claim Form	MT/1018231-001	02/11/18 16:35
OD: TP: Reporting Only	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
TP Insurer	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel: (	Fax: (
TP Particulars:	Veh No: SGH713B	INC () / Non-INC ()
Owner / Driver: (	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (	Date: (	Time: (
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79%. P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:-	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

Claimant's Particulars:-	NA 1807880	Invoice Preparation Checklist		Am't (\$)	Am't (\$)
				Inc Bill	Add. Bill
Driver/Owner:		1) AR: Accident Reporting (\$30);			
Contact No:		2) DA: Damage Assessment (\$100); INC (\$80)			
Damaged Portion:		3) TF: Towing Fee \$40/\$45			
		4) FT: Follow-Through Survey \$120			
		5) FT: Follow-Through Survey (Resurvey) \$30			
		For claiming against INC Only (wef 10 Jan 2005)			
		6) TR: Re-inspection \$75			
		7) N1: Idno DA + SMRT Survey \$160			
		8) NTUC Additional Services:-			
		ON*			
		*N5: Courtesy Car / Tpt Allowance \$5			
		*N6: Repair Co-ordination \$10			
		*N7: Post Repair Inspection \$25			
		*N8: DV / Collect Excess Coordination \$5			
		TE (N11): TP (N-in INC) against INC \$20			
		9) N12: Idno Mobile 30			
QC Checked by (Engr-In-Charge):		Invoice dated	Fee Charged		
Auditors' Comments:-					
Ref: 1:					
Ref: 2/3:					

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/11/2018 15:16
 Date Of Accident 02/11/2018 10:00
 Exact Location Of Accident CTE TWDS CITY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFH1899D
Insured/Policyholder
 Name Of Registered Owner HENG KAI TING
 NRIC No S8110930C
 Email Address WESLEYLIMPROPERTY@GMAIL.COM
 Mobile Phone No (LOCAL) +65-97697738
 Alternative Phone No OTHERS-91806198

Vehicle Particulars

Manufacturer BMW
 Model -
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5100979347
 Cover Note Number

Driver

Name of Driver HENG KAI TING
 NRIC No S8110930C
 Date Of Birth 20/03/1981
 Occupation INDOOR
 Date Of Driving Pass 01/04/2008
 Driving Experience 10 YEARS AND 7 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-97697738
 Fax Number
 Contact Number OTHERS-91806198
 Email Address WESLEYLIMPROPERTY@GMAIL.COM

Address	BLK 331A ANCHORVALE STREET #12-545
Postcode	541331
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH713B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LO WING FAI
NRIC/Passport Number	S1227421A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2 November 2018 vehicle A was traveling along CTE towards City. Shortly after AMK but before Braddell exit, on lane 2 (Two) of CTE, vehicle B suddenly jammed brake causing vehicle A to crash into vehicle B's rear. vehicle B suffered rear damages/dent. Vehicle A front damages dent crack broken pieces include head lights and rear engine interior and exterior damages plus paint work gone.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:
2/11/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:
2/11/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2/11/2018

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

Our ref 0606180203N057017891

06 Jun 2018

HENG KAI TING
APT BLK 331A ANCHORVALE STREET
#12-545
SINGAPORE 541331

002803



Dear Sir/Madam

**NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO.
SLW6506E WITH VEHICLE REGISTRATION NO. SFH1899D**

You may be pleased to know that your application of 06 Jun 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No.	: SFH1899D (Previously SLW6506E)
Vehicle Make	: B.M.W.
Vehicle Model	: 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Chassis No.	: WBAXG12040DX48267
Engine No./ Motor No.	: A0490144N20B20B / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : WBAXG12040DX48267, Engine No./ Motor No. : A0490144N20B20B / -) to display the new/ replacement registration number, SFH1899D by 09 Jun 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20180606124516362801 or the vehicle registration number when making your enquiry.

Yours sincerely

NG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
VEHICLE SERVICES GROUP
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)

From 15 February 2017, you do not need to display road tax disc on the windscreen of your vehicle. LTA has stopped issuing physical road tax discs as part of our efforts to streamline our processes. Please ensure that your original motor insurance certificate is readily available in your vehicle at all times. If you are driving into Malaysia, you are advised to carry printed proof of the validity of your road tax in your vehicle.

Reported on 2/11/2018
@ 1510hrs.

ACCIDENT STATEMENT

ACCIDENT DATE: (2/11/2018) (DD/MM/YYYY), TIME: (10:00) (HH:MM)

LOCATION: CTE Towards City

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SLW 6506E
b) INSURANCE COMPANY:
c) POLICY NUMBER:
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL:
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME:
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: CONTACT:
c) ADDRESS:

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: CONTACT: 97697738
c) ADDRESS:

* d) DATE OF BIRTH: (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS:

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO) OWNER
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED:

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SGH 713B MODEL:
b) DRIVER'S NAME: LOWING FAI
c) NRIC/FIN/PASSPORT: S1227421A CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: MODEL:
e) DRIVER'S NAME:
f) NRIC/FIN/PASSPORT: CONTACT:

Assessment Done
by Simon
Vehicle Drive
away by Driver
at 1625 / 2/11/2018

EMAIL = Wesley Lim property@gmail.com

VIDEO =

Ask Driver ?
Do not no. which workshop?

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SFH1899D
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Chassis No.:	WBAXG12040DX48267
Propellant:	Petrol
Engine No.:	A0490144N20B20B
Engine Capacity:	1997 cc
Maximum Power Output:	135.0 kW (181 bhp)
Maximum Laden Weight:	2220 kg
Unladen Weight:	1610 kg
Year Of Manufacture:	2012
Original Registration Date:	30 Aug 2012
Lifespan Expiry Date:	-
COE Category:	E - Open Category
Quota Premium:	\$92,700.00
COE Expiry Date:	29 Aug 2022
Road Tax Expiry Date:	27 Aug 2019
PARF Eligibility Expiry Date:	29 Aug 2022
Inspection Due Date:	27 Aug 2019
Intended Transfer Date:	02 Nov 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8110930C



Name
**HENG KAI TING
(WANG KAITING)**

Race
CHINESE

Date of birth
20-03-1981

Sex
F

Country of birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8110930C**

Name
**HENG KAI TING
(WANG KAITING)**

Birth Date **20 Mar 1981**

Issue Date **01 Apr 2008**




001587335F

4839858



NRIC No. **S8110930C**



Date of issue
16-03-2012

APT BLK 331A ANCHORVALE STREET #12-545
SINGAPORE 541331

NRIC No: **S8110930C** Date: **24/10/2014**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS DATE
01 Apr 2008

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg
with =< 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals =< 2500kg



Licence No: **S8110930C**



NP 428A

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5100979347 ✓

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SLW6506E** ✓
Chassis Number : WBAXG12040DX48267
2. Name of Policyholder : **HENG KAI TING** ✓
3. Effective Date of Insurance : **28 May 2018** ✓
4. Expiry Date of Insurance : **27 May 2019** ✓
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: HENG KAI TING
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TECK WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

德威信貸私人有限公司
TECK WEI CREDIT PTE LTD
Co. Reg. No. 200512300K
210 Turf Club Road, The Grandstand
Lot A8 Singapore 287995
Tel: 6465 0020 Fax: 6465 0017
Email: info@teckwei.com.sg

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TECK WEI CREDIT PTE. LTD. (00000572499)
Date of Issue : 25 May 2018 12:57 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

Hello, NAC_PAYA_UBI_800601

• Change Language

• Change Password

• Log Out

[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5100979347		HENG KAI TING	S8110930C	GPC	drive CLASSIC	SLW6506E	SLW6506E	28/05/2018	27/05/2019

Policy Information

Policy No.	5100979347	Policyholder Name	HENG KAI TING	Policyholder NRIC	S8110930C
Certificate No.					
Address	BLK 331A #12-545 ANCHORVALE STREET ANCHORVALE HARVEST SINGAPORE 541331				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	25/05/2018	Effective Date	28/05/2018 00:00	Expiry Date	27/05/2019 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0		
Agent	TECK WEI CREDIT PTE, LTD.	Agent Tel.	64650020 null	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	BLK 331A #12-545	Address 2	ANCHORVALE STREET	Address 3	ANCHORVALE HARVEST
Address 4	SINGAPORE 541331	Address Type	Singapore address	Post Code	541331
Unit No.	12-545	Related Policy Number	5100979347		

Insured Object: SLW6506E

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

Accident MT/1018231

Policy No.	5100979347	Vehicle No.	SLW6506E	GST Registration No.
Certificate No.				
Policyholder Name	HENG KAI TING			Policyholder NRIC
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Contact No.(Home)
Email Address		Special Remark		eCode
KFK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason
NCD Protection	No	NCD Entitlement(%)	30	Private Hire
Accident Details				
Report Date	02/11/2018 16:28	Accident Report Within 24 hrs	Yes	Accident Type
Date of Accident	02/11/2018	Time of Accident hh:mm	10:00	Country of Accident
Reporting Centre		Orange Force		ICM No.
Accident Location	CTE TWDS CITY			
Excess				
Own damage Excess	600.00	Additional Excess	0	Windscreen Excess
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00	
Third Party Excess	0.00	Outside Singapore TP Excess	0.00	
Benefits				
GST Registered Information				
GST Registered	No	GST Registration Date		
GST Registration No.		GST Status Verified		Yes
Modification History				
Policyholder Mailing Address				
Address 1	BLK 331A #12-545	Address 2	ANCHORVALE STREET	Address 3
Address 4	SINGAPORE 541331	Address Type	Singapore address	Post Code
Unit No.	12-545	Related Policy Number	5100979347	
OI Driver Info				
Driver Name	HENG KAI TING	Driver Type	Main Driver	Driver DOB
Unnamed driver Name		Driver NRIC	S8110930C	Driving Experience
Register Date of Driver License	01/04/2008	Driver Age	37	Contact No.(Home)
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Address 3
Address 1	BLK 331A	Address 2	ANCHORVALE STREET	Post Code
Address 4		Address Type	Singapore address	
Unit No.	#12-545			
Does he own a Singapore Registered car?	☐ Yes ☐ No	Driver Vehicle No.		Driver Insurer Com
Declaration				
Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☐ No	
Modification History				

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	HENG K
Contact No.(Mobile)	NIL	Contact No. (Home)	NIL
Email Address		OI Vehicle Number	SLW6506E
Claim Description	SLW6506E/ SGH713B ON 2 Nov 2018		
Preferred Workshop		Insured Liability	Partially at Fault
Report No.	Yes	Preferred Repair Option	Please Select
Date Registered		GIA report	Received
Report Taken By		Claim Close Date	02/11/2018 16:37
☐ Print AK letter		Workshop Repairer	

Save

Submit

Attachment



Accident No.	MT/1018231	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	02/11/2018 16:35

Path *		Category *		Confidential
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO

Message Read

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Des
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:37	NRIC/ Driving License	Normal	NRIC/ Driving 1
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:36	SAS	Normal	SAS 2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:35	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:35	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:34	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:33	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:33	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:33	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:33	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:33	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:32	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 16:32	Photos	Normal	Photos

ASSIGNMENT (10/01)

By: C.A.D. / Nature of Accident:

- 1) Vehicle hit Vehicle: ()
 - a) Motorcycle ()
 - b) Bicycle ()
 - c) Pedestrian ()
 - d) Animal ()
- 2) Vehicle hit Road Side Object:
 - a) Govt Property ()
 - b) Road Work Object ()
 - c) Private Property ()
- 3) Vehicle drop into drain: ()
- 4) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other: ()
- 5) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 6) Theft Case:
 - a) Stolen ()
 - b) Damage found when recovered ()
- 7) Fire:
 - a) Whilst driving ()
 - b) Parked ()
- 8) Accident date more than 24hrs: ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss: ()
- 2) SRS Light on: ()
- 3) ABS Light on: ()

By: Assessor - 1) Vehicle Information

Vehicle: **SFH1899D** Date: **30 Aug 2012**
 Type: ☒ Motorcycle / ☐ Bus / ☐ Van / ☐ Car / ☐ Prime Mover / ☐ Truck / ☐ Trailer
 Make & Model: **BMW 520i** Year: **1997**
 Colour: **Black** Front end / Rear / Side / Modified
 Engine: **WBA XG12040 DX 48267**
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Brakes: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Mech: ☒ Nil / ☐ Rins / ☐ STD A/Rins
 Type/Size: **F: 225/55 R17**
 R: **225/55 R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal	5 mm	R/Bal	6 mm
L/Bal	5 mm	L/Bal	6 mm

Parallel Import: Yes / ☒ No
 Towed-In: Yes / ☒ No
 Repair Type: ☒ LS / ☐ LB
 Towing Required: ☒ Yes / ☐ No
 No of Repair Days: **5**
 Vehicle in Elec: Yes / ☒ No
 D.O.L: **2/11/2018**
 Time: **4 pm**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a) Vehicle ()
 - b) Motorcycle ()
 - c) Bicycle ()
 - d) Pedestrian ()
 - e) Animal ()
 - f) Govt Object ()
 - g) Road Work Object ()
 - h) Private Property ()
 - i) Drain ()
 - j) Road Edge/Grass/Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Vandalism ()
 - d) Fire ()
 - e) Moving Object ()
 - f) Stolen ()
 - g) Stolen & Recovered ()

Time Started

Time Completed

By: C.A.D.

By: C.A.D.

By: C.A.D. / Potential Loss / Impact of Theft

MOTOR CAR (Fr)

Front Portion

Vehicle No: SFH 1899D

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRA	✓	✓
1002	991887	Frt Number Plate Base	CRA	✓	✓
1003	991889	Frt Number Plate Garnish			✓
1004	991300	Frt Bumper	DD	✓	✓
1005	992341	Frt Bumper Clips	NCC	✓	✓
1006	991325	Frt Bumper Bracket			✓
1007	991462	Frt Bumper Side Retainer			✓
1008	991433	Frt Bumper Reinforcement	DIS	✓	✓
1009	991318	Frt Bumper Base Emblem	DD	✓	✓
1010	991468	Frt Bumper Sponge	CUT	✓	✓
1011	991427	Frt Bumper Protector	CRA	✓	✓
1012	991420	Frt Bumper Pad			✓
1013	991363	Frt Bumper Grille	?	✓	✓
1014	991301	Frt Bumper Moulding			✓
1015	991407	Frt Bumper Lower Spoiler			✓
1016	991438	Frt Bumper Sensor	?	✓	✓
1017	995100	Frt LH Bumper Fog Lamp Cover	?	✓	✓
1018	991355	Frt RH Bumper Fog Lamp Cover	?	✓	✓
1019	995079	Frt LH Bumper Fog Lamp			✓
1020	995080	Frt RH Bumper Fog Lamp			✓
1021	991793	Frt Grille	DD	✓	✓
1022	991328	Frt Grille Emblem			✓
1023	991799	Frt Grille Chrome Moulding			✓
1024	991222	Frt Apron Panel			✓
1025	992013	Frt Support Panel			✓
1026	992025	Frt Support Panel Top Garnish Cover	CRA	✓	✓
1027	992416	Hom			✓
1028	991277	Frt Brace Panel			✓
1029	995153	Frt LH Headlamp Assy			✓
1030	991821	Frt RH Headlamp Assy	CRA	✓	✓
1031	995088	Frt LH Side Lamp			✓
1032	995089	Frt RH Side Lamp			✓
1033	990248	Bonnet			✓
1034	991328	Bonnet Emblem			✓
1035	990287	Bonnet Lock			✓
1036	990285	Bonnet Insulator			✓
1037	990273	Bonnet Flange			✓
1038	990261	Bonnet Damper			✓
1039	990305	Bonnet Rubber			✓
1040	990252	Bonnet Cable			✓
1041	990311	Bonnet Stand			✓
1042	990119	Air Con Condenser	?	✓	✓
1043	990122	Air Con Fan Assy			✓
1044	990134	Air Con Suction Pipe (Low Pressure)			✓
1045	990118	Air Con Suction Hose			✓
1046	990133	Air Con Discharge Pipe (High Pressure)			✓
1047	990114	Air Con Discharge Hose			✓
1048	990149	Air Con Liquid Pipe			✓
1049	995066	Air Con Receiver Drier			✓
1050	990111	Air Con Compressor Assy			✓
1051	995294	Air Con Belt			✓
1052	995074	Radiator	?	✓	✓
1053	992738	Radiator Cowling			✓
1054	992742	Radiator Fan Assy			✓
1055	992745	Radiator Fan Clutch			✓
1056	992758	Radiator Hose Top			✓
1057	992757	Radiator Hose Bottom			✓
1058	992741	Radiator Expansion Tank			✓
1059	990151	Air Duct	CRA	✓	✓
1060	990070	Air Cleaner Assy			✓
1061	990056	Air Cleaner Hose			✓
1062	990089	Air Cleaner Resonator			✓
1063	991712	Frt Exhaust Manifold			✓
1064	991713	Frt Exhaust Manifold Cover			✓
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			✓
1066	991714	Front Exhaust Pipe			✓
1067	990219	Battery			✓
1068	990224	Battery Cover			✓
1069	990223	Battery Bracket			✓
1070	990229	Battery Tray			✓

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			✓
1072	994011	Relay Box			✓
1073	995053	Wiper Washer Tank			✓
1074	995052	Wiper Washer Tank Motor			✓
1075	990159	Alternator Assy			✓
1076	990160	Alternator Belt			✓
1077	992688	Power Steering Pump			✓
1078	992669	Power Steering Belt			✓
1079	994431	Power Steering Cooler Pipe			✓
1080	992692	Power Steering Hose			✓
1081	990010	ABS Pump Control Unit			✓
1082	990427	Brake Master Pump Assy			✓
1083	990403	Brake Booster Pump Assy			✓
1084	991005	Engine Top Cover			✓
1085	991011	Engine Under Cover			✓
1086	990946	Engine Mounting			✓
1087	990949	Engine Mounting Frt			✓
1088	990950	Engine Mounting LH			✓
1089	990952	Engine Mounting RH			✓
1090	990951	Engine Mounting Rear			✓
1091	992234	Gear Box Mounting			✓
1092	991520	Frt LH Chassis Member			✓
1093	991520	Frt RH Chassis Member			✓
1094	990728	Frt Vertical Cross Member			✓
1095	991863	Frt Lower Cross Member			✓
1096	995070	Frt LH Fender			✓
1097	995072	Frt LH Fender Inner Panel			✓
1098	995147	Frt LH Fender Lamp			✓
1099	995148	Frt LH Fender Protector			✓
1100	991740	Frt LH Fender Inner Shield			✓
1101	995179	Frt LH Mudflap			✓
1102	995170	Frt LH Wheel Rim			✓
1103	994025	Frt LH Rim Cover			✓
1104	995065	Frt LH Tyre			✓
1105	995071	Frt RH Fender			✓
1106	991739	Frt RH Fender Inner Panel			✓
1107	991744	Frt RH Fender Lamp			✓
1108	991752	Frt RH Fender Protector			✓
1109	991740	Frt RH Fender Inner Shield			✓
1110	991884	Frt RH Mudflap			✓
1111	992087	Frt RH Wheel Rim			✓
1112	994025	Frt RH Rim Cover			✓
1113	995065	Frt RH Tyre			✓
1114	992093	Frt Windscreen Glass			✓
1115	992117	Frt Windscreen Rubber			✓
1116	992108	Frt Windscreen Moulding			✓
1117	992098	Frt Windscreen Sealant			✓
1118	991019	ERP Bracket			✓
1119	991020	ERP Unit			✓
1120	992140	Frt Wiper Arm			✓
1121	992142	Frt Wiper Blade			✓
1122	995045	Wiper Panel Garnish			✓
1123	991126	Firewall Panel			✓
1124	990753	Dashboard Assy			✓
1125	992282	Glove Box Cover			✓
1126	992281	Glove Box Compartment			✓
1127	994483	Steering Wheel Airbag			✓
1128	994485	Steering Wheel Airbag Sensor			✓
1129	990749	Dashboard Airbag			✓
1130	990750	Dashboard Airbag Sensor			✓
1131	990029	Airbag Control Unit			✓
1132	990864	Frt Driver Seat			✓
1133	991922	Frt RH Seat Belt Assy			✓
1134	991899	Frt Passenger Seat			✓
1135	995182	Frt LH Seat Belt Assy			✓
1136	990247	Sticker			✓
		Headlamp Washer Jet			✓

No of Items:

As per report:

Claim Handling

Task Transfer Exit

LOS SAL SUB

Accident MT/1018231

Policy No.	5100979347	Vehicle No.	SLW6506E	GST Registration No.	
Certificate No.					
Policyholder Name	HENG KAI TING			Policyholder NRIC	S8110930C
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	No Yes	TCA	No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	30	Private Hire	No

Accident Details

Report Date	02/11/2018 16:28	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	02/11/2018	Time of Accident hh:mm	10:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	CTE TWDS CITY				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 331A #12-545	Address 2	ANCHORVALE STREET	Address 3	ANCHORVALE HARVEST
Address 4	SINGAPORE 541331	Address Type	Singapore address	Post Code	541331
Unit No.	12-545	Related Policy Number	5100979347		

OI Driver Info

Driver Name	HENG KAI TING	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S8110930C	Driver DOB	20/03/1981
Register Date of Driver License	01/04/2008	Driver Age	37	Driving Experience	10
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 331A	Address 2	ANCHORVALE STREET	Address 3	
Address 4		Address Type	Singapore address	Post Code	541331
Unit No.	#12-545				
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes No
-------------------------------------	------	-------------	--------

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimee Bin Mantau

Claim Type	OD-MD	Insured Name	HENG KAI TING	Insured NRIC	S8110930C
Contact No.(Mobile)	NIL	Contact No. (Home)	NIL	Contact No. (Office)	
Email Address		OI Vehicle Number	SLW6506E	TP Vehicle Number	SGH713B
Claim Description	SLW6506E / SGH713B ON 2 Nov 2018			Name of Preferred Workshop	
Preferred Workshop	Yes	Preferred Repair Option		Insured Liability report	Partially at Fault
Date Registered	02/11/2018 16:38	Claim Close Date		Date Received	02/11/2018 16:38
Report Taken By		Workshop Repairer		Total Loss but Repaired	
Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment

Attachment

Vehicle Info

Vehicle Make	BMW	Vehicle Model	520i	Engine Capacity	
Date of Registration	30/08/2012	Classis No.	WBAXG12040DX48267		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

NO OF REPAIR DAYS : 5 /1X FRT BUMPER SIDE RETAINER REPLACE/1X FRT SUPPORT PANEL TOP GARNISH COVER REPLACE/1X AIR DUCT REPLACE/1X HEADLAMPWASHER JET UP

Remark

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root					
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
ABSORBER	3	16002601	BUMPER EMBLEM (FRONT)	1	Replace
ACCELERATOR	4	16005901	BUMPER SPONGE (FRONT)	1	Replace
ACTUATOR	5	16003201	BUMPER GRILLE (FRONT)	1	Unconfirm
ADVERTISEMENT STICKER	6	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm
AIR BAG	7	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm
AIR BLOWER	8	41300101	SUPPORT PANEL (FRONT)	1	Unconfirm
AIR BOX	9	15600101	BRACE PANEL (FRONT)	1	Unconfirm
AIR CHAMBER BOX	10	27700101	HEAD LAMP (LEFT)	1	Unconfirm
AIR CLEANER	11	16000101	BUMPER (FRONT)	1	Replace
AIR COMPRESSOR	12	16002401	BUMPER CLIPS (FRONT)	1	Replace
AIR CON	13	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
AIR CON (VAN)	14	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm
AIR COOLER	15	27100801	GRILLE EMBLEM (FRONT)	2	Replace
AIR DISTRIBUTOR	16	344001	RADIATOR	1	Unconfirm
AIR FILTER	17	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Unconfirm
AIR FLOW	18	27700102	HEAD LAMP (RIGHT)	1	Replace
AIR GRILLE	19	112023	AIR CON CONDENSER	1	Unconfirm
AIR HORN	20	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm
AIR INTAKE					
AIR RESONATOR BOX					
AIR THROTTLE BODY AND SENSOR					
ALARM					
ALTERNATOR					
ALUMINIUM PANEL - SIDE					
AMPLIFIER					
ANTENNA					

Save Submit

Claim Handling

Task Transfer Exit

Accident MT/1018231

LOS SAL SUB

Policy No.	5100979347	Vehicle No.	SLW6506E	GST Registration No.	
Certificate No.					
Policyholder Name	HENG KAI TING			Policyholder NRIC	S8110930C
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	No Yes	TCA	No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	30	Private Hire	No

Accident Details

Report Date	02/11/2018 16:38	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	02/11/2018	Time of Accident hh:mm	10:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	CTE TWDS CITY				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 331A #12-545	Address 2	ANCHORVALE STREET	Address 3	ANCHORVALE HARVEST
Address 4	SINGAPORE 541331	Address Type	Singapore address	Post Code	541331
Unit No.	12-545	Related Policy Number	5100979347		

OI Driver Info

Driver Name	HENG KAI TING	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S8110930C	Driver DOB	20/03/1981
Register Date of Driver License	01/04/2008	Driver Age	37	Driving Experience	10
Contact No.(Mobile)	97697738	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 331A	Address 2	ANCHORVALE STREET	Address 3	
Address 4		Address Type	Singapore address	Post Code	541331
Unit No.	#12-545				
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes No
-------------------------------------	------	-------------	--------

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimee Bin Mantau

Claim Type	OD-MD	Insured Name	HENG KAI TING	Insured NRIC	S8110
Contact No.(Mobile)	NIL	Contact No.(Home)	NIL	Contact No.(Office)	
Email Address		OI Vehicle Number	SLW6506E	TP Vehicle Number	SGH7J
Claim Description	SLW6506E / SGH713B ON 2 Nov 2018			Name of Preferred Workshop	
Preferred Workshop Contact Application	Yes	Preferred Repair Option		Insured Liability report	Partially at Fault Received
Date Registered	02/11/2018 16:38	Claim Close Date		Date Received	02/11/
Report Taken By		Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment Attachment

Accident No. MT/1018231 / Claim No. 001 /
Last Doc. Received Yes No Upload Date 02/11/2018 18:32

Path *

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Message Read

Category *	Confidential	Urgency *
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:32	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 02 Nov 2018 18:31	Photos	Normal	Photos 2018-11-2

VICES) on 02 Nov 2018 18:30

	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:30	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:29	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:29	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:29	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:29	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:29	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:28	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 18:27	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:37	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:36	SAS	Normal	SAS 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:35	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:35	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:34	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:33	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:33	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:33	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:33	Photos	Normal	Photos 2018-11-2
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 02 Nov 2018 16:32	Photos	Normal	Photos 2018-11-2

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 02 Nov 2018 16:32

Photos

Normal

Photos 2018-11-2

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 02 Nov 2018 16:32

Photos

Normal

Photos 2018-11-2

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 02 Nov 2018 16:32

Photos

Normal

Photos 2018-11-2

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 02 Nov 2018 16:32

Photos

Normal

Photos 2018-11-2

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 02 Nov 2018 16:32

Photos

Normal

Photos 2018-11-2

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading

LKK Paya Ubi

From: Zuraimee Bin Mantau <zuraimee.mantau@income.com.sg>
Sent: Monday, 5 November 2018 5:13 PM
To: Chew Goon Motor - Mrs Chew
Cc: LKK Paya Ubi
Subject: Vehicle SLW6506E (SFH1899D), OD Claim No: MT/1018231-001, DOA: 02/11/2018

Dear Chew Goon Motor

Excess \$600 applies.

Vehicle is currently with the owner. Please arrange with the owner Mr Lim at 91806198 for the repair.

NOTE: Vehicle registration number has been changed to SFH1899D.

Strictly no further supplementary is allowed.

**Please forward the invoice and DV within 7 working days to us once repairs has been done.
Update the 'Repair Status' when repairs are done.**

XX

Our Ref: MT/CA/OD/051/1018231-001/ZBM
05 Nov 2018
CHEW GOON MOTOR
BLK 10 AMK IND PARK 2A AVE 5
#01-15,16&17 AMK AUTOPOINT
SINGAPORE 568047

Dear Sir

CLAIM NUMBER: MT/1018231-001
REPAIR OF VEHICLE NUMBER: SLW6506E (SFH1899D)

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 05 Nov 2018

Make: BMW

Model: 520i

Estimated Repair Days: 5

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimee Bin Mantau at 64307891 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank you

Zuraimee Bin Mantau
Senior Executive
Motor Insurance
T +65 6430 7891
www.income.com.sg


made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with
you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : WNA118142285 Vehicle Registration No: SLW 6506E
Name (as shown in NRIC) : HENG KAI TING NRIC/FIN/Passport No : S8110930C
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : BLK 331A ANCHORVALE STREET #12-545 Singapore (541331)
Contact (Tel) : - Mobile No. : 91806198 / 97697738
Email Address : WESLEY LIM PROPERTY @ GMAIL.COM
Date of Accident : 02/11/2018 Time of Accident : 10:00
Place of Accident : CTE TWDS CITY
Insurance Company : NTUC Income Insurance Co-operative Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend the Owners New Vehicle number

Policyholder / Driver's Signature
Date:

 6/12/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: