

NATIONAL Assessment Centre Services. [wef 1 Jan'05]

Date In: 05/11/18	Job description	Date & Time Completed	Done by
Ref No: NA/INC18019997/13	SAS e-filing		
Veh No: SKN7222Z	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 28/10/18 1620	i-Motor Claim Form	07/10/18 360 -	COI
☒ TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: SK10550	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%. P: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

NA1807115	Invoice Preparation Checklist	Amf (\$)	Amf (\$)
Claimant's Particulars:	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	OD:		
	*N5: Courtesy Car / Tpl Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TE (N11): TP (Non INC) against INC \$20		
	9) N12: Idao Mobile 30		
	Invoice dated	Fax Charged	
	Invoice dated	Fax Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 09:26
Date Of Accident	28/10/2018 16:20
Exact Location Of Accident	ROCHOR EXIT BEND TWDS BUGIS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN7223Z
Insured/Policyholder	
Name Of Registered Owner	SUMASNI BINTE SUNAR
NRIC No	S1109699I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97457816
Alternative Phone No	OTHERS-97457816

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087337456-01
Cover Note Number	

Driver

Name of Driver	NAZARUDDIN BIN MASHRUDDIN
NRIC No	S8920248E
Date Of Birth	06/06/1989
Occupation	INDOOR
Date Of Driving Pass	12/12/2016
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92773549
Fax Number	
Contact Number	
Email Address	NAZTYKEYS@GMAIL.COM

Address	BLK 245 TAMPINES ST 21 #08-309
Postcode	521245
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : MASHRUDDIN BIN SAHARUDDIN GENDER: : MALE
Passenger 2	NAME: : SUMASNI BINTE SUNAR GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 2/11/2018



NAZARUDDIN MASTRUDIN

Driver's Signature

(If driver is not the policyholder)
Date & Time: 3 NOV 2018




05/11/18

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the long bend
- At the long bend, I slowed the vehicle down to 50km/h and braked further to about 40 km/h, while still maintaining a safe distance from the car in front. (about 2-3 vehicle distance)
- Just as the bend was about to end, still braking, my car skidded to the right. I jammed the brakes hard and counter-steered to the left. The car hit the right railing and "bounced off" towards the left. My steering wheel was locked and I couldn't control the direction of the car. It then hit the The car turned to face oncoming traffic by ^{skidding} swerving to the left and hit the left railing on the right side of the car.
- After the accident, I tried to move the car out of danger by doing a 3-point turn (with hazard lights on) and parked on the right-most lane. LTA and EMAS arrived within 3-5 minutes.
- The right front and rear tire tires are punctured, rims damaged. Front right bumper and rear right side bumper are damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 3/11/2018



NAZARUDDIN MASHRUDDIN

Driver's Signature

(If driver is not the policyholder)

Date & Time: 3 NOV 2018

 05/11/18

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

ACCIDENT STATEMENT

ACCIDENT DATE: (28 / 10 / 2018) (DD/MM/YYYY), TIME: (16 : 20) (HH:MM)

LOCATION: ROCHOR EXIT BEND (TOWARDS BUGIS)

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SKH 7223 Z
 b) INSURANCE COMPANY: NTUC INCOME
 c) POLICY NUMBER: 5087 3374 56
 d) POLICY TYPE: (COMPREHENSIVE) / THIRD PARTY / THIRD PARTY FIRE & THEFT
 e) MAKE & MODEL: TOYOTA ESTIMA
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE) / COMMERCIAL / MOTORCYCLE
 h) PURPOSE OF USING AT ACCIDENT TIME: PRIVATE
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: SUMASNI BTE SUNAR (MALE / FEMALE)
 B) NRIC/FIN/PASSPORT: S 110 9699 I CONTACT: 9745 7816
 C) ADDRESS: BLK 245 TAMPINES ST. 21 #08-309
 S 521245

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: NAZARUDDIN BIN MASHRUDDIN (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S 8920248 E CONTACT: 9277 3549
 c) ADDRESS: BLK 245 TAMPINES ST. 21 #08-309
 S 521245

* d) DATE OF BIRTH: (06 / 06 / 1989) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: 11 MONTHS

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: FAMILY (SON)

5. a) WEATHER CONDITION: (CLEAR / RAINING) / OTHERS
 b) ROAD SURFACE: (DRY / WET) / OTHERS
 6. WAS ANYBODY INJURED (YES / NO)
 7. a) REPORTED TO POLICE (YES / NO)
 IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: / MODEL: /
 b) DRIVER'S NAME: /
 c) NRIC/FIN/PASSPORT: / CONTACT: /

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: / MODEL: /
 e) DRIVER'S NAME: /
 f) NRIC/FIN/PASSPORT: / CONTACT: /

% No of passenger
 (including driver)
 (3)

PASSENGER: MASHRUDDIN
 BIN
 SAHARUDDIN
 (MALE)

- SUMASNI BTE
 SUNAR
 (FEMALE)

% No of passenger
 (including driver)
 ()

% No of passenger
 (including driver)
 ()

- ENTERPRISE ONE -
 "LIQUIMOLY" ENFINITIVE
 6747 6063

email = naztykeys@gmail.com

fax =

video =

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8920248E



Name
NAZARUDDIN BIN
MASHRUDDIN

Race
MALAY

Date of birth
05-06-1989

Sex
M

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Location Number S8920248E

Name
NAZARUDDIN BIN MASHRUDDIN

Birth Date: 05 Jun 1989

Issue Date: 12 May 2017



3866885



NRIC No. S8920248E



Date of issue
18-06-2004

Address
APT BLK 245 TAMPINES STREET 21
#08-309
SINGAPORE 521245

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg 12 Dec 2016

NP428A

Licence No: S8920248E



Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident

28/10/2018 16:20

Vehicle No. (For Motor)

SKN7223Z

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5087337456-01		SUMASNI BINTE SUNAR	S1109699I	GPC	drivo CLASSIC	SKN7223Z	SKN7223Z	11/01/2018	10/01/2019

Continue

Claim Handling

Accident MT/1018360

Policy No.	5087337456-01	Vehicle No.	SKN7223Z	GST Registration No.
Certificate No.				
Policyholder Name	SUMASNI BINTE SUNAR			Policyholder NRIC
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading
Contact No.(Mobile)	97457816	Contact No.(Office)	0	Contact No.(Home)
Email Address		Special Remark		eCode
KPK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason
NCD Protection	No	NCD Entitlement(%)	10	Private Hire

Accident Details

Report Date	05/11/2018 09:48	Accident Report Within 24 hrs	Yes	Accident Type
Date of Accident	28/10/2018	Time of Accident hh:mm	16:20	Country of Accident
Reporting Centre		Orange Force		ICM No.
Accident Location	ROCHOR EXIT BEND TWDS BUGIS			

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess
Unnamed Driver Excess	500.00	Outside Singapore OD Excess	600.00	
Third Party Excess	0.00	Outside Singapore TP Excess	0.00	

Benefits

Coverage	Sum Insured
Transport Allowance	99999999.99

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 245 #08-309	Address 2	TAMPINES STREET 21	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.	08-309	Related Policy Number	5087337456-01	

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB
Unnamed driver Name	NAZARUDDIN BIN MASHRUDDIN	Driver NRIC	S8920248E	Driver DOB
Register Date of Driver License	12/12/2016	Driver Age	29	Driving Experience
Contact No.(Mobile)	92773549	Contact No.(Office)	0	Contact No.(Home)
Address 1	BLK 245	Address 2	TAMPINES STREET 21	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.	#08-309			
Does he own a Singapore Registered car?	☐ Yes ☐ No	Driver Vehicle No.		Driver Insurer Com

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☐ No
-------------------------------------	------	-------------	--

Modification History

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	SUMAS
Contact No.(Mobile)	97477816	Contact No. (Home)	
Email Address	SUMASNI@ME.COM	Vehicle Number	SKN7223Z
Claim Description	SKN7223Z ON 28 Oct 2018		
Preferred Workshop	Preferred	Insured Liability	Fully at Fault
CONTRACT No. Finalisation	Yes	Repair Option	income to assign workshop
Date Registered	05/11/2018 09:56	GIA report	Received
Report Taken By	ROSLINDA	Claim Close Date	
		Workshop Repairer	

Print AK letter

Save

Submit

Attachment

Accident No.	MT/1018360	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	05/11/2018 00:00
Path *		Category *	Confidential
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read			

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	NRIC/ Driving License	Normal	NRIC/ Driving License
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	SAS	Normal	SAS 2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:56	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Nov 2018 09:54	Photos	Normal	Photos



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on
05 Nov 2018 09:54

Photos

Normal

Photos

Video List

Uploaded By/Date

Folder Date

File Name



Display in New Window

Scan and uploading

ASSESSMENT (IDAC)

By: CNOF Partner of Accident:

- | | |
|-----------------------------------|------------------------------------|
| 1) Vehicle hit Vehicle: | 2) Vehicle hit: |
| a) Motorcycle () | a) Pedestrian () |
| b) Motorcycle () | b) Animal () |
| c) Bicycle () | |
| 3) Vehicle hit Road Side Objects: | |
| a) Govt Property () | b) Road Work Object () |
| c) Private Property () | |
| 4) Vehicle drop into drain () | |
| 5) Damage due to Act of God: | |
| a) Fallen Object () | b) Flood () |
| c) Other: | |
| 6) Parked & Found Damaged: | |
| a) Vandalism () | b) Hit by Moving Object () |
| 7) Theft Case: | |
| a) Stolen () | b) Damage found when recovered () |
| 8) Fire: | |
| a) Whilst driving () | b) Parked () |
| 9) Accident date more than 24hrs: | () |

Remarks for internal information:

Remarks to appear in Works Order & Assessment report:

- | | |
|--------------------------|-----|
| 1) Potential Total Loss: | () |
| 2) SRS Light on: | () |
| 3) ABS Light on: | () |

By Assessor: 1) Vehicle Information:

Vehicle: **SKN 7223 Z** Date: **11 Jun 2014**
 Type: **MCar / Motorcycle / Bus / Van / Carry / Load / Prime Mover**
 Make & Model: **Toyota Estima Aeras 2.4** 2362
 Color: **White** Transmission Type: **Manual**
 Engine: **94606**
 C/A No: **ACR 50 0166571**
 Equip. Control: **3** / Fair / Poor / Burnt / or
 Steering: **3** / Jammed / Leaked / Burnt / or
 Brake: **3** / Jammed / Leaked / Burnt / or
 Model: **NR** / STD A/Rim / or
 Type Size: **F: 225/55 R17 - KUMHO**
 R: **- Michelin**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO / or

Front		Rear	
R/Bal:	6 mm	R/Bal:	6 mm
L/Bal:	6 mm	L/Bal:	6 mm

Parallel Import: Yes / No	Towed-In: Yes / No
Repair Type: LS / LB.I	Towing Required: Yes / No
No of Repair Days: 10	Vehicle in Blk: Yes / No
D.O.I: 5/11/2018	Time: 10.50 am

By Assessor- 2) Comments:

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- | | | | |
|-------------------------|--------------------|------------------------------|-------------------|
| a) Vehicle () | b) Motorcycle () | c) Bicycle () | d) Pedestrian () |
| e) Animal () | f) Govt Object () | g) Road Work Object () | |
| h) Private Property () | i) Drain () | j) Road Kerb/Glass Venge () | |

3) Vehicle does not seem damaged as a result of:

- | | | | |
|----------------------|---------------|---------------------------|-------------|
| a) Fallen Object () | b) Flood () | c) Vandalism () | d) Fire () |
| e) Moving Object () | f) Stolen () | g) Stolen & Recovered () | |

Time Started:

Time Completed:

1/2/20

1/2/20

4) Enter type of loss or repair of item.

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Tors (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

284

(1) Replace (✓) (2) Repair (R) (3) Check (C)
(4) Not Consistent (N)

Rear Portion

Vehicle No: SKN 7223 Z

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RA DIS	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RA	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	BUC	✓	
1229	993450	Rear RH Fender Protector	Lower CUT	✓	
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	RA	✓	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	BR	✓	
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre	CUT	✓	
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender RA Glass	RA	✓	
1242	993452	Rear Fender RA Glass Rubber	RA	✓	
1243	993453	Rear Fender RA Glass Sealant	RA	✓	
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Turn (14) Unconfirmed (15) Not Working.

MOTOR CAR (UC)

ACTION (ACT)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Vehicle No: SKN 7223 Z

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

No of Items: _____ Assessor: _____

Original copy

424

Condition (CON)

(01) Bent (02) Dented (03) Disparted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Tows (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

SC3302165

(1) Replace (✓) (2) Repair (X) (3) Check (I)
(4) Not Consistent (NC)

Aug 2015

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

Vehicle No: SKN 7223 Z

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector	SCR	R	
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

Claim Handling

[Task Transfer](#)
[Exit](#)
[Accident MT/1018360](#)
[LOS](#)
[SAL](#)
[SUB](#)

Policy No.	5087337456-01	Vehicle No.	SKN7223Z	GST Registration No.	
Certificate No.					
Policyholder Name	SUMASNI BINTE SUNAR			Policyholder NRIC	S1109699I
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97457816	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No ▾
KFK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

[Accident Details](#)

Report Date	05/11/2018 09:48	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	26/10/2018	Time of Accident hh:mm	16:20	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	ROCHOR EXIT BEND TWDS BUGIS				

[Excess](#)

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	500.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

[Benefits](#)

Coverage	Sum Insured
Transport Allowance	99999999.99

[GST Registered Information](#)

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

[Policyholder Mailing Address](#)

Address 1	BLK 245 #08-309	Address 2	TAMPINES STREET 21	Address 3	SINGAPORE 521245
Address 4		Address Type	Singapore address	Post Code	521245
Unit No.	08-309	Related Policy Number	5087337456-01		

[OI Driver Info](#)

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	NAZARUDDIN BIN MASHRUDDIN	Driver NRIC	S8920248E	Driver DOB	06/06/1989
Register Date of Driver License	12/12/2016	Driver Age	29	Driving Experience	1
Contact No.(Mobile)	92773549	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 245	Address 2	TAMPINES STREET 21	Address 3	SINGAPORE 521245
Address 4		Address Type	Singapore address	Post Code	521245
Unit No.	#08-309				
Does he own a Singapore Registered car?	☐ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

[Declaration](#)

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☐ No
-------------------------------------	------	-------------	--

Modification History

[Investigation](#)
[Claim 001 OD-MD](#)
[Claim Case Officer Yap Chee Ling](#)

Claim Type	OD-MD	Insured Name	SUMASNI BINTE SUNAR	Insured NRIC	S1109699I
Contact No.(Mobile)	97477816	Contact No. (Home)		Contact No. (Office)	
Email Address	SUMASNI@ME.COM	OI Vehicle Number	SKN7223Z	TP Vehicle Number	
Claim Description	SKN7223Z ON 28 Oct 2018			Name of Preferred Workshop	ENTERPRISE ON
Preferred Workshop Option	☐ Yes ☐ No				
Preferred Repair Option	☐ Yes ☐ No				
Income to assign workshop	☐ Yes ☐ No				
Insured Eligibility report	☐ Yes ☐ No				
Fully at Resolved	☐ Yes ☐ No				
Date Registered	05/11/2018 09:56	Claim Close Date		Date Received	07/11/2018 10:11
Report Taken By	ROSLINDA	Workshop Repairer		Total Loss but Repaired	
				OD Excess	

Print AK letter

Collected by
Workshop

Modification History

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment

Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	ESTIMA	Engine Capacity
Date of Registration	11/07/2014	Classis No.	ACR500166571	
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No	
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)

NO OF REPAIR:10 DAYS:FRT BUMPER TOW EYE COVER-REPLACE,FRT SUPPORT PANEL TOP GARNISH COVER-UNCONFIRM,AIRCON SUCTION PIPE(LOW PRESSURE)-UNCONFIRM,FRT REPLACE,REAR RH FENDER PROTECTOR LOWER_REPLACE,REAR RH WHEEL RIM-REPLACE,FRT RH TIE ROD-UNCONFIRM,

Remark

Remark for
Supplementary

Damage Listing

No.	Part No.	Description	Qty *	Repair Code *
1	32200101	NUMBER PLATE (FRONT)	1	Replace
2	32200201	NUMBER PLATE BASE (FRONT)	1	Unconfirm
3	16000101	BUMPER (FRONT)	1	Replace
4	16002401	BUMPER CLIPS (FRONT)	6	Replace
5	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
6	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
7	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm
8	16005901	BUMPER SPONGE (FRONT)	1	Replace
9	27700101	HEAD LAMP (LEFT)	1	Unconfirm
10	27700102	HEAD LAMP (RIGHT)	1	Replace
11	112023	AIR CON CONDENSER	1	Unconfirm
12	112044	AIR CON DISCHARGE PIPE	1	Unconfirm
13	344001	RADIATOR	1	Unconfirm
14	16003201	BUMPER GRILLE (FRONT)	1	Replace
15	16004201	BUMPER MOULDING (FRONT)	1	Unconfirm
16	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace
17	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm
18	41300101	SUPPORT PANEL (FRONT)	1	Unconfirm
19	43600102	TYRE (FRONT RIGHT)	1	Replace
20	16000102	BUMPER (REAR)	1	Replace
21	16002402	BUMPER CLIPS (REAR)	6	Replace
22	16005104	BUMPER RETAINER (REAR RIGHT)	1	Replace
23	16004904	BUMPER REFLECTOR (REAR RIGHT)	1	Unconfirm
24	35300101	REVERSE SENSOR (LEFT)	1	Unconfirm
25	35300102	REVERSE SENSOR (RIGHT)	1	Unconfirm
26	42000102	TAIL LAMP (RIGHT)	1	Unconfirm
27	25400904	FENDER INNER SHIELD (REAR RIGHT)	1	Replace
28	43600104	TYRE (REAR RIGHT)	1	Replace
29	401028	STEERING RACK & PINION	1	Unconfirm

Find a Part					
root	30	401021	STEERING CROSS MEMBER	1	Replace
Not Applicable	31	344005	RADIATOR COWLING	1	Unconfirm
ABS	32	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Unconfirm
ABSORBER	33	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Unconfirm
ACCELERATOR	34	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace
ACTUATOR	35	247017	EXHAUST PIPE	1	Unconfirm
ADVERTISEMENT STICKER	36	247021	EXHAUST PIPE MOUNTING	1	Unconfirm
AIR BAG	37	25400106	FENDER (REAR RIGHT)	1	Replace
AIR BLOWER	38	13700102	AXLE BEAM (REAR)	1	Unconfirm
AIR BOX	39	36600102	SHOCK ABSORBER (FRONT RIGHT)	1	Unconfirm
AIR CHAMBER BOX	40	36600602	SHOCK ABSORBER MOUNTING (FRONT RIGHT)	1	Unconfirm
AIR CLEANER	41	30000102	KNUCKLE ARM (FRONT RIGHT)	1	Unconfirm
AIR COMPRESSOR	42	30000202	KNUCKLE ARM BEARING (FRONT RIGHT)	1	Unconfirm
AIR CON	43	30500102	LOWER ARM (FRONT RIGHT)	1	Replace
AIR CON (VAN)	44	23600102	DRIVE SHAFT (FRONT RIGHT)	1	Unconfirm
AIR COOLER	45	36600104	SHOCK ABSORBER (REAR RIGHT)	1	Unconfirm
AIR DISTRIBUTOR	46	36600604	SHOCK ABSORBER MOUNTING (REAR RIGHT)	1	Unconfirm
AIR FILTER	47	30000104	KNUCKLE ARM (REAR RIGHT)	1	Unconfirm
AIR FLOW	48	30000204	KNUCKLE ARM BEARING (REAR RIGHT)	1	Unconfirm
AIR GRILLE	49	35500702	ROCKER PANEL (RIGHT)	1	Repair
AIR HORN	50	23305304	DOOR PROTECTOR (REAR RIGHT)	1	Repair
AIR INTAKE	51	30500104	LOWER ARM (REAR RIGHT)	1	Unconfirm
AIR RESONATOR BOX					
AIR THROTTLE BODY AND SENSOR					
ALARM					
ALTERNATOR					
ALUMINIUM PANEL - SIDE					
AMPLIFIER					
ANTENNA					
ANTI ROLL					
APRON					
ARCH					
ARM REST					
ASH TRAY					
AUTO CLUTCH					
AUTO COOLER PIPE					
AUTO CRUISE MOTOR					
AUTO TRANSMISSION					
AXLE					
BACK REST (M/C)					
BACK SEAT					
BALANCER					
BATTERY					
BEADING (M/C)					
BELT COVER (M/C)					
BELT TENSIONER					
BODY					
BODY (M/C)					
BOLT CAP (M/C)					
BOLT HEAD COVER (M/C)					
BONNET					
BOOT					
BOX (M/C)					
BOX BRACKET (M/C)					
BOX CARRIER (M/C)					
BOX DOOR					
BOX STICKER (M/C)					
BRACE PANEL					
BRAKE					
BRAKE - ABS					
BRAKE (M/C)					
BUMPER					
CABIN					
CAMBER					
CAMSHAFT					



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SG1N72232 Date In: _____ Time In: _____ with Keys: Yes / No _____

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Auto paint

Collection Date: 8/11/18 Time: 9:30 with Keys: Yes / No _____

Tow Truck No: W1866727 Tow Man: Tan Ching NRIC: S1684944

Signature: [Signature]

83097223

For office use

Attended by: JACKSON

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No _____

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No _____

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

Model: ESTIMA

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: Transport Allowance

Excess Applicable: 600 + 500

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.