

ASS. REC. BY:

REF:

(S3/ECTL18020006/Gcbez

Special Instruction:

Surveyor:

60

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

ECL

Date/Time:

05-11-2018 11:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

96TF 9653S

Insured:

XD 1745Y

at Workshop m/s

TK Car Repairs

Tel:

9746 3035

of

176 Sin Ming Drive #01-12

Policy No:

Claim No:

XD1745Y / SL/pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

05-11-2018 11:51am

Person Contacted:

Mr. Low

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	96TF 9653S - (S/ECTL17010276/Kgh3h2	DA: 010617
	XD 1745Y - NA/ENC13007379/TS.	DA: 22042013

Surveyor: PKS

REF:

3210F

ASSIGNMENT

(C-2021)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$13K

IDAC Accident Rpt.: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5479835Yr Regn: 27 Apr 2006

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan SunnyC.C. 1597Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 226801

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN/CAN/68 0100133

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 185/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 05-11-18Survey held at W/S3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 10

1)

☐

Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee: 50

Transportation:

S + RS, SI

Photos

Others

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

50

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 5 November, 2018 11:40 AM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : XD1745Y / TP : SGF9653S/LKK / DOA : 29/10/2018
Attachments: XD1745Y - SAS.pdf; SGF9653S - SAS.pdf; SGF9653S - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TK CAR REPAIRS PTE LTD**

ADDRESS : 176 SIN MING DRIVE
#01-12 SIN MING AUTOCARE
SINGAPORE 575721

PERSON TO CONTACT : MR LOW @ 9746 3035

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247



www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 05.11.2018
Our Reference: XD 1745Y/SL/pl
Your Reference: SGF 9653S

To: TK CAR REPAIRS PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SGF 9653S
Insured's Vehicle: XD 1745Y
Date Of Accident: 29.10.2018


We acknowledge receipt of your request for PRS on: 02.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



TK CAR REPAIRS PTE LTD

Business Reg. No. 201202611N

176, SIN MING DRIVE, #01-12 SIN MING AUTOCARE, SINGAPORE 575721 TEL: 6453 2598, 6453 9730
FAX: 6552 0866 Email: tklow50@hotmail.com

02.11.2018

ERGO INSURANCE PTE LTD
5, Temasek Boulevard, #04-01
Suntec Tower Five
SINGAPORE 038985

ATTN: MOTOR CLAIM DEPARTMENT (TP)

Dear Sir/Mdm

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION FOR
CLAIMANT: TAN YIE HERNG
ACCIDENT INVOLVING : SGF 9653 S & XD 1745 Y ON 29.10.2018 ALONG
PIONEER RD NORTH TWDS JLN AHMAD IBRAHIM R'ABOUT

Please be informed that the said vehicle can be inspected at:

176, Sin Ming Drive, #01-12,
Sin Ming Autocare
Singapore 575721
(Mr Low) HP: 97463035

Yours faithfully

FOR SURVEYOR

Please initial here after completion of
Pre-repair inspection. Thank You

Appointed Surveyor
(Name & Signature)
Date & Time
Of inspection

82880282
67418424
05/11/18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3210F

Vehicle Details

Vehicle No.:	SGF9653S
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	QG16408322
Chassis No.:	JN1CFAN16Z0100133
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,089.00
Original Registration Date:	27 Apr 2006
First Registration Date:	27 Apr 2006
Transfer Count:	2
Actual ARF Paid:	\$13,298.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	26 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$11,378.00
Total Rebate Amount:	\$11,378.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Nov 2018

OK

► Sunny Used Vehicle List (7 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Nissan Sunny 1.6A EX (COE till 03/2022)	\$18,800	\$5,670 /yr	02-Mar-2007	1,597 cc	130,000 km	Prem Roy Motoring	Availal
Very Well Taken Care Of By Owner, Accident Free! Serviced Regularly, Owner Just Changed Radiator, Wheel Bearing, Brake Pump And Gear 6 Owner Because There Was An Interchange Of Ownership Within C...							
Office No. - 66028046 Sandeep - 81132681 Kana - 96435365							
Nissan Sunny 1.6A EX (COE till 08/2021)	\$16,100	\$5,720 /yr	19-Sep-2006	1,597 cc	50,000 km	Drivetribes Pte Ltd	Availal
Cheapest And Lowest Mileage In The Market. \$1k Above Scrap. Price To Go. Under Used Ultra Low Mileage Sunny With Service Records. Tim Belt Set And Major Wear And Tear Done. All Oil And Fluids Repla...							
Office No. - 92722214 Nick - 91558832 Desmond Toh - 92722214							
Nissan Sunny 1.6M EX (COE till 05/2021)	\$13,800	\$5,380 /yr	08-Jun-2006	1,597 cc	125,000 km	StarBright Auto	Availal
3 Months Warranty From Our In-house Workshop.\$2800 Down Payment Only, Monthly \$430. Good Condition, No Repair Needed, Bank Loan house Loan Available, Trade In Welcome. Warranty From Our In-house Wo...							
Office No. - 67930080 Richard - 81667779 Jeff - 97955598							
Nissan Sunny 1.6A LE (COE till 12/2020)	\$16,000	\$7,520 /yr	24-Dec-2005	1,597 cc	280,000 km	SG Car Consign Pte Ltd	Availal
Beautiful Silver Unit Well Maintained By Owner. Selling Due To Upgrading. Highly Recommendable For Daily Usage, Family User, Uber/Grab Purposes. Trade In Welcome, Loan Available! Please Call To Arrang...							
Office No. - 61000200 Danny Loh - 97622873 Andy Tay - 94891030 Eric Lim - 94882822 Joey Kwan - 87158050							
Nissan Sunny 1.6A EX (OPC (COE till 04/2020)	\$15,900	\$10,970 /yr	20-Apr-2005	1,597 cc	85,000 km	SG Car Consign Pte Ltd	Availal
Extremely Low Mileage Car, Perfect Interior, Except That The Front Bumper Needs To Be Touched Up! Ideal For Short Term Usage! Engine I Well Maintained!							
Office No. - 61000200 Kelvin Liew - 91509055 Bryan Tan - 91795745							
Nissan Sunny 1.5M (COE till 10/2023)	\$16,800	\$3,400 /yr	17-Oct-1998	1,498 cc	-	Sincere Motoring Pte Ltd	Availal
(100% Quality Buy!) Well Maintained Unit Pre Owned From A Retiree Owner. Selling Due To Low Usage. Purchase Comes With 6 Months Eng And Gearbox Protection Plan With 24/7 Roadside Assistant And Repl...							
Office No. - 67476066 Hermann - 98595755 Edwin - 92331607 Sadiy - 85247485							
Nissan Sunny Coupe 1.6A (COE till 04/2019)	\$7,000	-	02-Oct-1991	1,597 cc	-	Monster Motors Pte Ltd	Availal
The Legendary NX 100. True Classic Beauty, 1 And Only In The Market. Left Around 4 Only In Singapore. A Guaranteed Head Turner. A Gre Project For Real Car Enthusiasts And Collectors. Still Eligible ...							
Office No. - 69090035 Rachel - 88082170 Ray - 90073753							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/11/2018 15:26
Date Of Accident	29/10/2018 14:40
Exact Location Of Accident	PIONEER RD NORTH TWDS JLN AHMAD IBRAHIM R'ABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGF9653S
Insured/Policyholder	
Name Of Registered Owner	TAN YIE HERNG
NRIC No	S8033210F
Email Address	CANDY.CLOE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81330003
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	NISSAN
Model	SUNNY-1.6 EX (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099868760
Cover Note Number	
Driver	
Name of Driver	TAN YIE HERNG
NRIC No	S8033210F
Date Of Birth	21/10/1980
Occupation	OUTDOOR
Date Of Driving Pass	13/02/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81330003
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	CANDY.CLOE@GMAIL.COM

Address	BLK 190 BOON LAY DRIVE #07-226
Postcode	640190
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1745Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN YIE HERNG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGF9653S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 2/11/18

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:




Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 29/10/2018 Time: 14:40 Location: Pioneer Road North
 Veh A: S6F9653 S Veh B: XD17454 No of pax: 1 Weather: Clear/dry Rain/Wet

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

☐ Claim OD/TP at Falcon-Air ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : The Car Repair
Email address : candy.chloe@gmail.com
& myself :
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

~~Policyholder's Signature~~

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20181101/2111

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181101/2111

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/11/2018 18:22		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN YIE HERNG			Address: APT BLK 190 BOON LAY DRIVE #07-226 SINGAPORE 640190		
ID Type / ID No.: NRIC NO / S8033210F			Contact No.: Home/Office: Mobile: 81330003		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 38	Date of Birth: 21/10/1980	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: INSURANCE AGENT / GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 29/10/2018 14:40	Type of Location: Roundabout
Location: Along Road 1 PIONEER ROAD NORTH TOWARDS JALAN AHMAD IBRAHIM ROUNDABOUT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGF9653S	Car	NISSAN	SUNNY 1.6EXA	Red	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGF9653S	NTUC Income Insurance Co-Operative Limited	5099868760	27/04/2018	26/04/2019



**SINGAPORE
POLICE FORCE**



T/20181101/2111

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181101/2111

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN YIE HERNG	ID No.	S8033210F
Related Vehicle	SGF9653S (Car)	Contact No.	81330003
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/10/2018	Date Discharge	01/11/2018
No. of Days granted Medical Leave	15	Degree of Injury	Serious

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION I WAS TRAVELLING ALONG THE SAID LOCATION. I WAS WAITING AT THE ROUNDABOUT LANE, WANTING TO WAIT FOR MY TURN TO MAKE THE EXIT. HOWEVER, WHILST WAITING, A HEAVY VEHICLE THEN COLLIDED ONTO THE REAR PORTION OF MY VEHICLE. I THEN BLACKED OUT FOR A MOMENT. I REGAIN CONSCIOUSNESS AFTER SOMETIME. I THEN HEARD PEOPLE KNOCKING ON THE DRIVER'S SIDE DOOR. I WIND DOWN AND ASKED THEM WHAT'S THE MATTER. AT THAT POINT OF TIME I WAS IN A STATE OF CONFUSION AS I WASN'T ABLE TO GRASP THE SITUATION AND THE FACT THAT I WAS ALREADY INVOLVED IN THE ACCIDENT. THEY INFORMED ME THAT AMBULANCE WILL BE ARRIVING SOON.

THE PARTICULARS OF THE HEAVY VEHICLE OWNER WHOM I HAVE RECEIVED IT FROM ONE OF THE PARAMEDICS PRESENT AT THE SCENE IS ONE 'CHAN YONG HOI, S7825059C'.



**SINGAPORE
POLICE FORCE**



T/20181101/2111

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20181101/2111

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
NG JIN SHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
01/11/2018 18:22

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SUFIYAN BIN KHAIRI
Contact No.: 65476390

Classification Of Case:

Authentication Stamp
NP168



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18020006/Gcbe2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 09-11-2018		
FIVE SINGAPORE 038985		Code: EGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 1745Y	Veh. Inspected	SGF 9653S	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD1745Y/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	05/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SUNNY	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JN1CFAN16Z0100133	Colour	MAROON	
Odometer	226801 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/65 R15	SONAR	6 mm	
L/H Rear Tyre	185/65 R15	SONAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2018	Inspect Date / Time	05/11/2018 (03:30 PM)	
Survey held at	TK CAR REPAIRS 176 SIN MING DRIVE #01-12 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	

Report Ref No. CS3/EGI18020006/Gcbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.