

ASS. REC. BY:

REF:

CS3/CT118020013 / Kcb

Special Instruction:

range & days

Surveyor

Mormen

Kenneth

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CT1

Date/Time:

02.11.2018 505pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 5202U

Insured:

GBD 6292P

at Workshop m/s

Lian Fah Spray Painting

Tel:

9481 7286

of

160 Sin Ming Drive #07-10

Policy No:

DMPCSN1709861801

Claim No:

SNM1800491400

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/02/2018

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

05-11-2018 11-01am

Person Contacted:

Mr. Chia

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLQ 5202U - X

GBD 6292P - X

07-11-2018

Confirmed with Mr. Chia, he got independent surveyor

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: ~~5~~ 5 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Yr Regn: 04 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/11 File pass to Catherine, no estimate

Range 5,000/2 - 6,000/2 -

Repair days ~~5~~

RECEIVED 13 NOV 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: PRS

Lump Sum / I.B.I: (\$)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S - RS \$

: Photos

: Others

TOTAL

9/11/18

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 17:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	L H Y DESIGN&BUILD, Co. Reg. No.: 53040783C		
Main Claimant:	SAN'S TOURS & CAR RENTALS, Co. Reg. No.: 08516300K		
Vehicle Reg. No.:	SLQ5202U	Date of Loss:	12/10/2018 10:00 - :59
Claim Type:	TP / SNM18D04914C02	Policy/Cover Note No.:	DMCVSN1709861801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD6292P	Policy No. (Claimant):	D18MTRENT000332
		Excess:	S\$0.00
Repairer:	Lian Fah Spray Painting (HQ) Block 160 Sin Ming Drive, #07-10 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]		
Driver/Custodian (Insured):	CHEW TECK GUAN (56 / Male), NRIC: S1480810H, Tel: +6597333890		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

5202

MOD19155126 J ComonDelGro Engineering Pte Ltd - Pandan
ENTRY DATE & TIME: 18/10/2018 05:17
SUBMITTED BY: Vo Yung Khong

SPIN TOURS
Hyundai E&C
Mr Sarder Dabir

EXCESS \$1,200/-

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 18/10/2018 11:02

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/10/2018 09:17
Date Of Accident 12/10/2018 10:30
Exact Location Of Accident PIE TOWARDS TUAS EXIT BKE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLQ5202U
Insured/Policyholder
Name Of Registered Owner SAN'S TOURS & CAR RENTALS
Co Reg No 08516300K
Email Address NOEMAIL
Mobile Phone No

Alternative Phone No OFFICE-67349922

Vehicle Particulars

Manufacturer HYUNDAI
Model DM SANTA FE 2.4 GLS AT 4WD SR

Exact Purpose for which vehicle was being used at time of accident PRIVATE USAGE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number D18MTRENT000332

Cover Note Number

Driver

Name of Driver SARDER DABIR
Passport No/FIN G8283280M
Date Of Birth 10/01/1981
Occupation OUTDOOR
Date Of Driving Pass 11/05/2009
Driving Experience 9 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90851615
Fax Number
Contact Number
Email Address NOEMAIL

Address 8, SHENTON WAY
#25-01 AXA TOWER
Postcode 058811
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions LIGHT RAIN
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 5

Passenger 1
NAME: JS LEE
GENDER: MALE

Passenger 2
NAME: JY SIM
GENDER: MALE

Passenger 3
NAME: KIMBERLY
GENDER: FEMALE

Passenger 4
NAME: MAY
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD5292P
Vehicle Make/Model/Colour TOYOTA/ UNKNOWN / UNKNOWN
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17/10/18

INFORMTELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
Tel: 6338 8778 FAX: 6262 6950

Reporting Centre Personnel's Signature
Name: Vo Yung Kheng
NRIC/FIN No.: G2638977T

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CHANGI

- On 12 OCT 2018 at about 10.33 pm. we were coming back to Tuas via PIE ext 24 to BKE slip road...
- We were stationary waiting to move in line queuing in the slip road to BKE
- Suddenly felt a jerking action in our vehicle SLQ 5202 U made (A) - we are hit by a Toyota Pickup GBD 6292 P made (B)
- Weather was light Rain & Road Surface is wet
- Driver is Chinese Male who say that he tried to brake his lorry but still move forward

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

REPORT DELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 608286
TEL: 6338 8778 FAX: 6262 6856

Reporting Centre Personnel's Signature
Name: VO Yung Khong
20130972T

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6300K
Vehicle Details	
Vehicle No.:	SLQ5202U
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	DM SANTA FE 2.4 GLS AT 4WD SR
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4KJHA936155
Chassis No.:	KMHSU81BSHU789673
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$29,419.00
Original Registration Date:	18 Apr 2017
First Registration Date:	18 Apr 2017
Transfer Count:	2
Actual ARF Paid:	\$33,187.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2027
PARF Rebate Amount:	\$24,890.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$42,732.00
Total Rebate Amount:	\$67,622.00

The information contained herein is correct as at 08 Nov 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 17:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	L H Y DESIGN&BUILD, Co. Reg. No.: 53040783C		
Main Claimant:	SAN'S TOURS & CAR RENTALS, Co. Reg. No.: 08516300K		
Vehicle Reg. No.:	SLQ5202U	Date of Loss:	12/10/2018 10:00 - :59 [17 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04914C02	Policy/Cover Note No.:	DMCVSN1709861801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD6292P	Policy No. (Claimant):	D18MTRENT000332
		Excess:	S\$0.00
Repairer:	Lian Fah Spray Painting (HQ) Block 160 Sin Ming Drive, #07-10 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/11/2018]		
Driver/Custodian (Insured):	CHEW TECK GUAN (56 / Male), NRIC: S1480810H, Tel: +6597333890		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ5202U (SNM18D04914C02)**
[GBD6292P]

TP

SAN'S TOURS & CAR RENTALS

Oct 12 2018 10:00AM

[L H Y DESIGN&BUILD]

Lian Fah Spray Painting

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 11:02	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	18/10/18 10:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	18/10/18 10:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	18/10/18 10:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	18/10/18 10:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	18/10/18 10:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 16:51	General View	Load PDF	
2	07/11/18 16:51	Photographs of Damaged Parts	Load PDF	
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/11/18 17:04	PRS	Load PDF	
2	02/11/18 17:04	OI GIA	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 11:02	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 11:02	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 10:32	Accident Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
2	18/10/18 10:32	Accident Photo	 Load JPG	✓
3	18/10/18 10:32	Accident Photo	 Load JPG	✓
4	18/10/18 10:32	Accident Photo	 Load JPG	✓
5	18/10/18 10:32	Accident Photo	 Load JPG	✓
6	18/10/18 10:32	Accident Photo	 Load JPG	✓
7	18/10/18 10:55	Accident Photo	 Load JPG	✓
8	18/10/18 10:55	Accident Photo	 Load JPG	✓
9	18/10/18 10:55	Accident Photo	 Load JPG	✓
10	18/10/18 10:55	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	18/10/18 11:02	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118020013/KCBS2
Date: 16/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1709861801
Claimant Vehicle No: SLQ5202U Insured Vehicle No: GBD6292P
Date of Loss: 12/10/2018 Nature of Claim: TP Claim No: SNM18D04914C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ5202U
Make & Model: HYUNDAI DM SANTA FE, 2.1 D 2.2 CRDI AT 4WD SR (A) Engine No: G4KJHA936155
Reg. Date: 18/04/2017 (Man. Year: 2017) Chassis No: KMHSU81BSHU789673
Colour: Metallic Blue Odometer: 17670 km
Engine Capacity: 2359 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Hankook 9 mm Rear Left Side: Hankook 9 mm
Front Right Side: Hankook 9 mm Rear Right Side: Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2018
Date Inspected: 05/11/2018 Inspected At: Lian Fah Spray Painting (HQ)
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2018)

Parts: M1-SUV HYUNDAI DM SANTA FE 2.1 D 2.2 CRDI AT 4WD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ5202U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >