

ASS. REC. BY:

REF: NS / AG218020015 / K6bn2 Special Instruction:

Survivor: Kennan

ASSIGNMENT (Office)

From (Person): Julie of NG1 Date/Time: 05-11-2018 958am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 8596C Insured: SKZ 947SD

at Workshop m/s Wei Lee Motor Tel: 64569830

of Blk 9 Sin Ming Ind Estate #01-32

Policy No: Claim No: C10002178/JM

Sum Insured: Excess:

Make of Veh: D.O.A. 27/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 05-11-2018 1037am Person Contacted: Karen H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJN 8596C - NS/INC18007662/K1vbn2 DCA: 250418
	SKZ 947SD - X
	61 Lpg @ 360d email lRed @ 6713.83, 65%
	MV: \$10500, C/A: \$6762, NV: \$3738 (Record purpose)

ASS. REC. BY:

REF:

AG-21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGN 8586C

Yr Regn:

03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Uva

c.c.

1887

Colour:

h. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

173026

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR05311Y9305103742

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7 mm

Rear

R/Bal.

6 mm

L/Bal.

3 mm

L/Bal.

5 mm

D.O.A.

27/10/18

D.O.I.


5/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8 Fr

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 21 DEC 2018

Date/Time, File Pass to?

11/12/18

Date/Time, File Return to?

2)

☐

Prell. Report

☐

Final Report

Days Of Repair:

11

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Fixes

Others

TOTAL

350

Report Format:

TP

Lump Sum / I.B.I. (\$

3600

Catherine Chong (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Monday, 5 November, 2018 9:58 AM
To: SUR; assignments
Subject: FW: TP survey for vehicle no: SJN8596C | Claim ref: C10002178/JM
Attachments: doc02711520181102152536.pdf

Importance: High

Hi Team

Please accept TPPD survey and survey in a without prejudice basis.
TP workshop requested for Mohamad Taufihk LKK Auto Consultants to survey their client's vehicle.

Thank you,
-Julie

From: karen Seah <weileemotorworks@gmail.com>
Sent: Monday, 5 November, 2018 9:34 AM
To: Julie Mangubat <julie.m@budgetdirect.com.sg>
Subject: Re: TP survey for vehicle no: SJN8596C | Claim ref: C10002178/JM

Hi,Julie
We would like to have Mohamad Taufihk LKK Auto Consultants to survey the vehicle.
Thank you.

On Mon, Nov 5, 2018 at 8:27 AM Julie Mangubat <julie.m@budgetdirect.com.sg> wrote:

WITHOUT PREJUDICE

Dear Sir

We refer to your email dated 2 November 2018.

Please refer to our list of surveyors for you to choose from.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Kenneth Kong LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd

6. Marcus Chua LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Kenji Tan FormTeam Adjusters Pte Ltd
13. Derrick Quok – In house Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you,

-Julie

From: karen Seah <weileemotorworks@gmail.com>
Sent: Friday, 2 November, 2018 3:26 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: TP survey for vehicle no: SJN8596C

Your insured vehicle no: SKZ9478D

Accident involving vehicle No: SJN8596C/SKZ9478D/SJW8189Y

DOA: 27/10/2018 AT Portsdown Ave twds Normanton park

Dear officer incharge

I refer to the above case, attached with the accident report.

Kindly arrange to survey the vehicle ASAP.

Best Regards,

Karen Seah

Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

--
Best Regards,

Karen Seah

Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

1813C

Vehicle Details

Vehicle No.:

SJN8596C

Vehicle to be Exported:

Yes

Intended Deregistration Date:

26 Nov 2018

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS G AUTO

Primary Colour:

Black

Manufacturing Year:

2009

Engine No.:

1NZX873777

Chassis No.:

MR053HY9305103742

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$13,472.00

Original Registration Date:

02 Mar 2009

First Registration Date:

02 Mar 2009

Transfer Count:

3

Actual ARF Paid:

\$13,472.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

01 Mar 2019

PARF Rebate Amount:

\$6,736.00

Intended COE Rebate Details

COE Expiry Date:

01 Mar 2019

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$1,020.00

COE Rebate Amount:

\$26.00

Total Rebate Amount:**\$6,762.00**

The information contained herein is correct as at 02 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2018 10:13
Date Of Accident	27/10/2018 22:10
Exact Location Of Accident	PORTSDOWN AVE TOWARDS NORMANTON PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN8596C
Insured/Policyholder	
Name Of Registered Owner	KH LEASING PTE. LTD.
Co Reg No	201611813C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97372593
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5104744635
Cover Note Number	
Driver	
Name of Driver	CHUA TEOW GEK
NRIC No	S7134947J
Date Of Birth	02/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	09/11/2001
Driving Experience	16 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97372593
Fax Number	
Contact Number	
Email Address	JENCHUA71@YAHOO.COM.SG

Address	BLK 337 HOUGANG AVE 7 #10-393 SINGAPORE
Postcode	530337
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NA GENDER: : MALE
Passenger 2	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4519999 - FAX NO: 65535679
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ9478D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN TAU SING IVAN

NRIC/Passport Number

S70079901

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJW8189Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A - SJU8596C
B - SKZ9478D
C - SJU08189Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181028/2004

1 of 4

Report No. T/20181028/2004

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No. 1800-4519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/10/2018 01:36	Vide Report No.: D/20181027/0150	Station Diary No.: 14
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHUA TEOW GEK			Address: APT BLK 337 HOUGANG AVENUE 7 #10-393 SINGAPORE 530337		
ID Type / ID No.: NRIC NO / S7134947J			Contact No.: Home/Office: Mobile: 97372593		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 47	Date of Birth: 02/10/1971	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRIVATE HIRED CAR DRIVER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/10/2018 22:10	Type of Location: Flyover
Location: PORTSDOWN AVENUE TOWARDS NORMANTON PARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJN8596C	Car					0
SJW8189Y	Car					0
SKZ9478D	Car					0

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181028/2004

2 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20181028/2004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	CHUA TEOW GEK	ID No.	S7134947J
Related Vehicle	SJN8596C (Car)	Contact No.	97372593
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	TAN TAU SING IVAN	ID No.	S7007990I
Related Vehicle	SKZ9478D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 27/10/2018 at about 2210hrs, I was driving my car, SJN8596C as I was working as a Grabcar driver with 2 passengers seated at the back passenger seat along Portsdown Ave at the 3rd lane. As I was wanted to make my way to the slip road towards Normanton Park. I check my side mirror and ensured that it is clear to filter to the 4th lane before I proceeded to change lane. Suddenly, I felt a heavy impact from the rear of my car and I collided to the divider. I immediately came out of my car to make a check and discovered that there was one car SKZ9478D, driver, Tan Tau Sing Ivan had collided the rear of my car and subsequently the car behind him, SJY8189Y also collided to the rear of this car resulting a chain accident.

Mr Tan then called for ambulance because the he found out that the third car deployed air bag and was informed by the driver that his wife felt pain on the chest. Traffic police, SSgt Ahmad Syafiq came down to scene and attended to all of us. He also took my car camera memory card and the Mr tan car camera memory card. I was also informed that one of the passenger from the third was conveyed the hospital.

I wish to state that I am not injured during the accident and my car was badly damaged and it was towed away to a workshop by the car rental agency.

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20181028/2004

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No. 1800-4519999

3 of 4

Report No. T/20181028/2004

CONTINUATION OF REPORT

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

02, Nov 2018

Auto & General Insurance (S)Pte
Budget Direct Insurance
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
S 239924

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle no: SKZ9478D

Accident involving vehicle no: SJN8596C/SKZ9478D/SJW8189Y

DOA: 27/10/2018 AT Portsdown Ave Twds Normanton Park

Dear officer incharge

Re: Estimate cost of repair for vehicle SJN8596C

To supply--

Description	Qty	Amount	
Rear bumper	1	431.90	✓
Rear bumper retainer	2	98.50	✓
Rear bumper clip		38.00	✓
Taillamp @328	2	656.00	✓
Taillamp gasket @28	2	56.00	✓
End panel	1	571.20	✓
End panel top garnish	1	202.50	✓
Spare tyre panel	1	560.20	X
Spare tyre board	1	41.60	X
Lid	1	520.00	✓
Lid lock	1	29.20	✓
Lid VIOS emblem	1	12.20	✓
Lid-TOYOTA logo	1	24.30	✓
Boot weather strip	1	42.80	50/50
Front bumper	1	482.20	✓
Front bumper retainer	2	52.40	✓
Front bumper clip		42.00	✓
Front bumper lower grille	1	123.20	✓
Headlamp @ 427.80	2	855.60	✓
Front grille	1	172.30	✓
Front support panel	1	427.90	✓
Front bumper enforcement	1	268.60	✓
Front bumper enforcement bracket	2	112.60	✓

Not Authorised

11 days

Resurvey After Paint

11 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front brace panel	1	R	91.20	✓
Bonnet	1	R	452.50	✓
Bonnet hinge @44.30	2	old	88.60	✓
Radiator	1	SL	544.00	X
Condensor	1	R	1,245.00	✓
Fan motor	1	SL	263.70	X
Fan cowling	1	SL	225.80	X
Fan blade	1	R	171.10	X
Front bumper tow cover	1	SL	22.00	X
	Parts		8,925.10	
	Parts less 25%		2,231.27	
			6,693.83	

Front number plate w bracket

Reverse sensor

To remove/replace radiator, condenser, fan assy. Recharge air con gas.

To remove front and rear damaged parts and attachments

Cut n weld damaged panel.

Straighten front n rear chassis where necessary.

Repair/reshape dented/damaged areas.

Replace/align all parts into position.

To spray paint-front n rear

Tow fee

R 40.00 ✓
Shore 220.00 200m
180.00 100l

1,600.00 1400l
1,500.00 1400l
80.00 50l

10213.83



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18020015/Kqbn2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 26-12-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 9478D	Veh. Inspected	SJN 8596C
Policy No.		Coverage (\$)	0.00
Claim No.	C10002178/JM	Excess (\$)	0.00
Assign From	JULIE	Assign Date	05/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305103742	Colour	METALLIC BLACK
Odometer	173026	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	7 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	3 mm
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2018	Inspection Date	05/11/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 11 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 8596C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	431.90	431.90
2	REAR BUMPER RETAINER	DISTORTED	98.50	98.50
1	REAR BUMPER CLIP	NECESSARY	38.00	38.00
2	TAILLAMP @\$328.00	CRACKED	656.00	656.00
2	TAILLAMP GASKET @\$28.00	NECESSARY	56.00	56.00
1	END PANEL	BENT	571.20	571.20
1	END PANEL TOP GARNISH	DENTED	202.50	202.50
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	560.20	-
1	SPARE TYRE BOARD	SERVICEABLE	41.60	-
1	LID	BENT	520.00	520.00
1	LID LOCK	DENTED	29.20	29.20
1	LID VIOS EMBLEM	NECESSARY	12.20	12.20
1	LID "TOYOTA" LOGO	NECESSARY	24.30	24.30
1	FRONT BUMPER	BENT	482.20	482.20
2	FRONT BUMPER RETAINER	N/S DISTORTED	52.40	26.20
1	FRONT BUMPER CLIP	NECESSARY	42.00	42.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	123.20	123.20
2	HEADLAMP @\$427.80	O/S MTG CRACKED	855.60	427.80
1	FRONT GRILLE	CRACKED	172.30	172.30
1	FRONT SUPPORT PANEL	BENT	427.90	427.90
1	FRONT BUMPER ENFORCEMENT	BENT	268.60	268.60
2	FRONT BUMPER ENFORCEMENT BRACKET	DISTORTED	112.60	112.60
1	FRONT BRACE PANEL	BENT	91.20	91.20
1	BONNET	BENT	452.50	452.50
2	BONNET HINGE @\$44.30	O/S DISTORTED	88.60	44.30
1	RADIATOR	SERVICEABLE	544.00	-
1	CONDENSOR	BENT	1,245.00	1,245.00
1	FAN MOTOR	SERVICEABLE	263.70	-
1	FAN COWLING	SERVICEABLE	225.80	-
1	FAN BLADE	SERVICEABLE	171.10	-
1	FRONT BUMPER TOW COVER	SERVICEABLE	22.00	-
	LESS 25% DISCOUNT		-2,220.58	-1,638.90
			6,661.72	4,916.70

Report Ref No. CS/AGI18020015/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT WEATHER STRIP (50%)(SN) LESS 25% DISCOUNT	DENTED	42.80 -10.70 32.10	21.40 - 21.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE W BRACKET (SN)	BENT	40.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	220.00 260.00	200.00 240.00
	<u>LABOUR</u>			
	TO REMOVE/REPLACE RADIATOR,CONDENSER,FAN ASSY.RECHARGE AIR CON GAS.		180.00	100.00
	TO REMOVE FRONT AND REAR DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.STRAIGHTEN FRONT N REAR CHASSIS WHERE NECESSARY.REPAIR/RESHAPE DENTED/DAMAGED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		1,600.00	1,400.00
	TO SPRAY PAINT-FRONT N REAR.		1,500.00	1,400.00
	TOW FEE.		80.00	50.00
			3,360.00	2,950.00
	GRAND TOTAL		10,313.82	8,128.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/AGI18020015/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.