

Surveyor

REF: CSI/LPC18020019/ESD3⁵⁴

Special Instruction:

Part by Part: \$15,255.96

ASSIGNMENT (Office)

From (Person): Gemild poh of LPC Date/Time: 5/11/2018
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: CA Appraiser

Workshop: AE Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: XE 957D Insured: MCP 8756

at Workshop m/s AE Auto Tel:

of 160 8in Ming Drive #06-01

Policy No: Claim No: 16/17/17/VC10/233061

Sum Insured: Excess:

Make of Veh: D.O.A. 18/03/2017

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 10 days)

Date/Time: 18/10/19 Submit Final Fig \$7,164.95, 6 days (Red \$8,091.01/ 53%; Original 10 days)

Date/Time	Action/Instruction
24/6/19	Market value of the vehicle at the material time of accident pending TP GIA Report.
26/6/19	pending TP GIA Report. After Get GIA Report pass to Simon.
	MV - \$140K (Est)
	LTA - \$13,726 (Est)
	Nett - \$126,274 (Est)

RECEIVED 18 OCT 2019

17/10/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

150

- | | | | |
|--------------|--------------|--------------|----------------|
| 1) Date/Time | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 5 November, 2018 11:29 AM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; LILLIAN SIM BEE LIAN
Subject: FW: Second opinion - XE 957 D; DOL : 18/03/2017; OUR REF : 16/17/17/VC10/233061
Attachments: 233061 ADJ REPORT.pdf; 233061 RIMV.pdf

Dear Catherine,

Kindly assist.

You can request the color photos from them directly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: LILLIAN SIM BEE LIAN
Sent: Saturday, 3 November, 2018 11:17 AM
To: GERALD POH WEE BIN
Subject: Second opinion - XE 957 D; DOL : 18/03/2017; OUR REF : 16/17/17/VC10/233061

Lonpac External Confidential

Dear Gerald,

Would appreciate if you could help to get a second opinion from your panel adjusters on the reasonability of cost of repairs to the claimant's vehicle vis a vis the circumstances of accident as well as the **market value of the vehicle at the material time of accident.**

Attached please find the following:-

- 1) Claimant's survey report.
- 2) Vehicle registration details.

Thanks and regards,
LILLIAN SIM
CLAIMS DEPARTMENT | LONPAC INSURANCE BHD
T : 03-27237716 F : 03-20342654 EMAIL : lilliansim@lonpac.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2017 15:03
Date Of Accident	18/03/2017 09:15
Exact Location Of Accident	PIE(TUAS) NEAR STEVEN EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE957D
Insured/Policyholder	
Name Of Registered Owner	PQ SWIFTVAN LOGISTICS PTE LTD
Co Reg No	198202262E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-NOPHONE
Vehicle Particulars	
Manufacturer	UD Trucks
Model	ESCOT V-10.8 D GKB5ELDHNT (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	CN780811
Cover Note Number	
Driver	
Name of Driver	RAMLI BIN ARSHAD
NRIC No	S1485233F
Date Of Birth	08/09/1961
Occupation	Outdoor
Date Of Driving Pass	11/12/1985
Driving Experience	31 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-93859173
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 64 KALLANG BAHRU #13-637
Postcode	330064
Was driver an employee of the Insured's Company	Yes
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	Yes
Foreign Vehicle Registration Number	MCP8756 (Commercial Vehicle)
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Traffic Police Headquarters
Police Station Address	ROAD: 10 Ubi Avenue 3 Singapore , POSTCODE: 408865 , COUNTRY: Singapore
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO: T/20170318/2103

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	MCP8756
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	MOHD NORHASBY BIN GHAZALI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE8155J
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver TAN POH CHUAN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)
Details of Witness
Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number XB6505B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)
Details of Witness
Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK WITH MY INSURER FOR MORE DETAILS.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

	<p>A = XG057P</p> <p>B = MCP057P</p> <p>C = MCP057P</p> <p>D = XB6505B</p>
--	--

Describe Circumstances of the Accident

As per police report No. 7/20170318/7103.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other workshop
☐ For record purpose
 Policy No. 2780811.
 Insurer AXA Veh. No. XE457D

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20170318/2103

1 of 4

Report No. T/20170318/2103

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2017 15:54		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: RAMLI BIN ARSHID			Address: APT BLK 64 KALLANG BAHRU #13-367 HDB- KALLANG/WHAMPOA/NOVENA SINGAPORE 330064		
ID Type / ID No.: NRIC NO / S1485233F			Contact No.: Home/Office:		Mobile: 93859173
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 55	Date of Birth: 08/09/1961	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: PRIME MOVER DRIVER			Driving Licence Information: Class: 3,4,5		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/03/2017 09:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY NEAR STEVENS ROAD EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: CHAIN COLLISION			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBE8155J	Lorry				Slightly Damaged	0
MCP8756	TRAILER				Slightly Damaged	0
XB6505B	TRUCK				Slightly Damaged	0
XE957D	TRUCK				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20170318/2103

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4
Report No. T/20170318/2103

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN POH CHUAN	ID No.	S1498513A
Related Vehicle	GBE8155J (Lorry)	Contact No.	84959677
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MOHD NORHASBY BIN GHAZALI	ID No.	831019045311
Related Vehicle	MCP8756 (TRAILER)	Contact No.	91577662
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	RAMLI BIN ARSHID	ID No.	S1485233F
Related Vehicle	XE957D (TRUCK)	Contact No.	93859173
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

AT THE ABOVE MENTIONED DATE AND TIME, I (XE957D) WAS TRAVELLING ALONG PIE NEAR STEVENS ROAD EXIT. I WAS TRAVELLING ON THE EXTREME LEFT LANE OF THE THREE LANE ROAD. AS THE LORRY (GBE8155J) APPLIED EMERGENCY BRAKES, I FOLLOWED SUIT TO PREVENT THE COLLISION. HOWEVER, A MALAYSIAN TRAILER (MCP8756) COULD NOT BRAKE IN TIME AND COLLIDE ONTO MY TRUCK. THE IMPACT CAUSED MY TRUCK TO ALSO COLLIDE WITH THE LORRY. MY TRUCK SUFFERED DENTS AND SCRATCHES TO BOTH FRONT AND REAR. WE THEN EXCHANGED PARTICULARS.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20170318/2103

3 of 4

Report No. T/20170318/2103

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20170318/2103

4 of 4

Report No. T/20170318/2103

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
WOO JUN HON

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt LIM JUN HUI, ADRIAN
Contact No.: 65476350

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
18/03/2017 15:54

Classification Of Case:

The owner and vehicle particulars for Vehicle No. XE957D as at 28 Aug 2015 are as follows:

1.	Name	: PQ SWIFTVAN LOGISTICS PTE. LTD.
2.	Identification No. Type	: Company
3.	Identification No.	: 198202262E
4.	Place Of Passport Issue	: -
5.	Registered Address	: 18 ENTERPRISE ROAD SINGAPORE 629824
6.	Mailing Address	: -
7.	Vehicle No.	: XE957D
8.	Effective Date of Ownership	: 28 Aug 2015
9.	Original Registration Date	: 28 Aug 2015
10.	First Registration Date	: 28 Aug 2015
11.	Vehicle Type	: B36 - Goods (Open) Prime Mover
12.	Vehicle Scheme	: Normal
13.	Attachment 1	: No Attachment
14.	Attachment 2	: -
15.	Attachment 3	: -
16.	Vehicle Make	: UD TRUCKS
17.	Vehicle Model	: GKB5ELDHNT ESCOT V
18.	Year of Manufacture	: 2015
19.	Primary Colour	: White
20.	Secondary Colour	: -
21.	Passenger Capacity	: 2
22.	Chassis/Trailer Chassis No.	: GKB5E00611 / -
23.	Propellant/Emission Standard	: Diesel / Euro V
24.	Engine No./Motor No.	: GH11729226 / -
25.	Engine Capacity(cc)/Power Rating(kW)	: 10837 / -
26.	Maximum Power Output(kW/bhp)	: - / -
27.	Unladen Weight(kg)	: 6800
28.	Maximum Laden Weight(kg)	: 55000
29.	Open Market Value	: \$69,571.00
30.	PARF Eligibility	: No
31.	PARF Eligibility Expiry Date	: -
32.	Minimum PARF Benefit	: \$0.00
33.	IU Label No.	: -
34.	COE No.	: 2015082805002118D
35.	COE Expiry Date	: 27 Aug 2025
36.	COE Category	:
37.	Quota Premium/Prevailing Quota Premium	: \$50,584.00
38.	Actual Quota Premium/PQP Paid	: \$16,308.00
39.	Actual ARF Paid	: \$3,479.00
40.	CO2 Emission(g/km)	: -
41.	Actual CEVS Rebate Utilised	: -
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: 27 Aug 2035
45.	Road Tax Amount	: \$1,275.00
46.	Road Tax Start Date	: 28 Aug 2015
47.	Road Tax End Date	: 27 Feb 2016
48.	Remarks	: -



Enquire PARF/COE Rebate for Registered Vehicle

The information contained herein is correct as at 25 Jun 2019

date: 18/2/17

PARK: NIL

LOB = $\frac{1}{2} \times \frac{\text{but not more than}}{10 \text{ yrs}}$

$$= 16308 \times \frac{101}{120}$$

$$= 13725.90$$

V/A: PART + COE

$$= 13705.90$$

$$\omega_{CTA} = 137 \text{ meV (est)}$$

3 BEST WAYS TO SELL YOUR CAR!

POST AN AD

Sell it yourself

SELL BY BIDDING

Get dealers to bid

CONSIGNMENT

Get help to sell directly

FIND OUT MORE

UD Trucks

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼



Advanced Search

Home » Used Cars » Bell Auto Pte Ltd » UD Trucks GKB5E

UD Trucks GKB5E

Overview

Financial

Accessories

Similar

Research

Photos

Map



WHOLESALE EXPERIENCE AT YOUR CONVENIENCE

Price	\$105,800	Lifespan	03-Aug-2035
Depreciation ⓘ	\$17,300 /yr View models with similar depre	Reg Date	04-Aug-2015 (6yrs 1mth 10days COE left)
Mileage	N.A.	Manufactured ⓘ	2015
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$30,576 as of today (change)	OMV ⓘ	\$70,292
COE ⓘ	\$50,001	ARF ⓘ	\$3,515
Engine Cap	10,837 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	6,800 kg		

Type of Vehicle Truck

Description

One Of The Most Wanted UD 4X2 55Ton Prime Mover In The Market. Vehicle In Superb Condition. Well Maintained By The Previous Owner. New Spray Work. 100% Loan Available. Easy Approval. High Value Trade In For Your Vehicle, View To Believe. Interested Party, Please Contact Us To Test Drive And Find Out More! We Are Pleased To Serve You.

Category

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Get the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information


Company	Bell Auto Pte Ltd	
	» dealer's pricelist	
	» 90 vehs sold 131 vehs availat	
Address	8 Tuas Avenue 18 (Level 5 & 7)	
	Search cars nearby this location	
Office No	67457076	
Contact Person(s)	Ah Marc	909161
	Derrick Tan	945901

MV - 140K

Our Reference: TP17-058045-AE
Your Reference: -
Vehicle Number: XE957D

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Front and Rear portion**. Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **10 working days** are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Ang Guea Kiang
Automotive Appraiser
MSAAA

Disclaimer

Pursuant to your instruction, we have **NOT AUTHORIZED** repair. The assessment was conducted on a "**Without Prejudice**" basis. If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **CA APPRAISER PTE LTD** for any reliance on this report by any third party.

Our Reference : TP17-058045-AE

Your Reference : -

Vehicle Number : XE957D

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
PARTS FRONTAL (LIST ITEMS)					
1	1	FRONT BUMPER	BENT	2,620.67	2127.19 / 2,620.67 X
2	1	FRONT BUMPER BRACKET LH	BENT	291.51	SK 291.51 X
3	1	FRONT BUMPER BRACKET RH	BENT	291.51	SK 291.51 X
4	1	FRT BUMPER CTR INNER GARNISH LH	MISSING	51.49	51.49 X
5	1	FRT BUMPER CTR INNER GARNISH RH	MISSING	51.49	51.49 X
6	1	FRT BUMPER CTR OUTER GARNISH LH	MISSING	78.50	78.50 X
7	1	FRT BUMPER CTR OUTER GARNISH RH	MISSING	78.50	78.50 X
8	1	HEADLAMP LH	CUT	1,422.99	5233.96 - 10% 1,422.99 X
9	1	HEADLAMP RH	CUT	1,422.99	4799.75 1,422.99 X
10	1	FRT RADIATOR GRILLE	CRACKED	1,367.77	R 1,367.77 X
11	1SET	FRT RADIATOR GRILLE CLIP	NECESSARY	50.00	SK 50.00 X
				7,727.42	7,727.42
				less 10%	10%
				772.74	772.74
Parts Frontal sub Total :				6,954.68	6,954.68
PARTS REAR (LIST ITEMS)					
12	1	TAILLAMP LH	CRACKED	419.40	SK 419.40 X
13	1	TAILLAMP RH	CRACKED	419.40	300 / 419.40 X
14	1	REVERSE LAMP LH	CUT/ BENT	128.50	SK 128.50 X
15	1	REVERSE LAMP RH	CUT/ BENT	128.50	SK 128.50 X
16	1	REAR NUMBER PLATE HOLDER	BENT	231.90	148 / 231.90 X
17	1	RR RH SPRING LEAF SHACKLE	DISTORTED	516.20	828 - 10% 380 / 516.20 X
18	1	RR RH SPRING LEAF SHACKLE BRACKET	CRACKED	812.50	SK 812.50 X
19	2	RR RH SPRING LEAF SHACKLE PIN @\$169.97	NECESSARY	339.94	SK 339.94 X
20	1	REAR LH SPRING LEAF SHACKLE	DISTORTED	516.20	SK 516.20 X
				3,512.54	3,512.54
				less 10%	10%
				351.25	351.25
Parts Rear sub Total :				3,161.29	3,161.29

Page - 3

5454.95

Our Reference : TP17-058045-AE

Your Reference : -

Vehicle Number : XE957D

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
21	1	SPECIAL NETT ITEMS (FRONTAL)	DENTED		Δ 25
		FRONT NUMBER PLATE		40.00	40.00 ✓
		Special Nett Frontal Sub Total:		40.00	40.00
22	1	SPECIAL NETT ITEMS (REAR)	DENTED		Δ 25
		REAR NUMBER PLATE		40.00	40.00 ✓
		Special Nett Rear Sub Total:		40.00	40.00
		Total Parts:		10,195.96	10,195.96

80
50

Our Reference : **TP17-058045-AE**
 Your Reference : -
 Vehicle Number : **XE957D**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT(\$\$)
LABOUR FRONTAL			
1	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (frontal)	1,200.00	499 ✓ 1,000.00
2	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (frontal)	1,400.00	400 ✓ 1,200.00
3	To check wirings and lightings. (frontal)	100.00	30 ✓ 80.00
4	To supply and apply rust proofing treatment to affected panel. (frontal)	100.00	30 ✓ 100.00 X
LABOUR REAR			
5	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (Rear)	1,200.00	300 ✓ 1,000.00
6	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (rear)	1,000.00	200 ✓ 800.00
7	To supply and apply rust proofing treatment to affected panel. (rear)	120.00	30 ✓ 100.00 X
8	To remove/refix rear LH wheels, Left spring, replace leaf spring shackle kit.	400.00	X 350.00
9	To remove/refix rear RH wheels, Left spring, replace leaf spring shackle kit.	400.00	300 350.00
10	To check on rear wiring system, lamp socket wire for rear.	120.00	30 ✓ 80.00
Labour Total :		6,040.00	5,060.00
TOTAL (PARTS & LABOUR) :		16,235.96	15,255.96

Adjustment / Recommendations

Note : (For Part By Part Repair)

The workshop has agreed to undertake the repair at our adjusted amount of **\$15,255.96**

Under normal circumstances, the repair period would be about **10** working days.

6 days
 P- 5454.95 = 7164.95 1660
 N- 50
 L- 1660
 L/S- 5731.96
 = 5750
 Page - 5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 957D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	2,620.67	2,127.10
1	FRONT BUMPER BRACKET LH	SERVICEABLE	291.51	-
1	FRONT BUMPER BRACKET RH	SERVICEABLE	291.51	-
1	FRT BUMPER CTR INNER GARNISH LH	MISSING	51.49	51.49
1	FRT BUMPER CTR INNER GARNISH RH	MISSING	51.49	51.49
1	FRT BUMPER CTR OUTER GARNISH LH	MISSING	78.50	78.50
1	FRT BUMPER CTR OUTER GARNISH RH	MISSING	78.50	78.50
1	HEADLAMP LH	CUT	1,422.99	1,422.99
1	HEADLAMP RH	CUT	1,422.99	1,422.99
1	FRT RADIATOR GRILLE	TO REPAIR SEE LABOUR	1,367.77	-
1	SET FRT RADIATOR GRILLE CLIP	SERVICEABLE	50.00	-
1	TAILLAMP LH	SERVICEABLE	419.40	-
1	TAILLAMP RH	CRACKED	419.40	300.00
1	REVERSE LAMP LH	SERVICEABLE	128.50	-
1	REVERSE LAMP RH	SERVICEABLE	128.50	-
1	REAR NUMBER PLATE HOLDER	BENT	231.90	148.00
1	RR RH SPRING LEAF SHACKLE	DISTORTED	516.20	380.00
1	RR RH SPRING LEAF SHACKLE BRACKET	SERVICEABLE	812.50	-
2	RR RH SPRING LEAF SHACKLE PIN @ \$169.97	SERVICEABLE	339.94	-
1	REAR LH SPRING LEAF SHACKLE	SERVICEABLE	516.20	-
	LESS 10% DISCOUNT		-1,124.00	-606.11
			10,115.96	5,454.95
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	DENTED	40.00	25.00
1	REAR NUMBER PLATE (SN)	DENTED	40.00	25.00
			80.00	50.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & DISMANTLE DAMAGED PARTS TO CUT AND CHISEL OUT ATTACHMENT PARTS. TO KNOCK, STRAIGHTEN OUT DENTS WHERE NECESSARY, TO WELD REFIX READJUST & RESHAPE SAME. (FRONTAL) INCLUSIVE OF THE REPAIR OF FRT RADIATOR GRILLE.		1,200.00	400.00
	TO RESPRAY PAINTING ON ALL AFFECTED PARTS, TO SUPPLY PAINT MATERIAL I.E SAND PAPER, RUBBING COMPOUND, THINNER, PAINT, LACQUER, ETC. (FRONTAL)		1,400.00	400.00
	TO CHECK WIRINGS AND LIGHTINGS. (FRONTAL)		100.00	30.00
	TO SUPPLY AND APPLY RUST PROOFING TREATMENT TO AFFECTED PANEL. (FRONTAL)	NOT NECESSARY	100.00	-
	TO REMOVE & DISMANTLE DAMAGED PARTS TO CUT AND CHISEL OUT ATTACHMENT PARTS. TO KNOCK, STRAIGHTEN OUT DENTS WHERE NECESSARY, TO WELD REFIX READJUST & RESHAPE SAME. (REAR)		1,200.00	300.00
	TO RESPRAY PAINTING ON ALL AFFECTED PARTS, TO SUPPLY PAINT MATERIAL I.E SAND PAPER, RUBBING COMPOUND, THINNER, PAINT, LACQUER, ETC. (REAR)		1,000.00	200.00
	TO SUPPLY AND APPLY RUST PROOFING TREATMENT TO AFFECTED PANEL. (REAR)	NOT NECESSARY	120.00	-
	TO REMOVE / REFIX REAR LH WHEELS, LEFT SPRING, REPLACE LEAF SPRING SHACKLE KIT.	NOT NECESSARY	400.00	-
	TO REMOVE / REFIX REAR RH WHEELS, LEFT SPRING, REPLACE LEAF SPRING SHACKLE KIT.		400.00	300.00
	TO CHECK AND REAR WIRING SYSTEM, LAMP SOCKET WIRE OF REAR.		120.00	30.00
			6,040.00	1,660.00
	GRAND TOTAL		16,235.96	7,164.95
RECOMMENDED COST OF REPAIRS				7,164.95

Report Ref No. CS1/LPC18020019/Esd3s2

MARKET VALUE: \$140,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,726.00(EST)=NETT VALUE: \$126,274.00(EST)

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.