



Our Ref

T 1018 / SHC1476T /WT(st)

Your Ref:

Date

Dear Sir

13-Nov-18

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

CHINA TAIPING INSURANCE CO LTD

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell

Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Yishun nun Industrial Park A Singapore 768732

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

WITHOUT PREJUDICE

ACCIDENT INVOLVING OUR TAXI SHC1476T YOUR INSURED SKS8954P 31.10.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor SHC1476T which was involved in the captioned accident with your insured Vehicle No: vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SKS8954P** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,277.07
6	days Loss of Rental @ \$ 128.40 per day	\$ 385.20 shu
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation Fees	\$ -
	Sub Total	\$ 1,669.76

HIRER'S CLAIM

c)

d)

80.00 per days 240.00 days Loss of Income @ \$ **Total Claims:** 1.909.76

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs: a)

SKS8954P

b) LTA search slip/s of:

SHC1476T GIA / Police report/s of :

Letter of authority from owner / hirer / operator

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

(X) Photograph/s of Accident Scene(x) Downtime/Mileage record

(x) Rental Rate letter

4

pcs.

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHC1476T , SKS8954P

ON 31-Oct-18 19:10

ALONG

TAMPINES AVE 2 > AVE 5

I / We

WONG KONG CHOY WIL... (Hirer) NRIC No.: S7432166F

and/or

(Relief) NRIC No.:

Taxi Number

SHC1476T

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

01-Nov-2018

Name of Hirer

WONG KONG CHOY WILSON

Hirer NRIC

S7432166F

Signature:

Address

213 MARSILING CRESCENT #03-79

730213

Contact No.

96647925



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

320 Ubi Road 3 Singapore 408649

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page:

8010012 CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER	VEHCLE SHC1476		INV. NO/DATE 91407100 12.11.2018 JOB NO. 305233550 ODOMETER READING DATE/TIME IN 01.11.2018 14:55			
3 ANSON ROAD #16-00 SINGAPORE SG 079909	MAKK HYUNDA I					
CONTACT NO: 62222366	MODEL TONTO	1 2.)				
	DATE 0 28.09.					
Description: 3P 31.10.18		CHASSIS CODE KMHC851CVKU114760				
S/No Part No.	Qty	Unit Price	%Disc	Net.		
PART REQUISITION						
0001 04-01-0104-2282 IONIQVC COVER-RR F	UMPER# 1	459.40	20.00	367.5		
0002 FNPS NO PI	ATE(S) 1	35.00	0.00	35.00		
0003 04-01-0104-2533 JONIQV2 MOULDING A	SSY-RR 1	451.25	20.00	361.00		
	SUB-TOTAL	:	76	53.52		
JOB NATURE						
0001 L PANEL BEATING	FREAR 20	200.00		200.00		
0002 23-502 SPRAYPAINT ON AFFECTE	ED AREA 20	200.00		200.00		
0003 L REMOVE/REFIX REVERSE	SENSOR 3	30.00	30.00)		
	SUB-TOTAL	:		430.00		

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91407100	1,277.07	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 57970

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page:

801.001.2

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHC1476T

INV. NO/DATE 91407100 12.11.2018

MAKE HYUNDAI

JOB NO. 305233550

MODEL. IONIQ(G2) ODOMETER READING

DATE OF REG 28.09.2018

DATE/TIME IN 01.11.2018 14:55

CHASSIS CODE KMHC851CVKU114760

Items total

1,193.52

Add GST @

7,000 %

83.55

Invoice amount

1,277.07

KATHERINETAN 12.11.2018 14:15:46 Issued by

Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. **AMOUNT** ACCOUNT No. INVOICE No. 8010012 91407100 1,277.07

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18101006

Date: 12 November 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

31/10/2018 @ 19:10 hrs

ALONG

TAMPINES AVE 2 > AVE 5

INVOLVING

SKS8954P

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC1476T (the "Taxi"). The Taxi was hired to WONG KONG CHOY WILSON IC NO S7432166F a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$128.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

•	HOURS OPERATED (TIME)	07	0305	1535 0250	OXI IXO	0230	1653	1505 0240	1440	1450 0250		(ı
	HOURS OP	FROM	1530	535	2770	1530	off	1505	5400	1450		1433	(380
	MILEAGE	(KM)	363	344	397	784	393	315	370	253		3	J.W
コナイバ イロ	MILEAGE READING		11335	b t 9 11	13076	12360	12753	13068	13418	13671			
20	NAME OF DRIVER		Wilson work	Wilson word	500	Wilson Wond	540	wilson work	ovig,	Wilson wonh		Morraphy	repar
	DATE		27/10/18	28/10/18	34/10/18	3.9/10/18	1420 2145 30/10/18	3240 0755 30/10/18	81/10/18	31/16/18	1445 0115 01/11/18	01-11-18	03-1-1-63
	ATED (TIME)	10	2155	0510	2210	2250 1035 39	2145	0755	1425 0625	500 0130	0115	0226	1505 0100
	HOURS OPERATED (TIME)	FROM	1350 2155	2355 0750	1540	2750	1420	3240	1425	1500	1445	1500 0226	1505
		(KM)	239	744	178	275	757	704	296	244	379	249	735
		{EADING	5114	15:0	9 2 6	1 1 6	897	7 7 9	8 9 6	7 1 2	- 5	140	2 1 5

11/1/2018

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD C01 SKS8954P 31 Oct 2018 / 19:10:00 Successful

Previous OK

SUC 14767











