(08/11/13) wef

ASS. REC. BY: Marcus

REF: Axa/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 6845E

at Workshop m/s Kah ...

of ...

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Bal. or Market Value: 30k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTA 2/11

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJV 6845E Yr Regn: 5/2/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Honda ODyssey c.c 2354

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 240168 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRB38509C201535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	3	mm	R/Bal.	5	mm
L/Bal.	3	mm	L/Bal.	5	mm
D.O.A.	30/10/18		D.O.I.	26/11/18	

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rep 11k.
	undercarriage? tyre 1yrs 3mth next 8889

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation:

__S + RS, __SI

Photos

Others

TOTAL