

Surveyor: Kavin

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 3218J Yr Regn: 3 Jan, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tr / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 c.c. 1680

Colour: Blue A/C: Ins U / Std / NI / NA

Sp. Reading: 593238 T/Radio: Ins U / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHLB414ADU043454

Gen. Cond: Good / F / Poor / Burnt

Steering: In order / E / Jammed / Leaked / Burnt or

Brake: In order / E / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / 6 / A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/11/8 D.O.I. 2/11/8

Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AxA</u>
	<u>4s</u>

Date/Time, File Pass to?  : Prel. Report

1) \_\_\_\_\_  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
_____ \$ + RS. _____ SI	
Photos	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

### Workshops

member of COMFORTDELGRO

Date/Time: 02.11.2018 11:12 Page : 1

Team: ARC Repair TP(CLSO)1

### JOB CARD


Sales Order:

JC NO.: 305233556

OMER  S OMER NO. 7010045 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO.: SHC3218J	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 02.11.2018 09:05
	YR OF MANU 03.01.2014	TARGET DATE
	CHASSIS CODE KMHLB41UMDU043454	COMPLETION DATE/TIME:
	UNIT CARD NO.	

### JOB DESCRIPTION

Accident Date: 01.11.2018  
NATURE: 3P 01.11.18/C



RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR

\_\_\_\_\_  
CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

o.: SHC3218J LIMTS

Vehicle No.: SHC3218J

\_\_\_\_\_  
Service Advisor Signature/Date

\_\_\_\_\_  
Name of Service Advisor Date

Returned to Service Reception upon collection

To be kept by Security Guard