

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

AXA-4S

(Fri)

Date: 02.11.2018

Time: 11:49:44

Page: 1

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305233556
REGN NO : SHC3218J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.01.2014
DATE/TIME IN : 02.11.2018 09:05
ACCIDENT DATE : 01.11.2018

1200

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0578-G	FRT BUMPER	1	544.50	20.00	435.60	X report
0002	04-01-0103-0573-A	FRT FENDER RH	1	566.30	20.00	453.04	/
0003	03-01-0103-0120-G	FRT FENDER SHIELD RH	1	174.90	20.00	139.92	X
0004	04-01-0103-0658-G	FRT WHEEL CAP RH	1	107.10	20.00	85.68	/
0005	04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	?
0006	04-01-0103-0640-G	FRT BUMPER BRKT RH	1	24.60	20.00	19.68	?

SUB-TOTAL : 1,151.84

JOB NATURE

0000	L	PANEL BEATING					440.00 200
0001	23-502	SPRAYPAINT ON AFFECTED AREA					440.00 400
0002	20-00	TUFF COAT ON AFFECTED PARTS.					40.00 20
0003	L	WHEEL ALIGNMENT					120.00 X

SUB-TOTAL : 1,040.00

AXA-4S (Fri)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305233556
REGN NO : SHC3218J
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.01.2014
DATE/TIME IN : 02.11.2018 09:05
ACCIDENT DATE : 01.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

[Handwritten signature]

TOTAL : 2,191.84

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Kahni UCKY
2/11/18 1330 hr.
3 Pgs
4/5
After Repair photos

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: