

NATIONAL Assessment Centre Services

[wef 1 Jan'05] **MA118143495**

Date In: 5/11/18 - 21:22	Job description	Date & Time Completed	Done by
Ref No: NA/INCIF 20062/B24	SAS e-filing		
Veh No: JLK8789P	E-mail (within 5hrs, AIC 2hrs)		
D.O.A : 4/10/18 - 13:45	i-Motor Claim Form	M7/10/1839-001	5/11/18 21:51
OD : TP : Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by <u>Fax / Hand</u> to <u>Owner/Wksp</u>		

Preferred Wksp / INC Assign Wksp / QW: (Tel:	Fax:
TP Particulars:	Veh No:	INC () / Non-INC ()
Owner / Driver: (Tel:	()
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (Date:	Time: ()
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury :

Date/Time	Actions
	MV 38,000/2
	PV 29,578/2
	NV 8,500/2
	Repair days 12
	TCM 1/11/18

NA1807355	Invoice Preparation Checklist		Amt (\$)	Amt (\$)
			for Bill	Add Bill
Claimant's Particulars :-	1) AR : Accident Reporting (\$30);			
Driver/Owner:	2) DA : Damage Assessment (\$100); INC (\$80)			
Contact No:	3) TF : Towing Fee \$40/\$45			
Damaged Portion:	4) FT : Follow-Through Survey \$120			
QC Checked by (Engr-In-Charge):	5) FT : Follow-Through Survey (Resurvey) \$30			
	For claiming against UNC Only (wef 10 Jan 2005)			
	6) TR : Re-inspection \$75			
	7) N1 : Idac DA + SMRT Survey \$160			
	8) NTUC Additional Services:-			
	OD*			
	*N5: Courtesy Car / Tpt Allowance \$5			
	*N6: Repair Co-ordination \$10			
	*N7: Post Repair Inspection \$25			
	*N8: DV / Collect Excess Coordination \$5			
	TP (N11) : TP (Non INC) against INC \$20			
	9) N12: Idac Mobile 30			
	Invoice dated	Fee Charged		
	Invoice dated	Fee Charged		

Auditors' Comments :-

Ref 1:

Ref 2/3:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 20:22
Date Of Accident	14/10/2018 13:45
Exact Location Of Accident	WOODLANDS DR 14
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB8789P
Insured/Policyholder	
Name Of Registered Owner	DATYN LEASING PTE LTD
Co Reg No	201801727M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	BMW
Model	523I A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098922961
Cover Note Number	

Driver

Name of Driver	RAMLI BIN ACHIN
NRIC No	S1673112I
Date Of Birth	28/10/1964
Occupation	OUTDOOR
Date Of Driving Pass	25/04/1997
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86005710
Fax Number	
Contact Number	OFFICE-86005710
Email Address	NOEMAIL

Address	BLK 556 WOODLANDS DRIVE 53 #06-49
Postcode	730556
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20181014/2097.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Rater to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- ❖ Complete and submit this form to the individual insurance authorised reporting centre.
- ❖ Please report correctly on the details of the accident to speed up the claim process.
- ❖ This form must be filled up by the policy holder and/or authorised driver.
- ❖ Information provided must be as fruitful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- ❖ The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- ❖ Any false reporting may be referred to the traffic police department for investigation.

Accident details

Date and time of accident	Date: 14/10/2015 (DD/MM/YY) Time: 13:45 (HH:MM)
Exact location of accident	Along Road 1 Woodlands Drive 14

Details of vehicle

Vehicle registration number	SKB 8787 P
Vehicle make and model	Bmw 523i
Type of vehicle	Saloon <input checked="" type="checkbox"/> MPV <input type="checkbox"/> CRV <input type="checkbox"/> Van <input type="checkbox"/> Lorry <input type="checkbox"/> Bus <input type="checkbox"/> Motorcycle <input type="checkbox"/> Others: _____
Vehicle category	Private <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Motorcycle <input type="checkbox"/>
Purpose of using at said time	(commercial)
Are you claiming under your own insurance company?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> if no, please select: Third part claim <input type="checkbox"/> Reporting only <input type="checkbox"/>

Insurance information

Insurance company	NTUC
Policy number	
Type of policy	Comprehensive <input checked="" type="checkbox"/> Third party fire & theft <input type="checkbox"/> TP only <input type="checkbox"/>

Insured / Policy holder

Name	DIATIN LEASING PTE LTD	Male <input type="checkbox"/> Female <input type="checkbox"/>
NRIC / Fin / Passport number	20150727M	
Contact		
Address	5001 Beach Road #08-11 (199588) Golden Mile Complex	

Driver

Same as insured above ☐ (skip to D.O.B)

Name	Ramli Bin Achin	Male <input checked="" type="checkbox"/> Female <input type="checkbox"/>
NRIC / Fin / Passport number	S1673112 I	
Contact	8600 5710	
Address	APT BLK WOODLANDS DRIVE #06-41 S 730556	
Email address		
Date of birth	28-10-1969	
Occupation	Indoor <input type="checkbox"/> Outdoor <input checked="" type="checkbox"/>	
Driving date pass	25 April 1997	

General information of the accident

Was driver an employee of the insured's company?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Accident captured by camera?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Weather condition	Clear <input type="checkbox"/> Raining <input checked="" type="checkbox"/> Others: _____
Road surface	Dry <input type="checkbox"/> Wet <input checked="" type="checkbox"/>
No of passenger	1 (Inclusive of driver)

Passenger 1

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Passenger 2

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Passenger 3

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Passenger 4

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Passenger 5

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Passenger 6

Name	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>

Other information

Was anybody injured?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Was other vehicle damaged?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

Details of police action

Reported to police?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> If yes, please state which police station.
Police station name	Jurong West NPC

Third party vehicle 1

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Third party vehicle 2

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Third party vehicle 3

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Third party vehicle 4

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Third party vehicle 5

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Third party vehicle 6

Name	
Contact number	
NRIC / Fin / Passport number	
Vehicle registration number	
Vehicle make model	

Witness 1

Name	
------	--

Witness 2

Name	
------	--

Injured person 1

Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Injured person 2

Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Injured person 3

Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Injured person 4

Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/>	No <input type="checkbox"/>



SINGAPORE POLICE FORCE



T/20181014/2097

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20181014/2097

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/10/2018 20:34		Vide Report No.:		Station Diary No.: 119	
Informant's Particulars					
Name of Informant: RAMLI BIN ACHIN			Address: APT BLK 556 WOODLANDS DRIVE 53 #06-49 SINGAPORE 730556		
ID Type / ID No.: NRIC NO / S1673112I			Contact No.: Home/Office: Mobile: 86005710		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 28/10/1964	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,2A,3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 14/10/2018 01:45	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS DRIVE 14 hump near to passenger pickup point				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKB8789P	Car		BMW 523I	Black	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181014/2097

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20181014/2097

CONTINUATION OF REPORT

Driver			
Name	RAMLI BIN ACHIN	ID No.	S1673112I
Related Vehicle	NIL	Contact No.	86005710
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving my car and going to pick up my passengers from Blk520 Woodlands Dr 14 as I am Grab driver. I entered Woodlands Dr 14 from Woodlands Ave 4 and was searching for my passengers at the vicinity of Blk520. When I approached Blk520 Woodlands Dr 14, I saw my passengers waving at me and I waved back to them. However I did not realize that there is a kerb and road divider in front of me. My car hit on the kerb, 03 poles and 01 white box consists of wire. Traffic police was at scene and advised me to lodge a report and no one is injured.



**SINGAPORE
POLICE FORCE**



T/20181014/2097

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20181014/2097

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J / Sgt 2 BALJIT SINGH GREWAL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/10/2018 20:34
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case: SN 126
Authentication Stamp NP168 	Signature :

Singapore Police Force

1765824



NRIC No: S16731121



David Group Date of issue
B* 07-03-1994

APT BLK 558 WOODLANDS DRIVE 53 #08-48
SINGAPORE 730558
NRIC No: S16731121 Date: 02/08/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	25 Mar 1986
Class 2A	Motorcycles between 201 cc and 400 cc	25 Mar 1986
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	25 Apr 1997
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	01 Sep 1997

NP 428A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S16731121



RAMLI BIN ACHIN
نامی بن اچین
RELAY
Date of birth: 20-10-1964 Sex: M
Country of birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S16731121
Name: RAMLI BIN ACHIN



Birth Date: 28 Oct 1964
Issue Date: 27 Oct 2003





Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5098922961

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SK88789P**
 Chassis Number : WBAFP32090C257688
2. Name of Policyholder : DATYN LEASING PTE LTD
3. Effective Date of Insurance : 15 Mar 2018
4. Expiry Date of Insurance : 14 Mar 2019
5. Persons or Classes of Persons entitled to drive#
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TAN WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : AUTOSHIELD PTE. LTD. (00000573469)
 Date of Issue : 13 Mar 2018 16:28 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5098922961		DATYN LEASING PTE LTD	201801727M	GPC	drive CLASSIC	SKB8789P	SKB8789P	15/03/2018	14/03/2019

Policy Information

Policy No.	5098922961	Policyholder Name	DATYN LEASING PTE LTD	Policyholder NRIC	201801727M
Certificate No.					
Address	5001 BEACH ROAD #08-11 GOLDEN MILE COMPLEX SINGAPORE 199588				
Product Name	PRIVATE CAR INSURANCE	Plan	Group Policy Flag N		
Policy Issue Date	13/03/2018	Effective Date	15/03/2018 00:00	Expiry Date	14/03/2019 23:59
Excess Type	All Claims Excess				
Third Party Excess	1500	Own damage Excess	2000	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	2000	Outside Singapore TP Excess	1500	Young/Inexperience Driver Excess	
Agent	AUTOSHIELD PTE. LTD.	Agent Tel.	63850777	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	5001 BEACH ROAD	Address 2	#08-11 GOLDEN MILE COMPLE	Address 3	SINGAPORE 199588
Address 4			Address Type	Singapore address	Post Code
Unit No.			Related Policy Number	5101941141	199588

Insured Object: SKB8789P

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
1	16/03/2018 00:00	Basic Information Endorsement	Endorsement Undo	<p>Thank you for giving us the opportunity to serve you. We confirm that from 16 Mar 2018, the following policy details are amended as follows: 1. The Policy is extended to cover use for hire or reward. 2. An excess of S\$2,000.00 is imposed under Section 1 of this Policy. 3. An excess of S\$1,500.00 is imposed under Section 2 of this Policy. 4. The Policy does not cover any driver who is below 22 years old or with less than 2 years driving experience. In view of this amendment, an additional premium of \$457.39 (inclusive of GST) is payable under your policy. Please ignore this premium payment request if you have since made payment. Otherwise, we would appreciate it if you could make payment to us within 14 days from the date of this letter. For cheque payment, please issue the cheque in favour of "NTUC Income" with your name and policy number indicated on the reverse of the cheque. Alternatively, you could also make payment at any of our branches by cash, credit card or NETS.</p> <p>Thank you for giving us the opportunity to serve you. We confirm that from 16 Mar 2018, the following amendment(s) is/are</p>

Claim Handling

Exit

Accident MT/1018539

Policy No.	5095922951	Vehicle No.	SKB8789P	GST Registration No.	
Certificate No.					
Policyholder Name	DATYN LEASING PTE LTD			Policyholder NRIC	201801727M
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	0	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	<input type="text"/>
KFK	<input checked="" type="radio"/> No <input type="radio"/> Yes	TCA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	Yes

Accident Details

Report Date	05/11/2018 21:49	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	14/10/2018	Time of Accident (hh:mm)	13:45	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	WOODLANDS DR 14				

Excess

Own damage Excess	2,000.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess	2,000.00		
Third Party Excess	1,500.00	Outside Singapore TP Excess	1,500.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	No
Modification History			

Policyholder Mailing Address

Address 1	5001 BEACH ROAD	Address 2	#08-11 GOLDEN MILE COMPLE	Address 3	SINGAPORE 199588
Address 4		Address Type	Singapore address	Post Code	199588
Unit No.		Related Policy Number	5101941141		

D1 Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	RANLI BON ACHIN	Driver NRIC	S16731121	Driver DOB	28/10/1964
Register Date of Driver License	25/04/1997	Driver Age	53	Driving Experience	21
Contact No.(Mobile)	86005710	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 556	Address 2	WOODLANDS DRIVE 53	Address 3	SINGAPORE 730556
Address 4		Address Type	Singapore address	Post Code	730556
Unit No.	05-40				
Does he own a Singapore Registered car?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
-------------------------------------	------	-------------	---

Modification History

Claim 001 New

Claim Type *	CO-MD	Insured Name	DATYN LEASING PTE LTD	Insured NRIC	201801727M
Contact No.(Mobile)	97521595	Contact No.(Home)		Contact No.(Office)	
Email Address		D1 Vehicle Number	SKB8789P	TP Vehicle Number	
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	SKB8789P ON 14 Oct 2018				
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault	Name of Preferred Workshop	
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	05/11/2018 21:53	Claim Close Date		Date Received	05/11/2018 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	

Save Submit

Attachment

Accident No.	MT/1018539	Claim No.	001
Last Doc. Received	<input checked="" type="radio"/> Yes <input type="radio"/> No	Upload Date	05/11/2018 21:52

Path *	Category *	Confidential	Urgency *	Description *
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Please Select

Please Select

Please Select

Please Select

Please Select

☐ Send Message

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CD)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	SAS	Normal	SAS 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV(CES) on 05 Nov 2018 21:52	Photos	Normal	Photos 2018-11-5		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
<input type="button" value="Display in New Window"/> <input type="button" value="Scan and uploading"/>				

<https://gicclaim.income.com.sg/gcs/icm/eclaim/registrationSave.do>

5/11/2018

ASSIGNMENT (IDAC)

By CSO - Nature of Accident:

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorist () a) Pedestrian ()
- b) Motorcycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn Property () b) Road Work Object ()
(Eg: signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case:
- a) Stolen () b) Damage found ()
when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SKB 8789P Yr Regn: 15/7/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make & Model: BMW 523i c.c. 2497

Colour BLACK Transmission Type: Auto / Manual

Eng/No: 0216737N52B25AF Sp. Reading: 144216

C/No: WBAFP32090C257688

Gen. Cond: Good / Fair / Poor / Burnt or _____

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 255/55/17
R: 255/55/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: 7 Vehicle in Idac: Yes / No

D.O.I. 7/11/18 Time: 1600

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BR	✓	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR	✓	
1005	992341	Frt Bumper Clips	NGC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NGC	✓	
1008	991433	Frt Bumper Reinforcement	?		
1009	991318	Frt Bumper Beam	?		
1010	991468	Frt Bumper Sponge	?		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille L/R	BR	✓	2
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	?		
1021	991793	Frt Grille	?		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel	?		
1029	995153	Frt LH Headlamp Assy	?		
1030	991821	Frt RH Headlamp Assy	?		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	?		
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	?		
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy	?		
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SKB 8789P**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	BR	✓	
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt	?		
1088	990950	Engine Mounting LH	?		
1089	990952	Engine Mounting RH	?		
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member	?		
1096	995070	Frt LH Fender	SCR	R	X
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	SCR	R	X
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Bumper Emblem	NGC	✓	

No of Items: **23**

ASTRONOM

TGCim *lun* 7/11/18

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Pin (06) Scratched
 (07) Deformed (08) Blended (09) Functional (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Not Insured (15) Not Working

MOTOR CAR (LH)

ACTION (C)

(1) Replace (2) Repair (3) Check (4)
 (5) Not Considered (6) C

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	SCR	R	X
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SKB 8789P

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	SCR	R	X
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1147	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender	SCR	R	X
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: 3

Assessor:

Repair days 12

TCM

Wm

7/11/18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1727M
Vehicle Details	
Vehicle No.:	SKB8789P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	02167373N52B25AF
Chassis No.:	WBAFP32090C257688
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,550.00
Original Registration Date:	15 Jul 2010
First Registration Date:	15 Jul 2010
Transfer Count:	3
Actual ARF Paid:	\$41,550.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2020
PARF Rebate Amount:	\$22,852.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$6,726.00
Total Rebate Amount:	\$29,578.00

The information contained herein is correct as at 07 Nov 2018

OK

Dep 12,270/4v
1023/mtw

MV 38,000/2
PV 29,578/2
NV 8,500/2

lin

7/11/18

**BMW 5 Series 523i Highline**

-

N.A

13-Dec-2010

2,497 cc

-

Luxury

SOLD

Fully Maintained And Service By PML Agent. Still Got 1 Free Servicing At PML. High PARF Paper Rebate Of Plus Body Total \$48000. Flexible Loan And Insurance Packages Available! Offer High Trade In! Luxur...

Posted: 30-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$43,900****\$12,250 /yr**

30-Jul-2010

2,497 cc

131,889 km

Luxury

Available

Original Grey With Beige Interior, 20" Sportsrims, Non-Smoker Owner, Well Maintained Exterior And Interior By Owner, With Pml Records Available, Accident-Free. Highline Model. Luxurious And Spacious C...

Posted: 28-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$39,800****\$12,270 /yr**

28-Jun-2010

2,497 cc

174,755 km

Luxury

Available

Completely Stock With No Modifications, Nice Beige Exterior With Cream Leather Interior. Low Depreciation! Trade In Welcome, Consignment Unit, Call Us For No Obligation Viewing Now.

Car Search

Posted: 28-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

PREMIUM AD**Compare your car insurance quotations!**

Save 25% on your car insurance, compare your quote from 10 insurers! Make your choice on zero excess and own workshop! Get your cheaper quote now!

Find out more!

**BMW 5 Series 523i Highline****\$43,500****\$13,680 /yr**

21-May-2010

2,497 cc

150,000 km

Luxury

Available

Original Grey With Dark Grey Interior, Non-smoker Owner, Well Maintained Exterior And Interior By Owner, With PML Records Available, Accident-free. Highline Model. Luxurious And Spacious Cabin. For Yo...

Car Empire Automobiles Pte Ltd

Posted: 27-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i**

-

N.A

31-May-2010

2,497 cc

-

Luxury

SOLD

Full Agent Maintained! Low Mileage! Your Most Suitable Choice Of Continental Ride! Pull Through The Years Of Buying Pre-Owned Cars With High COE Value To Reduce On The Depreciation Value With High PAR...

Posted: 25-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i**

-

N.A

15-Dec-2010

2,497 cc

-

Luxury

SOLD

Well Maintained By Careful Owner, Negotiable. Major Services Recently Completed.

Posted: 24-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

DIRECT OWNER**BMW 5 Series 523i**

-

N.A

28-Jun-2010

2,497 cc

-

Luxury

SOLD

1 Owner Sapphire Black F10! 100% Loan Approval Rate! 15% Down Payment Available. Offer Flexible Loan And Insurance Packages, No Chassis Or Structural Damage. Most Wear And Tear Has Been Replaced Inclu...

Posted: 23-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i**

-

N.A

03-Dec-2010

2,497 cc

-

Luxury

SOLD

Definitely One Of The Best Condition Blue F10 In The Market! Super Well Maintained By Previous Owner! 100% Accident Free! STA Evaluation Welcome! View To Believe! High Loan Available! High Trade In Fo...

Posted: 17-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i**

-

N.A

26-May-2010

2,497 cc

-

Luxury

SOLD

Full Stock, Ultra Healthy Condition Unit, The Most Problem Free F10 5 Series. Pure 2.5L Power With No Turbo Or Supercharge Which Make Maintenance Lesser And Also Much More Durable And Reliable. Spacio...

Posted: 16-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i Highline**

-

N.A

27-Oct-2010

2,497 cc

-

Luxury

SOLD

Fully Maintained/Service In PML Road Tax Just Renewed Till Apr 2019! High Bank Loans Available Up To 90%! Fast Approval. Almost As Good As New. Superb Low Mileage Clocked From Previous Expat Owner R...

Tradelt.Com Pte Ltd

Posted: 16-Oct-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

PREMIUM AD

Compare [1]

BMW 5 Series 523i Highline

-

N.A

27-Oct-2010

2,497 cc

-

Luxury

SOLD

Select used cars to **Compare** or **Add to Alert**

Shortlist [1]



BMW 5 Series 523i

28-Jun-2010

To compare cars, select from the search results.

To compare cars, select from the search results.

To compare cars, select from the search results.

Add to Shortlist

Compare Now

Clear All

Claim Handling

Task Transfer Exit

Accident MT/1018539

LOG SAVE SUB

Policy No.	S098922961	Vehicle No.	SKB8789P	GST Registration No.	
Certificate No.					
Policyholder Name	DATYN LEASING PTE LTD			Policyholder NRIC	201801727M
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	0	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	11
KFA	<input checked="" type="radio"/> No <input type="radio"/> Yes	TCA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	Yes

Accident Details

Report Date	05/11/2018 21:49	Accident Report Within 24 hrs	No	Accident Type	Collided into Property
Date of Accident	14/10/2018	Time of Accident hh:mm	13:45	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	WOODLANDS DR 14				

Excess

Own damage Excess	2,000.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess	2,000.00		
Third Party Excess	1,500.00	Outside Singapore TP Excess	1,500.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date		GST Status Verified	Yes
GST Registration No.					
Modification History	07/11/2018 10:22:14 Deborah Mui changed GST Status verified from No to Yes				

Policyholder Mailing Address

Address 1	5001 BEACH ROAD	Address 2	#08-11 GOLDEN MILE COMPLE	Address 3	SINGAPORE 199588
Address 4		Address Type	Singapore address	Post Code	199588
Unit No.		Related Policy Number	S101941141		

OS Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	28/10/1964
Unnamed driver Name	RAMLI BEN ACHON	Driver NRIC	S16731121	Driving Experience	21
Register Date of Driver License	25/04/1997	Driver Age	53	Contact No.(Home)	0
Contact No.(Mobile)	86005710	Contact No.(Office)	0	Address 3	SINGAPORE 730556
Address 1	BLK 556	Address 2	WOODLANDS DRIVE 53	Post Code	730556
Address 4		Address Type	Singapore address		
Unit No.	06-49				
Does he own a Singapore Registered car?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No		
Modification History	07/11/2018 17:18 s025755 Modify Accident Report Within 24 hrs(Yes->No)				

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimie Bin Mantau

LOG SAVE SUB

Claim Type	OD-MD	Insured Name	DATYN LEASING PTE LTD	Insured NRIC	201801727M
Contact No.(Mobile)	87521595	Contact No.(Home)		Contact No.(Office)	
Email Address		OT Vehicle Number	SKB8789P	TP Vehicle Number	
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	SKB8789P ON 14 Oct 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	income to assign workshop	GIA report	Received
Date Registered	05/11/2018 21:53	Claim Close Date		Date Received	05/11/2018 00:00
Report Taken By	Jeckson	Workshop Repairer		Total Loss but Repaired	
<input checked="" type="checkbox"/> Print AK letter				OD Excess Collected by Workshop	
Modification History					

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	BMW	Vehicle Model	523i	Engine Capacity	
Date of Registration	15/07/2010	Class No.	WBAPP32090C257688		
Towing Required *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Vehicle in IDAC *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Parallel Import *	<input type="radio"/> Yes <input checked="" type="radio"/> No

Type of Tender *	Own Damage	Assessor Name *	TG LIM	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTRE	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cust		Total Loss *	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Market Value(\$)		Scrap Value(\$)		Economical Repair Value(\$)
REMARK: NO OF REPAIR DAY: 12 DAYS				
Remark:				
Remark for Supplementary:				

Damage Listing

Find a Part

root

- Not Applicable
- ABS
- ABSORBER
- ACCELERATOR
- ACTUATOR
- ADVERTISEMENT STICKER
- AIR BAG
- AIR BLOWER
- AIR BOX
- AIR CHAMBER BOX
- AIR CLEANER
- AIR COMPRESSOR
- AIR CON
- AIR CON (VAN)
- AIR COOLER
- AIR DISTRIBUTOR
- AIR FILTER
- AIR FLOW
- AIR GRILLE
- AIR HORN
- AIR INTAKE
- AIR RESONATOR BOX
- AIR THROTTLE BODY AND SENSOR
- ALARM
- ALTERNATOR
- ALUMINUM PANEL - SIDE
- AMPLIFIER
- ANTENNA
- ANTI ROLL
- APRON
- ARCH
- ARM REST
- ASH TRAY
- AUTO CLUTCH
- AUTO COOLER PIPE
- AUTO CRUISE MOTOR
- AUTO TRANSMISSION
- AXLE

No.	Part No.	Description	Qty *	Repair Code *	
1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
2	16000101	BUMPER (FRONT)	1	Replace	X
3	16002401	BUMPER CLIPS (FRONT)	1	Replace	X
4	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
5	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
6	16001001	BUMPER BEAM (FRONT)	1	Unconfirm	X
7	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm	X
8	16003201	BUMPER GRILLE (FRONT)	2	Replace	X
9	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	X
10	15600101	BRACE PANEL (FRONT)	1	Unconfirm	X
11	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
12	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	X
13	112023	AIR CON CONDENSER	1	Unconfirm	X
14	344001	RADIATOR	1	Unconfirm	X
15	344008	RADIATOR FAN	1	Unconfirm	X
16	243014	ENGINE LOWER COVER	1	Replace	X
17	24301903	ENGINE MOUNTING (FRONT)	1	Unconfirm	X
18	23300201	DOOR (FRONT LEFT)	1	Repair	X
19	23300203	DOOR (REAR LEFT)	1	Repair	X
20	25400105	FENDER (REAR LEFT)	1	Repair	X
21	24301904	ENGINE MOUNTING (LEFT)	1	Unconfirm	X
22	24301906	ENGINE MOUNTING (RIGHT)	1	Unconfirm	X
23	22200101	CROSS MEMBER (FRONT)	1	Unconfirm	X
24	25400102	FENDER (FRONT LEFT)	1	Repair	X
25	25400103	FENDER (FRONT RIGHT)	1	Repair	X
26	16002601	BUMPER EMBLEM (FRONT)	1	Replace	X



NATIONAL ASSESSMENT CENTRE SERVICES

(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SLC8789P Date In: 21/10/05 Time In: 16:00 with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Bodyfix

Collection Date: 9/11 Time: 1620 with Keys: Yes / No

Tow Truck No: YK 6230T Tow Man: Jimmy Tay NRIC: S8617581J

Signature: 933/1494

For office use

Attended by: _____

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Friday, 9 November 2018 3:45 PM
To: AMKAUTOPOINT; LKK Paya Ubi
Subject: FW: SKB8789P UNDER OD CLAIM: MT/1018539

Dear Autopoint

Please tow this vehicle from Idac and contact Mr Augustine of Datyn Leasing at 97521595 when the repair is done, OD excess \$2000.

Our Ref: MT/CA/OD/051/1018539-001/NHJ

09 Nov 2018

AMK AUTOPOINT PTE LTD

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A

#01-22 AMK AUTOPOINT

SINGAPORE 568047

Dear Sir

CLAIM NUMBER: MT/1018539-001

REPAIR OF VEHICLE NUMBER: SKB8789P

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 09 Nov 2018

Make: BMW

Model: 523i

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 2000.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank You

Ng Hak Joo

Iata-Uftaa-Itc, Anziif (Aff)

Executive

Motor Insurance

T +65 64307890

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.