

ASS. REC. BY:

REF:

(S3 / CT18020085 / Gcbez)

Special Instruction:

Surveyor
Maiman

92

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

02-11-2018 4:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 3086A

Insured:

SLX 2338U

at Workshop m/s

Auburn Auto

Tel:

9619 1525

of

176 Sin Ming Driv #04-18

Policy No:

DmpCSN1813561800

Claim No:

SNM18D05037102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Wp

after 2pm

H.O.D. Endorsement:

Date/Time:

07-11-2018 9:05am

Person Contacted:

Eric

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

05-11-2018 @ 10:30 am Jaron check wksp number got another contact number

@ 3:12 pm - Jaron ask me call wksp on 07-11-2018 - repairer oversea.

SJA 3086A - x

SLX 2338U - x

(08/11/13)

Surveys

Red.

REF:

Gi

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Auburn Auto

of

#04-18 Auto Care

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

STQ3086A

Yr Regn:

Apr / 09

Type: ☒ Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan sylphy c.c. 1498

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

150928

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No:

JN1BAAG118.0107111

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

07-11-18

Survey held at

WS

4pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 4

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

150

Transportation:

☐

Interview (\$

Photos

☐

Tech. Invs (\$

Others

☐

Weekend (\$

Report Format: PRE

Lump Sum / I.B.I: (\$ _____)

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MDM LAI SOK KENG, ID: S6923461E		
Main Claimant:	ELJ FLEET MANAGEMENT PTE LTD, Co. Reg. No.: 201801120H		
Vehicle Reg. No.:	SJQ3086A	Date of Loss:	20/10/2018 22:00 - :59
Claim Type:	TP / SNM18D05037C02	Policy/Cover Note No.:	DMPCSN1813561800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLX2338U	Policy No. (Claimant):	5098276679
		Excess:	S\$0.00
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]		
Driver/Custodian (Insured):	LINUS LIM XUN YI (18 / Male), NRIC: S9941464B, Tel: +6584183169		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJQ3086A		
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	SYLPHY 1.5 4AT		
Chassis No. :	JN1BAAG11Z0107111		
Propellant :	Petrol		
Engine No. :	HR15061456B		
Engine Capacity :	1498 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1520 kg		
Unladen Weight :	1175 kg		
Year Of Manufacture :	2008		
Original Registration Date :	30 Apr 2009		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$7,589.00		
COE Expiry Date :	29 Apr 2019		
Road Tax Expiry Date :	29 Apr 2019		
PARF Eligibility Expiry Date :	29 Apr 2019		
Inspection Due Date :	29 Apr 2020		
Intended Transfer Date :	08 Nov 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1120H
Vehicle Details	
Vehicle No.:	SJQ3086A
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5 4AT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	HR15061456B
Chassis No.:	JN1BAAG11Z0107111
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$20,038.00
Original Registration Date:	30 Apr 2009
First Registration Date:	30 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$20,038.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2019
PARF Rebate Amount:	\$10,019.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,589.00
COE Rebate Amount:	\$360.00
Total Rebate Amount:	\$10,379.00

The information contained herein is correct as at 08 Nov 2018

OK

MVA218140945 / VAC - Sin Ming
ENTRY DATE & TIME: 30/10/2018 16:11
SUBMITTED BY: James Ng Wing Kin

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 30/10/2018 16:22

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2018 16:11
Date Of Accident	20/10/2018 22:00
Exact Location Of Accident	AMK AVE 10 JUNCTION ITE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ3086A
Insured/Policyholder	
Name Of Registered Owner	ELJ FLEET MANAGEMENT PTE LTD
Co Reg No	201801120H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93688585
Alternative Phone No	Office-93688585

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5098276679
Cover Note Number	

Driver

Name of Driver	MICHELLE ELLEN LEE HUI CHEN
NRIC No	S8906408B
Date Of Birth	21/02/1989
Occupation	INDOOR
Date Of Driving Pass	30/01/2018
Driving Experience	0 YEAR AND 8 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97583568

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 124A RIVERVALE DRIVE #02-201

Postcode

541124

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

SENGKANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025
, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800 - 3438999 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLX2338U

Vehicle Make/Model/Colour

HONDA STREAM / RED

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LINUS LIM XUN YI

NRIC/Passport Number

S9941464B

11/8/2018

E-FILE

Contact Number 84183169
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MICHELLE ELLEN LEE HUI CHEN
Approximate Age 29
Injuries Sustain NECK PAIN, NAUSEA, GIDDY
Injured person in which vehicle? SJQ3086A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLK 124 RIVERVALE DRIVE #02-201
Postcode 541124

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

26 OCT 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: NG WING KIN JAMES
S7927881E

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
Police
Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Signature
Date & Time:

26 OCT 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's signature

Name: NG WING KIN JAMES
NRIC/FIN No.: S7927881E

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20181021/2081

1 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20181021/2081

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2018 21:22		Vide Report No.:		Station Diary No.: 134	
Informant's Particulars					
Name of Informant: MICHELLE ELLEN LEE HUI CHEN			Address: APT BLK 124A RIVERVALE DRIVE #02-201 SINGAPORE 541124		
ID Type / ID No.: NRIC NO / S8906408B			Contact No.: Home/Office: Mobile: 97583568		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 29	Date of Birth: 21/02/1989	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Pet groomer			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 20/10/2018 22:00	Type of Location: Traffic Light
Location: Along Road 1 ANG MO KIO AVENUE 10 Along Ang Mo Kio Avenue 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ3086A	Car	NISSAN	SYLPHY 1.5 4AT	Brown		0
SLX2338U	Car	HONDA	STREAM 1.8 RSZ A	Red		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20181021/2081

2 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20181021/2081

CONTINUATION OF REPORT

Driver			
Name	MICHELLE ELLEN LEE HUI CHEN	ID No.	S8906408B
Related Vehicle	SJQ3086A (Car)	Contact No.	97583568
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/10/2018	Date Discharge	21/10/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Driver			
Name	LINUS LIM XUN YI	ID No.	S9941464B
Related Vehicle	SLX2338U (Car)	Contact No.	84183169
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/10/2018 at about 2200hrs, I was driving along Ang Mo Kio Avenue 10 when I came to a complete stop at a traffic light. I was on the most right lane, about to make a right turn. When the traffic light turned green, I immediately felt an impact on the back of my vehicle. I got off my vehicle to make a check, the rear bumper and the boot of my vehicle was damaged. We exchanged our particulars and drove off.

I wish to state that no police attended to my accident, no one was conveyed to the hospital. I am lodging this report for vehicle insurance and medical claims purposes. That is all.

Sketch Plan #5

**SINGAPORE
POLICE FORCE**

T/20181021/2081

3 of 3

Report No. T/20181021/2081

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 LEE LI TING, JOLYNE

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
21/10/2018 21:22

Classification Of Case:

Sketch Plan #6

ELJ FLEET MANAGEMENT PTE LTD.
UEN 201801120 H.

This is to confirm that the vehicle SJQ 3086 A was
rented to Ms Michelle Ellen Lee Hui Chen from 7 Sept 2018
to 19 April 2019 for personal use.



Scanned with CamScanner

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 16:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case


Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MDM LAI SOK KENG, ID: S6923461E								
Main Claimant:	ELJ FLEET MANAGEMENT PTE LTD, Co. Reg. No.: 201801120H								
Vehicle Reg. No.:	SJQ3086A	Date of Loss:	20/10/2018 22:00 - :59 [113 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05037C02	Policy/Cover Note No.:	DMPCSN1813561800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX2338U	Policy No. (Claimant):	5098276679						
		Excess:	S\$0.00						
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/11/2018]								
Driver/Custodian (Insured):	LINUS LIM XUN YI (18 / Male), NRIC: S9941464B, Tel: +6584183169								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									







Claim Documents

*SJQ3086A (SNM18D05037C02)
[SLX2338U]
TP
ELJ FLEET MANAGEMENT PTE LTD
Oct 20 2018 10:00PM
[MDM LAI SOK KENG]
Auburn Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	30/10/18 16:22	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	30/10/18 16:21	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	08/11/18 16:41	General View							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	02/11/18 16:11	PRS							Load PDF		
2	02/11/18 16:11	OI GIA							Load PDF		
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	30/10/18 16:21	Sketch Plan [Linked Accident Report Documents]							Load TIF		
2	30/10/18 16:21	Sketch Plan #2 [Linked Accident Report Documents]							Load TIF		
3	30/10/18 16:21	Sketch Plan #3 [Linked Accident Report Documents]							Load TIF		
4	30/10/18 16:21	Sketch Plan #4 [Linked Accident Report Documents]							Load TIF		
5	30/10/18 16:21	Sketch Plan #5 [Linked Accident Report Documents]							Load TIF		
6	30/10/18 16:21	Sketch Plan #6 [Linked Accident Report Documents]							Load TIF		

Linked Accident Report Documents

										View <input type="button" value="View in Browser"/>	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)								Thumbnail	Print
1	30/10/18 16:22	Accident Statement								 Load HTM	
Photos/Images											

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	30/10/18 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	30/10/18 16:21	Sketch Plan	 Load TIF	
2	30/10/18 16:21	Sketch Plan #2	 Load TIF	
3	30/10/18 16:21	Sketch Plan #3	 Load TIF	
4	30/10/18 16:21	Sketch Plan #4	 Load TIF	
5	30/10/18 16:21	Sketch Plan #5	 Load TIF	
6	30/10/18 16:21	Sketch Plan #6	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT18020085/GCBE2

Date: 09/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1813561800

Claimant Vehicle
No: SJQ3086AInsured Vehicle
No: SLX2338U

Date of Loss: 20/10/2018

Nature of Claim: TP

Claim
No: SNM18D05037C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ3086A

Make & Model: NISSAN SYLPHY, 1.5 (A)

Reg. Date: 30/04/2009 (Man. Year: 2008)

Colour: Grey

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: HR15061456B

Chassis No: JN1BAAG11Z0107111

Odometer: 150928 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2018

Date Inspected: 07/11/2018 Inspected At:

Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2018)
Parts: 143	NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ3086A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >