

ASS. REC. BY:

REF:

CS3 / III/8020134 / K143

Special Instruction:

Surveyor: KalvinASSIGNMENT (Office)From (Person): Joel Noh

of

IIIDate/Time: 07-11-2018 253pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 8029A

Insured:

SHC 8764R

at Workshop m/s

Michelin Engineering

Tel:

88233003

of

5b Luyang Way #06-0764404928Policy No: MCOM0015

Claim No:

MCT18100981

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 07-11-2018 3:17pm

Person Contacted:

RizanVehicle: IN / 014

Date/Time

Action/Instruction (X) Estimate

GBH 8029A - XSHC 8764R - CS3 / IGL18019887 / K143DA: 31-10-2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1 Vehicle Not In

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019 Edit Reg		07 Nov 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R		
Vehicle Reg. No.:	GBH8029A	Date of Loss:	31/10/2018 11:00 - :59
Claim Type:	TP / MCT18100981	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHC8764R	Policy No. (Claimant):	
		Excess:	
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 16/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 7 November, 2018 2:53 PM
To: Catherine Chong (LKK Auto)
Cc: Yvonne; Mekavathanan Sarangapani; Pooi Chin Han Daniel
Subject: FW: India Insured SHC8764R [EAL.2018.6035.MK.ya - GBH8029A]
Attachments: 181107-GIA report GBH8029A(new).pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : GBH8029A
III INSURED VEHICLE NO. : SHC8764R
DATE OF LOSS : 31/10/2018

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK to conduct the pre-repair survey.

This claim is handled by **daniel**

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Joel Nah
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 206 Fax: 6224 4174

SHC8764R

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

India International Insurance Pte Ltd
64 Cecil Street,
#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **SHC8764R**
Comfort Transportation Pte Ltd
383 Sin Ming Drive
GAS Building
Singapore 575717

Dear Sir/Madam,

CLAIMANT: PAN PACIFIC VAN & TRUCK LEASING PTE LTD
ACCIDENT INVOLVING GBH8029A & SHC8764R ON 31 OCTOBER 2018 ALONG CHOA CHU KANG AVENUE 2 AT ABOUT 1150 HOURS

We are instructed by **PAN PACIFIC VAN & TRUCK LEASING PTE LTD** to notify you (the insurer of **SHC8764R**) of a road traffic accident on **31 OCTOBER 2018 ALONG CHOA CHU KANG AVENUE 2 AT ABOUT 1150 HOURS** involving our client's vehicle registration number **GBH8029A** and vehicle registration number **SHC8764R** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **GBH8029A** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Dennis Yap Teck Wee - Pal's Appraiser Pte Ltd
4. Yap Teck Chye - Mc-Coy appraiser Pte Ltd

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Celine Fong (LKKAUTO)


From: Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Sent: Friday, 16 August 2019 1:52 PM
To: Admin-D (LKKAUTO); Motor Claim - III
Cc: assignments
Subject: III Ref: MCT18100981 RE: [Resend PRI] India Insured SHC8764R [EAL.2018.6035.MK.ya - GBH8029A]

Dear Nivita,

We refer to your email below.

PRI cannot be conducted after almost a year later. Moreover we have a video recording that shows that TP had reversed and hit into IV. Video is uploaded in merimen along with TP GIA report.

Please arrange to deny this claim after going through the video and GIA reports.



A: GBH8029A

B: SHC 8764R

Daniel Pooi

**Motor Claims Department
India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company



From: Admin-D (LKKAUTO) [mailto:admin-d@lkkauto.com]
Sent: Friday, 16 August, 2019 11:27 AM
To: Motor Claim - III <motorclaim@iii.com.sg>; Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: [Resend PRI] India Insured SHC8764R [EAL.2018.6035.MK.ya - GBH8029A]

Dear Daniel,

Please be informed that we were still pending for survey arrangement due to unavailability of the owner.

We manage to call the workshop again and has arranged for the survey on 20/08/2019.

Best Regards

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2018 12:47
Date Of Accident	31/10/2018 11:50
Exact Location Of Accident	CHOA CHU KANG AVENUE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH8029A
Insured/Policyholder	
Name Of Registered Owner	PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Co Reg No	201511635R
Email Address	PANPACIFICLEASING22@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64404428

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5MT 5DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ18-000183
Cover Note Number	01/10/2018 TO 30/09/2010

Driver

Name of Driver	WONG CHENG MUN
NRIC No	S8927593H
Date Of Birth	13/08/1989
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92316672
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 557 WOODLANDS DRIVE 53 #06-67 (S) 730557
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : AH HUI
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with police report t/20181031/2053

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8764R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SHEN PACIFIC VAN & TRUCK LEASING PTE. LTD.
CO. REG. NO: 201611635R
NO. 32 JOO CHAIY ROAD
SINGAPORE 427371
TEL: 6440 4428 FAX: 6445 3516

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

1254 pm
2/11/18



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: GBH8029A

B. SHC 8764R

Refer with police report T/20181031/257

I hereby declare the foregoing particulars are true in every respect.

CO. REG. NO: 201511535R
NO. 52 JOO CHIAT ROAD
SINGAPORE 427374

TEL: 8440 4428 FAX: 6345 0516

Policyholder's Signature: _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

1254 pm
2/11/18



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181031/2053

1 of 3

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20181031/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/10/2018 13:04		Vide Report No.: J/20181031/0078		Station Diary No.: 63	
Informant's Particulars					
Name of Informant: WONG CHENG MUN			Address: APT BLK 557 WOODLANDS DRIVE 53 #06-67 SINGAPORE 730557		
ID Type / ID No.: NRIC NO / S8927593H			Contact No.: Home/Office: Mobile: 92316672		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 13/08/1989	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: INTERIOR CONTRACTOR			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/10/2018 11:50	Type of Location: T-Junction
Location: Along Road 1 CHOA CHU KANG AVENUE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBH8029A	Van				Slightly Damaged	0
SHC8764R	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181031/2053

2 of 3

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20181031/2053

CONTINUATION OF REPORT

Driver			
Name	WONG CHENG MUN		ID No. S8927593H
Related Vehicle	GBH8029A (Van)		Contact No. 92316672
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Unknown		ID No. NIL
Related Vehicle	SHC8764R (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 31/10/2018 at about 1150hrs, I was about to exit the cluster near Blk 276 Choa Chu Kang Ave 2 when suddenly, I felt a collision on the rear of my vehicle. I alighted and noticed a taxi, bearing the registration plate number SHC8764R, had collided onto the rear of my vehicle.

No TP or Ambulance attended to the scene, and nobody was injured. However, Police attended as a dispute broke out between the taxi driver and me. There was a small scratch on the rear of my vehicle. I did not manage to get particulars of the tax driver before he drove off.



**SINGAPORE
POLICE FORCE**



T/20181031/2053

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3


Report No. T/20181031/2053

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 3 LAM SIANG LIAN 	
Signature Of Interpreter: _____ Not applicable	
Singapore Police Force	
Officer In Charge Of Case: TP / GIT / Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN Contact No.: 65476185	

Authentication Stamp
NP168

Signature Of Informant: 
Date/Time: 31/10/2018 13:04
Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	635R
Vehicle Details	
Vehicle No.:	GBH8029A
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25424707A
Chassis No.:	JN1MC2E26Z0009196
Maximum Power Output:	-
Open Market Value:	\$25,062.00
Original Registration Date:	01 Oct 2018
First Registration Date:	01 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,104.00
COE Rebate Amount:	\$24,649.00
Total Rebate Amount:	\$24,649.00

The information contained herein is correct as at 26 Aug 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI Vehicle Not In

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2019 Edit Reg		07 Nov 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD , Co. Reg. No.: 201511635R								
Vehicle Reg. No.:	GBH8029A	Date of Loss:	31/10/2018 11:00 - :59 [30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18100981	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC8764R	Policy No. (Claimant):							
		Excess:							
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 16/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH8029A (MCT18100981)**
[SHC8764R]

TP

PAN PACIFIC VAN & TRUCK LEASING PTE LTD

Oct 31 2018 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

Michelin Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/08/19 11:10	Video - Accident IV	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
16	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
17	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
18	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
20	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
21	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
22	21/08/19 08:54	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 09:06	Singapore Accident Statement	Load PDF	
2	16/08/19 13:42	Singapore Accident Statement TP GBH8029A	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18020134/K1CF3S2
Date: 12/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : GBH8029A **Insured Vehicle No :** SHC8764R
 Date of Loss: 31/10/2018 Nature of Claim: TP Claim No: MCT18100981

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH8029A**
 Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A) Engine No: YD25424707A
 Reg. Date: 01/10/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009196
 Colour: Silver Odometer: 23464 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/11/2018
 Date Inspected: 20/08/2019 Inspected At: Michelin Engineering Pte Ltd (HQ)
 56 Loyang Way, #06-07 Loyang Enterprise Building,
 Singapore 508775
 Estimated Period of Repair: 0.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Sep 2019)

Parts: N/A NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH8029A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >