

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Plus/Less	Repair Estimates	SLS 8807 U	
Total of Cost / List \$ 1,510.67 (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on : at	Parts (a) Cost / List Price Items	\$ 2,014.22	
(b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor Company Survey conducted on at	Plus/Less 25%	\$ 503.56	
Total of Nett Item (c) Special Nett Items Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :	Total of Cost / List	\$ 1,510.67	
Total of Nett Item (c) Special Nett Items Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :	(b) Nett Price Items		
(c) Special Nett Items Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :at	Less		
Total Parts Cost Labour \$ 1,480.00 Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :	Total of Nett Item		
Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :	(c) Special Nett Items		
Total \$ 2,990.67 The above total will be subjected to 7% G.S.T. Name of Surveyor : Company : Survey conducted on :	Total Parts Cost		
Name of Surveyor : Company : Survey conducted on :at	Labour	\$ 1,480.00	
Name of Surveyor : Company : Survey conducted on :	Total	\$ 2,990.67	
Company :atat	The above total will be subjected to	% G.S.T.	
Company :atat			
Survey conducted on :at	Name of Surveyor		
Carvey Contaction on	Company		
Remarks By Surveyor	Survey conducted on	:at	
Nemarks by Surveyor	Pomarks By Surveyor		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		uthorized / is not authorized until further notice.	
(b) Recommended Days of Repair :day(s)	·		
(c) Resurvey : Required / Not Required	. ,		
(0) (1000.10)	(o) rosarvoy		
(d) Excess :\$	(d) Excess	;\$ <u> </u>	
(e) Signature of surveyor : Date:	(e) Signature of surveyor	: Date:	



ESTEEM PERFORMANCE PTE LTD

PLP Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

S	p	a	r	е	P	a	r	ts	

Vehicle No. :	SLS 8807 U	Submit By	% *	Carmen Lim
Make & Model:	TOYOTA PRIUS	Year Manufacture	:	2017
Chassis No :	JTDKB3FU403571911	Engine No.	;	
***************************************		Cost/List		

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	1	\$450.80		
2	Front bumper clip	10	\$40.00		
3	Front bumper side retainer LH	1	\$107.20		
4	Front bumper emblem	1	\$87.10		
5	LH front fender	. 1	\$868.70		
6	LH front fender undershield	1	\$195.60		
7	LH front fender undershield clip	10	\$25.00		
8	LHF fender wording "HYBRID"	1	\$44.17		
9	LH rear hub cab	1	\$195.65		
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23				<u>.</u>	1

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	_	٠.	_		
L	а	n	O	u	ır

Vehicle No.	:	SLS 8807 U	Submit By :_	Carmen Lim
Make & Model	:	TOYOTA PRIUS	Year of Manufacture:	2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,LHF FENDER)	\$600.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,LHF FENDER)	\$600.00	
3	To check wiring	\$50.00	
4	To do wheel alignment	\$150.00	
5	To tuff coat	\$80.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

atoresato.	
	ACCIDENT STATEMENT
Date Of Report	18/08/2018 21:31
Date Of Accident	18/08/2018 14:10
Exact Location Of Accident	DEMPSEY RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLS8807U
Insured/Policyholder	

Name Of Registered Owner GRAB RENTALS PTE LTD

Co Reg No 201617200G Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-66550005

Vehicle Particulars

Manufacturer TOYOTA
Model PRIUS HYBRID

Exact Purpose for which vehicle was being used at

time of accident

HIRE & REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number A29069766MKF

Cover Note Number

Driver

Name of Driver

NRIC No

S0189129D

Date Of Birth

Occupation

Date Of Driving Pass

LAU TONG LEE

S0189129D

OUTDOOR

14/11/1984

Driving Experience 33 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96477758

Fax Number

Contact Number

EMail Address NOEMAIL

APT BLK 180 BOON LAY DRIVE Address

#07-676

641180 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

NO

1

NO

NO

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

I was driving straight along Dempsey hill when suddenly Veh b make a right turn and collided with my car. My left portion was scratch and no injury involved.

Attachment(s)

Are accident photos available for attachment?

YES NO

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJT8708R

Vehicle Make/Model/Colour TOYOTA / PICNIC AUTO

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN DRIVER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

- 1. Please report correctly the details of the socident to speed up the Claims process
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any within interpresentation or withholding of material facts may allow insurance companies to report distributions and acceptance of this form by insurance companies is not an admission of policy liability on the part of trisurance companies.
 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of trisurance Association.
 5. Any lates reporting may be referred to the Policy for Investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association.
 7. By the lodgement of his report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made evaluable aforesaid.
 8. Consent under the Porsonal Date Protection Act (PDPA)
 1. Understand, spicnowedge, gares and consent that:
 (a) Ny insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are parmillad to colect, use, declose and/or process my personal distributions and particular and any workshop and the General Insurance Association of Singapore ("GIA") may/are parmillad to colect, use, declose and/or my insurance (collactivery the Personal Information and only insurance (collactivery the Personal Information and other languages and provided by me or possessed by process or personal distributions and provided by the process of the responsibility of the process of the responsibility of the process of the responsibility of the process of the proce

VERIFIED BY ALAX MARS REPORTING OFFICER Md ShariL

Witnessed by Reporting Centre Personnal

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters	3
-------------------------------------	---

was driving straight along Dempsey hi collided with my car. My left portion was	ll when suddenly Veh b make a right turn and s scratch and no injury involved.
Taxi Voucher No.:	
ECLARATION	
We declare that the above particulars & information provi	ided above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER -	
MOHAMED SHARIL BIN SATAR	$\left(\begin{array}{c} 1 \\ 1 \end{array} \right)$
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
•	
MARS Officer	Registered Owner or Driver's Signature
ob Complete Date/Time	Date/Time:
18 August 2018 at 4:50 PM	18 August 2018 at 4:50 PM
TO MANAGE AND OF THE	70 / Mgdot 20 (0 dt 7/00) (4)

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

05 Nov 2018 / 11:33:29

Receipt Date/Time: 05 Nov 2018 / 11:33:29

Tax Invoice/Receipt

Receipt No.: ITNET-00000-181105-000714

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No. Result of Insurance Enquiry - SJT8708R As at 18 Aug 2018/14:10:00			Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Insurance Co: AXA INSURANCE PTE LTD					
1 Insurance Enquiry - SJT8708R Enquiry Fee 20181105113250599548			7.00	0.49	7.49
	Sub-Tota	al	7.00	0.49	7.49
	Total Be	fore Rounding	7.00	0.49	7.49
	Roundin	g Difference			0.04
	Total An	ount Payable			7.45
	Paid By				
		20181105113256963	Direct Debit; eNE (Internet Banking)		7.45
	Total				7.45
	Cash Ch	ange			0.00
	Tendered	l Amount			7.45
	Excess F	Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.