

15/02/10

INS. CASE OWNER:

CC 4 / AXA1802

LKK:

IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 11/12/2018

After call ltr to OI: 28/12/2018

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$ 2,073.80

(3 days)

Reduction:

43.66 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

Repair Cost: (w/ GST)

\$ 2,218.97

Loss of Rental (LOR):

\$ 321.00

(3 days)

x \$100.00 + 7% GST

Loss of Use (LOU):

\$ -

(S

x

days)

Loss of Income (LOI):

\$ -

(S

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOU

☐

[Tick only one]

GIA/LTA Search

\$ 7.45

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost

\$ -

Total:

\$ 2547.42

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$ 2,547.42

Name 1:

Kah Motor Co Sdn Bhd

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350.00

COPY SENT

REF: ASM(AXA)

ASSIGNMENT

From: Date: 18/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKS 8019P

at Workshop n/s: Kah Motor

of: 15 Ubi Road 4

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 9.30am

Any

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

65%

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

1181 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS lup

3025F

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: 51458019P Regn: S 15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make: Honda HR-V G.C. 1497

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 079091 T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 6/11/18

D.O.I. 18/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 57468 6 yrs bnd.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.F. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18020196/fb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 08-11-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 14Y	Veh. Inspected	SKS 8019P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/11/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

6841 2132
OIC: Poh Kin Lkkanto

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKS8019P
Chassis No : MRHRU1830FP000119
Model : HRV LX-SIN CVT YM 2015
Owner's Name : NG CHEE KIONG
Ins Policy No. : 18-MW004278-R03
Date of Accident : 6/11/2018

Document No. : SQT18004764
Date : 7. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15Z71000122
Date | Time : 7. Nov 2018 2:32:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :
DID : +65 6846 5573
HP : +65 8100 6306
Email : anychua@honda.com.sg

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 71570) OWNER: NG CHEE KIONG OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 06/11/2018@15.15PM SURVEYED BY: REF NO: CCA/ASM18020196/fb3 TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SJR14Y (TOYOTA/PINIC/BUE)						
91505-TM8-003	CLIP,BUMPER <i>rec</i>	14	2.30	25	24.15	1.69	25.84
33100-T7S-T51	HEADLIGHT ASSY,R. <i>pu</i>	1	358.60	25	268.95	18.83	287.78
71101-T7J-H00ZZ	FACEFR.BUMPER <i>Deep cut</i>	1	468.20	25	349.65	24.48	374.13
71140-T7A-000	BEAMR.FR.BUMPER UPPER <i>11</i>	1	24.60	25	18.45	1.29	19.74
71193-T7A-000	SPACERR.FR.BUMPER SIDE <i>SC</i>	1	10.40	25	7.80	0.55	8.35
60210-T8N-T20ZZ	PANEL COMP,R.FR.FENDER <i>SC</i>	1	358.30	25	268.72	18.81	287.53
74107-T7M-H01	PROTECTORR.FR.WHEEL ARCH <i>groth</i>	1	150.60	25	112.95	7.91	120.86
Sum Item					1050.67	73.56	1,124.23
BOSUN	SUNDRIES <i>rec</i>	1	40.00	20	40.00	2.80	42.80
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	120.00	100	120.00	8.40	128.40
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	1	1120.00	100	1120.00	78.40	1198.40
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	1	1350.00	900	1350.00	94.50	1444.50
Sum Labor					2630.00	184.10	2,814.10

Survey By

Date & Time

Excess

Status

Signature

marcus Hah
18/12/18
not Affected
take photo before repair
3 dy.
p/p & 2073.80

Total Amount 3,680.67 257.66 3,938.33

Total (Inclusive of GST) 3,938.33

LK Auto Consultant is hereby notify
The Policyholder that the surveyor will be carrying out the survey on the following basis:

- To survey damaged part(s) during resurvey
- Repairs must be subject to confirmation
- The survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

3687.72

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: MRHRU1830FP000119
License No: SKS8019P
Mileage: 79090
Engine No: L15Z71000122

Document No: SVO18075136
Printed By: CSLIM
Order Date: 18. December 2018
Order Time: 2:32:00 PM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 71570) OWNER: NG CHEE KIONG OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 06/11/2018@15.15PM SURVEYED BY: <i>Marcus Chua (LTA Auto)</i> 18/12/2018 REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SJR14Y (TOYOTA/PINIC/BLUE)							
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84	
04711-T7A-N00ZZ	FACE,FR.BUMPER	1	475.60	25	356.70	24.97	381.67	
74107-T7M-H01	PROTECTORR.FR.WHEEL ARCH	1	150.60	25	112.95	7.91	120.86	
	SUM PARTS:				493.80	34.57	528.37	
BOSUN	0760	1	20.00		20.00	1.40	21.40	
BML01I	SUNDRIES EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	100.00		100.00	7.00	107.00	
BKBH01S	EXT-YJ STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20	
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	900.00		900.00	63.00	963.00	
	SUM LABOUR:				1,580.00	110.80	1,690.80	
	TOTAL SGD				2,073.80	145.17	2,218.97	
	Total Payable (SGD)						2,218.97	

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

6841 2132
DIC = Poh Kin LKauto

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKS8019P

Chassis No : MRHRU1830FP000119

Model : HRV LX-SIN CVT YM 2015

Owner's Name : NG CHEE KIONG

Ins Policy No. : 18-MW004278-R03

Date of Accident : 6/11/2018

Document No. : SQT18004764

Date : 7. Nov 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15Z71000122

Date | Time : 7. Nov 2018 2:32:00 PM

Surveyor Name : DID : +65 6846 5673
HP : +65 8100 6306

Survey Date : Email : arychua@honda.com.sg

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71570)						
	OWNER: NG CHEE KIONG						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 06/11/2018@15.15PM						
	SURVEYED BY:						
	REF NO: CCA/ASM18020196/fb3						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SJR14Y (TOYOTA/PINIC/BLUE)						
91505-TM8-003	CLIP,BUMPER <i>rec</i>	14	2.30	✓ 25	24.15	1.69	25.84
33100-T7S-T51	HEADLIGHT ASSY,R.	1	358.60	? 25	268.95	18.83	287.78
71101-T7J-H00ZZ	FACEFR.BUMPER <i>2007 cur</i>	1	466.20	✓ 25	349.65	24.48	374.13
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	24.60	? 25	18.45	1.29	19.74
71193-T7A-000	SPACERR.FR.BUMPER SIDE <i>24</i>	1	10.40	✓ 25	7.80	0.55	8.35
60210-T8N-T20ZZ	PANEL COMP,R.FR.FENDER <i>2</i>	1	358.30	X 25	268.72	18.81	287.53
74107-T7M-H01	PROTECTORR.FR.WHEEL ARCH <i>groth</i>	1	150.60	✓ 25	112.95	7.91	120.86
Sum Item					1050.67	73.56	1,124.23
BOSUN	SUNDRIES <i>rec</i>	1	40.00	20	40.00	2.80	42.80
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	120.00	100	120.00	8.40	128.40
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1120.00	150	1120.00	78.40	1198.40
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1350.00	900	1350.00	94.50	1444.50
Sum Labor					2630.00	184.10	2,814.10

Survey By

Date & Time

Excess

Status

Signature

marcus Hale

18/12/18

not Affected

take photo before repair.

3 dy.

Total Amount 3,680.67

Total (Inclusive of GST) 3,938.33

257.66 3,938.33

LK Auto Consultants hence notify

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paper notes are subject to confirmation
- This survey policy is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date



Service Request Details

Claim

S8M0125H

Reference

None

Loss Date

November 6, 2018

Request Date

November 8, 2018

Due Date

November 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

08/11/2018 @ 9:57am
Any veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKS8019P

Make

TPVD HONDA

Model

JAZZ 1.3

Service Address

Primary Contact/Insured

GHAI RAJDEEP

3 SIGLAP ROAD, #02-32 MANDARIN GARDENS CONDO, 448907, Singapore

RAJDEEPPGHAI@GMAIL.COM

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2018 12:35
Date Of Accident	06/11/2018 15:30
Exact Location Of Accident	RACE COURSE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR14Y
Insured/Policyholder	
Name Of Registered Owner	RAJDEEP GHAI
NRIC No	S7168562D
Email Address	RAJDEEPPGHAI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98629261
Alternative Phone No	OFFICE-98629261

Vehicle Particulars

Manufacturer	TOYOTA
Model	PICNIC-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA370056
Cover Note Number	

Driver

Name of Driver	RAJDEEP GHAI
NRIC No	S7168562D
Date Of Birth	23/11/1971
Occupation	INDOOR
Date Of Driving Pass	12/04/2011
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98629261
Fax Number	
Contact Number	OFFICE-98629261
Email Address	RAJDEEPPGHAI@GMAIL.COM


Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan





date

27/06/2019

policy number

VA1 / GA370056

account number

14886

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 289)-Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1960 (Malaysia)

Policy details

Policyholder name	GHAI RAJDEEP	Certificate number	GA370056 / 1
Cover	Comprehensive	Chassis number	JTEGH238600026046
Plan name	Toyota Prestige	Engine number	1A2H334772
NCD applicable	50%		
Vehicle registration number	SJR14Y		
Period of Insurance	from 25/06/2018 to 24/06/2019 (both dates inclusive)		
Finance loan company	Nil		

Authorized Drivers

(a) The Policyholder

(b) Any Named Driver as stated in the Policy;

(c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

- Use of the motor vehicle is connected to the Policyholder's business
- Use for the carriage of passengers (besides commercial hire or reward) in connection with the Policyholder's business
- Use for social, domestic, and personal purposes

The Policy does not cover:

- Use for commercial hire or reward, or for racing, pace-making, reliability trial, or speed testing
- Use while drawing a trailer, except for the towing of a disabled person's mechanically propelled vehicle

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Basic Own Damage Excess
Windscreen Excess

\$65 1,000.00
Not Applicable

Young/Inexperienced driver excess

An additional excess of \$2500 (to be added to any excess imposed under the Policy) whilst the Insured MotorCar is being driven by any driver aged below 23 years old and /or has been issued a valid driving license to drive in Singapore for the relevant class of vehicle for less than one year

Young and/ or Inexperienced driver shall mean any person who:

- Is less than 23 years old, and/or
- Has been issued with a valid driving license to drive in Singapore for the relevant class of vehicle for less than 1 year

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

1 of 3



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 November, 2018

GHAI RAJDEEP
3 SIGLAP ROAD, #02-32 MANDARIN GARDENS CONDO,
Singapore 448907

Dear Sir,

OUR REF : CC4/ASM18020196/fb3
YOUR REF : SJR 14Y
ACCIDENT INVOLVING SJR 14Y & SKS 8019P on 06/11/2018 ALONG/AT
CHANDRA ROAD

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to pohkin@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 2132 if you have any further enquiries.

Yours sincerely,
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD
Motor Claim Department

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 4 January 2019 12:13 PM
To: 'Faeaz'
Cc: 'Liew Thye Wui'
Subject: Our Ref: CC4/ASM18020196/Ufb3; Your Ref: SKS 8019P (DOA: 06/11/2018)
Attachments: DV SKS 8019P.pdf
Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/ASM18020196/Ufb3
Your Ref: SKS 8019P (DOA: 06/11/2018)

Dear Sir/Madam,

We refer to above matter and your letter of demand dated 28th December 2018.

We hereby confirmed settlement as below:

1. Cost of Repair (w/gst)	S\$ 2,218.97
2. Loss of Rental (\$100.00 x 3 days)+7%gst	S\$ 321.00
3. LTA search fee	<u>S\$ 7.45</u>
	<u>S\$2,547.42</u>

Please duly sign the DV attached and return for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



<S8M0125H> IA with mandate uploaded

Type

🔗 Question

Message

Hi PohKin, pls proceed. Tks

Reply



<S8M0125H> IA with mandate uploaded

Type

🗨 Question

Message

Dear Winnie, Liability: Insured collided into the third party vehicle (parked). Liability is down against our insured. We did clarify with insured (Mr Rajdeep) the nature of the accident and he agree to settle and aware that NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Kah Motor Co Shn Bhd" is as follows: - 1)COR(w/gst) : \$2,218.97 + 2) Loss of Rental (3daysx\$100.00+7%gst): \$321.00 + 3) LTA Search: \$7.45=Total: \$2,547.42. **03days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 31/12/2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/12/2018

Survey Details:

Date of loss	6-Nov-18
Date of appointment	8-Nov-18
Date of survey	18-Dec-18
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS 8019P
Make and Model	HONDA HRV 1.5 LX CVT
Date of registration	8/5/2015
Excess	
Market Value	\$65,000
Parf Rebate	\$57,468
Nett Loss	\$7,532

Repair details:

Initial Estimate	\$ 3,680.67
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 493.80	list price -25%
Check items (estimate)	\$ -	
Labour	\$ 1,580.00	
Total	\$ 2,073.80	
Lump Sum(if applicable)	\$ -	

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	2,218.97
Loss of use	\$	-
Loss of rental	\$	321.00
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	-
Proposed Total	\$	2,547.42

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJR 14Y (Insd veh)	Model:	HONDA HRV (A)
	SKS 8019P (TP veh)		
Date of Accident:	06/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,945.86	
Final Repair Cost	:	\$	2,218.97	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	321.00	3 days
LTA / GIA Search Fee	:	\$	7.45	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,547.42

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO. SDN. BHD.	:	\$ 2,547.42

NUR SHAQILAH BTE ABDOL
WAHAB

15/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020196/Ufb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: WINNIE HO

Date : 15-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 14Y	Veh. Inspected	SKS 8019P
Policy No.	GA370056	Coverage (\$)	0.00
Claim No.	S8M0125H	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	08/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHRU1830FP000119	Colour	BLUE
Odometer	079091	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R17	DUNLOP	6 mm
L/H Front Tyre	225/50R17	DUNLOP	6 mm
R/H Rear Tyre	225/50R17	DUNLOP	6 mm
L/H Rear Tyre	225/50R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/11/2018	Inspection Date	18/12/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 8019P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
14	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	24.15	24.15
1	HEADLIGHT ASSY, R. (SN) (CONSISTENT)	SERVICEABLE	268.95	-
1	FACEFR.BUMPER (SN) (CONSISTENT)	DEEP CUT	356.70	356.70
1	BEAMR.FR.BUMPER UPPER (SN) (CONSISTENT)	NOT NECESSARY	18.45	-
1	SPACERR.FR.BUMPER SIDE (SN) (CONSISTENT)	SERVICEABLE	7.80	-
1	PANEL COMP,R.FR.FENDER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	268.72	-
1	PROTECTOR.FR.WHEEL ARCH (SN) (CONSISTENT)	GRAZED	112.95	112.95
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	40.00	20.00
			1,097.72	513.80
	<u>LABOUR</u>			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		120.00	100.00
	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF PANEL COMP,R.FR.FENDER.		1,120.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,350.00	900.00
			2,590.00	1,560.00
	GRAND TOTAL		3,687.72	2,073.80
	RECOMMENDED COST OF REPAIRS			2,073.80

Report Ref No. CC4/ASM18020196/Ufb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.