Surveyor: NAZ | REF: ASM(AXA) | W73K | NPG3 | (P)

ASSIGNMENT

From: Date: 08.11.2018

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 2704H

at Workshop m/s Elite Automaik

of 180 Woodlands Ind Park E5 #0177

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 65K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJL 2704H Yr Regn: 9 SEP / 2015

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA COROLLA ALTIS c.c 1,598

Colour GREY A/C: (Insured) / Std / NI / NA

Sp.Reading 56,735 T/Radio: (Insured) / Std / NI / NA

Eng/No:

C/No: MR053REH104537713

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / (STD) A/Rim or

Tyre Size: F: 205 / 55 R16

R: "

BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	3/11/18	D.O.I.	8/11/18

Survey held at ELITE AUTO

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	~~GOE (Ewarded 10 yrs) KH 8/9/2025~~
	ASM (AXA) L/S

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee.

Transportation

Add Fee: ☐ : Site Insp ($) ___S + RS___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)