

23/03/2002

ASS. REC. BY:

REF:

C93 / SMO18020245 / Jcho

Special Instruction:

Survivor

Muhmin

ASSIGNMENT (Office)

From (Person):

Enoh Pau Wong

of

SMO

Date/Time:

08/11/2018 4:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 4464D

Insured:

GBF 2329J

at Workshop m/s

Orion Autoclinic

Tel:

9444 476

of

No. 25 Kaki Bukit Rd 4 #D3-32. Synergy

Policy No:

D18MTPCYE002784

Claim No:

CMTD 1804 S76

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07-11-2018

(Client's Record)

07-11-2018 @ after 11am

CA / REV / REP. / REV 24 HRS Wp.

H.O.D. Endorsement:

Date/Time:

08/11/2018 4:53pm

Person Contacted:

Kenneth

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJW 4464D - X
	GBF 2329J - X
	Dismantle: 12/11/2018
	After repair: 14/11/2018

YRS  
Hwee Jie  
Musmen

REF: SMO

ASSIGNMENT

From: Date: 09-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 4464D

at Workshop m/s Orion Autodinic

of 25 Kaki Bukit Rd 4 #13-32

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW 4464D Yr Regn: 25 Mar 2010

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Honda fit C.C. 1339

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 113848 T/Radio: Insured / Std / NI / NA

Eng/No: L13A4202373

C/No: GE61184575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R15

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/11/18 D.O.I. 9/11/18

Survey held at — @ 1330

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$4000-\$5000  
6 days

15/11/2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS \$

) Photos

) Other

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

100

60460

10

230

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2018		08 Nov 2018 16:40 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	LIAN LEE WOODEN CASE MAKER CO PTE LTD, Co. Reg. No.: 200207347K		
Main Claimant:	UNKNOWN4876		
Vehicle Reg. No.:	SJW4464D	Date of Loss:	07/11/2018 16:00 - :59
Claim Type:	TP / CMTD1804876	Policy/Cover Note No.:	D18MTPCVE002784 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF2329J	Policy No. (Claimant):	
		Excess:	
Repairer:	Orion Autoclinic (HQ) NO.25 K BT RD 4 #03-31 SYNERGY @ KBT, 417800 Kaki Bukit - Tel: 91444476		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/11/2018]		
Driver/Custodian (Insured):	KER HUI CHING (), NRIC: S0215189H, Tel: +6592983234		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9694E
<b>Vehicle Details</b>	
Vehicle No.:	SJW4464D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	L13A4202373
Chassis No.:	GE61184575
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,223.00
Original Registration Date:	25 Mar 2010
First Registration Date:	25 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$14,223.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2020
PARF Rebate Amount:	\$7,822.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$2,857.00
<b>Total Rebate Amount:</b>	<b>\$10,679.00</b>

The information contained herein is correct as at 09 Nov 2018

OK

## EQ Insurance Company Limited

9 Maxwell Road #1703 Tower One, MND Complex, Singapore 061110  
 Tel: 65 6271 3133 | Fax: 65 6271 3553 | www.eqinsurance.com.sg  
 reg no: 1978-00439-N



## CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 183 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

PRIVATE CAR  
Comprehensive

Certificate No.: DMPPHQ18-004426

1. Index Mark and Registration Number of Vehicles  
 SJWM454D

2. Name of Policyholder  
 ROSHAN BINTE NASID

3. Effective Date of the Commencement of Insurance for the purpose of the Act  
 25/06/2018

4. Date of Expiry of Insurance  
 24/09/2019

5. Person or Classes of Persons entitled to drive\*

- (a) The Policyholder  
 (b) Any other person who is driving on the Policyholder's order or with his permission.

\*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use\*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover:

- (a) use for hire or reward  
 (b) use for racing, pace-making, reliability trials or speed testing  
 (c) use for the carriage of goods (other than samples) in connection with any trade or business  
 (d) use for any purpose in connection with the Motor Trade

\*Limitation rendered inoperative by Section 3 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 179) and Section 95 of the Road Transport Act, 1987.  
 (Malaysia) will not be involved under these headings.

We (EQ Insurance Company Limited) hereby certify that this Certificate of Insurance is issued in accordance with the provisions of the Road Transport Act, 1987 and the Motor Vehicles (Third-Party Risks and Compensation) Act, 1987 and the Motor Vehicles (Third-Party Risks and Compensation) Rules, 1959 and the Motor Vehicles (Third-Party Risks and Compensation) Rules, 1996.

Form: MK2  
 Excess:  
 Insured/Named Driver SGD500.00  
 Unnamed Drivers SGD1,000.00  
 YEID Additional SGD3,000.00

EQ Insurance-MARS Motor  
 Accident Help Center

6311 3211



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2018 17:00
Date Of Accident	07/11/2018 16:30
Exact Location Of Accident	BLK 546A MSCP SERANGOON NORTH AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW4464D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROSMAH BINTE RASID
NRIC No	S1559694E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90050095
Alternative Phone No	OFFICE-90050095

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-004426
Cover Note Number	

### Driver

Name of Driver	ROSMAH BINTE RASID
NRIC No	S1559694E
Date Of Birth	25/05/1962
Occupation	INDOOR
Date Of Driving Pass	22/05/1998
Driving Experience	20 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90050095
Fax Number	
Contact Number	OFFICE-90050095
Email Address	NOEMAIL

Address	BLK 279A SENGKANG EAST AVENUE #07-517
Postcode	541279
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2329J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KER HUI CHONG
NRIC/Passport Number	
Contact Number	92983234
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: \_\_\_\_\_

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: \_\_\_\_\_

  
 Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/IN No: \_\_\_\_\_





### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2018		08 Nov 2018 16:40 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LIAN LEE WOODEN CASE MAKER CO PTE LTD</b> , Co. Reg. No.: 200207347K									
Main Claimant: <b>UNKNOWN4876</b>									
Vehicle Reg. No.: <b>SJW4464D</b>		Date of Loss: 07/11/2018 16:00 - :59 [103 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / CMTD1804876</b>		Policy/Cover Note No.: D18MTPCVE002784 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>GBF2329J</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Orion Autoclinic (HQ)</b> NO.25 K BT RD 4 #03-31 SYNERGY @ KBT, 417800 Kaki Bukit - Tel: 91444476									
Handling Insurer: <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>GNOH PAU LOONG</b> - 63295217]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 19/11/2018]									
Driver/Custodian (Insured): <b>KER HUI CHING ()</b> , NRIC: S0215189H, Tel: +6592983234									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJW4464D (CMTD1804876)**  
**[GBF2329J]**  
**TP**  
**UNKNOWN4876**  
**Nov 7 2018 4:00PM**  
**[LIAN LEE WOODEN CASE MAKER CO PTE LTD]**  
**Orion Autoclinic**

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		Sompo Insurance Singapore Pte. Ltd. (HQ)							Thumbnail	Print	
1	08/11/18 16:40		Accident Statement From:SC - Reg. No: GBF2329J, Claimant: LIAN LEE WOODEN CASE MAKER CO PTE LTD							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
2	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
3	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
4	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
5	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
6	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
7	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
8	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
9	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
10	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
11	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
12	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
13	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
14	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
15	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
16	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
17	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
18	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
19	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
20	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
21	13/11/18 09:47		General View							Load JPG	<input checked="" type="checkbox"/>	
22	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
23	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
24	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
25	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
26	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
27	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
28	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
29	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
30	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
31	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
32	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
33	13/11/18 09:48		Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/11/18 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	16/11/18 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	08/11/18 16:07	EMAIL - EAST ASIA LAW	 Load PDF	
2	08/11/18 16:40	PRS - LKK	 Load HTM	

## Documents Checklist

**DOCUMENTS CHECKLIST**[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^

v

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18020245/JCBE2

Date: 17/12/2018

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE002784
Claimant Vehicle No :	SJW4464D	Insured Vehicle No :	GBF2329J
Date of Loss:	07/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804876

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJW4464D		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4202373
Reg. Date:	25/03/2010 (Man. Year: 2009)	Chassis No:	GE61184575
Colour:	Red	Odometer:	113848 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	08/11/2018	
Date Inspected:	09/11/2018 Inspected At:	Orion Autoclinic (HQ) NO.25 K BT RD 4 #03-31 SYNERGY @ KBT Singapore 417800
Estimated Period of Repair:	6.0 days	

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
<b>Parts:</b>	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW4464D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >