

ASS. REC. BY:

REF: CS/CT118020352 / Nsbbs ✓ Special Instruction:

Surveyor: Malim ASSIGNMENT (Office)

From (Person): Dng Chim Kiat of CTI Date/Time: 07/11/2018 3:06pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 7635S Insured: 6BG 7953T

at Workshop m/s Connect 3 Tel: 9850 9666

of 566 Woodlands Rd

Policy No: DMLVSN13067991800 Claim No: SWM18D05281C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 07/11/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) 12-11-2018 @ 10am H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 09-11-2018 3:26pm Person Contacted: Winnie Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 7635S - NBA (CT118020189 / Y) <span style="float: right;">DA-07/11/2018</span>
	6BG 7953T - X
<u>05/07/19</u>	<u>@ 17:45 pm checked with Winnie Gopalan, vehicle has not sent in for repair.</u>



**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2018		09 Nov 2018 15:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]																					
Insured:	WONG'S STEAM LAUNDRY & DRY CLEANING, Co. Reg. No.: 38743700B																						
Main Claimant:	LOI TRANSPORT, Co. Reg. No.: 53334795E																						
Vehicle Reg. No.:	PC7635S	Date of Loss:	07/11/2018 16:00 - :59 [148 Months and 4 Days From LTA Reg Date (Man Yr)]																				
Claim Type:	TP / SNM18D05281C02	Policy/Cover Note No.:	DMCVSN3067991800 (Comprehensive) Coverage: 31/10/2018 - 30/10/2019																				
Vehicle Reg. No. (Insured):	GBG7953T	Policy No. (Claimant):																					
		Excess:	\$0.00																				
Repairer:	Connect3 (mandal Estate) (HQ) 566 Woodlands Road, 728697 Mandal - Tel: 98509666																						
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2018]																						
Driver/Custodian (Insured):	WONG JIA QI (55 / Female), NRIC: S2502781G																						
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>																				
There are no mail for this case.																							
<b>ALL ASSOCIATED TASKS</b>																							
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>				Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?														
No results.																							
<table border="1"> <thead> <tr> <th><a href="#">View All</a></th> <th><a href="#">Search Tasks</a></th> <th><a href="#">Create New Task</a></th> <th><a href="#">Complete</a></th> </tr> </thead> </table>				<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>																
<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>																				

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2018 10:33
Date Of Accident	07/11/2018 16:25
Exact Location Of Accident	JUNCTION OF TUAS SOUTH AVENUE 4 AND TUAS WEST ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC7635S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	M/S LOI TRANSIT
Co Reg No	53334795E
Email Address	CONNECT3WINNIE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90265556
Alternative Phone No	OFFICE-93918330

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	BE639JRMHDEA-3.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN3064651800
Cover Note Number	

### Driver

Name of Driver	SEAH SOON TECK
NRIC No	S1184938E
Date Of Birth	03/06/1956
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1979
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90265556
Fax Number	
Contact Number	OTHERS-93918330
E Mail Address	CONNECT3WINNIE@GMAIL.COM

Address BLK 629 HOUGANG AVENUE 8  
 #11-88  
 Postcode 530629  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBG7953T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

X  
Policyholder's Signature  
Date & Time:

T  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:


08/10/2018  
Reporting Centre Personnel's Signature  
Name: KAPU VATHI  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

A= PC76355  
B= GBC7953T

\_\_\_\_\_  
Tues West Road  
\_\_\_\_\_



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/11/2018 @ 16:25hrs, I was driving my car PC76355 along Tues South Ave 4 intend to turn right to Tues West Rd & as it is clear for my turn to turn right, I proceed to turn when a vehicle GBC7953T drove up @ a fast speed & collided against my car front on position as a result.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/VIN No.:

*[Handwritten Signature]* 08/11/2018  
Name: *[Handwritten Name]*  
NIC/VIN No.:

Transaction ref 20181003104812611338

The owner and vehicle particulars for Vehicle No. PC7635S as at 03 Oct 2018 are as follows:

1. Name	: LOI TRANSIST
2. Identification No. Type	: Business
3. Identification No.	: 53334795E
4. Country/Region	: -
5. Vehicle No.	: PC7635S
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 03 Oct 2018
8. Original Registration Date	: 03 Jul 2006
9. First Registration Date	: 03 Jul 2006
10. Vehicle Type	: Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus
11. Vehicle Scheme	: Public Service Vehicle (Others)
12. Attachment 1	: Air-Conditioned
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: MITSUBISHI
16. Vehicle Model	: BE639JRMHDEA
17. Year of Manufacture	: 2006
18. Primary Colour	: White
19. Secondary Colour	: -
20. Passenger Capacity	: 23
21. Chassis/Trailer Chassis No.	: BE639JD00305 / -
22. Propellant	: Diesel
23. Engine No./Motor No.	: 4D34K84214 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 3908 / -
25. Maximum Power Output(kW/bhp)	: - / -
26. Unladen Weight(kg)	: 3780

**CONNECT 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

GST : 53360061L

QT18/PC7635S/TPC-346

**China Taiping Insurance (Singapore) Pte Ltd**

3 Anson Rd #15-02

Springleaf Tower

Singapore 079909

## QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC7635S

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Front bumper	1	2,341.76	2,341.76	XR
2.	Front bumper bracket	1	231.46	231.46	?
3.	RH rear view mirror (round - bottom)	1	98.31	98.31	/MIS
4.	RH rear view mirror (-round - bottom)	1	491.76	491.76	/CRK
5.	RH rear view mirror bracket	1	105.90	105.90	/CRK
6.	Front RH headlamp upper moulding	1	164.69	164.69	?
7.	Front RH signal lamp	1	265.56	265.56	/SCR
8.	Front RH door	1	3,565.60	3,565.60	/DEF
9.	Front RH driver step panel	1	558.00	558.00	?
10.	Front RH driver door hinge	1	335.90	335.90	?
11.	Front RH driver door inner trims	1	765.80	765.80	?
12.	Front panel	1	3,809.58	3,809.58	XR
13.	Mark fuso	1	60.58	60.58	XND
14.	Mark Rosa	1	54.14	54.14	XNN
15.	Sealant	4	40.00	160.00	XNN
16.	Remove & refit front windscreen	1	500.00	500.00	XNN

17.	Transfer Rh driver door fittings	1	200.00	200.00	100
18.	Apply anti rust	1	200.00	200.00	100
19.	Check wiring	1	80.00	80.00	50
20.	Spray painting	1	1,600.00	1,600.00	1,100
21.	Labour charges	1	1,500.00	1,500.00	1,000
<b>SUB-TOTAL</b>				<b>S\$17,089.04</b>	

- Price before 7% gst

Thank you.  
Yours faithfully,

*Winnie*



Winnie Chai  
HP: 9850-9666

NAZ LKK

12/11/18

L/S

4 DAYS

CHECK ITBM PHOTO  
AFTER REPAIR PHOTO

*[Signature]*  
15/11/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2018		09 Nov 2018 15:06 <a href="#">Edit Adj Rpt</a>	<b>S\$6,877.13</b> <a href="#">Edit Estimates</a>	<b>S\$6,877.13</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>WONG'S STEAM LAUNDRY &amp; DRY CLEANING</b> , Co. Reg. No.: 38743700B								
Main Claimant:	<b>LOI TRANSPORT</b> , Co. Reg. No.: 53334795E								
Vehicle Reg. No.:	<b>PC7635S</b>	Date of Loss:	07/11/2018 16:00 - :59 [148 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D05281C02</b>	Policy/Cover Note No.:	DMCVSN3067991800 (Comprehensive) Coverage: 31/10/2018 - 30/10/2019						
Vehicle Reg. No. (Insured):	<b>GBG7953T</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Connect3 (mandai Estate) (HQ)</b> 566 Woodlands Road, 728697 Mandai - Tel: 98509666								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 20/11/2018]								
Driver/Custodian (Insured):	WONG JIA QI (55 / Female) , NRIC: S2502781G Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*PC7635S (SNM18D05281C02)  
 [GBG7953T]  
 TP  
 LOI TRANSPORT  
 Nov 7 2018 4:00PM  
 [WONG'S STEAM LAUNDRY & DRY CLEANING]  
 Connect3 (mandai Estate)

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			<b>View</b> <input type="button" value="View in Browser"/>	
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	14/11/18 12:01	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/11/18 14:59	<b>Estimate</b>	Load PDF	
2	09/11/18 14:59	<b>OI GIA REPORT</b>	Load PDF	
3	09/11/18 14:59	<b>TP GIA REPORT</b>	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020352/NSBS2  
Date: 12/07/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3067991800		
Claimant Vehicle No :	PC7635S	Insured Vehicle No :	GBG7953T		
Date of Loss:	07/11/2018	Nature of Claim:	TP	Claim No:	SNM18D05281C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	PC7635S	Engine No:	4D34K84214
Make & Model:	MITSUBISHI BE639JRMHDEA, 3.9 D (M)	Chassis No:	BE639JD00305
Reg. Date:	03/07/2006 (Man. Year: 2006)	Odometer:	653061 km
Colour:	White		
Engine Capacity:	3908 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/75 R17.5	Rear Tyre Size:	215/75 R17.5
Front Left Side:	Michelin 5 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,009.04	4,527.13	8,481.91	65.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,350.00	1,730.00	42.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,089.04</b>	<b>6,877.13</b>	<b>10,211.91</b>	<b>59.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,196.23</b>	<b>481.40</b>	<b>714.83</b>	<b>59.76</b>
<b>Nett Amount (S\$)</b>	<b>18,285.27</b>	<b>7,358.53</b>	<b>10,926.74</b>	<b>59.76</b>

## INSPECTION

Date of Assignment:	09/11/2018	Inspected At:	566 Woodlands Road Singapore 728697 Repairer: Connect3
Date Inspected:	12/11/2018		
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,055.85 NETT)

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 12 Jul 2019)
<b>Parts:</b>	N/A MITSUBISHI BE639JRMHDEA 3.9 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC7635S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,341.76 F	*- F
2	1		*FRONT BUMPER BRACKET	*Check	231.46 F	*- F
3	1		*RH REAR VIEW MIRROR (ROUND & BOTTOM)	Missing	98.31 F	*98.31 F
4	1		*RH REAR VIEW MIRROR	Cracked	491.76 F	*491.76 F
5	1		*RH REAR VIEW MIRROR BRACKET	Cracked	105.90 F	*105.90 F
6	1		*FRONT RH HEADLAMP UPPER MOULDING	*Check	164.69 F	*- F
7	1		*FRONT RH SIGNAL LAMP	Scratched	265.56 F	*265.56 F
8	1		*FRONT RH DOOR	Deformed	3,565.60 F	*3,565.60 F
9	1		*FRONT RH DRIVER STEP PANEL	*Check	558.00 F	*- F
10	1		*FRONT RH DRIVER DOOR HINGE	*Check	335.90 F	*- F
11	1		*FRONT RH DRIVER DOOR INNER TRIMS	*Check	765.80 F	*- F
12	1		*FRONT PANEL	Repair	3,809.58 F	*- F
13	1		*MARK FUSO	Not Necessary	60.58 F	*- F
14	1		*MARK ROSA	Not Necessary	54.14 F	*- F
15	4		*SEALANT	Not Necessary	160.00 F	*- F
<b>Total Parts (S\$)</b>					<b>13,009.04</b>	<b>4,527.13</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIT FRONT WINDSCREEN	New	500.00	0.00
2	TRANSFER RH DRIVER DOOR FITTINGS	New	200.00	100.00
3	APPLY ANTI RUST	New	200.00	100.00
4	CHECK WIRING	New	80.00	50.00
5	SPRAY PAINTING	New	1,600.00	1,100.00
6	LABOUR CHARGES	New	1,500.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>4,080.00</b>	<b>2,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >