



Your Ref: 17.23002 S.CK.xy

Date: 24th May 2019

Our Ref: CS1/LAW18020378/Ktbe2

M/s Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKG 1960E
INSURED VEHICLE: SBG 67Y
ACCIDENT DATE: 06/03/2017**

We thank you for your instruction on 09/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKG 1960E from M/s Premier Appraiser Services.
- b) Survey report by Chow Automobile Assessor & Surveyor with colour photographs.
- c) Final Repair Bill of SKG 1960E from M/s T & B Motor Repairs Services Pte Ltd.
- d) Singapore Accident Statement of Vehicles SKG 1960E and SBG 67Y.
- e) Police Report of Vehicles SKG 1960E.
- f) Colour damaged vehicle photographs of SKG 1960E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKG 1960E
Make & Model	: Volkswagen Scirocco 1.4L AT TSI 1372Q5
Year of Registration	: 2010
Chassis Number	: WVWZZZ13ZAV432987
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.