



Your Ref: 18.25512 PD-O

Date: 16th Nov 2018

Our Ref: CS3/ASM18012776/Gqbe2-1

M/s Axa Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJK 724T
INSURED VEHICLE: SCW 10P
ACCIDENT DATE: 11/07/2018**

We thank you for your instruction on 09/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJK 724T from M/s S C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SCW 10P.
- c) Final Repair Bill of SJK 724T from Motor Intel Automo Pte Ltd.
- d) Colour damaged vehicle photographs of SJK 724T.

Pre-Repair Inspection Date : 18/07/2018 at M/s Motor Intel Automo Pte Ltd, 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJK 724T
Make & Model	: Toyota Camry
Year of Registration	: 2008
Chassis Number	: MR053BK4007029389
Engine Capacity	: 2362 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.