

Surveyor: Pam

REF:

10398/12/10/13 (2) 3312A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 7146Rat Workshop m/s Carcraftersof 48, BOA HUMAN RD EAST #05-155Insured: Asm

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

12-30 Tony

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 30k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKD 7146R Yr Regn: 2011 / D6CType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Transporter 1.4 c.c. 1390Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 76266 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG222 1T2CW 05-3397Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 1"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 02/11/18

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 15/11/18

Survey held at

CarcraftersDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orN/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3312A
Vehicle Details	
Vehicle No.:	SKD7146R
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4L AT TSI 1T32B4
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	CAV363623
Chassis No.:	WVGZZZ1TZCW053397
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,825.00
Original Registration Date:	30 Dec 2011
First Registration Date:	30 Dec 2011
Transfer Count:	0
Actual ARF Paid:	\$21,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2021
PARF Rebate Amount:	\$14,186.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$42,600.00
COE Rebate Amount:	\$13,295.00
Total Rebate Amount:	\$27,481.00

The information contained herein is correct as at 15 Nov 2018

OK

38,000

27,481