

22/03/2002

ASS. REC. BY:

REF:

C83/CT18020406/Th32

Special Instruction:

Surveyor:

**ASSIGNMENT (Office)**From (Person): Irene Tay of CTI Date/Time: 9/11/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SJU 6201T Insured: SKU 6963Rat Workshop m/s Eclipse. Auto. Tel: 812 88789 Frankieof 155 Kaki Bukit Ave 1 #01-00.Policy No: DMPCCN3048981800 Claim No: SNM18005168C03

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 30/10/2018  
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12/11 Person Contacted: Frankie Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SJU 6201T - C83/11/01/17/032/Th322 DOA: 17/6/2017.</u>
	<u>SKU 6963R - X</u>
	<u>Dismantle: 13/11/2018</u>
	<u>After repair: 14/11/2018</u>

PRS

REF: CT1

Hwee Jie

## ASSIGNMENT

From:

Date:

12/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJU 6201T

at Workshop m/s

Eclipse Auto

of

155 kaki Bukit Ave 1

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJU 6201T

Yr Regn:

18 Dec 2009

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Premio

c.c 1496

Colour:

Purple

A/C:

Insured / Std / NI / NA

Sp. Reading:

202089

T/Radio: Insured / Std / NI / NA

Eng/No:

1NZ0538358

C/No:

NZT 2603054765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/10/18

D.O.I.

12/11/18

Survey held at

- @ 1415

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$4,500 - \$5,500  
6 days

*[Signature]*  
15/11/2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation:

) \$ + RS \$

) Photos

) Others

Report Format:

PRE

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2018		09 Nov 2018 16:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SERENA TAN YUN RU, ID: S8722488J		
Main Claimant:	DREAM CAR LEASING PTE LTD, Co. Reg. No.: 201420013Z		
Vehicle Reg. No.:	SJU6201T	Date of Loss:	30/10/2018 20:00 - :59
Claim Type:	TP / SNM18D05168C02	Policy/Cover Note No.:	DMPCSN3048981800 (Comprehensive)
Vehicle Reg. No. (Insured):	SKU6963R	Policy No. (Claimant):	DMCFHQ18-000174
		Excess:	S\$0.00
Repairer:	Vehicle Claims Specialist Pte Ltd (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26, 408711 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2018]		
Driver/Custodian (Insured):	SERENA TAN YUN RU (31 / Male), NRIC: S8722488J		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

email wait respond

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0013Z
<b>Vehicle Details</b>	
Vehicle No.:	SJU6201T
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREMIO 1.5F A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	1NZD538358
Chassis No.:	NZT2603054765
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$19,545.00
Original Registration Date:	18 Dec 2009
First Registration Date:	18 Dec 2009
Transfer Count:	2
Actual ARF Paid:	\$19,545.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2019
PARF Rebate Amount:	\$10,749.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,899.00
COE Rebate Amount:	\$2,072.00
<b>Total Rebate Amount:</b>	<b>\$12,821.00</b>

The information contained herein is correct as at 12 Nov 2018

OK

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	02/11/2018 13:28
Date Of Accident	30/10/2018 20:30
Exact Location Of Accident	CTE TOWARDS ANG MO KIO
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SJU6201T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DREAM CAR LEASING PTE LTD
Co Reg No	201420013Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67489747

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	PREMIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

**Insurance Company**

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ18-000174
Cover Note Number	

**Driver**

Name of Driver	TAN SEE LEE
NRIC No	S8070484D
Date Of Birth	09/11/1980
Occupation	OUTDOOR
Date Of Driving Pass	31/07/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81336388
Fax Number	
Contact Number	
Email Address	RACHELTAN41@HOTMAIL.COM

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJM4786C
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM HAN LEONG GEORGE
NRIC/Passport Number	S7641675C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TAN SEE LEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJU6201T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

### Sketch Plan #2

## SKETCH PLAN

A: SDU 6201T  
B: SKV 6963L  
C: SJM 4786C

CTE Towards  
Ang Moksio

John  
Barnard

Back 1-

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

[illegible]

## DECLARATION

**UWe declares the foregoing particulars are true in every respect.**



### Policyholder Signature

Date & Time: 01/11/15

6:20pm  
GARYK Smith/PerForm 1/3

**Driver's Signature**

**(If driver is not the policyholder)**

Date & Time: 01/11/18  
6.30pm



**Reporting Centre Personnel's Signature**

**Keywords:**

**NRIC/FOM No.:**



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8070484D




TAN BEE LEE  
陈诗莉  
Date of Birth: 09-11-1980  
Gender: F  
Place of Birth: SINGAPORE



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8070484D



Machine: S8070484D  
Valid Until: 08-04-2007

SPRING DRIVE LICENSING UNIT  
SINGAPORE 700097  
Licence No: S8070484D Date: 28-01-2007 Valid: 28-01-2007


NEI

Zone 3A Motor cars without clutch pedals (Auto) - 5000kg  
with < 7 passengers, exclusive of the driver; and  
other motor vehicles without clutch pedals - 2000kg

31 Jul 2008

Licence No: S8070484D

NP 428A



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

1/11/18  
6:30pm

QUANX SketchPlanForm\_V3

*[Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time:

1/11/18  
6:30pm



Reporting Centre Personnel's Signature

Name:

NHC/FBI No.:

Address	BLK 501D WELLINGTON CIRCLE #03-88
Postcode	754501
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRED
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMPAWANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 4 SEMPAWANG CRESCENT , <b>POSTCODE:</b> 757633 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-5549999 - <b>FAX NO:</b> 68522499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU6963R
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SERENA TAN YUNRU
NRIC/Passport Number	S8722488J
Contact Number	96683088
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2018		09 Nov 2018 16:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SERENA TAN YUN RU</b> , ID: S8722488J								
Main Claimant:	<b>DREAM CAR LEASING PTE LTD</b> , Co. Reg. No.: 201420013Z								
Vehicle Reg. No.:	<b>SJU6201T</b>	Date of Loss:	30/10/2018 20:00 - :59 [106 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D05168C02</b>	Policy/Cover Note No.:	DMPCSN3048981800 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKU6963R</b>	Policy No. (Claimant):	DMCFHQ18-000174						
		Excess:	S\$0.00						
Repairer:	<b>Vehicle Claims Specialist Pte Ltd (HQ)</b> BLK 3018A UBI ROAD 1, #01-24/25/26, 408711 Ubi - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Claimant's Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 20/11/2018]								
Driver/Custodian (Insured):	SERENA TAN YUN RU (31 / Male), NRIC: S8722488J								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJU6201T (SNM18D05168C02)**  
**[SKU6963R]**

TP

**DREAM CAR LEASING PTE LTD**

**Oct 30 2018 8:00PM**

















**[SERENA TAN YUN RU]**

**Vehicle Claims Specialist Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)							Thumbnail	Print	
1	02/11/18 14:00	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)							Thumbnail	Print	
1	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	02/11/18 13:48	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	13/11/18 15:37	General View								Load PDF	
2	13/11/18 15:47	Photographs of Damaged Parts								Load PDF	
3	16/11/18 11:19	Photo After Spray								Load PDF	
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	09/11/18 16:37	PRS								Load PDF	
2	09/11/18 16:37	TP GIA								Load PDF	
3	09/11/18 16:37	OI GIA								Load PDF	
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)							Thumbnail	Print	
1	02/11/18 13:44	Sketch Plan [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	02/11/18 13:44	Sketch Plan #2 [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	02/11/18 13:44	Sketch Plan #3 [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	02/11/18 13:44	Sketch Plan #4 [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	02/11/18 13:44	Sketch Plan #5 [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	02/11/18 13:44	Sketch Plan #6 [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	02/11/18 13:45	Common Statement [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/11/18 14:00	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/11/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	02/11/18 13:44	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	02/11/18 13:44	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	02/11/18 13:44	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	02/11/18 13:44	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>
5	02/11/18 13:44	Sketch Plan #5	 Load JPG	<input checked="" type="checkbox"/>
6	02/11/18 13:44	Sketch Plan #6	 Load JPG	<input checked="" type="checkbox"/>
7	02/11/18 13:45	Common Statement	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18020406/JCBE2

Date: 23/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3048981800
Claimant Vehicle No :	SJU6201T	Insured Vehicle No :	SKU6963R
Date of Loss:	30/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05168C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJU6201T</b>	Engine No:	1NZD538358
Make & Model:	TOYOTA PREMIO, 1.5 (A)	Chassis No:	NZT2603054765
Reg. Date:	18/12/2009 (Man. Year: 2009)	Odometer:	202089 km
Colour:	Purple		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	09/11/2018	
Date Inspected:	12/11/2018	Inspected At:
		ECLIPSE AUTO PTE LTD 155 KAKI BUKIT AVENUE 1 #01-00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012
Estimated Period of Repair:	6.0 days	

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2018)
<b>Parts:</b> 143	TOYOTA PREMIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU6201T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >