



T 1118 / SHA7977K /JW(st) Our Ref : Your ref:

Date

19-Nov-18

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell 205 Braddell Road Singapore 579701

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Yishun 01 Yishun Industrial Park A Singapore 768732

EQ Insurance Company Limited 5 Maxwell Road, MND Complex #17-00 Tower Block

Singapore 069110

Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHA7977K YOUR INSURED GBG3250P ON 09.11.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No: SHA7977K which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving GBG3250P we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 4,214.34
2	4 days Loss of Rental @ \$ 125.19 per day	\$ 500.76 ₅₀
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation Fees	\$ 14
	Sub Total :	\$ 4.722.59

HIRER'S CLAIM

7	4	days Loss of Income @	\$ 80.00	per day	\$ 320.00
				Total Claims:	\$ 5,042.59

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs:

pcs. GBG3250P

b) LTA search slip/s of:

SHA7977K

c) GIA / Police report/s of :

- d) Letter of authority from owner / hirer / operator
 - () Witness statement/s () Towing/Medical bill/receipts () Certificate of Insurance
 - (X) Photograph/s of Accident Scene (x) Downtime/Mileage record

(x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Jim Wong

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.









LETTER OF	AUTHOR	ISATION
-----------	--------	---------

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHA7977K , GBG3250P

ON 09-Nov-18 08:50

ALONG

TAMPINES RD TWDS KPE

I / We

LIM TIONG HUNG

(Hirer) NRIC No.:

S1230419F

and/or

(Relief) NRIC No.:

Taxi Number

SHA7977K

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

09-Nov-2018

Name of Hirer

LIM TIONG HUNG

Hirer NRIC

S1230419F

Signature :

Address

17 HOUGANG AVENUE 3 #10-149

530017

Contact No.

90219071



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873

COMPANY REG. NO.: 199506048W

Page: 1

8010325

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

Description: 3P 09.11.18

VEHCLE NO SHA7977K INV. NO/DATE 91407859 15.11.2018

MAKE HYUNDAI

JOB NO. 305236881

MODEL IONIQ(G2) ODOMETER READING

DATE OF REG 18.10.2018

DATE/TIME IN 09.11.2018 09:35

CHASSIS CODE KMHC851CVKU114800

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	FNPS	NO PLATE(S)	1	25.00	0.00	25.00
0002	04-01-0104-2282	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0003	04-01-0104-2533	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00
0004	04-01-0104-2256	IONIQ PANEL ASSY-TAIL GAT	1	1,748.00	20.00	1,398.40
0005	04-01-0104-2270	IONIQ EMBLEM-HYBRID	1	24.30	20.00	19.44
0006	04-01-0104-2271	IONIQ EMBLEM-IONIQ	1	31.30	20.00	25.04
0007	28-01-0103-0005	(I40/SONATA)REAR BOOT LOG	1	30.00	0.00	30.00
0008	28-01-0103-0006	(I40/SONATA)REAR BOOT TEL	1	30.00	0.00	30.00
0009	04-01-0104-2397	IONIQ LAMP ASSY-REAR COMB	1	556.80	20.00	445.44
0010	04-01-0104-3919	IONIQ STAY-RR BUMPER RH	1	138.10	20.00	110.48
0011	04-01-0104-3819	IONIQ STAY-RR BUMPER LH	1	138.10	20.00	110.48

¹⁾ WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91407859	4,214.34	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GI NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTI

³⁾ INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.

I) PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCE WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE CORRECT AND BINDING



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 76873

COMPANY REG. NO.: 199506048W Page: 2

8010325

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

VEHCLE NO SHA7977K

INV. NO/DATE 91407859 15.11.2018

MAKE HYUNDAI JOB NO. 305236881

MODEL IONIQ(G2) ODOMETER READING

DATE OF REG 18.10.2018

DATE/TIME IN 09.11.2018 09:35

84

CHASSIS CODE KMHC851CVKU114800

S/No	Part No.		Qty	Unit Price	%Disc	Net
0012	04-01-0104-2288	S IONIQ BEAM-RR BUMPER	1 SUB-TOTAL	294.80	20.00	235.8 8.64
JOB N	IATURE					
0001	L	PANEL BEATING	30	00.00	300.00	
0002	23-502	SPRAYPAINT ON AFFECTED AREA	40	00.00	400.00	
0003	L	R/I REVERSE SENSOR	3	30.00	30.00	
	20-05	REAR BUMPER MAT**	5	50.00	50.00	
0004			SUB-TOTAL	:	7	780.00

ComfortDelGro Engineering Pte Ltd

A member of COMFORIDELGRO

Head Office: 205 Braddell Road Singapore 579701

AC	COUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
	8010325	91407859	4,214.34	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873

COMPANY REG. NO.: 199506048W

8010325

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

VEHCLE NO SHA7977K

INV. NO/DATE 91407859 15.11.2018

MAKE HYUNDAI

JOB NO. 305236881

MODEL IONIQ(G2) ODOMETER READING

DATE OF REG 18.10.2018

DATE/TIME IN 09.11.2018 09:35

CHASSIS CODE KMHC851CVKU114800

Items total

3,938.64

Add GST @

7.000 %

275.70

Invoice amount

4,214.34

Issued by : CHEWBEELENG 15.11.2018 14:15:44
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. BANK/CHQ No. INVOICE No. **AMOUNT** 4,214.34 8010325 91407859

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18110238

N-1-- 45 N----- 0040

Date: 15 November 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

09/11/2018 @ 08:50 hrs

ALONG

TAMPINES RD TWDS KPE

INVOLVING

GBG3250P

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA7977K (the "Taxi"). The Taxi was hired to LIM TIONG HUNG IC NO S1230419F a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	HOURS OPERATED (TIME)	FROM TO	0935 /	(mg) /									
	MILEAGE	(KM)	F	Cart									
JILLO V	MILEAGE BEADING	WILEAGE DEADING		7									
3	_	NAME OF DRIVER	Accident	ROAL	_								
		DAIE	1 6	11/51	-								
	HOURS OPERATED (TIME)	FROM TO	0830 2200	0830 1813	0880 1780	0830 2000	0845 2235	0830 1937	0880 2080	0925 1950	5212 0580	0830 2120	C645 09 tS

N

MILEAGE TRAVELLED (KM)

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status |

Insurance Company Code

Insurance Company Name

GBG3250P

09 Nov 2018 / 08:50:00

Successful

E04

EQ INSURANCE COMPANY LTD

Previous

OK

54A 7977K

























