

ASS. REC. BY:

REF:

CS3/AG118020445/Jcb2

Special Instruction:

Surveyor:

**ASSIGNMENT (Office)**From (Person): Julie Mangubat of Agai Date/Time: 12/11/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SLF2200H Insured: SLF9938Lat Workshop m/s Apex Motoring Tel: 9234 2543of 25 Kaki Bukit Rd 4 #01-55Policy No: \_\_\_\_\_ Claim No: C10002230/JM

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/11/2018  
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12/11 Person Contacted: Mr Wei Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SLH2200H-X</u>
	<u>SLF9938L-X</u>
	<u>Diamond: 13/11/2018</u>
	<u>No. GIA.</u>
	<u>After Repair: 23-11-2018</u>

PRs  
Survivor Three Jia

REF:


AGI

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLE2200H  
 at Workshop m/s Apex Motoring  
 of 25 Kaki Bukit Rd 4 # 01-55 Synergy  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLE 2200H Yr Regn: No record  
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Alt's Alt's C.C. 1598  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 206734 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MRO53REH104539283  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/55Z R16  
 R: \_\_\_\_\_


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Gre max

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>10/11/2018</u>	D.O.I.	<u>12/11/18 @ 0449pm</u>
Survey held at <u>@ 1655</u>			

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Front, Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$5000 - \$7000 6 days
	 15/11/2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation: \_\_\_\_\_

\_\_\_\_ \$ + RS. \_\_\_\_ \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format: PRC

Lump Sum / I.B.I: (\$

100

**Catherine Chong (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Monday, 12 November, 2018 11:38 AM  
**To:** SUR; Admin-D (LKKAuto)  
**Subject:** FW: Our ref: C10002230/JM || Your ref: SLE2200H  
**Attachments:** FAX\_20181110\_1541836250\_20.pdf

Hi Team

Please accept TPPD PRS for this case please.

**The vehicle is now at our workshop awaiting for your inspection at the following  
Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800  
Mobile No. 9234 2543 Email : peijie@expresscar.com.sg Mr Wei. **Kindly  
surveyors list to us. Thanks.****

Thank you,  
-Julie

---

**From:** Julie Mangubat  
**Sent:** Monday, 12 November, 2018 11:34 AM  
**To:** 'peijie@expresscar.com.sg' <peijie@expresscar.com.sg>  
**Subject:** RE: Our ref: C10002230/JM || Your ref: SLE2200H

Without Prejudice

Dear Sir

We regret to inform that we are not agreeable to your list of surveyors.  
We will proceed to appoint our own surveyor to do PRS.

**Please also submit your client's accident report for our reference.**

Thank you,  
-Julie

-----Original Message-----

**From:** peijie@expresscar.com.sg <peijie@expresscar.com.sg>  
**Sent:** Monday, 12 November, 2018 11:22 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Subject:** Re: Our ref: C10002230/JM || Your ref: SLE2200H

To Whom It May Concern,

We do not agree to your surveyor list.  
Kindly refer below for our surveyor list :

- 1) Teo Hoon Tong – Kelvin Automotive Appraising Services
- 2) Chang Fuh Keong, Dave – Sincere Appraisal Services
- 3) Ho Joo Loong, Danny – HJL Auto Appraiser Services



10/11/2018

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD  
190 Clemenceau Avenue #03-01  
Singapore 239924  
Fax : 67250611

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SLE 2200 H AND VEHICLE NO. SLF 9938 L  
ON 10/11/2018 @ 1248 HRS**

We are the appointed repair workshop of vehicle no. **SLE 2200 H**

We understand that you are the insurer of vehicle no. **SLF 9938 L**

The owner of vehicle number **SLE 2200 H** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800

Mobile No. 9234 2543 Email : peijie@expresscar.com.sg Mr Wei. **Kindly email 10 surveyors list to us.** Thanks.

Yours faithfully





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AUTO & GENERAL INSURANCE (S) PL		Ref: CS3/AGI18020445/Jcbe2		
(BUDGET DIRECT INSURANCE)190CLEMENCEAU AVENUE #03-01 S S CSINGAPORE 239924		Date: 04-12-2018		
		Code: AGI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLF 9938L	Veh. Inspected	SLE 2200H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10002230/JM	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	12/11/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR053REH104539283	Colour	GREY	
Odometer	206734 KM	Steering	JAMMED	
Brakes	JAMMED	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55Z R16	GREMAX	6 mm	
L/H Front Tyre	205/55Z R16	GREMAX	6 mm	
R/H Rear Tyre	205/55Z R16	GREMAX	6 mm	
L/H Rear Tyre	205/55Z R16	GREMAX	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
<b>5. General Information</b>				
Accident Date	10/11/2018	Inspect Date / Time	12/11/2018 ( 04:49 PM )	
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$7,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/AGI18020445/Jcbe2

**Inspected By**

ONG HWE E JIE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.