

22/03/2002

ASS. REC. BY:

REF:

CE3/SMO18020458/Ucber2

Special Instruction:

Surveyor:

Mehmen

ASSIGNMENT (Office)

From (Person): Gnch Pau Leong of SMO. Date/Time: 12/11/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STY 1153K Insured: SLD 484Z

at Workshop m/s Af Motorworkz Tel:

of 66 Kaki Bukit Ave 6

Policy No: D18MTPV01008239 Claim No: CMTD1804917

Sum Insured: Excess:

Make of Veh: D.O.A. 10/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12/11 Person Contacted: Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction () Estimate
	STY 1153K - X
	SLD 484Z - X.
	Dismantle: 14/11/2018

REF:

SMO

ASSIGNMENT

From:

Date: 13/11

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SJY1153K

at Workshop m/s AF Motorworkz

of 66 Kaki Bukit Ave 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

29

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJY1153K

Yr Regn:

8 / 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Honda civic

C.C

1799

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

113460

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMF01630A-S 200033

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

ok

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

(B) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/11/2018

D.O.I.

13/11/18

Survey held at

10.45

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

g/s R/L, n/s R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRG NO softw 47A20197
1/1/18 Ins. net 4803

6-7K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee.

100

Transportation

60

S + RS. \$

Photos

Others

10

TOTAL

170

Report Format :

PRG.

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018		12 Nov 2018 17:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SUNIL KUMAR SETHI, ID: S1353262A		
Main Claimant:	SIM CHUN SIONG VINCENT, ID: S7130112E		
Vehicle Reg. No.:	SJY1153K	Date of Loss:	10/11/2018 10:00 - :59
Claim Type:	TP / CMTD1804917	Policy/Cover Note No.:	D18MTPV01008239 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD484Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB, 417895 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/11/2018]		
Adj Asg. Remarks:	- PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(IN)

12/11/18 @ 5:41pm

12/11/2018 Survey

Ask Surveyor check got estimate
with boss when survey

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0112E
Vehicle Details	
Vehicle No.:	SJY1153K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	R18A15000203
Chassis No.:	JHMF1630AS200033
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$24,856.00
Original Registration Date:	02 Aug 2010
First Registration Date:	02 Aug 2010
Transfer Count:	0
Actual ARF Paid:	\$24,856.00 12428
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2020
PARF Rebate Amount:	\$13,670.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$39,002.00
COE Rebate Amount:	\$6,527.00
Total Rebate Amount:	\$20,197.00

The information contained herein is correct as at 13 Nov 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



2.88%p.a Lowest Interest@GV
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd









Browse by Category

Sort by Date Posted 20 results/page

8 vehicles

Honda Civic

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Civic		Any	Any	2010	Any	Any	Any	Available
	Honda Civic	1.6A VTI	\$26,000	\$9,710 /yr	01-Jun-2010	1,595 cc	-	Sedan	Available
Tip Top Condition, Powerful And Low Maintenance Cost, Stock Condition With No Modifi Cations Done. Accident Free. No Repair Needed. Cold Aircon. Good For COE Renewal. Got My New Car And Therefore Urge...									
Posted: 13-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic	1.8A VTI-S	\$30,300	\$10,050 /yr	08-Sep-2010	1,799 cc	110,467 km	Sedan	Available
90% Loan Available! Careful Lady Owner Well Maintained And In Excellent Condition! Best Priced Civic 1.8 In The Market! High PARF Rebate! 10% Drive Away Available! Call For A Viewing Appointment Today...									
Autotruster Traders Pte Ltd									
Posted: 11-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic	1.6A VTI	\$26,800	\$9,180 /yr	18-Jun-2010	1,595 cc	-	Sedan	Available
Very Well Maintained Condition, Fuel Efficient And Reliable Model, Very Smooth And Responsive Drive And Also Stable Enough For Long Drives. Car Still Looks Pristine Despite Its Age With Good Exterior ...									
Posted: 10-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic	Hybrid 1.3A	\$25,800	\$9,800 /yr	18-Jun-2010	1,339 cc	105,339 km	Sedan	Available
Graded B by STA									
Fuel Type: Petrol-Electric									
1 Year Comprehensive Warranty Inclusive! \$2K Down Payment! STA Certified Accident Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Opt...									
Cosmo Automobiles									
Posted: 10-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic	Hybrid 1.3A	\$29,000	\$11,250 /yr	15-Jul-2010	1,339 cc	-	Sedan	Available
Fuel Type: Petrol-Electric									
Posted: 09-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									
	Honda Civic	1.6A VTI	\$28,000	\$9,070 /yr	13-Jul-2010	1,595 cc	92,000 km	Sedan	Available
Tip Top Condition, Very Well Maintained, High OMV And Low Mileage (92000 Km Only!). Road Tax Till Jan 2019. Next Servicing On 98000 Km. Kindly Drop An Email With Contact Number If You Are Keen.									
Posted: 02-Nov-2018 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2018 14:26
Date Of Accident	10/11/2018 10:25
Exact Location Of Accident	ALONG ALJUNIED RD TWDS GEYLANG (OUTSIDE ESSO STATI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY1153K
Insured/Policyholder	
Name Of Registered Owner	SIM CHUN SIONG VINCENT
NRIC No	S7130112E
Email Address	VINCENT.SIM@POWERLOGICASIA.COM
Mobile Phone No	(LOCAL) +65-96867067
Alternative Phone No	OFFICE-96867067

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P0964020
Cover Note Number	

Driver

Name of Driver	SIM CHUN SIONG VINCENT
NRIC No	S7130112E
Date Of Birth	25/08/1971
Occupation	INDOOR
Date Of Driving Pass	07/06/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96867067
Fax Number	
Contact Number	OFFICE-96867067
Email Address	VINCENT.SIM@POWERLOGICASIA.COM

Address	BLK 403 SERANGOON AVE 1 #04-27
Postcode	550403
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT 10.20AM, I WAS TRAVELLING ALONG ALJUNIED ROAD AT A SPEED OF 50KM/HR TOWARDS GEYLANG. I WAS ON THE RIGHT SIDE OF A 2 LANES ROAD. WHILE I WAS GOING STRAIGHT, THE HONDA VEZEL CAME OUT OF NOWHERE ON THE LEFT AT A FAST SPEED AND HIT THE LEFT SIDE OF MY CAR. AT THAT INSTANCE, I HAD TO SWERVE TO THE RIGHT SWIFTLY.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD484Z
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	ERVIN SETHI
NRIC/Passport Number	
Contact Number	81983815
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 10:20am I was travelling along Aljunied Road at a speed of 50++ KM/H towards Geylang. I was on the right side of a two lane road. While I was going straight the Honda Vezel came out of nowhere on the left at a ~~fast~~ fast. 8th speed and hit the left side of my car. At that instance, I had to avert to the right swiftly.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 10/11/2018 12:07 PM
General Sketch Plan Form V3

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018		12 Nov 2018 17:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SUNIL KUMAR SETHI , ID: S1353262A									
Main Claimant: SIM CHUN SIONG VINCENT , ID: S7130112E									
Vehicle Reg. No.: SJY1153K		Date of Loss: 10/11/2018 10:00 - :59 [99 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1804917		Policy/Cover Note No.: D18MTPV01008239 (Comprehensive)							
Vehicle Reg. No. (Insured): SLD484Z		Policy No. (Claimant):							
		Excess:							
Repairer: Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB, 417895 Kaki Bukit - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/11/2018]									
Adj Asg. Remarks: - PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY1153K (CMTD1804917)
[SLD484Z]
TP
SIM CHUN SIONG VINCENT
Nov 10 2018 10:00AM
[SUNIL KUMAR SETHI]
Af Motorworkz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
2	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
3	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
4	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
5	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
6	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
7	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
8	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
9	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
10	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
11	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
12	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
13	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
14	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
15	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
16	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
17	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
18	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
19	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
20	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
21	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
22	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
23	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
24	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
25	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
26	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
27	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
28	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
29	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
30	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
31	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
32	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
33	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
34	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
35	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
36	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					
37	15/11/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
67	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
68	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
69	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
70	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
71	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
72	15/11/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
73	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	15/11/18 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/11/18 13:12	Certificate Schedule	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18020458/UCBE2

Date: 16/11/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01008239

Claimant Vehicle No: SJY1153K Insured Vehicle No: SLD484Z

Date of Loss: 10/11/2018 Nature of Claim: TP Claim No: CMTD1804917

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY1153K**
 Make & Model: HONDA CIVIC, 1.3 EC8 (M) Engine No: R18A15000203
 Reg. Date: 02/08/2010 (Man. Year: 2009) Chassis No: JHMF1630AS200033
 Colour: Black Odometer: 113460 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/11/2018

Date Inspected: 13/11/2018 Inspected At: Af Motorworkz Pte Ltd (HQ)
 66 KAKI BUKIT AVE 6, ARK@KB
 Singapore 417895

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts:	144	HONDA CIVIC 1.3 EC8 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY1153K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >