

ASS. REC. BY:

REF: CS/EGI/8020488/TISC317

Special Instruction:

Surveyor: Tau HiehASSIGNMENT (Office)From (Person): Yee pei Li of EGI Date/Time: 13/11/18 @ 10:22am

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKH 8393R Insured: YM 6929Sat Workshop in/s Kah Motor Tel: 64715419of 255 Alexander RoadPolicy No: _____ Claim No: YM 6929S/SA/pl

Sum Insured: _____ Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 02/11/1814/11/18 @ Morning

H.O.D. Endorsement: _____


CA / REV / REP. / REV 24 HRS (DS)

Date/Time: 10:13am @ 13/11/18 Person Contacted: Mr. NgVehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 8393R - NBA/INC/18019929 / Y DOA: 2/11/2018
	YM 6929S - NBA/INC/18019929 / Y DOA: 2/11/2018
15/11/18	@ 16:05 p.m. revised PA to PC L: via email.

ASSIGNMENT

From: Date:
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No:
 at Workshop / Mile:
 of:
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Veh No: SKH 8393K. Yr Regn: 2017 May
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: Honda HRV C.C. 1496
 Colour: Black A/C Insured / Std / NI / NA
 Sp. Reading: 19237 T/Radio: Insured / Std / NI / NA

Eng/No:
 CNo: JHM RU18306X-201908
 Gen. Cond. Good / Fair / Poor / Burnt

Sleering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/60R16
 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: R/Bal. 6 mm L/Bal. 6 mm D.O.A. 14/11/18 @ 1145
 Rear: R/Bal. 6 mm L/Bal. 6 mm

Survey held at: Mohd Nur Hafiz
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
 23/11/18 Confirmed P/P \$ 6,299.63 @ 5 days with Resul.
 (\$ 4,504.15 Rd - 42%)

RECEIVED 26 NOV 2018

Date/Time: File Page 207
 26/11/18 Typist
 Date/Time: File Return 107
☐ : Prel. Report
☒ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Weekend \$

Survey Fee
 Transportation:
 1. 2. 3. 4. 5. 6. 7. 8. 9. 10.
 TOTAL

350
 350

Report Format:
 Lump Sum / I.B./ \$ 6,299.63 P/P

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 13 November 2018 10:22 AM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : YM6929S / TP : SKH8393R/LKK / DOA : 02/11/2018
Attachments: YM6929S - SAS.pdf; SKH8393R - SAS.pdf; SKH8393R - PRS FORM.pdf; RE: 3rd party direct settlement for Skh8393R/ & your insured YM6929S /DO... (34.9 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **KAH MOTO CO. SDN. BHD.**,

ADDRESS : 255 ALEXANDRA ROAD
SINGAPORE 159937

PERSON TO CONTACT : NG SIN HAI @ 6471 5419

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on DIRECT SETTLEMENT basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 05.11.2018
Our Reference: YM 6929S/SA/pl
Your Reference: SKH 8393R

To: KAH MOTOR CO. SDN BHD

Sent via Fax
or
Email shng@kahmotor.onmicrosoft.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKH 8393R
Insured's Vehicle: YM 6929S
Date Of Accident: 02.11.2018

We acknowledge receipt of your request for PRS on: 02.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - SITI</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 10:53 AM
To: 'Ng Sin Hai'
Cc: Taufikh (LKKAuto); SUR
Subject: RE: Submission Pre-Invoice for vehicle SKH8393R

Hi Sin Hai,

Confirmed final fig of \$ 6,299.63 (part by part) @ 5 days of repairs before GST.

Final invoice and all supporting documents sent over to ERGO Insurance Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Saturday, 17 November 2018 10:21 AM
To: Taufikh@lkkauto.com; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SKH8393R

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$6,299.63 (before GST)

No of working days : 05 days. (LOR)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai
Sent: Tuesday, 19 June, 2018 9:54 AM
To: Taufikh@lkkauto.com; 'SUR' <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SLK1294R

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 15 November 2018 4:05 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; Admin-D (LKKAuto)
Subject: RE: YM6929S / TP : SKH8393R/LKK / DOA : 02/11/2018
Attachments: SKH 8393R - Preli Advise.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SKH 8393R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 13 November 2018 10:22 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : YM6929S / TP : SKH8393R/LKK / DOA : 02/11/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **KAH MOTO CO. SDN. BHD.,**

ADDRESS : 255 ALEXANDRA ROAD
SINGAPORE 159937

PERSON TO CONTACT : NG SIN HAI @ 6471 5419

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on DIRECT SETTLEMENT basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YM6929S/SA/pl

Date: 15 November 2018

Our Ref: CS/EG118020488/T1sd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKH 8393R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2018 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,603.54</u>
Revised Estimate Amount	: <u>S\$ 6,111.99</u>
"Check" Items Amount	: <u>S\$ 320.00</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2018 10:55
Date Of Accident	02/11/2018 08:30
Exact Location Of Accident	BLK 699A HOUGANG STREET 52
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH8393R
Insured/Policyholder	
Name Of Registered Owner	ZHANG GUANGQING
NRIC No	S8506581E
Email Address	EDMUNDZG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98368876
Alternative Phone No	OTHERS-98368876

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PICK UP PARENT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104814972
Cover Note Number	

Driver

Name of Driver	ZHANG GUANGQING
NRIC No	S8506581E
Date Of Birth	10/03/1985
Occupation	INDOOR
Date Of Driving Pass	09/05/2007
Driving Experience	11 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98368876
Fax Number	
Contact Number	OTHERS-98368876
Email Address	EDMUNDZG@GMAIL.COM

Address	BLK 470B UPPER SERANGOON ROAD #14-320
Postcode	532470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM6929S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 2/11/2018
10.45am

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Joseph Lim
NRIC/FIN No.: 1011111111

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked and stationary -
 A lorry was behind me, stationary at point of parking.
 A few minutes later the lorry reversed and hit my car from the back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 2/11/2018
 10.45AM

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Kishu Kumar
 NRIC/FIN No.:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985

Registration No : SKH8393R

Chassis No : JHMRU1830GX201908

Model : HRV LX-SIN CVT YM 2016

Owner's Name : ZHANG GUANGQING

Ins Policy No. :

Date of Accident : 2/11/2018

Document No. : SQT18004718

Date : 2 Nov 2018

Customer No. : WZN004

Svc Advisor :

Engine No : L15B4531908

Date | Time : 2 Nov 2018 6:42:11 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:ZHANG GUANGQING OWNER INSURER:NTUC ACC DATE:02/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER:ERGO TP VEH:YM6929S						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	SEALANT FOR TAILGATE	1	80.00	✓	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	✓	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	✓	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	✓	80.00	5.60	85.60
BOMISC1	RESET AND CALIBRATE ALL SMART ENTRY	1	560.00	380	560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL.	1	2500.00	1120	2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00	900	2000.00	140.00	2140.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00	✓	380.00	26.60	406.60
				Sum Labor	7740.00	541.80	8,281.80
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00	✓	320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR.	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R,LID	1	269.90	25	202.42	14.17	216.59

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985

Registration No : SKH8393R

Chassis No : JHMRU1830GX201908

Model : HRV LX-SIN CVT YM 2016

Owner's Name : ZHANG GUANGQING

Ins Policy No. :

Date of Accident : 2/11/2018

Document No. : SQT18004718

Date : 2. Nov 2018

Customer No. : WZN004

Svc Advisor :

Engine No : L15B4531908

Date | Time : 2. Nov 2018 6:42:11 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
34155-T7A-J01	LIGHT ASSYLID	1	X 269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	TAIL GATE COMP	1	bt 855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	X 98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE	1	X 78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	X 136.00	25	102.00	7.14	109.14
75722-T7W-A01	EMBLEMRR.	1	ne 13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	X 156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	X 156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	X 94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	X 94.10	25	70.57	4.94	75.51
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	X 11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	X 11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	8	ne 2.30	25	13.80	0.97	14.77
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	ne 19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	ne 8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	ne 19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	ne 4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	ne 3.50	25	10.50	0.74	11.24
91502-S70-003	FASTENER B	2	ne 5.20	25	7.80	0.55	8.35
91536-SS0-J01	FASTENER AW/SHIELD	2	ne 3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	ne 60.00		120.00	8.40	128.40
Sum Item					2863.54	200.46	3,064.00

Survey By

Date & Time

Excess

Status

Signature

Tanphk 97495446
14/11/18 2:11:45
wp

16/11/18

5 days

Resurvey before paid
sur@hkauto.com

10,803.35

Total Amount 10,803.54 742.28 11,345.80

Total (Inclusive of GST) 11,345.80

the Repairer of the following:

- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/11/2018 6:59:23 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S8506581E / ZHANG
 Chassis No: JHMRU1830GX201908
 License No: SKH8393R
 Mileage: 16189
 Engine No: L15B4531908

Document No: SVO18067611
 Printed By: SHNG
 Order Date: 14. November 2018
 Order Time: 11:57:55 AM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incd GST
	SUPPLEMENTARY						
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
34100-T5A-003	LIGHT ASSYLICENSE	1	31.80	25	23.85	1.67	25.52
74890-T7A-J12ZD	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36
91513-T6A-003	CLIPTAILGATE SPOILER	9	2.50	25	16.87	1.18	18.05
	SUM PARTS:				200.24	14.01	214.25
	TOTAL SGD				200.24	14.01	214.25

Total Payable (SGD)

214.25

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZN004 / ERGO INSURANCE
Chassis No: JHMRU1830GX201908
License No: SKH8393R
Mileage: 16189
Engine No: L15B4531908

Document No: SVO18067611
Printed By: SHNG
Order Date: 14. November 2018
Order Time: 11:57:55 AM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:ZHANG GUANGQING OWNER INSURER:NTUC ACC DATE:02/11/2018 SURVEYED BY:TAUFIK DATE:14/11/2018 REF NO: TP INSURER:ERGO TP VEH:YM6929S						
33502-T7A-J01	LAMP UNTR.	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	3.50	25	10.50	0.74	11.24
91502-S70-003	FASTENER B	2	5.20	25	7.80	0.55	8.35
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
34100-T5A-003	LIGHT ASSYLICENSE	1	31.80	25	23.85	1.67	25.52
74890-T7A-J12ZD	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36
91513-T6A-003	CLIPTAILGATE SPOILER	9	2.50	25	16.87	1.18	18.05
	SUM PARTS:				1,569.63	109.88	1,679.51
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	1729 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	1718 SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	1718 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BMI02D	1729 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	280.00		280.00	19.60	299.60
BKTG02R	1729 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20
BG02D	1438 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00		560.00	39.20	599.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZN004 / ERGO INSURANCE
Chassis No: JHMRU1830GX201908
License No: SKH8393R
Mileage: 16189
Engine No: L15B4531908

Document No: SVO18067611
Printed By: SHNG
Order Date: 14. November 2018
Order Time: 11:57:55 AM
Service Advisor: NG SIN HAI

BODAMKIT	1438	1	80.00	80.00	5.60	85.60
	WINDSCREEN DAM KIT.					
BOMISC1	1438	1	380.00	380.00	28.60	408.60
	RESET AND CALIBRATE ALL SMART ENTRY					
BKRP02M	1729	1	1,120.00	1,120.00	78.40	1,198.40
	CUT OFF & RENEW RR PANEL					
	RR FLOOR PAN & RENEW DAMAGE PARTS.					
BP06R	1718	1	900.00	900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					
	REAR PORTION					
BKBU01R	1438	1	380.00	380.00	28.60	408.60
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA					
			SUM LABOUR:	4,730.00	331.10	5,061.10
			TOTAL SGD	6,299.63	440.98	6,740.61
Total Payable (SGD)						6,740.61

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18020488/T1sd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 05-12-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 6929S	Veh. Inspected	SKH 8393R	
Policy No.		Coverage (\$)	0.00	
Claim No.	YM6929S/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1830GX201908	Colour	BLACK	
Odometer	19237	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2018	Inspection Date	14/11/2018	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 8393R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	VPC 4PCS REAR SENSORS (SN)	NOT NECESSARY	320.00	-
1	LAMP UNITR. (SN)	CRACKED	331.12	331.12
1	LAMP UNITL. (SN)	NOT NECESSARY	331.12	-
1	LIGHT ASSY, R.LID (SN)	CRACKED	202.42	202.42
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	202.42	-
1	TAIL GATE COMP (SN)	BENT	641.77	629.17
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	74.02	-
1	LOCK ASSYTAILGATE (SN)	NOT NECESSARY	59.17	-
1	LINING ASSYTAILGATE (SN)	NOT NECESSARY	102.00	-
1	EMBLEMRR. (SN)	NECESSARY	9.97	9.97
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	117.22	-
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	117.22	-
1	FACER.RR.BUMPER CORNER (SN)	NOT NECESSARY	70.57	-
1	FACEL.RR.BUMPER CORNER (SN)	NOT NECESSARY	70.57	-
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
8	CLIP, BUMPER (SN)	NECESSARY	13.80	13.80
1	RUBBER CR.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
1	RUBBER CL. WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (SN)	NECESSARY	10.50	10.50
2	FASTENER B (SN)	NECESSARY	7.80	7.80
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.70	5.70
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	EMBLEM,RR.I-VTEC (SN) (ADDITIONAL)	NECESSARY	10.87	10.87
2	GROMMET SCREW (SN) (ADDITIONAL)	NECESSARY	3.45	3.45
1	LIGHT ASSYLICENSE (SN) (ADDITIONAL)	CRACKED	23.85	23.85
1	GARNISH ASSYRR.LICENSE (SN) (ADDITIONAL)	CRACKED	145.20	145.20

Report Ref No. CS/EGI18020488/T1sd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
9	CLIPTAILGATE SPOILER (SN) (ADDITIONAL)	NECESSARY	16.87	16.87
			3,163.78	1,599.63
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		180.00	180.00
	SEALANT FOR TAILGATE.		80.00	80.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	180.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		560.00	560.00
	REMOVE & INSTALL RR. WINDSCREEN.		560.00	560.00
	WINDSCREEN DAM KIT.		80.00	80.00
	RESET AND CALIBRATE ALL SMART ENTRY.		560.00	380.00
	CUT OFF & RENEW RR PANEL.		2,500.00	1,120.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		2,000.00	900.00
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.		380.00	380.00
			7,640.00	4,700.00
GRAND TOTAL			10,803.78	6,299.63
RECOMMENDED COST OF REPAIRS				6,299.63

Report Ref No. CS/EGI18020488/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.