

ASS. REC. BY:

REF: CS3/AIG18020499/Jcd32

Special Instruction:

Surveyor: Hwee Jee  
Momen

ASSIGNMENT (Office)

From (Person): Chin Jee Ying

of

AIG

Date/Time: 13/11/2018 @ 11:08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 4889Y

Insured:

SGH 5959B

at Workshop m/s

Eclipse Auto

Tel:

81288789

of

155 Kaki Bukit Ave 1 - Shun Li Ind. Park Level 1

Policy No:

2100476341

Claim No:

2929691479SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

12:40pm @ 13/11/18

Person Contacted:

Frankie

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SLG 4889Y - X</u>
	<u>SGH 5959B - X</u>
	<u>Diamondle: 14/11/2018</u>

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 13/11/2018  
 Estimated Cost: \_\_\_\_\_  
 OD  TP  WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLG 4889Y  
 at Workshop m/s Eclipse Auto  
 of 155 kaki Bukit Ave 1, shun ti Ind. Park  
 Insured: Level 1  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: Frankie @ 8128 8789

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : **Yes** or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or No  
 Est. Repairs: 6 days Res.: **Yes** or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or No  
 CA / REV / REP. / 24 HRS <sup>(up)</sup>  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLG 4889Y Yr Regn: 30 Sep 2016  
 Type:  M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mercedes C200 c.c. 1991  
 Colour: Green A/C: Insured / Std / NI / NA  
 Sp. Reading: 26353 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD2053422F338693  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 275/30 R19  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU  PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 6/11/18 D.O.I. 13/11/18  
 Survey held at — @ 1515  
 Des. of Damages  Front / Rear / O/S / N/S / U/C / Rooftop or  
Front  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>6 days</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format : DAR  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 6  
 Resurvey No. of Trip: 1  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	<u>180</u>
Transportation:	_____
Photos	_____
Others	<u>20</u>
<b>TOTAL</b>	<b><u>200</u></b>

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying

To: assignments

Cc: Fong, Andy-SY

Sent: 13/11/2018 11:08:36 AM

Attachments:  [VCS FORM1.pdf](#)  [SLG4889Y GIA.PDF](#)  [LIST OF SURVEYORS.PDF](#)  
 [FORM3 SLG 4889Y.PDF](#)

---

Hi LKK,

Kindly assist to survey by today, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VEHICLE CLAIMS SPECIALIST PTE LTD  
UEN 201802773H

Date: 12<sup>th</sup> November 2018

Your ref: SGH 5959B

BY EMAIL ONLY

Our ref: VCS/SLG 4889Y/EA/PD

**To: AIG ASIA PACIFIC INSURANCE PTE LTD**

Attn: Motor Claims Dept

Dear Sirs,

**CORRESPONDANCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION  
PROTOCOL FOR NIMA CASES.**

We refer to your email dated 12<sup>th</sup> November 2018.

Please note that the said vehicle can be inspected at:

**ECLIPSE AUTO PTE LTD**

155 KAKI BUKIT AVE 1  
SHUNLI IND.PK LEVEL 1  
SINGAPORE 416012

Contact No: 81288789

**Please call for to arrange for an appointment before conducting the pre-repair inspection.**

Please note that the vehicle will be available for pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without further notice or reference to you. All our client's right are expressly reserved.

**PLEASE REPLY BY EMAIL ONLY : VCSSG01@GMAIL.COM**

**DO NOT REPLY BY FAX**

Yours faithfully

**VCS**  
Vehicle Claims Specialist Pte Ltd

VEHICLE CLAIMS SPECIALIST PTE LTD  
UEN 201802773H

*PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING*

Date: 9<sup>th</sup> November 2018

Your ref: SGH 5959B

*BY FAX ONLY*

Our ref: VCS/SGH 5959B/EA/PD

(6415 3727)

**To: AIG ASIA PACIFIC INSURANCE PTE LTD**

Attn: Motor Claims Department

Dear Sirs,

**NOTICE OF ROAD TRAFFIC ACCIDENT ON 6<sup>th</sup> NOVEMBER 2018 INVOLVING  
MOTOR VEHICLE NO. SLG 4889Y AND SGH 5959B AT BLK 65A KALLANG  
BAHRU DECK 1A LOT 20 AT ABOUT 2130 HOURS. PURSUANT TO  
PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES**

We represent for DREAM CAR LEASING PTE LTD to formally notify you of a road traffic accident as described above involving our customer's vehicle number SLG 4889Y and vehicle number SGH 5959B which was driven by you/your authorize driver, servant and/or agent at the material time. A copy of the Singapore Accident Statement Report filed is enclosed.

We are instructed to propose the use of one of the motor surveyors named in the attached list to conduct the pre-repair survey as a single joint expert.

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. Failing which our customer / we shall proceed to repair the vehicle without further reference to you.

**PLEASE REPLY BY EMAIL ONLY : [VCSSG01@GMAIL.COM](mailto:VCSSG01@GMAIL.COM)**

**DO NOT REPLY BY FAX**

Yours faithfully

**VCS**  
Vehicle Claims Specialist Pte Ltd  
Enc.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0013Z
Vehicle Details	
Vehicle No.:	SLG4889Y
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AMG
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	27492030514463
Chassis No.:	WDD2053422F338693
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$48,049.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$54,269.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$40,701.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$43,691.00
<b>Total Rebate Amount:</b>	<b>\$84,392.00</b>

The information contained herein is correct as at 15 Nov 2018

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	08/11/2018 12:07
Date Of Accident	06/11/2018 21:30
Exact Location Of Accident	BLK 65A KALLANG BAHRU DECK 1A LOT 20
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4889Y
Name Of Registered Owner	DREAM CAR LEASING PTE LTD
Co Reg No	0 201420013Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67489747
Manufacturer	MERCEDES-BENZ
Model	C200 AMG LINE (R18 LED)-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMPPHQ18-006632
Cover Note Number	

Name of Driver	KOH BEE HONG
NRIC No	S6928566Z
Date Of Birth	18/08/1969
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2004
Driving Experience	14 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96953595
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 64 KALLANG BAHRU #09-361  
Postcode 330064  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
Weather Conditions CLEAR  
Road Surface DRY

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 0

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,  
POSTCODE: 319194 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

REFER TO POLICE REPORT.

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGH5959B  
Vehicle Make/Model/Colour JAGUAR XJL  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver KWEK SENG LEE  
NRIC/Passport Number S7521041H  
Contact Number 98515959  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:



  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S6928566Z



Name  
KOH BEE HONG  
許美凤

Race  
CHINESE

Date of birth  
18-08-1969

Sex  
F

Country/Place of birth  
SINGAPORE




S6928566Z

4331764




NRIC No. S6928566Z




Date of issue  
12-09-2014

ADDRESS  
APT BLK 64 KALLANG BAHRU  
#09-361  
SINGAPORE 330064

5351764



NRIC No S6928566Z



Date of Issue  
12-09-2014

Address  
APT BLK 64 KALLANG BAHRU  
#09-361  
SINGAPORE 330064


**PUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number S6928566Z

Name  
KOH BEE HONG

*pass date*  
30/1/2004

Birth Date 18 Aug 1969  
Issue Date 23 Jun 2014



002318001H



**SINGAPORE  
POLICE FORCE**



T/20181107/2003

-1 of 3

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

Report No. T/20181107/2003

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/11/2018 01:44	Vide Report No.: A/20181106/0233	Station Diary No.: 10
--	-------------------------------------	--------------------------

## Informant's Particulars

Name of Informant: KOH BEE HONG		Address: APT BLK 64 KALLANG BAHRU #09-361 SINGAPORE 330064	
ID Type / ID No.: NRIC NO / S6928566Z		Contact No.: Home/Office:                      Mobile: 96953595	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 49	Date of Birth: 18/08/1969	Type of Informant: Vehicle Owner
Race: Chinese		Language: English	Institution / School Name:
Occupation: CAR RENTAL SALES PERSON		Driving Licence Information: Class: 3	Date of Expiry:

## General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink: Drive: No	Date/Time of Accident: 06/11/2018 10:15	Type of Location: Car Park
Location: Along Road 1 KALLANG BAHRU at Blk 65A Kallang Bahru, which is a MSCP, Deck 1A, unknown lot number			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLG4889Y	Car	MERCEDES BENZ	C200 AMG	Silver	Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20181107/2003

BI  
2 of 3

Police Station Of Origin:  
Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

Report No. T/20181107/2003

CONTINUATION OF REPORT

Vehicle Owner			
Name	KOH BEE HONG	ID No.	S6928566Z
Related Vehicle	SLG4889Y (Car)	Contact No.	96953595
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 06/11/18 at about 1015hrs, I parked my company's vehicle bearing registration no. SLG4889Y at Blk 65A Kallang Bahru, which is a multi-story carpark. I had parked my vehicle at Deck 1A, unknown lot number. Before I left my vehicle, I noted everything to be intact and undamaged.

However, on the same date at about 1045hrs, I returned to my vehicle, only to discover that the front bumper and registration plate of my vehicle were dislodged. I then retrieved the camera footage from the camera installed at the front of my vehicle, and realised that one silver Jaguar model car of unknown registration no. had collided against the front side of my vehicle while turning after it drove down from the upper deck.

Subsequently, I called the traffic police, and they came down to the scene and attended to me. Before they left, they took the SD card of my camera containing the footage, and advised me to lodge an accident report, vide A/20181106/0233.

I wish to state that the said vehicle had drove too fast, and I could not verify the car plate number of the said vehicle. The date and time stated on my camera was incorrect.

Common Statement



**SINGAPORE  
POLICE FORCE**



T/20181107/2003

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

3 of 3  
Report No. T/20181107/2003

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sgt 2 MARCUS TEO

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
07/11/2018 01:44

Officer In Charge Of Case:  
TP / HRT /  
Sr Staff Sgt TAN JEOK LENG  
Contact No.: 65476144

Classification Of Case:  
SN 168

Authentication Stamp  
NP168

Sorry I hit your car last  
Night.

Please call 98518959  
for settlement (Mr Kanchaj)

**MOTOR CAR (Frt)**

**Front Portion**

Vehicle No: **SLG 4889Y**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	MIS	/	1
1002	991887	Frt Number Plate Base	CRA	/	1
1003	991889	Frt Number Plate Garnish	CRA	/	1
1004	991300	Frt Bumper	DB	/	1
1005	992341	Frt Bumper Clips	NEC	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	/	
1008	991433	Frt Bumper Reinforcement		?	
1009	991318	Frt Bumper Beam	DIS	/	
1010	991468	Frt Bumper Sponge	CRA	/	1
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper <b>Low Eye Cover</b>		?	
1013	991363	Frt Bumper Grille	CRA	/	1
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	CRA	/	1
1016	991438	Frt Bumper Sensor		?	4
1017	995100	Frt LH Bumper Fog Lamp Cover		?	
1018	991355	Frt RH Bumper Fog Lamp Cover		?	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	/	1
1022	991328	Frt Grille Emblem	CRA	/	1
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	CRA	/	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy		?	
1030	991821	Frt RH Headlamp Assy	CRA	/	2
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			?
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			SCR R
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			CRA
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		<b>RH Headlamp Lower Bracket</b>			?

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2018 <a href="#">Edit Reg</a>		13 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>KWEK SENG LEE</b> , ID: S7521041H								
Main Claimant:	<b>DREAM CAR LEASING PTE LTD</b> , Co. Reg. No.: 201420013Z								
Vehicle Reg. No.:	<b>SLG4889Y</b>	Date of Loss:	06/11/2018 21:00 - :59 [25 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 2929691479SG</b>		Policy/Cover Note No.:	2100476341 (Comprehensive)					
Vehicle Reg. No. (Insured):	<b>SGH5959B</b>	Policy No. (Claimant):							
Repairer:	<b>Eclipse Auto Pte Ltd (HQ)</b> 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01, 416012 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 22/11/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (14/11/2018): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG4889Y (2929691479SG)  
[SGH5959B]  
TP  
DREAM CAR LEASING PTE LTD  
Nov 6 2018 9:00PM  
[KWEK SENG LEE]  
Eclipse Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
<b>Video</b>															1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	16/11/18 14:58	TP video										 Load MP4	<input type="checkbox"/>				
<b>Photos/Images</b>															3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
2	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
3	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
4	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
5	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
6	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
7	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
8	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
9	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
10	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
11	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
12	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
13	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
14	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
15	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
16	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
17	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
18	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
19	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
20	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
21	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
22	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
23	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
24	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
25	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
26	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
27	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
28	15/11/18 13:57	General View										 Load JPG	<input checked="" type="checkbox"/>				
29	15/11/18 13:58	Photographs of Damaged Parts										 Load JPG	<input checked="" type="checkbox"/>				
30	15/11/18 13:58	Photographs of Damaged Parts										 Load JPG	<input checked="" type="checkbox"/>				
31	15/11/18 13:58	Photographs of Damaged Parts										 Load JPG	<input checked="" type="checkbox"/>				
32	15/11/18 13:58	Photographs of Damaged Parts										 Load JPG	<input checked="" type="checkbox"/>				
33	15/11/18 13:58	Photographs of Damaged Parts										 Load JPG	<input checked="" type="checkbox"/>				
34	15/11/18 13:58	Photographs of Damaged Parts										Load JPG	<input type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	15/11/18 13:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/11/18 10:22	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18020499/JCD3E2

Date: 27/11/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100476341
<b>Claimant Vehicle No :</b> SLG4889Y	<b>Insured Vehicle No :</b>	SGH5959B
Date of Loss: 06/11/2018	Nature of Claim: TP	Claim No: 2929691479SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLG4889Y</b>	
Make & Model:	MERCEDES-BENZ C200 AMG LINE (R18 LED), 2.0 (A)	Engine No: 27492030514463
Reg. Date:	30/09/2016 (Man. Year: 2016)	Chassis No: WDD2053422F338693
Colour:	Green	Odometer: 26353 km
Engine Capacity:	1991 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	275/30 R19	Rear Tyre Size:	275/30 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	13/11/2018	
Date Inspected:	13/11/2018 Inspected At:	Eclipse Auto Pte Ltd (HQ) 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01 Singapore 416012
Estimated Period of Repair:	6.0 days	

**Adjuster:** ONG HWEE JIE

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Cracked	0.00 F	*- F
4	1		*FRT BUMPER	Dented	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
8	1		*FRT BUMPER BEAM	Distorted	0.00 F	*- F
9	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
10	1		*FRT BUMPER TOW EYE COVER	* Check	0.00 F	*- F
11	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
12	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
13	4		*FRT BUMPER SENSOR	* Check	0.00 F	*- F
14	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
15	1		*FRT RH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
16	1		*FRT GRILLE	Cracked	0.00 F	*- F
17	1		*FRT GRILLE EMBLEM	Cut	0.00 F	*- F
18	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
19	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F
20	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
21	1		*ENGINE UNDER COVER	* Check	0.00 F	*- F
22	1		*FRT RH FENDER	Repair	0.00 F	*- F
23	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
24	1		*RH HEADLAMP LOWER BRACKET	* Check	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >