

Surgycor: MARINS DOI: 13/11/18 Date / Time: 13/11/18

Pre-assign / CCU / FTE: SJZ 6226 X Registered in Meriton: 13/11/18



Insured Vehicle No.: SJZ 6226 X
 Name of Insured: LOW LEUNG
 Insured Tel No.: HP: 9/11/18
 Excess Sec II :SS
 Is driver the owner? (YES / NO) Nature of Accident:

Claim No.:
 Policy No.:
 Make / Model: Lexus RX400
 Place of Accident: Whitley Rd

If NO, Driver Name / Age: Driver Tel No.: (YES / NO)
 CI GIA REPORT: (YES / NO) ; TP GIA REPORT: (YES / NO)
 Insured Liability: % Final ? Yes / No

S/CB 12270 → → → → →

INSRS: WSP: Tel: Liability: RMKS:	<u>Soc Leon</u> <u>roc 6226 X</u>	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
---	--------------------------------------	---	--	---	--	---

Date/Time	STAGE	DATE / PIC
<u>20/11</u>	<u>CRB 12270 - X</u>	<u>SJZ 6226 X - X</u>
<u>30/11</u>	<u>3VC 01 LAST</u>	
<u>19-12-18</u>	<u>LOD IN</u>	
	<u>FUR MANDATE</u>	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call CI:	
	After call ltr to CI:	<u>19-12-18 JUY</u>
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to CI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	P/B:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

FINAL SETTLEMENT Date/Time: 16-5-19 Confirm with: TRENE Email: Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28
 Repair Cost: \$ 12,600
 Loss of Rental (LOR): \$ - (7 days)
 Loss of Use (LOU): \$ 700 (3/00 x 7 days)
 Loss of Income (LOI): \$ - (3 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: \$ 2.2V
 Medical: \$ -
 Disbursement: \$ - (e.g. Tow/Independent)
 Legal Cost: \$ -
 Total: \$ 11,300 Global Sum SS: 10,302.22
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee:

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: \$ 10,302 Name 1: SOC LEON MOTOR WORKS
 Payee 2: (Strike if N.A.) \$ X Name 2: X
 Payee 3: (Strike if N.A.) \$ X Name 3: X

REF: ALG

ASSIGNMENT

From: Date 13/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKB1222D

at Workshop no: Soc Leon Motor

of 1 Kaki Bukit Ave 6 #01-71

Insured: SJE6226X

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 356.

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lump Sum: 21 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: next 12504

Veh No: SKB1222D Yr Regn: 29/9/09

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA /

Make: Lexus GS450H cc 3458

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 101027 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHBC965925020004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40Z R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A: 9/11/18 D.O.I: 13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/11/18 LTA 22496 10mb, plus rep 16500. Confused L/S #10.600 with reason

R (B6, 7A 2.34/397)

Date/Time File Pass to?

: Prel. Report

Days Of Repair:

11

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time File Return to?

Transportation

12

Add Fee: Site Insp (S)

(S+P) (S)

Interview (S)

(P) (S)

Tech Insp (S)

(C) (S)

Weekend (S)

(S)

Report Format :

Lump Sum / I.B.f: (S)

TOTAL

REPAIRING OF
MOTOR VEHICLES
PANEL BEATING
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速良摩'哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmor@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

M/S YONG LEE SENG HOLDINGS PTE LTD

DATE: 12/11/2018

DOA: 09/11/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKB 1222D (LEXUS GS450H)

	Description		List Price	
1 pc	Rear bootlid	but/bul	\$ 1,217.85	✓
2 pcs	Bootlid hinge @S\$274.45	17	\$ 548.90	X
1 pc	Bootlid lock	twl	\$ 581.90	✓
1 pc	Bootlid weatherstrip	twl	\$ 274.10	✓
1 pc	Hinge side garnish (near rear fender) 115.10	topn	\$ 278.45	✓
1 pc	Bootlid lower garnish	tro	\$ 281.90	✓
1 pc	Logo	rel	\$ 121.10	✓
1 pc	Lexus emblem	rel	\$ 124.45	✓
1 pc	GS450h emblem	rel	\$ 131.35	✓
1 pc	Limited emblem	rel	\$ 121.10	✓
1 pc	Rear lh fender	ra	\$ 1,200.50	α
1 pc	Taillamp (lh)	bro	\$ 581.90	✓
1 pc	Taillamp panel (lh)	n	\$ 374.45	X
1 pc	Rear bumper	rb	\$ 978.10	✓
1 pc	Towing cover 60	to.1	\$ 121.10	✓
1 pc	Bumper side retainer (lh)	but	\$ 134.45	✓
1 pc	Bumper reinforcement	but	\$ 581.90	✓
1 pc	Sponge	top	\$ 78.00	✓
1 pc	Rear end panel	but/bul	\$ 972.10	✓
1 pc	Panel top garnish	twl	\$ 561.60	✓
1 set	Rear windscreen moulding	17	\$ 274.85	α
1 pc	Front bumper	no/re	\$ 972.45	✓
2 pcs	Bumper side retainer @S\$171.10	but	\$ 342.20	✓
1 pc	No plate garnish	but	\$ 182.25	✓
20 pcs	Bumper clips @S\$12.90 60	rel	\$ 258.00	✓
1 pc	Lower grille	n	\$ 274.45	α
1 pc	Front grille	cm	\$ 591.60	✓
1 pc	Grille chrome	cm	\$ 377.75	✓
1 pc	Logo	den	\$ 172.45	✓

not affect
also
2/s \$10,600
1 day
13/11/18
take the money

1 pc	Headlamp (rh)	cm	\$	1,712.85	0
1 pc	Chrome rim	17	\$	378.55	2
			\$	14,802.60	
			\$	(1,480.26)	
			\$	13,322.34	
	<u>Special Nett Items</u>				
	<u>Towing fee (By king dolley)</u>		\$	150.00	120
1 set	No. plate & housing	cm	\$	60.00	40
1 set	Reverse sensor	Shrub	\$	280.00	200
	To remove & fix reverse sensor		\$	80.00	50
	To spray anti-rust		\$	180.00	60
	To remove & fix rear windscreen glass	17	\$	150.00	X
	Rear windscreen gum	17	\$	50.00	X
	Labour charges for knocking & replacing parts.		\$	1,600.00	1200
	Spraypainting		\$	1,500.00	1400
	TOTAL :		\$	<u>17,372.34</u>	

3070

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速 良 摩 哆
SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 20663900K

修理汽車貨車兼
打嗎甲燒好噴漆
代理保險：車禍
賠償及買賣汽車

30 November 2018

AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Department)
78 Shenton Way #08-16
Singapore 079120

Dear Sir/Madam,

**RE: ACCIDENT ON 09/11/2018 ALONG WHITLEY RD INVOLVING YOUR INSURED'S
VEHICLE SJZ 6226X AND OUR CLIENT'S VEHICLE SKB 1222D**

We are assisting our client, M/s Yong Lee Seng Holdings Pte Ltd, the owner of vehicle no. SKB 1222D in the above matter.

Please note that the above accident was caused by the driver of vehicle no. SJZ 6226X which was insured with you at the time of accident. As a result of the accident, our client's vehicle has suffered damages and was put to loss and expenses as follows:

1) Repair cost	S\$ 10,600.00
2) Loss of use for 7 days @S\$150 per day	1,050.00
3) Search fee	2.00
TOTAL	<u>S\$ 11,652.00</u>

We enclosed herewith all relevant documents for your perusal.

Hope to receive your reply soonest possible.

Yours faithfully



SOC LEON MOTOR WORKS

Encl. Final repair bill/Letter of Authority
Accident Statement/Cert of Insurance
Search letter

Print Received Message

This mail is associated with :

***SKB1222D (6057512899SG)**
[SJZ6226X]
TP
YONG LEE SENG HOLDINGS PTE LTD
Nov 9 2018 12:00AM
[LOW LIANG]
Soc Leon Motor Works

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 25/04/2019 16:40 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10302.00) - SKB1222D - Claim Handler: MdNoor, Norsiah

Approved:10302.00:Cost of repair \$ 8,000.00 (repair limit)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18020503/Uja3

19 December 2018

LOW LIANG
8 ROBIN LANE
SINGAPORE 258238

Dear Sir/Madam,

ACCIDENT INVOLVING SJZ 6226X / SKB 1222D / OTHERS ON 09/11/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Joy Irene
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

TO WHOM IT MAY CONCERN

LETTER OF AUTHORITY

Accident on 9/11/18 at Whitley Rd before turning right into Malvern Rd involving SKB 1222D, SJZ 6226X & SGP 4536D

I/We, Yong Lee Seng Holdings Pte Ltd

NRIC No. 200708336N of _____

_____, owner of Motor Vehicle Registration No. SKB 1222D insured by NTUC Income Insurance Co-operative Ltd under Policy No. 50684 83255-04 do hereby authorise M/S. SOC LEON MOTOR WORKS, 1 Kaki Bukit Ave 6 Blk D 01-91, Singapore 417883 as my/our authorised representative to write, negotiate & settle claim on my/our behalf in my/our claim against the owner/or driver of Motor Vehicle Registration No. SJZ 6226X in respect of the abovementioned accident.

I/We also hereby authorise that the agreed settlement sum be made in favour of my/our representative, M/S. SOC LEON MOTOR WORKS and that the said payment be forwarded to them as full and final discharge of my/our claim.

I/We hereby exonerate the AIG Asia Pacific Insurance Pte Ltd

_____ and/or their insured and/or driver of Vehicle No. SJZ 6226X from any liability after payment of any claim to my/our authorised representative M/S. SOC LEON MOTOR WORKS.

Dated: 9-Nov-2018

Signature X

(Co's Stamp if necessary)



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **SOC LEON MOTOR WORKS** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$10,302.00** (Global Sum) for vehicle no. **SKB 1222D** that was damaged pursuant to the accident which occurred on **09/11/2018** (date) along **WHITLEY ROAD** (location) involving vehicle no/s **SJZ 6226X**. This is pursuant to the inspection conducted on **13/11/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **YONG LEE SENG HOLDINGS PTE LTD** ("the third party claimant") of vehicle no. **SKB 1222D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKB 1222D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17th (day) of May (month) 2019 (year)



OKS

Signed by appointed surveyor

速 良 摩 哆
SOC LEON MOTOR WORKS
AUTOBAY@KAKI BUKIT
1 Kaki Bukit Avenue 6 #01-91
Singapore 417883
Tel: 8747 7858, 8747 2343

Signed by "the workshop" (with chop)

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆
SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 20663900K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

M/S YONG LEE SENG HOLDINGS PTE LTD

DATE: 30/11/2018

DOA: 09/11/2018

INVOICE NO : 8056

REPAIR COST FOR VEHICLE NO. SKB 1222 D (LEXUS GS450H)

LUMP SUM AT COST OF REPAIRS

S 10,600.00

速 良 摩 哆
SOC LEON MOTOR WORKS

.....
Authorized Signature



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-174377

Date of Request: 12/11/2018

Your Ref No:

Online Purchase

Soc Leon Motor Works
 1 Kaki Bukit Ave 6, #01-91
 AutoBay@Kaki Bukit
 Singapore 417883

Dear Sir/Madam,

Enquiry Date: 12/11/2018

Enquiry By: IRENE LEONG SUM PHENG

TP Vehicle No.: SJZ6226X

Accident Date: 09/11/2018

SKB 1222 D

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJZ6226X	AIG Asia Pacific Insurance Pte. Ltd.	30/05/2018-29/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-174377

Date of Request: 12/11/2018

Your Ref No:

Online Purchase

 Soc Leon Motor Works
 1 Kaki Bukit Ave 6,#01-91
 AutoBay@Kaki Bukit
 Singapore 417883

Dear Sir/Madam,

 Enquiry Date: 12/11/2018
 Enquiry By: IRENE LEONG SUM PHENG
 TP Vehicle No: SJZ6226X
 Accident Date: 09/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018 Edit Reg		13 Nov 2018 00:00 Edit Adj Rpt	S\$10,600.00 Edit Estimates	S\$10,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LOW LIANG , ID: 514244573								
Main Claimant:	YONG LEE SENG HOLDINGS PTE LTD , Co. Reg. No.: 200706236N								
Vehicle Reg. No.:	SKB1222D	Date of Loss:	09/11/2018 00:00 - :59 [109 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6057512899SG	Policy/Cover Note No.:	2100251335 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJZ6226X	Policy No. (Claimant):	5068483255-04						
		Excess:							
Repairer:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AIG_SG_EXPRESS (25/04/2019): Alert - Adj Mandate Approved (S\$10302.00) - SKB1222D - Claim Handler: MdNoor, No... • AIG_SG_EXPRESS (07/03/2019): Alert - Adj Mandate Approved (S\$8702.00) - SKB1222D - Claim Handler: MdNoor, Nor... • AIG_SG (14/11/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB1222D (6057512899SG)**
[SJZ6226X]
TP
YONG LEE SENG HOLDINGS PTE LTD
Nov 9 2018 12:00AM
[LOW LIANG]
Soc Leon Motor Works

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	13/11/18 19:10	Chassis Number							Load JPG <input checked="" type="checkbox"/>		
2	13/11/18 19:10	Odometer Reading							Load JPG <input checked="" type="checkbox"/>		
3	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
4	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
5	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
6	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
7	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
8	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
9	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
10	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
11	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
12	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
13	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
14	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
15	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
16	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
17	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
18	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
19	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
20	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
21	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
22	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
23	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
24	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
25	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
26	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
27	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
28	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
29	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
30	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
31	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
32	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
33	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		
34	13/11/18 19:11	General View							Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/11/18 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
81	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
82	13/11/18 19:12	General View	 Load JPG	<input checked="" type="checkbox"/>
83	13/11/18 19:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	13/11/18 19:15	Reinspection Photo		<input checked="" type="checkbox"/>
85	13/11/18 19:15	Reinspection Photo		<input checked="" type="checkbox"/>
86	13/11/18 19:15	Reinspection Photo		<input checked="" type="checkbox"/>
87	13/11/18 19:15	Reinspection Photo		<input checked="" type="checkbox"/>
88	13/11/18 19:15	Reinspection Photo		<input checked="" type="checkbox"/>
89	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
90	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
91	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
92	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
93	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
94	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
95	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
96	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
97	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
98	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
99	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
100	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
101	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
102	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
103	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
104	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
105	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
106	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
107	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
108	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
109	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
110	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
111	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
112	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
113	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
114	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
115	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
116	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
117	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
118	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
119	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
120	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
121	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
122	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
123	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
124	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
125	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
126	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
127	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
128	13/11/18 19:16	Reinspection Photo		<input checked="" type="checkbox"/>
129	22/11/18 08:30	Reinspection Photo		<input checked="" type="checkbox"/>
130	22/11/18 08:30	Reinspection Photo		<input checked="" type="checkbox"/>
131	22/11/18 08:30	Reinspection Photo		<input checked="" type="checkbox"/>
132	22/11/18 08:30	Reinspection Photo		<input checked="" type="checkbox"/>
133	22/11/18 08:30	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	22/11/18 08:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	22/11/18 08:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/18 12:00	TP ESTIMATE - MARKED	 Load PDF	
2	19/11/18 12:00	TP GIA REPORT	 Load PDF	
3	07/01/19 12:44	GIA SEARCH	 Load PDF	
4	23/05/19 10:32	WORKSHOP INVOICE	 Load PDF	
5	23/05/19 10:32	AUTHORISATION TO ACT FORM	 Load PDF	
6	23/05/19 10:32	Release Voucher	 Load PDF	
7	23/05/19 10:32	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/11/18 10:10	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJZ6226X (Insd veh)	Model:	LEXUS GS450H 3.5 LUXURY (L10) (A)
	SKB1222D (TP veh)		
Date of Accident:	09/11/2018		

Global Sum Settlement	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	17,372.34
Final Repair Cost	: \$	10,302.00
Loss of Use	: \$	7.00 days at \$100.00 per day
Rental (if any)	: \$	days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	10,302.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)		
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)		
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%) Assessed Liability (*): ____ 100 ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks _____		

Payment Instruction: Payee's Breakdown		
1)	Soc Leon Motor Works	: \$ 10,302.00
2)		: \$
3)		: \$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

23 May
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18020503/UJA3Q2
Date: 23/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100251335
Claimant Vehicle No : SKB1222D	Insured Vehicle No :	SJZ6226X
Date of Loss: 09/11/2018	Nature of Claim:	TP
	Claim No:	6057512899SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB1222D	Engine No:	2GR8672679
Make & Model:	LEXUS GS450H, 3.5 Luxury (L10) (A)	Chassis No:	JTHBC96S905020004
Reg. Date:	29/09/2009 (Man. Year: 2009)	Odometer:	101027 km
Colour:	Black	Engine Capacity:	3456 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,712.34	10,435.60	3,276.74	23.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	2,830.00	830.00	22.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,372.34	13,265.60	4,106.74	23.64
Approved Total (Overridden) (S\$)		10,600.00		
Nett Amount (S\$)	17,372.34	10,600.00	6,772.34	38.98
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,302.00		
Global Sum Settlement (S\$)		10,302.00		

INSPECTION

Date of Assignment:	13/11/2018	
Date Inspected:	13/11/2018 Inspected At:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent / Buckled	1,217.85 FL	*1,217.85 FL
2	2		*BOOTLID HINGE	Not Necessary	548.90 FL	*- FL
3	1		*BOOTLID LOCK	Twisted	581.90 FL	*581.90 FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	274.10 FL	*274.10 FL
5	1		*HINGE SIDE GARNISH (NEAR REAR FENDER)	Torn	278.45 FL	*115.10 FL
6	1		*BOOTLID LOWER GARNISH	Cracked	281.90 FL	*281.90 FL
7	1		*LOGO	Necessary	121.10 FL	*121.10 FL
8	1		*LEXUS EMBLEM	Necessary	124.45 FL	*124.45 FL
9	1		*GS450H EMBLEM	Necessary	131.35 FL	*131.35 FL
10	1		*LIMITED EMBLEM	Necessary	121.10 FL	*121.10 FL
11	1		*REAR LH FENDER	Repair	1,200.50 FL	*- FL
12	1		*TAILLAMP (LH)	Broken	581.90 FL	*581.90 FL
13	1		*TAILLAMP PANEL (LH)	Repair	374.45 FL	*- FL
14	1		*REAR BUMPER	Distorted	978.10 FL	*978.10 FL
15	1		*TOWING COVER	Torn	121.10 FL	*60.00 FL
16	1		*BUMPER SIDE RETAINER (LH)	Bent	134.45 FL	*134.45 FL
17	1		*BUMPER REINFORCEMENT	Bent	581.90 FL	*581.90 FL
18	1		*SPONGE	Torn	78.00 FL	*78.00 FL
19	1		*REAR END PANEL	Badly Dented	972.10 FL	*972.10 FL
20	1		*PANEL TOP GARNISH	Twisted	561.60 FL	*561.60 FL
21	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	274.85 FL	*- FL
22	1		*FRONT BUMPER	Dented / Deformed	972.45 FL	*972.45 FL
23	2		*BUMPER SIDE RETAINER	Bent	342.20 FL	*342.20 FL
24	1		*NO PLATE GARNISH	Bent	182.25 FL	*182.25 FL
25	20		*BUMPER CLIPS	Necessary	258.00 FL	*60.00 FL
26	1		*LOWER GRILLE	Repair	274.45 FL	*- FL
27	1		*FRONT GRILLE	Cracked	591.60 FL	*591.60 FL
28	1		*GRILLE EMBLEM	Cracked	377.75 FL	*377.75 FL
29	1		*LOGO	Necessary	172.45 FL	*172.45 FL
30	1		*HEADLAMP (RH)	Cracked	1,712.85 FL	*1,712.85 FL
31	1		*CHROME RIM	Not Necessary	378.55 FL	*- FL
32	1		*SET NO.PLATE & HOUSING	Cracked	60.00 FS	*40.00 FS
33	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR WINDSCREEN GUM	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	15,192.60	11,568.45
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,480.26	1,132.85
Total Parts (\$\$)	13,712.34	10,435.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & FIX REVERSE SENSOR	New	80.00	50.00
2	TO SPRAY ANTI-RUST	New	180.00	60.00
3	TO REMOVE & FIX REAR WINDSCREEN GLASS	New	150.00	0.00
4	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	1,600.00	1,200.00
5	SPRAY PAINTING	New	1,500.00	1,400.00
6	TOWING FEE (BY KING DOLLEY)	New	150.00	120.00
Gross Labour Cost (S\$)			3,660.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >