

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.11.2018

REPAIR ESTIMATE

Time: 08:45:39

Page: 1

EQ - (P/P)
LKK - kalvin

(Sat) IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305236888
REGN NO : SH 7877Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 20.12.2017
DATE/TIME IN : 09.11.2018 12:15
ACCIDENT DATE : 09.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0593-G FRT DOOR LH 1 2,256.40 20.00 1,805.12

0002 28-01-0103-0003-A FRT DR COMFORTDELGRO LH 1 75.00 75.00

SUB-TOTAL : 1,880.12

JOB NATURE

0000 L PANEL BEATING

~~220.00~~ 250

0001 23-502 SPRAYPAINT ON AFFECTED AREA

~~220.00~~ 240

SUB-TOTAL : 440.00

TOTAL : 2,320.12

LMF

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Kalvin LKK
12/11/18
2 days
P/P
Before Part photo

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: