

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not marked

ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

11/11/18
Perman After pay
3 days

Date : 10/11/2018

Vehicle No : SKD 9557A

Veh Make/Model : Fiat Bravo

YOM : 2011

Chassis No : ZFA19800004313357

Date of Accident : 07/11/2018

No	Qty	Description	Amount \$
List Items:-			
1	1	Tail gate	\$ R 1,870.00 X
2	1	Tail gate windscreen glass moulding	\$ R 306.00 X
3	1	Tail gate badge	\$ R 198.00 X
4	1	Tail gate "BRAVO" emblem	\$ R 142.50 X
5	1	Tail gate lock	\$ R 264.00 X
6	1	Tail gate weatherstrip	\$ S 196.50 7
7	1	Rear bumper	\$ R 836.00 1
8	2	Rear bumper side retainer	\$ D 198.00 1
9	1	Rear bumper lower lid	\$ R 616.00 2
10	1	Rear bumper tow cover	\$ R 68.40 X
11	1	Rear LH bumper lower lid light (white)	\$ 330.00 7
12	1	Rear RH bumper lower lid light (red)	\$ 330.00 7
13	1	Rear bumper reinforcement	\$ 616.00 7
14	1	End panel	\$ R 1,144.00 X
15	1	End panel top ganish	\$ R 378.00 X
Total - List Item			\$ 7,493.40
Less 10%			\$ 502 749.34
Total			\$ 6,744.06
Special Nett Items:-			
1	1	Rear number plate with holder	\$ R 55.00 455n
2	1 Set	Rear reverse sensor	\$ 210.00 ?
3	10	Rear bumper clip	\$ R 50.00 1
4	6	End panel top ganish clip	\$ R 30.00 X
5	10	Tail gate trim board clip	\$ R 50.00 X
6	1	Tail gate windscreen glass gum/sealant	\$ R 80.00 X
7	1	Wrap sticker on rear bumper	\$ R 200.00 1
8	1	Wrap sticker on tail gate	\$ R 250.00 X
Total - SN Item			\$ 925.00
Balance b/f			\$ 7,669.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

