



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020521/K1pb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 24-10-2019



ATTN: YVONNE ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5547X	Veh. Inspected	SHB 8837U
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M012M0	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	13/11/2018

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5451749	Colour	SILVER
Odometer	472417	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/11/2018	Inspection Date	13/11/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------